

Jia LE

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
 42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
 (Email Address : woonmeng @singnet.com.sg)
 Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

To : AIG Asia Pacific Insurance Pte Ltd
 Motor Claims Dept

Dear Sirs :

TP CLAIM

Date : 27 Sep 19

Fax : 64193727

RE : ESTIMATE COST FOR OPEL COMBO - GM3328J
ACCIDENT INVOLVING GM3328J & SGK7678H ON 31/08/2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>	
1	Rear bumper <i>de-</i>	1pc	\$ 858.00	
2	Rear bumper bracket (plastic) @\$68ea <i>1. n</i>	2pcs	\$ 136.00	
3	Rear bumper bracket (Metal) @\$68ea <i>1. n</i>	2pcs	\$ 136.00	
4	Rear tailgate o/s <i>repair</i>	1pc	\$ 99.00 X	
5	Combo 1.7 <i>n</i>	1pc	\$ 99.00	
6	CDTI <i>n</i>	1pc	\$ 99.00	
7	Rear tailgate lock o/s X <i>SVL</i>	1pc	\$ 198.00 X	
8	Rear tailgate n/s <i>repair</i>	1pc	\$ 1,095.00 V	
9	Rear end panel <i>repair</i>	1pc	\$ 357.00 X	
10	Opel <i>n</i>	1pc	\$ 65.00	
			\$ 3,142.00	1393
			\$ (314.20)	10%
			\$ 2,827.80	1253.70
	Less 10%			
11	70km. <i>n</i>	1pc	\$ 10 15.00	
12	5pax <i>n</i>	1pc	\$ 10 15.00	
13	Rear windscreen sealant. X <i>n</i>	2pcs	\$ 40.00 X	
14	Rear number plate <i>U</i>	1pc	\$ 35.00	
15	Rear sensor. <i>n</i>	1set	\$ 220.00	
	Sum Carried Forward		\$ 3,152.80	275

Sum Carried Forward

\$ 3,152.80

Labour Charge & Misc

To remove, repair, replace & install
damaged parts.

To R & R sensor wiring.

To R & R wiring.

To R & R rear windscreen glass o/s.

To R & R rear windscreen glass n/s.

To putty & spray painting.

Total

P - 1253.70

S/N - 275.00

L - 1160.00

Supp-P - 508.50

T - 3197.20

20%

2557.76

L/S - 2550

4 days

Rasul

Hp 90010068


4 days

L/S

27/09/19 @ 1500

Resewing after repair

} \$ 800.00 ⁵⁰⁰ ~~450~~
}
\$ 80.00 ⁶⁰ ~~60~~
\$ 60.00 Xnn
\$ 80.00 Xnn
\$ 80.00 Xnn } 1160
\$ 800.00 ⁶⁰⁰ ~~600~~
\$ 5,052.80



email to Rasol on 27/9/15

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
(Email Adress : woonmeng @singnet.com.sg)
Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept

Date : 27 Sep 19

Dear Sirs :

Fax : 64193727

RE : ESTIMATE COST FOR OPEL COMBO - GM3328J (SUPPLEMENTARY) ACCIDENT INVOLVING GM3328J & SGK7678H ON 31/08/2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper sponge @\$105ea	2pcs	\$ 210.00 <i>Cra</i>
2	Rear bumper reinforcement.	1pc	\$ 355.00 <i>St</i>
			\$ 565.00
	Less 10%		\$ (56.50)
			<u>\$ 508.50</u>

Total

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.