

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 03 Sep 2019

**Preliminary Advice**

Vehicle No	: SKP6895E	Accident Date	: 29/08/2019
Make	: AUDI Q3	Policy No.	: 2100387642-04
Assignment Date	: 03/09/2019	Excess	: S\$0.00
Date of Inspection	: 02/09/2019	Est. Duration of Repair	: 9 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident. Undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	17,652.00
Revised Amount	:S\$	10,419.00
Check Items (Estimated)	:S\$	1,807.00
Total	:S\$	12,226.00

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	55,956.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,044.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Some parts items still pending parts prices.