

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

30 AUG 2019

E S T I M A T E

Estimate No. : b1 52542
Date Estimated : 30/08/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Wee Peter Jude
83 Jalan Kampong Chantek

Singapore 588642

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS3578A	J642786	09/04/2015	320iA ED	0

DESCRIPTION

To replace rear bumper and attachment include knocking
cause by the accident .

VALUE

1,770.00

painting rear bumper

1,038.00

To check electrical wiring systems and lightings at the
rear section for proper function.

177.00

Sundries.

80.00

Total Labour 1: 3,065.00

DESCRIPTION

RR BUMPER BOTTOM REINFORCEMENT
REAR BUMPER CENTRE GUIDE
REAR BUMPER CARRIER (ECE)
REAR BUMPER PANEL PRIMED BASIS
REAR BUMPER LH SIDE GUIDE
REAR BUMPER RH SIDE GUIDE
DECOUPLING RING PDC TORQUE CONVERTE
ULTRASONIC SENSOR BLACK

QTY PRIC VALUE

1	69.80	69.80
1	55.75	55.75
1	467.95	467.95
1	1,178.85	1,178.85
1	58.50	58.50
1	58.50	58.50
4	5.05	20.20
4	236.85	947.40

Total Parts : 2,856.95

Labour 1	:	3,065.00
Parts	:	2,856.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	414.54
Grand Total	:	6,336.49

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **