

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
AUTO	O & GENERAL IN	SURANCE (S) PL	Ref : CS/AGI19015578/	ef : CS/AGI19015578/Kyf3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date: 10-09-2019		
			Code: AGI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKH 8441K	Veh. Inspected	SHF 717P	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10003874/JM	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	02/09/2019	
2. Vehicle Particulars & Condition					
	Make & Model	RENAULT LATITUDE (A)	c.c	1995	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	VF1ABL15AUC281219	Colour	METALLIC WHITE / RED	
	Odometer	353083	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/60 R16	TOURING	9 mm	
	L/H Front Tyre	215/60 R16	TOURING	9 mm	
	R/H Rear Tyre	215/60 R16	GITI	8 mm	
	L/H Rear Tyre	215/60 R16	GITI	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	28/08/2019	Inspection Date	02/09/2019	
	Survey held at	TRANS-CAB AUTO SERVICES	PTE LTD		
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
		·		·	

2 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: