

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

VEHICLE NO : SHA 892S (Supplementary)

DATE : 6.09.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Tail Lamp Quarter Panel (LH) <i>Dental</i>			\$ 226.50 ✓
	SUB TOTAL			\$ 226.50
	LESS 20%			\$ <del>45.30</del>
	DISCOUNTED TOTAL			\$ 181.20
	<i>05/09/2019</i> <i>Jgm</i> <i>2 KE Auto</i> <i>[Signature]</i>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				