

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : **SMP 505 Y**

Model : **MERCEDES C180**

Year :

Chassis No :

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear bumper	1	\$ 2,113.50	\$1460.00 2,113.50
2	Rear bumper side retainer RH	1	\$ 186.20	\$ 186.20
3	Rear bumper side chrome	2	\$ 243.50	\$356.00 487.00
4	Rear bumper center chrome	1	\$ 236.40	\$ 236.40
5	Rear bumper tow cap	1	\$ 183.60	\$ 183.60
6	Bootlid	1	\$ 2,014.75	\$1844.12 2,014.75
7	Bootlid logo	1	\$ 147.60	\$ 147.60
8	Bootlid emblem 'KOMPRESSER'	1	\$ 130.75	\$ 130.75
9	Bootlid emblem 'C 180'	1	\$ 186.70	\$ 82.00 186.70
10	Bootlid emblem 'C&C'	1	\$ 158.30	\$ 65.00 158.30
11	Bootlid weatherstrip	1	\$ 223.40	\$ 223.40
12	Rear end panel top garnish	1	\$ 172.40	\$ 172.40
13	Taillamp RH	1	\$ 1,041.00	\$ 1,041.00
14	Taillamp lower bracket RH	1	\$ 189.70	\$158.00 189.70
Parts Sub Total :				\$5318.52 7,471.30
10% Discount :				\$ 531.85 747.13
PARTS TOTAL :				\$4786.67 6,724.17

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Taillamp seal	1	\$ 80.00	\$60.00 80.00
3	Rear bumper reverse sensor	2	\$ 256.00	\$500.00 1,024.00
4	Rear bumper clips	1	\$ 80.00	\$50.00 80.00
5	Rear end panel top garnish clips	1	\$ 60.00	\$ 60.00
6	Taillamp clips RH	1	\$ 60.00	\$30.00 60.00
SPECIAL NETT TOTAL :				\$640.00 1,384.00

Nos.	LABOUR	S\$
1	R&R bootlid component	\$ 80.00 100.00
2	R&R reverse sensor	\$ 80.00 100.00
3	To disconnect wire harness to facilitate repair work, reconnect and check functions	\$60.00 80.00
4	R&R interior upholstery	\$50.00 100.00
5	Panel beat	\$600.00 1,000.00
6	Rust proofing	\$ 60.00 100.00
7	Spray painting	\$600.00 1,000.00
LABOUR TOTAL :		\$1530.00 2,480.00

Survey & Resurvey 27/12/19

TGLim

1000 hrs

lin

Camp Sam repair

Repair Days 5

PARTS TOTAL : \$ 6,724.17 4786.67
 SPECIAL NETT TOTAL : \$ 1,384.00 640.00
 LABOUR TOTAL : \$ 2,480.00 1530.00
GRAND TOTAL : \$ 10,588.17 6956.67

@ 20% 1391.31