

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

CHINA


VEHICLE NO : SHA 7947Y

DATE 3/9/2019 10:38

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Door (LH) — <i>Replaced</i>			\$ 2,201.10	
	Rear Door Outer Moulding (LH) — <i>Paint</i>			\$ 35.80	
	Rear Door Outer Handle (LH) — <i>con</i>			\$ 36.30	
	<i>Front Door (LH) x repair</i>				
	SUB TOTAL			\$ 2,273.20	
	LESS 20%			\$ 454.64	
	DISCOUNTED TOTAL			\$ 1,818.56	
	Rear Door Comfortdelgro & Apps Sticker (LH) — <i>new</i>			\$ 80.00	Nett
	Front Door Coloured Comfort Logo (LH) — <i>new</i>			\$ 75.00	Nett
				\$ 155.00	
	Labour Charge				
	Panel Beating			\$ 400.00 ²⁰⁰	
	Spray Painting Charge			\$ 600.00 ⁴⁰⁰	
	Tuff Kote			\$ 50.00 ⁴⁰	
	Transfer of Door			\$ 80.00 ⁵⁰	
	TOTAL LABOUR			\$ 1,130.00	
	ESTIMATE TOTAL			\$ 3,103.56	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					



Larry Ng

Kalish (CEN)
3/9/19 13:00hrs
2 days.
4/5
After Repair photo