

12/20/2018

ASS. REC. BY:

Assigner: Marcus

REF: CS1U0119015678/Uyd3n2

Special Instruction:

ASSIGNMENT (Office)

From (Person): Jenny kw

of UOI

Date/Time: 4/9/19 @ 3:31pm

Estimated Cost:

Bill to:

OF PP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFE 27B

Insured:

YL 9220M

at Workshop m/s

Falcon Air

Tel:

6789 7997

of

Blk 9006 Tampines St. 93 # 01-200

Policy No:

Claim No:

M11D08091909

Sum Insured:

Excess:

D.O.A. 4/09/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 4:06pm @ 4/9/19

Person Contacted:

Joel

Vehicle IN/OUT

Date/Time

Action/Instruction

1st time

SFE 27B-CCG/A1415012416/Ap93q2

D.O.A. 21/07/2015

YL 9220M-X

10/11/13) wel

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GI / PR Seen

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

N/S	O/S

81156.

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

L7A68042

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 3 17

(A)

Make: Toyota Estima

Colour: white

Sp. Reading: 130763

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Red = 7186-50, 39%

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS = \$

Photos

Others

TOTAL

8x25=200

300+200

60

80+80

122

842

842

842

842

RECEIVED 13 SEP 2019

11/9/19

1/5 @ 11.000 confid with Insf (Red = 7186-50, 39%)

12/9/19 Typist

11,000

Nivitha (LKK Auto)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Wednesday, 4 September 2019 3:31 PM
To: JOEL; SUR; assignments
Subject: RE: 3pty claim against your insured YL9220M(SFE27B)
Attachments: 20190904142559.zip

WITHOUT PREJUDICE

Dear Joel,

We will appoint LKK as SJE as agreed.
Please let us have a copy of the estimated costs of repairs.

Dear Shiau Chan,

Please arrange to survey the vehicle at Falcon Air - Tampines.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: JOEL [mailto:joel@falconair.com.sg]
Sent: Wednesday, 4 September, 2019 3:13 PM
To: LEW JENNY <jennylew@uoi.com.sg>
Subject: Re: 3pty claim against your insured YL9220M(SFE27B)

Dear Jenny,

Pls assign LKK to conduct the PRS as a single joint expert.

Thanks and regards,
Joel Ng
Falcon-Air(Tampines)
67897997

From: LEW JENNY
Sent: Wednesday, September 04, 2019 2:59 PM
To: JOEL
Subject: RE: 3pty claim against your insured YL9220M(SFE27B)

WITHOUT PREJUDICE

Dear Joel,

Pursuant to the amended Pre-action Protocol for Non-Injury Motor Accident (NIMA), we enclose a list of our Surveyors, for your attention.

In this case, we propose to appoint M/s Priority Services.

Please revert to the undersigned within **two (2) working days** whether you have any objections to the appointment of any of our Surveyors, failing which we shall proceed to carry out the survey of your client's vehicle by our appointed Surveyors.

Please forward us a copy of the estimated cost of repair.

We reserve all our rights in this matter.

Thank You.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: JOEL [<mailto:joel@falconair.com.sg>]

Sent: Wednesday, 4 September, 2019 2:32 PM

To: LEW JENNY <jennylew@uoi.com.sg>

Subject: 3pty claim against your insured YL9220M(SFE27B)

Dear Jenny,

Pls see attached document and provide a list of 10 surveyors.

Thanks and regards,
Joel Ng
Falcon-Air(Tampines)
67897997

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Renewal Coe Toyota Vios 1.5A



2.88% P.A. \$0 Admin Fee; \$0
Down, Monthly From \$438, Std
"B" 2 Yr Warranty
GV Credit Pte Ltd StarAd



Browse by Category ▼

Sort by Date Posted

5 vehicles

toyota estima

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	toyota estima	Any	Any	2017	Any	Any	
	Toyota Estima 2.4A Aeras Premium Moonroof	\$135,800	\$13,850 /yr	16-Nov-2017	2,362 cc	14,000 km	
Lowest Depreciation And Price With Lowest Special Offer Interest Rate At 1.98%! 14000km Only As Good As New Car Condition! ARF \$44465, 7 Seater, Highest Spec Premium Model With Power Tailgate And Electric Seat! Call Us To Avoid Disappointment!							
Auto Zoom Enterprise Pte Ltd							
Posted: 01-Sep-2019 Tags: 2017 Toyota Estima, 2017 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota							
	Toyota Estima 2.4A Aeras Premium Moonroof	\$131,800	\$13,760 /yr	21-Aug-2017	2,362 cc	35,000 km	
12 Months Warranty, Attractive Financing Available And Free Titan X! Comes With Dual Moonroof And Twin Sliding Doors! Best Family C Choice In The Market! Flexible In-House Financing Package And Trade In Available, Price Negotiable. View The Car At Our Leng Kee Shc							
Supreme Cars Pte Ltd							
Posted: 29-Aug-2019 Tags: 2017 Toyota Estima, 2017 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota							
	Toyota Estima 2.4A Aeras Premium Moonroof	\$133,888	\$14,070 /yr	19-Oct-2017	2,362 cc	16,000 km	
Full Original Bodykit. Condition As Good As New! Very Well Maintained By Owner. Always Parked Under Shade. Comes With High-grade Solar Film, Magnetic Sunshade And New Tyres. High Loans Up To 80% With Lowest Interest Rates From 2.28%. Trade In Welcome. Cal							
Posted: 27-Aug-2019 Tags: 2017 Toyota Estima, 2017 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota							
	Toyota Estima 2.4A Aeras Premium Moonroof	\$133,688	\$14,170 /yr	31-Aug-2017	2,362 cc	33,000 km	
Spacious 7 Seater Unit With Auto Tailgate/ Sliding Doors. Genuine Low Mileage Done! Very Well Maintained Condition, Perfect Drive For Families. With 1-Year Warranty Available. Trade In And Flexible Loan Available, Call Now To View! Viewing By Appointment Only							
360 VR Cars							
Posted: 21-Aug-2019 Tags: 2017 Toyota Estima, 2017 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota							

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



ta Estima 2.4A Aeras
ium Moonroof

\$132,800**\$13,870 /yr****18-Aug-2017****2,362 cc****32,339 km**

Compare

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	269A
Vehicle Details	
Vehicle No.:	SFE27B
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS PREMIUM 2.4 CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	2AZ4A57316
Chassis No.:	ACR507137805
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$35,896.00
Original Registration Date:	21 Mar 2017
First Registration Date:	21 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$42,255.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2027
PARF Rebate Amount:	\$31,691.00
Intended COE Rebate Details	
COE Expiry Date:	20 Mar 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$48,556.00
COE Rebate Amount:	\$36,351.00
Total Rebate Amount:	\$68,042.00

The information contained herein is correct as at 05 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/09/2019 13:54
Date Of Accident	04/09/2019 09:10
Exact Location Of Accident	T-JUNCTION OF TUAS SOUTH AVE 3 / TUAS CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFE27B
Insured/Policyholder	
Name Of Registered Owner	HO SOON EE
NRIC No	S1440269A
Email Address	SOONEE269@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97551065
Alternative Phone No	OTHERS-97551065
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ESTIMA-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088898798-02
Cover Note Number	
Driver	
Name of Driver	TAN TECK SENG
NRIC No	S1440282I
Date Of Birth	08/05/1960
Occupation	OUTDOOR
Date Of Driving Pass	12/07/1978
Driving Experience	41 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96245455
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK248 TAMPINES STREET 21 #08-271
Postcode	521248
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : HO SOON EE GENDER: : FEMALE
Passenger 2	NAME: : MR KHOA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER SKETCH PLAN ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YL9220M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	APPADURAI PRABAKARAN
NRIC/Passport Number	G2024109N
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name HOO SOON EE
Approximate Age
Injuries Sustain
Injured person in which vehicle? SFE27B
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name TAN TECK SENG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SFE27B
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 3

Name MR KHOA
Approximate Age
Injuries Sustain
Injured person in which vehicle? SFE27B
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan Pg. 1


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 4/9/19

Sketch Plan Pg. 2

SKETCH PLAN



A - SFE 27 B

B - YL9220M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Tues South Ave 3, just as I was approaching the traffic junction the light had change to Red. I stop my vehicle, second later I felt a huge jerk and a loud sound from the rear and my vehicle was push forward to a distance. I went down and realize that this vehicle YL9220M had collided onto my vehicle (A).

☒ claim OD / TP at Falcon-Air ☐ claim OD / TP Own W/shop ☐ Reporting Only

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver's not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NHIC/IN No.:





FALCON-AIR

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD #28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D

Estimate : ES707475

Date : 04/09/2019

Vehicle Num. : SFE 27B

Make/Model : TOYOTA ESTIMA

Chassis/Eng# :

Accident Date : 04/09/2019

Claim No. :

Reference : 3 PTY 1/2

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

PARTS PURCHASED :				
1.	1PC	REAR BUMPER		
2.	2PCS	REAR BUMPER SIDE RETAINER - LONG		
3.	12PCS	REAR BUMPER CLIP		
4.	1PC	REAR BUMPER TOW HOOK COVER		
5.	1PC	O/S REAR BUMPER REFLECTOR		
6.	1PC	TAILGATE		
7.	1PC	TAILGATE INNER TRIM BOARD		
8.	20PCS	TAILGATE INNER TRIM BOARD CLIPS		
9.	1PC	TAILGATE LOCK		
10.	2PCS	TAILGATE HINGES		
11.	1PC	TAILGATE CHROME MOULDING		
12.	1PC	O/S TAILGATE VERTICAL INNER TRIM		
13.	2PCS	TAILGATE DAMPER		
14.	1PC	TAILGATE GLASS MOULDING		
15.	2PCS	REAR BUMPER SIDE RETAINER - SHORT		
16.	1PC	TAILGATE LOGO EMBLEM		
17.	1PC	TAILGATE ESTIMA EMBLEM		
18.	2PCS	TAILGATE LAMP		
19.	1PC	O/S TAILLAMP		
20.	1PC	O/S TAILLAMP PANEL		
21.	2PCS	O/S TAILLAMP CLIP		
22.	1PC	O/S REAR FENDER GLASS CW MLDING		

rec /	35.00	Ref	350.00	✓
	2.00	rec	70.00	✓
		rec	24.00	✓
		rec	15.00	✓
		rec	45.00	✓
		rec	880.00	✓
		rec	550.00	✓
	2.00	rec	40.00	✓
		rec	195.00	✓
	48.00	rec	96.00	X
		rec	135.00	✓
		rec	175.00	X
	115.00	rec	230.00	X
		rec	55.00	✓
	30.00	rec	60.00	✓
		rec	28.00	✓
		rec	30.00	✓
	285.00	rec	570.00	✓
		rec	285.00	✓
		rec	125.00	✓
	8.00	rec	16.00	X
		rec	420.00	✓

Not Added
H/alk
4/9/19

Take photo. After repair -
12 day.

1/5 # 11,000/

CONTINUE / ...

3502

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD #28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

Estimate : ES707475

Date : 04/09/2019

Vehicle Num. : SFE 27B

Make/Model : TOYOTA ESTIMA

Chassis/Eng# :

Accident Date : 04/09/2019

Claim No. :

Reference : 3 PTY 1/2

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1PC	O/S REAR FENDER	Body 700.00	✓
24.	1PC	O/S REAR FENDER INNER TRIM- TOP	11 195.00	X
25.	1PC	O/S REAR FENDER INNER TRIM- BOTTOM	680.00	✓
26.	16PCS	O/S REAR FENDER INNER TRIM CLIPS	2.00 32.00	✓
27.	1PC	O/S REAR FENDER INNER SHIELD	11 55.00	X
28.	10PCS	O/S REAR FENDER INNER SHIELD CLIPS	2.00 20.00	X
29.	1PC	REAR END PANEL	310.00	✓
30.	5PCS	REAR END PANEL GARNISH CLIP	2.00 10.00	✓
31.	1PC	REAR END PANEL GARNISH	135.00	✓
32.	1PC	REAR COMPARTMENT PANEL	500.00	✓
33.	1PC	REAR AIRCON BLOWER HOUSING ASSY	1850.00	✓
34.	2PCS	TAILGATE SIDE RUBBER	35.00 70.00	✓
35.	2PCS	TAILGATE STOPPER	12.00 24.00	X
36.	1PC	TAILGATE WEATHERSTRIP	130.00	✓
37.	1PC	TAILGATE LAMP- CENTER	210.00	✓
Total Parts Purchased S\$:			9,315.00	
10.00% Of The Above Parts S\$:			931.50	
Based On Cost Plus S\$:			10,246.50	
1.	1SET	SPECIAL NETT ITEMS :		
		REVERSE SENSOR	280.00	200 ✓
2.	1SET	REVERSE CAMERA	350.00	✓

CONTINUE / ...

7989
17
8787.9

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD #28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

Estimate : ES707475

Date : 04/09/2019

Vehicle Num. : SFE 27B

Make/Model : TOYOTA ESTIMA

Chassis/Eng#

Accident Date : 04/09/2019

Claim No. :

Reference : 3 PTY 1/2

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
3.	1PC	TAILGATE BODY SEALANT	11	100.00 X
4.	1PC	TAILGATE GLASS INNER SEAL	50	50.00 30
5.	2BTL	TAILGATE GLASS SEALANT	45.00	90.00 40
6.	1BTL	O/S REAR FENDER 1/4 GLASS SEALANT	45.00	45.00 40
7.	1PC	O/S REAR FENDER 1/4 GLASS INNER SEAL	40.00	40.00 ✓
8.	1PC	REAR NUMBER PLATE	45.00	45.00 40
9.	1PC	O/S FENDER GLASS SOLAR FILM	11	150.00 X
10.	1SET	REAR COMPARTMENT PANEL INSULATOR RUBBER	300.00	300.00 150
Special Nett Total S\$			850	1,450.00
LABOUR :				
TO CHECK LIGHT SYSTEM				50.00 30
INSTALL REVERSE CAMERA				150.00 50
TO VACCUM, REOIL AND REGAS AIR CON				100.00 ✓
ANTI-RUST				180.00 100
TO APPLY BODY SEALANT ON BODY JOINTS				180.00 50
INSTALL REVERSE SENSOR IN NEW BUMPER				80.00 40
INSTALL TAILGATE GLASS				120.00 ✓
TRANSFER TAILGATE PARTS				120.00 60
REMOVE/REFIT TRIMS, GARNISHES, SEAT, CARPET ETC				280.00 100

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD #28-01 SPRINGLEAF TOWER
SINGAPORE 079909

Attention : Motor Claim Department

Contact : 62227733 Fax No. : 63273869 /3870

Estimate : ES707475

Date : 04/09/2019

Vehicle Num. : SFE 27B

Make/Model : TOYOTA ESTIMA

Chassis/Eng#

Accident Date : 04/09/2019

Claim No.

Reference : 3 PTY 1/2

Policy No.

S/N	Quantity	Particular	Unit Price	Amount S\$
		RE-INITIALISE TAILGATE/SENSORS	350.00	100
		REPLACE O/S RR FENDER GLASS	100.00	80
		CHASSIS ALIGNMENT TO SPECIFICATION	300.00	X
		TO REPLACE REAR AIRCON HOUSING	280.00	60
		TO REPAIR WIRE HARNESS	200.00	X
		LABOUR/PANEL BEATING	2,400.00	2000
		RNR O/S RR DOOR ETC		
		SPRAY PAINTING	1,600.00	1200
		Labour Total S\$:	6,490.00	4090

E. & O.E.

Total S\$: 18,186.50

for FALCON-AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 8787.90
S.N - 890.00
L - 4090.00

13767.90
202

11014.

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD		Ref : CS/UOI19015678/Uyd3n2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date : 18-09-2019	
Code : UOI2			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YL 9220M	Veh. Inspected	SFE 27B
Policy No.		Coverage (\$)	0.00
Claim No.	M11D08091909	Excess (\$)	0.00
Assign From	JENNY LEW	Assign Date	04/09/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ESTIMA AERAS (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ACR507137805	Colour	WHITE
Odometer	130763	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R18	MICHELIN	6 mm
L/H Front Tyre	225/50 R18	MICHELIN	6 mm
R/H Rear Tyre	225/50 R18	MICHELIN	6 mm
L/H Rear Tyre	225/50 R18	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/09/2019	Inspection Date	04/09/2019
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFE 27B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (WCP)	DISTORTED	350.00	350.00
2	REAR BUMPER SIDE RETAINER-LONG @\$35.00 (WCP)	NECESSARY / BENT	70.00	70.00
12	REAR BUMPER CLIP @\$2.00 (WCP)	NECESSARY	24.00	24.00
1	REAR BUMPER TOW HOOK COVER (WCP)	DEFORMED	15.00	15.00
1	O/S REAR BUMPER REFLECTOR (WCP)	CRACKED	45.00	45.00
1	TAILGATE (WCP)	BADLY DENTED	880.00	880.00
1	TAILGATE INNER TRIM BOARD (WCP)	DEFORMED / TORN	550.00	550.00
20	TAILGATE INNER TRIM BOARD CLIPS @\$2.00 (WCP)	NECESSARY	40.00	40.00
1	TAILGATE LOCK (WCP)	DENTED	195.00	195.00
2	TAILGATE HINGES @\$48.00 (WCP)	NOT NECESSARY	96.00	-
1	TAILGATE CHROME MOULDING (WCP)	CRACKED	135.00	135.00
1	O/S TAILGATE VERTICAL INNER TRIM (WCP)	NOT NECESSARY	175.00	-
2	TAILGATE DAMPER @\$115.00 (WCP)	NOT NECESSARY	230.00	-
1	TAILGATE GLASS MOULDING (WCP)	NECESSARY	55.00	55.00
2	REAR BUMPER SIDE RETAINER-SHORT @\$30.00 (WCP)	O/S BENT	60.00	30.00
1	TAILGATE LOGO EMBLEM (WCP)	NECESSARY	28.00	28.00
1	TAILGATE ESTIMA EMBLEM (WCP)	NECESSARY	30.00	30.00
2	TAILGATE LAMP @\$285.00 (WCP)	O/S CRACKED	570.00	285.00
1	O/S TAILLAMP (WCP)	CRACKED	285.00	285.00
1	O/S TAILLAMP PANEL (WCP)	BENT	125.00	125.00
2	O/S TAILLAMP CLIP @\$8.00 (WCP)	NOT NECESSARY	16.00	-
1	O/S REAR FENDER GLASS C/W MOULDING (WCP)	NECESSARY	420.00	420.00
1	O/S REAR FENDER (WCP)	BADLY DENTED	700.00	700.00
1	O/S REAR FENDER INNER TRIM-TOP (WCP)	NOT NECESSARY	195.00	-
1	O/S REAR FENDER INNER TRIM-BOTTOM (WCP)	CRACKED	680.00	680.00
16	O/S REAR FENDER INNER TRIM CLIPS @\$2.00 (WCP)	NECESSARY	32.00	32.00
1	O/S REAR FENDER INNER SHIELD (WCP)	NOT NECESSARY	55.00	-
10	O/S REAR FENDER INNER SHIELD CLIPS @\$2.00 (WCP)	NOT NECESSARY	20.00	-
1	REAR END PANEL (WCP)	BADLY DENTED	310.00	310.00
5	REAR END PANEL GARNISH CLIP @\$2.00 (WCP)	NECESSARY	10.00	10.00
1	REAR END PANEL GARNISH (WCP)	DEFORMED / TWISTED	135.00	135.00
1	REAR COMPARTMENT PANEL (WCP)	CRUMPLED / BUCKLED	500.00	500.00

Report Ref No. CS/UOI19015678/Uyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR AIRCON BLOWER HOUSING ASSY (WCP)	CRACKED	1,850.00	1,650.00
2	TAILGATE SIDE RUBBER @\$35.00 (WCP)	NECESSARY	70.00	70.00
2	TAILGATE STOPPER @\$12.00 (WCP)	NOT NECESSARY	24.00	-
1	TAILGATE WEATHERSTRIP (WCP)	TWISTED	130.00	130.00
1	TAILGATE LAMP-CENTER (WCP)	CRACKED	210.00	210.00
	COST PLUS 10%		931.50	798.90
			10,246.50	8,787.90
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REVERSE CAMERA (SN)	SHORTED	350.00	350.00
1	TAILGATE BODY SEALANT (SN)	NOT NECESSARY	100.00	-
1	TAILGATE GLASS INNER SEAL (SN)	NECESSARY	50.00	30.00
2	BTLS TAILGATE GLASS SEALANT @\$45.00 (SN)	NECESSARY	90.00	40.00
1	BTL O/S REAR FENDER 1/4 GLASS SEALANT (SN)	NECESSARY	45.00	40.00
1	O/S REAR FENDER 1/4 GLASS INNER SEAL (SN)	NECESSARY	40.00	40.00
1	REAR NUMBER PLATE (SN)	SCRATCHED	45.00	40.00
1	O/S FENDER GLASS SOLAR FILM (SN)	NOT NECESSARY	150.00	-
1	SET REAR COMPARTMENT PANEL INSULATOR RUBBER (SN)	NECESSARY	300.00	150.00
			1,450.00	890.00
	<u>LABOUR</u>			
	TO CHECK LIGHT SYSTEM.		50.00	30.00
	INSTALL REVERSE CAMERA.		150.00	50.00
	TO VACCUM.REOIL AND REGAS AIR CON.		100.00	100.00
	ANTI-RUST.		180.00	100.00
	TO APPLY BODY SEALANT ON BODY JOINTS.		180.00	50.00
	INSTALL REVERSE SENSOR IN NEW BUMPER.		80.00	40.00
	INSTALL TAILGATE GLASS.		120.00	120.00
	TRANSFER TAILGATE PARTS.		120.00	60.00
	REMOVE/REFIT TRIMS,GARNISHES,SEAT,CARPET,ETC.		280.00	100.00
	RE-INITIALISE TAILGATE/SENSORS.		350.00	100.00
	REPLACE O/S RR FENDER GLASS.		100.00	80.00
	CHASSIS ALIGNMENT TO SPECIFICATION.	NOT NECESSARY	300.00	-
	TO REPLACE REAR AIRCON HOUSING.		280.00	60.00
	TO REPAIR WIRE HARNESS.	NOT NECESSARY	200.00	-
	LABOUR/PANEL BEATING.RNR O/S RR DOOR ETC.		2,400.00	2,000.00

Report Ref No. CS/UOI19015678/Uyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING.		1,600.00	1,200.00
			6,490.00	4,090.00
	GRAND TOTAL		18,186.50	13,767.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00

Report Ref No. CS/UOI19015678/Uyd3n2


CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.