

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD #16-01
CITY HOUSE
Singapore 068877
TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department
Your Ref No: 19/FC/TP-180 (09)
Claim Type: Third Party
Accident Date: 02/09/2019
TP Veh Reg No: SHA747D

Estimate No: EST0005013
Date: 24 Sep 2019
Policy No: MS000455
Veh Reg No: SKZ1481X
Make/Model: TOYOTA ALTIS
Chasis No: MR053REH104543894
Engine No: 1ZRY245478
Reg. Date: 12/01/2016

Estimate Repair Cost to Vehicle No :SKZ1481X

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
<u>Supplementary Parts to Repair</u>			
<u>List Price</u>			
1 BRACE PANEL	1 PC	155.00	
2 RADIATOR FAN MOTOR CONTROL UNIT	1 PC	470.00	
3 BATTERY TOP BRACKET	1 PC	55.00	
		680.00	
	Less 25%	170.00	510.00
<u>Labour</u>			
4 REPAIR WIRE HARNESS	1 UNIT	100.00	
		100.00	100.00
Total			S\$ 610.00
GST Amount			S\$ 42.70
Total Amount Payable			S\$ 652.70

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

list 18,309.50
- 25% 13,732.13
SN 204
Cc 2340

24/09/2019

16,276.13