

SUPREME AUTO SERVICE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date:

PARTICULARS

AMOUNT (\$)

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: SLW 5190 M / MAZDA 3	
1 pc	front fender LH	380.80
1 pc	front fender dust cover	132.90
10 pcs	front fender dust cover clips	35.00
1 pc	front bumper	866.80
	front fog lamp	168.90
	front fog lamp cover	32.80
1 pc	front headlamp	1,070.70
1 pc	front shock absorber	301.40
1 pc	front lower arm	509.50
1 pc	front knuckle arm	402.60
1 pc	front wheel bearing with hub	568.80
1 pc	alloy rim	986.80
	sub-total	5,457.00
	less 15% 201	818.55
	sub-total	4,638.45
	To remove & replace the parts mentioned above, panel beat & realign the necessary affected areas.	600.00
	To check wiring system.	50.00
	To apply rust proofing on affected areas.	50.00
	To apply putty & spray painting on affected areas.	500.00
	To remove & install front undercarriage parts to enable repair.	200.00
	To replace alloy rim & perform wheel bearing.	60.00
	To machine press wheel bearing.	80.00
	To perform 4 wheels computerised alignment.	70.00
	Total	6,248.45

PYRO CARS PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Not Authorized
11 Lays @ 2800/hr
Resurvey After Paint
4 days

Date: 5/9/2019