LKK Auto Consultants Pte Ltd (Co. Reg. No: 198607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

| To: | AIG Asia Pacific Insurance Pte, Ltd. AIG Building 78 Shenton Way #08-16 Singapore 079120 | | From: | LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933 | | | | | |
|--------|---|-------------------|--|---|--------|----------------------|--------------------------|--|--|
| Attn: | | Date: 09 Sep 2019 | | | | | | | |
| | | | Prelin | ninary Adv | ice | | | | |
| /ahicl | e No | | SBR448Z | | Accid | dent Date | : 03/09/2019 | | |
| Aake | 2000 | | : AUDI Q5 SPORT | | | y No. | 1800064901 | | |
| | | | 09/09/2019 | | Exce | | : S\$0.00 | | |
| | | | : 06/09/2019 | | | Duration of Repair | : 12.00 | | |
| | ction | | PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699 | | | | | | |
| oint | of In | npact / Ge | neral Description of Damages | | | | | | |
| The v | ehicle | e sustained | impact / damages n/s body and | parts claimed | are c | onsistent to the acc | ident. | | |
| | | | Repairer's Estimate (Gross) | | SS | 33,936.00 | | | |
| | | | Revised Amount | | SS | 20,792.00 | | | |
| | | | Check Items (Estimated) | | SS | 801.00 | | | |
| | | | Total | | S\$ | 21,593.00 | | | |
| | | | Lump Sum Repair | | S\$ | | | | |
| | | | Total Loss Consideration | | | | | | |
| | | | New for Old Value | | SS | | | | |
| | | | Pre-Accident Value | | SS | 171,000.00 | | | |
| | | | COE / PARF Rebate | | S\$ | 74,571.00 | | | |
| | | | Salvage Value | | S\$ | | | | |
| | | | Margin for Repair | | S\$ | 96,429.00 | | | |
| Rema | arks | | | | | | | | |
| (X | T | | is repairable at our adjusted amo your authorisation. | ount. We have | also | confirmed excess a | and policy coverage, Kin | | |
| (|) т | he vehicle | is uneconomical to be repaired, y | you are advise | d to i | nvite tender for the | wreck. | | |
| (|) . | Other comm | Sec. 10 | | | | | | |

View Received Message

This mail is associated with:

*SBR448Z (3572816051SG)

00 Sep 3 2019 1:00PM [CHUA SWEE TUCK] Premium Automobiles Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 09/09/2019 17:08 PM. From

To

Alert - Adj Mandate Approved (\$\$20792.00) - SBR448Z - Claim Handler: Mithoo Singh, Aashweenjeet Kaur Subject

Approved:20792.00:Spray paint 3 panels + 3 blend panels - 4.5 panels \$2475.00 why 6 panels given? Re-inspection to be done for damage check and supplementary items / labour,

DOCUMENTS SUMMARY

There are no documents.

View Sent Message

This mail is associated with :

*SBR448Z (3572816051SG)

OD Sep 3 2019 1:00PM [CHUA SWEE TUCK] Premium Automobiles Pte Ltd

View Recipients | Print Message | Delete Message | Forward Resend

LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 10/09/2019 10:36 AM. From

AIG_SG; Victor_KohCK To Re: Alert - Adj Mandate Approved (\$\$20792.00) - SBR448Z - Claim Handler: Mithoo Singh, Aashweenjeet Kaur Subject

Dear Sir/Madam,

Spray paint 3 panels + 3 blend panels - 4.5 panels \$2475.00 why 6 panels given?

According to surveyor,

Rear bumper, Rear fender, Rear door -3 x \$550=\$1650

End panel, Sill panel, Door Entrance, Roof Channel, Drain panel-\$1200

Wheel Arch Trim -2 x \$175=\$350.00

Door handle-\$100

Total-\$3300/-

Best Regards,

Veron Chen

<-- Original Message -->

From: AIG_SG

To: LKK_HQ

Sent On: 09/09/2019 05:08 PM

Subject: Alert - Adj Mandate Approved (5\$20792.00) - SBR448Z - Claim Handler: Mithoo Singh, Aashweenjeet Kaur

Approved: 20792.00: Spray paint 3 panels + 3 blend panels - 4.5 panels \$2475.00 why 6 panels given? Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with:

*SBR448Z (3572816051SG)

OD Sep 3 2019 1:00PM [CHUA SWEE TUCK] Premium Automobiles Pte Ltd

Reply All | Mark as Unread | Print Message | Delete Message | Forward

AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 09/09/2019 17:08 PM. From

Alert - Adj Mandate Approved (\$\$20792.00) - SBR448Z - Claim Handler: Mithoo Singh, Aashweenjeet Kaur Subject

Approved: 20792.00: Spray paint 3 panels + 3 blend panels - 4.5 panels \$2475.00 why 6 panels given? Re-inspection to be done for damage check and supplementary items / labour,

DOCUMENTS SUMMARY

There are no documents.

Rear Burper ?

Rear Gender 3+550 1650. End Penel. 2 SIII Panel. 2 Dust Entrence Rust Channel Panol

Wheel Are Trim x02 = 195 x 2 = 350 Door Hordle = 100

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 9 September 2019 5:25 PM

To:

Claims Dept; SUR

Cc:

(nora.khai@premiumauto.com.sg)

Subject:

RE: OD CLAIM FOR SBR 448 Z ON 3/9/2019

Dear TRoy.

As instructed by our client, please proceed to repair the insured vehicle SBR 448Z (Excess \$1000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Monday, 9 September 2019 11:39 AM

To: Claims Dept <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Subject: FW: OD CLAIM FOR SBR 448 Z ON 3/9/2019

Dear TRoy,

Where is parts No 21- No 40?

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims < claims@premiumauto.com.sg>

Sent: Friday, 6 September 2019 3:44 PM

To: Admin-D (LKKAuto) admin-d@lkkauto.com; Admin-a@lkkauto.com; SUR sur@lkkauto.com;

Cc: 'Glaims' <claims@premiumauto.com.sg>

Subject: RE: OD CLAIM FOR SBR 448 Z ON 3/9/2019

Dear all,

Survey was just done by surveyor. Herein attached the estimate repair with marking for your reference. Kindly assist to advise this mentioned case.

Thanks

Best Regards, TRoy Goh Claims Advisor

Premium Automobiles Pte Ltd (Neg No 1999022773W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg



This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims [mailto:claims@premiumauto.com.sg] Sent: Thursday, 5 September 2019 12:05 PM To: 'Admin-D (LKKAuto)'; 'Admin A'; 'SUR'

Cc: 'Claims'

Subject: RE: OD CLAIM FOR SBR 448 Z ON 3/9/2019

Dear all,

Attached is the estimate for your kind reference.

Best Regards, Syafiq Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W) 55 Ubi Road 1 Road Singapore 408699 p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183 e. claims@premiumauto.com.sg w. www.audi.com.sg Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims < claims@premiumauto.com.sg > Sent: Wednesday, 4 September 2019 2:29 PM

To: 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Cc: 'Claims' <<u>claims@premiumauto.com.sg</u>>
Subject: OD CLAIM FOR SBR 448 Z ON 3/9/2019

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report for your reference.

We will forward you the estimate once it is available.

Please arrange survey on 6/9/2019, 1.30pm. owner waiting

Best Regards, Syafiq Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W) 55 Ubi Road 1 Road Singapore 408699 p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183 e. claims@premiumauto.com.sg w. www.audi.com.sg



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 16 January 2020 11:46 AM

To:

'Boo seng yak'; Guo Qiang (LKKAuto); SUR; Carrine Leong;

jiayee.yap@premiumauto.com.sg; Chang Chee Sing

Subject:

RE: FINAL REVISION - SBR448Z - OD AIG - SURVEYED 6 SEP 19

Dear Mr Boo.

Confirm repair cost of \$19,330.64 before excess \$1000 and GST @ 12 days

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com> Sent: Wednesday, 15 January 2020 3:02 PM

To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Jiayee.yap@premiumauto.com.sg; Chang Chee Sing

<claims@premiumauto.com.sg>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: FINAL REVISION - SBR448Z - OD AIG - SURVEYED 6 SEP 19

Hi Guo Qiang and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$19,330.64 @ 12 days exclude 1 Sunday.

Your early closure is well appreciated. OWNER REQUEST TO CLOSE - URGENT.

Best regards - jb

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Owner ID Type: | Singapore NRIC |
|--|---------------------------------------|
| Owner ID: | 528D |
| Vehicle No.: | |
| Vehicle to be Exported: | 5BR448Z |
| | No |
| Intended Deregistration Date: Vehicle Make: | 08 Sep 2019 |
| | AUDI |
| Vehicle Model: | Q5 SPORT 2.0 TFSI QU 5 TRONIC |
| Primary Colour: | Blue |
| Manufacturing Year: | 2018 |
| Engine No.: | DAX035185 |
| Chassis No.: | WAUZZZFYXJ2153860 |
| Maximum Power Output: | 185.0 kW (248 bhp) |
| Open Market Value: | \$44,967.00 |
| Original Registration Date: | 20 Jun 2018 |
| First Registration Date: | 20 Jun 2018 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$54,954.00 |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 19 Jun 2028 |
| PARF Rebate Amount: | \$41,215.00 |
| | |
| COE Expiry Date: | 19 Jun 2028 |
| COE Category. | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$37,989.00 |
| COE Rebate Amount: | \$33,356.00 |
| Total Rebate Amount: | \$74,571.00 |

The information contained herein is correct as at 08 Sep 2019

SGCARMART.COM THE DNLY PLACE FOR SMART CAR BUYERS

audi q5 Used Vehicle List (5 vehicles)

Car Model Price Depreciation Reg Date Eng Cap Mileage Company Availability Audi Q5 2.0A TFSI Quattro 5171,000 \$17,080 /yr 04-May-2018 1,984 cc 15,000 km Precise Auto Trading Available

High Loan Available: 5 Years Warranty From Optima Werkz Until 3/5/2023, Apple Car Play Installed. Car In Pristine Condition! No Repairs. Needed! Internal Transfer Between 2 Expats. Interest From 2.28%....

Office No. - -

Wei Quan - 97713559 | Marcus Ong - 94897930 | Feng - 91153492

27-Jun-2018 1,984 cc Audi Q5 2.0A TFSI Quattro S- \$210,000 \$20,730 /yr 15,000 km Munich Alpina Pte Ltd tronic Sport

Offer Loan Interest At 2,28%, Extremely Well Maintained, Comes With Agent Warranty 5 Years, Up To 70% Financing Of Car Price Possible, It's 100% Accident-Free. View To Believe! Welcome Trade In, Call/...

Office No. - -

Zen - 90234262 | Ben - 91849182

Audi Q5 2.0A TFSI Quattro S- \$176,800 \$16,790 /yr 26-Jul-2018 1,984 cc 17,600 km Car House Pte Ltd Available tronic Sport

Only 1 Owner With Low Mileage, Extremely Well Maintained, Comes With Agent Warranty 5 Years. Up To 70% Financing Of Car Price Possible, It's 100% Accident-Free, View To Believe! Welcome Trade In, Call/...

Office No. - 64631939

Teo - 96116191 | Damien - 87848949 | Wing - 82273461 | Michelle - 86063381

Audi Q5 2.0A TFSI Quattro S- \$184,800 \$17,200 /yr Available 27-Nov-2018 1,984 cc 19,000 km Speedo Motoring tronic Sport

Owner Coinsignment, Premium Auto 5 Years Warranty, 3 Years Free Servicing. In House Loan Available. Overtrade Available. Call Javier 91811291 For Viewing Appointment.

Office No. - 67637757

Javier Eu - 91811291

Audi Q5 2.0A TFSI Quattro S- \$184,999 \$17,070 /yr 29-Nov-2018 1.984 cc 16,500 km Premium Automobiles Available

Latest Q5 With Virtual Cockpit! Management Unit! Agent Warranty Till Nov 2023 Unlimited Mileage! Certified Multipoint Check! High In House Loan Approval! Audi Bank Interest Rate 2,28%! Showroom Superb...

Office No. - 68365223

Vena Kwok - 97300219

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for CDE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagens. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & CDE results.

© 2004-2019 sgCarMart. All rights reserved.



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: CHUA SWEE TUCK

Period of Insurance

: 20 Jun 2019 To 19 Jun 2020

Engine No.

: DAX 035185

Chassis No.

: WAUZZZFYXJ2153860

Vehicle No.

: SBR448Z

Policy No.

: 1800064901-01

Endorsement No.

Issued Date

: 10 Jun 2019

ABOUT THE COVER

Make/Model

: AUDI Q5 Sport 2.0 TFSI qu

Engine Capacity/Tonnage : 1,984.00 CC

Sum Insured : Market Value

First Year of Registration : 2018

Driver Restriction

NA

Off Peak Car : No

Insuring with COE/PARF

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" (*IDR") If You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition

: 30 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for fire or reward, driving luston, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade;

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

CHUA SWEE TUCK - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Util Road 1 Singapore 408699 63662323

For other: Approved Reporting Centres/AIG Authorised Repervirs, please contact our 24-hour accident emergency hotine at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.ag or AIG SG Mobile App. Simply search and download "AIG SG" from (Tunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

I/We hereby certify that the policy to which this Certificate of Insurance relates it issued in accordance with the provisions of the Motor Vehicles (Third Party Rieks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Rieks) Rules, 1959 (Malaysia)

0504125217

PREMIUM LEASING - EF

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

SSPMLU

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the nost working day of the accident.
- Submit Witi/Summons/Correspondences from third partyties) to AIG immediately.

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s). If applicable.
- Collect details (name, address and contact number) of witnesses and/or by to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

- To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
- 2. Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
- At the time of collection of the Rental Car, the original insurance policy and schedule issued by AlG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
- The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
- 5. Rental cars are strictly for use in Singapore only.
- Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
- Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

"The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

UNDERTAKING

| 1 CHUA SWE | TUCK (NRIC No. 57032528D), hereby |
|--|---|
| | Accident Statement lodged by me on 04 SEP 2019 |
| | ertaining to the accident involving motor car Reg. No |
| SBR448Z in which | ch I was the driver are true and accurate to the best of my |
| knowledge, information and | |
| I acknowledge that my insu | arers are not liable under the contract of insurance if there is |
| a breach of policy terms an | d conditions. |
| there is evidence emerges irrevocably undertake to a insurance and I undertake | s that there is a breach of policy terms and conditions, absolve my insurer from all liability under the contract of to re-pay any sums paid by my insurers pursuant to the receipt of written demand by my insurers. CHUA SWEE TUCK |
| Nric No. | |
| | 57032528D |
| Date | : 04 SEP 2019 |
| Signature | : ha |
| Name of Policyholder | : CHUA SHEE TUCK |
| Nric No. | : 57032520D |
| Date | : 11 0-0 2.19 |



AIG Asia Pacific Insurance Pte. Ltd AIG Building 78 Shenton Way

MOTOR ACCIDENT INTERVIEW FORM

| NAME | 1 | CHUA SNEE TUCK |
|--|-------------|--|
| VEHICLE NUMBER | 4 | SBR 448Z |
| DATE/ TIME OF ACCIDENT | 12 | 03 SEP 2019 / 1300 HRS |
| PLACE OF ACCIDENT | 930 | 10 CANBERRA DRIVE, CONDO CAR PARK |
| THIRD PARTY VEHICLE (IF ANY) | | NIL |
| | | RE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT? AS STATED ABOVE . INTENDED TO GO |
| TO WORK | | |
| 59354 | | IVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED? |
| | | 5. DEGS SCRATCHES TO THE ARAA ARIVE |
| DOOR AND BUMPET | | SURROUNDING AREA (INCLUDING LEFT-READ |
| WERE YOU OR YOUR PASSENGER/S INJ FOR INVESTIGATION? | URED? IF IN | JURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE |
| ha | | |

NAME: CHUA SHEE TUCK

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP: 11113

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/OD/1064/2019/NS

Date : 5-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chua Swee Tuck
Address : 10 Canberra Drive

#01-15

Vehicle No : SBR 448 Z

Model Code : Audi Q5 SPORT 2.0 TFSI QU

Model / Year : 20/6/2018 Engine No : DAX 035185

Chassis No : WAUZZZfyxj2153860

Mileage

Date In

Estimated By : Johnny Boo / Allan Wu

Accident Date : 3-Sep-19

Place of Accident : 10 Canberra Drive

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBR 448 Z

| S/n | Nature of Jobs | | Estimated Charges | Surveyor's Recommendation |
|-----|--|-----|----------------------|------------------------------|
| 1 | To remove and reinstall rear parking aid and rear lid kick sensor. Check function. | 5/N | \$ 360.00 | 1 / |
| 2 | To renew lhs 1/4 glass to facilitate fender renewal. | S/N | \$ 300.00 | / / |
| 3 | To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages. | S/N | \$ 280.00 | 1 |
| 4 | To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay tray, electrical and audio components. | S/N | \$ 1,400.00 | 1 |
| | SUB TOTAL LABOUR CHARGES | : | \$ 2,340.00 | |

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBR 448 Z

| S/n | Nature of Jobs | | | Estimated Charges | Surveyor's Recommendation |
|-----|--|-------|----|----------------------|------------------------------|
| 5 | To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain air bag. | 5/N : | s | 1,400.00 | |
| 6 | To dismantle rear bumper, rear lid and lhs rear door. Cut out and weld lhs rear fender. Renew rear bumper and lhs rear door. Re-organise crash management components. Reinstall all parts removed, | 7 : | ş | 7,200.00 | 3500 / |
| 7 | To respray rear upper bumper, the rear fender, the rear door, door handles, the sill panel, door entrances, roof channel, drain panel, end panelling, door cover and both rear wheel arch trims. To carry out stone shipment and joint sealer works. | | S | 7,100.00 | 3300 V |
| 8 | to carry out diagnostic checks. | | S | 192.00 | 1 / |
| | TOTAL LABOUR CHARGES | : - | \$ | 15,892.00 | |

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax Material List for Accident Vehicle Regn No. SBR 448 Z

| S/N | Parts Description | _ | S/Nett | Remark |
|-----|--|----|-----------|---------|
| 1 | REAR UPPER BUMPER X Report | s | 1,571.00 | |
| 2 | REAR LOWER BUMPER X | \$ | 1,077.00 | |
| 3 | REAR BUMPER TOWING EYE COVER - LH X | \$ | 43.00 | |
| 4 | REAR BUMPER TOWING EYE COVER - RH X | 5 | 26.00 | |
| 5 | TAIL LIGHT LH X | S | 627.00 | |
| 6 | REAR BUMPER GUIDE SECTION - LH | S | 76.00 | |
| 7 | REAR BUMPER FOAM FILLER PIECE - LH X / | S | 56.00 | |
| В | REAR FENDER - SIDE PANEL - LH / Buc. | 5 | 4,072.00 | 3257.60 |
| 9 | 1/4 GLASS / WC | 5 | 750.00 | |
| 0 | REAR DOOR - LH / DO | \$ | 2,829.00 | 72,6300 |
| 1 | DOOR SEAL BRACKET | \$ | 39.00 | 3176 |
| 2 | OUTER DOOR SEAL - LH REAR / NEC | \$ | 190.00 | (52 |
| 3 | BONDING AGENT X NEC | 5 | 45.00 | |
| 4 | CLEANING SOLUTION X X) NEC | s | 65.00 | |
| 5 | DOOR SEALING STRIP X X | \$ | 15.00 | |
| 16 | OUTER DOOR SEAL - LH REAR | S | 201.00 | 160.80 |
| 17 | DOOR CATCH X VV | 5 | 132.00 | |
| 18 | REAR DOOR ATTACHMENT PARTS | S | 201.00 | |
| 9 | DOOR HANDLETRIM PLATE-LH X REPORT. | \$ | 250.00 | |
| 20 | DOOR HANDLE SENSOR - LH X A/A/ | \$ | 208.00 | |
| | SUB TOTAL SPARE PARTS : | \$ | 12,473.00 | |
| | | | | |

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.

| | | | | Damaged P | arts & Prices |
|-----|--|-----|-----|-----------|---------------|
| S/N | Parts Description | | _ | S/Nett | Remark |
| 21 | EXTERIOR DOOR HANDLE - LH X | | \$ | 35.00 | |
| >> | DOOR HANDLE HOUSING X | | \$ | 16.00 | |
| 23 | DOOR HANDLE TRIM X | | 5 | 149.00 | |
| 24 | REAR DOOR COVER - LH | | \$ | 577.00 | 461-20 |
| 25 | DOOR HANDLE HOUSING X DOOR HANDLE TRIM X REAR DOOR COVER - LH & REAR WHEEL COVER - LH / RH & **C . | 2 | \$ | 974.00 | 779,26 |
| 26 | ACRYLIC SEALANT / | S/N | 5 | 180.00 | 180 |
| 7 | CAVITY WAX / | S/N | \$ | 140.00 | 140 |
| 8 | STONE CHIP / | S/N | 5 | 180.00 | 180 |
| 29 | METAL FILLER POWDER / | S/N | 5 | 280.00 | 280 |
| 30 | 1/4 GLASS SEALANT | S/N | \$ | 100.00 | 100 |
| 31 | SUNDRIES 1 VMC. | | \$ | 600.00 | 13.28 |
| | TOTAL SPARE PARTS | - 8 | \$ | 15,704.00 | |
| | TOTAL LABOUR CHARGES | \$ | \$ | 15,892.00 | 18,232 |
| | GRAND TOTAL | 1 | \$- | 31,596.00 | 33,936 |
| | All charges are not inclusive of GST. | 8 | | | |

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability Remarks

12 Days. | Violellar befre part photos. GuoQiang -82880282

06/9/19. GXOSS TBA

Not Authorised

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd LKK Auto Consultants hence notify the Repairer of the following:

- * To resurvey before/after spray painting
- . To display damaged partis) c. ng resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- . No illegal modification(s) is allowed.
- . Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs

Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183

Reference : PA/OD/1064/2019/NS

Date : 5-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chua Swee Tuck

Address : 10 Canberra Drive

#01-15

Singapore 768142

Telephone : HP +65 98206421

Type of Claim : Own Damage Claim

Policy No. : 1800064901

Vehicle No : SBR 448 Z

Model Code : Audi Q5 SPORT 2.0 TFSI QU

Model / Year : 20/6/2018 Engine No : DAX 035185

Chassis No : WAUZZZfyxj2153860

Mileage :

Date In

Estimated By : Johnny Boo / Allan Wu

Accident Date : 3-Sep-19

Place of Accident : 10 Canberra Drive

Hi Guo Qiang

12 days exclude 1 Sunday

Jb 15 Jan 20,

URGENT CLOSURE OWNER REQUESTED

WIP: 11113

Premium Automobiles 55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBR 448 Z

| S/n | Nature of Jobs | Estimated Charges | Surveyor's Recommendation | | | |
|-----|--|----------------------|------------------------------|----------|----|----------|
| 1 | To remove and reinstall rear parking aid and rear lid kick sensor. Check function. | S/N | \$ | 360.00 | s | 360.00 |
| 2 | To renew lhs 1/4 glass to facilitate fender renewal. | S/N | \$ | 300.00 | \$ | 300.00 |
| 3 | To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages. | S/N | \$ | 280.00 | s | 280.00 |
| 4 | To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay tray, electrical and audio components. | S/N | \$ | 1,400.00 | s | 1,400.00 |
| | SUB TOTAL LABOUR CHARGES | : | \$ | 2,340.00 | \$ | 2,340.00 |

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBR 448 Z

| S/n | Nature of Jobs | | | Estimated Charges | Surveyor's ecommendation | |
|-----|--|-----|----|----------------------|--------------------------|-----------|
| | c/f | | | | s | 2,340.00 |
| 5 | To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain air bag. | S/N | \$ | 1,400.00 | s | 1,400.00 |
| 6 | To dismantle rear bumper, rear lid and lhs rear door. Cut out and weld lhs rear fender. Renew rear bumper and lhs rear door. Re-organise crash management components. Reinstall all parts removed, | | \$ | 7,200.00 | \$ | 3,500.00 |
| 7 | To respray rear upper bumper, lhs rear fender, lhs rear door, door handles, lhs sill panel, door entrances, roof channel, drain panel, end panelling, door cover and both rear wheel arch trims. To carry out stone shipment and joint sealer works. | | \$ | 7,100.00 | s | 3,300.00 |
| 8 | to carry out diagnostic checks. | | \$ | 192.00 | \$ | 192.00 |
| | TOTAL LABOUR CHARGES | : | \$ | 15,892.00 | s | 10,732.00 |

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBR 448 Z

| | | | Damaged Pa | rts & | Prices |
|-----|------------------------------------|--------|------------|-------|----------|
| S/N | Parts Description | | S/Nett | | Remark |
| 1 | REAR UPPER BUMPER | \$ | 1,571.00 | | |
| 2 | REAR LOWER BUMPER | \$ | 1,077.00 | | |
| 3 | REAR BUMPER TOWING EYE COVER - LH | \$ | 43.00 | | |
| 4 | REAR BUMPER TOWING EYE COVER - RH | \$ | 26.00 | | |
| 5 | TAIL LIGHT LH | \$ | 627.00 | | |
| 6 | REAR BUMPER GUIDE SECTION - LH | \$ | 76.00 | | |
| 7 | REAR BUMPER FOAM FILLER PIECE - LH | \$ | 56.00 | | |
| 8 | REAR FENDER - SIDE PANEL - LH | s | 4,072.00 | S | 3,257.60 |
| 9 | 1/4 GLASS | \$ | 750.00 | s | 599.60 |
| 10 | REAR DOOR - LH | \$ | 2,829.00 | \$ | 2,263.20 |
| 11 | DOOR SEAL BRACKET | \$ | 39.00 | \$ | 31.76 |
| 12 | OUTER DOOR SEAL - LH REAR | NEC \$ | 190.00 | \$ | 152.00 |
| 13 | BONDING AGENT | NEC \$ | 45.00 | | |
| 14 | CLEANING SOLUTION | NEC \$ | 65.00 | | |
| 15 | DOOR SEALING STRIP | \$ | 15.00 | | |
| 16 | OUTER DOOR SEAL - LH REAR | \$ | 201.00 | \$ | 160.80 |
| 17 | DOOR CATCH | \$ | 132.00 | | |
| 18 | REAR DOOR ATTACHMENT PARTS | \$ | 201.00 | | |
| 19 | DOOR HANDLE TRIM PLATE - LH | \$ | 250.00 | | |
| 20 | DOOR HANDLE SENSOR - LH | \$ | 208.00 | | |
| | SUB TOTAL SPARE PARTS | | 12,473.00 | \$ | 6,464.96 |

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.

| | | | | Damaged Pa | Parts & Prices | | |
|-----|----------------------------|-----|--------|------------|----------------|-----------|--|
| S/N | Parts Description | | S/Nett | | Remark | | |
| | | c/f | | | \$ | 6,464.96 | |
| 41 | EXTERIOR DOOR HANDLE - LH | | \$ | 35.00 | | | |
| 42 | DOOR HANDLE HOUSING | | S | 16,00 | | | |
| 43 | DOOR HANDLE TRIM | | \$ | 149.00 | | | |
| 44 | REAR DOOR COVER - LH | | \$ | 577.00 | \$ | 461.20 | |
| 45 | REAR WHEEL COVER - LH / RH | 2 | \$ | 974.00 | \$ | 779.20 | |
| 46 | ACRYLIC SEALANT | S/N | \$ | 180.00 | S | 180.00 | |
| 47 | CAVITY WAX | S/N | \$ | 140.00 | \$ | 140.00 | |
| 48 | STONE CHIP | S/N | \$ | 180.00 | \$ | 180.00 | |
| 49 | METAL FILLER POWDER | S/N | \$ | 280.00 | \$ | 280.00 | |
| 50 | 1/4 GLASS SEALANT | S/N | \$ | 100.00 | \$ | 100.00 | |
| 51 | SUNDRIES | | \$ | 600.00 | 5 | 13.28 | |
| | TOTAL SPARE PARTS | | \$ | 15,704.00 | \$ | 8,598.64 | |
| | TOTAL LABOUR CHARGES | 2 | s | 15,892.00 | \$ | 10,732.00 | |
| | GRAND TOTAL | 12 | 5 | 31,596.00 | \$ | 19,330.64 | |
| | | | _ | | | | |

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :

Liability : Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept

Yr Ref: SBR 448 Z

Norah Khai 6768 9911 6841 1183

Nora.khai@premiumauto.com.sg Body & Paint Dept PA/OD/1064/2019/NH

18th February 2020

from

Telephone +65-Telefax +65-

EMail

Our department

Our Ref Your Ref Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SBR 448 Z, Audi Q5 SPORT 2.0 TFSI qu S-TRONIC.

With reference to the above-mentioned vehicle, no. SBR 448 Z, claimant, Mr. Chua Swee Tuck, please find the related document per attached.

- A copy of the Original invoice no. 85014851 S\$ 19,613.78.
- A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encl AIG - SBR 448 Z Premium Automobiles Pte Ltr Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323

Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Main Telefax 6471 3733

Alexandra Service Centre 281 Alexandra Road Singapore 159938 Main Telephone 6386 2223 Main Talefax 6475 1023

Ubi Service Centre 55 Libi Road 1 Singapore 408699 Main Telephone 6388 2323 Main Telefax 6841 1183

Customer Service Service Appointment 24-hour Breakdown Service 8366 2323 customer care@oremiumauto.com.sg Email

INS TAX INVOICE

Page

1.

14:19

Company Reg. No. 199902271W GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120 079120

Invoice No: 85014851

Account: A0006

0)

Date : 17/02/2020

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

Regn No: sbR04482 (V 38348)

Regn Date: 20/06/2018

Term : 30

Mileage: 30497

WIP No.: 11113

Model: Q5 SPORT 2.0 TFSI qu 5 tronic Chassis; WAUZZZFYXJ2153860

Order : SBR0448Z

Engine: DAX 035185

Dept: U

You have been assisted by :- UB-Tony Foong

(33)

| | | Details | Qty | Unit Price | Amount |
|---|----------|--|----------|------------|-----------|
| 2 | EXC | Insurance Excess/Liability M: 8888 | -1000.00 | 1.00 | -1,000.00 |
| | BODYWORK | TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR, CHECK FUNCTION. | 360.00 | 1.00 | 360.00 |
| | BODYWORK | TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER | 300.00 | 1.00 | 300.00 |
| | BODYWORK | TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES | 280.00 | 1.00 | 280.00 |
| | BODYWORK | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAY, ELECTRICAL AND AUDIO EQUIPMENT | 1400.00 | 1.00 | 1,400.00 |
| | BODYWORK | M: TO SUPPLY ACRYLIC SEALANT, CAVITY WAX, STONE CHIP, METAL FILLER POWDER AND 1/4 GLASS SEALANT | 880.00 | 1.00 | 880.00 |
| | BODYWORK | TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD FILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG | 1400.00 | 1.00 | 1,400.00 |
| | BODYWORK | M: TO DISMANTLE REAR BUMPER, REAR LID AND LHS REAR DOOR.CUT OUT AND WELD LHS REAR FENDER. RENEW REAR DOOR.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED | 3500.00 | 1.00 | 3,500.00 |
| | BODYWORK | TO RESPRAY REAR UPPER BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL, END PANELLING AND | 3300.00 | 1.00 | 3,300.00 |

Premium Automobiles Pte Ltd



Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Main Telefax 6471 3733

Alexandra Service Centre 281 Alexandra Road Singapore 159938 Main Telephone 6386 2223 Main Telefax 6475 1023

Ubi Service Centre 55 Ubi Road Singapore 408699 Main Telephone 6388 2323 Main Telefax 6641 1183

Customer Service Service Appointment 24-hour Breakdown Service 6366 2323 9828 1233 customer care@premiu auto.com.sg

INS TAX INVOICE

Page

2

14:19

Company Reg. No. 199902271W GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120 079120

Invoice No: 85014851

Term : 30

Account: A0006

0)

Date : 17/02/2020

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

Regn No: SBR0448Z

(V

Regn Date: 20/06/2018

Mileage: 30497

WIP No.: 11113

38348)

Order : SBR0448Z

Model: Q5 SPORT 2.0 TFSI qu 8 tronic Chassis: WAUZZZFYXJ2153860

Engine: DAX 035185

Dept: U

You have been assisted by :- UB-Tony Foong

(33)

| | Details | | Qty | Unit Price | Amount |
|--|--|--|--|---|--|
| S BODYWORK X A80A809837 STL X A80A845297H NVB X A80A833051B STL X A80A83911B X A80A853917A GRU X A80A853817A GRU X A80A853818A GRU X A80A839151A X AWHT005180 | DOOR COVER.TO CARRY OUT STONE CHIP TAND JOINT SEAER WORK TO CARRY OUT DIAGNOSTIC CHECK (A) (GER) SUBPART 10/9 (A) (SK) SIDE WINDO 10 DOOR SEAL(LAST) (A) (SK) DOOR SEAL 10/ COVER (LAST) AP COVER AP COVER AP (A) (SK) BRACKET 5/10/ BOLT AP | Less 020% Less 020% Less 020% Less 020% Less 020% Less 020% Less 020% Less 020% | 1,00 1,00 1,00 1,00 1,00 1,00 1,00 2,00 | 1.00 4072.00 749.50 2829.00 190.00 201.00 576.30 487.00 39.70 8.30 | 192.00 3,257.60 599.60 2,263.20 160.80 461.20 389.60 31.76 13.28 |

7,718.64 Parts Labour 0.00 11,612.00 Sublet Menus 0.00 Lubricant 0.00

Sub-Total 18,330.64 1,283.14 7% GST 19,613.78 Grand Total

Received by

For & on behalf of Premium Automobiles Pte Ltd

Telefax

to AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Motor Claims Dept Yr Ref: SBR 448 Z Norah Khai 6768 9828 6841 1183 from Telephone +65-Telefax +65-

Body Repair

Mobile +65-Our department Your Claim Ref

PA/OD/1064/2019/TG 19 October 2019 Our Ref Date

total pages

Showroom

9 Leng Kee Road Singapore 159090

55 Ubi Road 1 Singapore 408699

Premium Automobiles Pte Ltd

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres

Telephone (65) 6366 2323 Telefax (65) 6841 1183

RE: CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model

Audi Q SPORT 2.0 TFSI QU

Vehicle Chassis No.

WAUZZZFYXJ2153860

Vehicle Regn No.

SBR 448 Z

Vehicle Mileage

26373 KM

Vehicle Owner

Mr. Chua Swee Tuck

Certificate No

1800064901

Own Damage Excess :

\$ 1070.00 (Inclusive GST)

Accident Date

: 03/09/2019

Place

10 Canberra Drive

Repair Cost

\$ 19.613 78

WIP No.

: 11113

:

Repairer's Name

Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

...CLAIM SUBFOLDER...(Pending for Survey Report)

| Case: | Notified | Est Submitted | Adj Assigned | Adj Rpt | | Ad) Subr | mitted | Ins Auth'ed | Status | | |
|--|----------------------|--|--------------------------------------|-----------------------------|--------|----------------------|--|-------------------------------------|--------------------------------|------------|-----------|
| | 09 Sep 2019 11:57 | | 09 Sep 2019 10:50 Edit Adj Rpt | S\$19,330.6 Edit Estimat | 1000 | \$\$19,33 View Rp | Control of the Contro | | Pending for Survey Cancel Case | | vey Repor |
| , | dain . | Re | ference | C | laim D | etails | | Documen | its | 1 | Show All |
| CLAIM SU | BFOLDER DE | TAILS | | | | | [Created | d by insurer] | | | |
| Insured: | CHUA SW | EE TUCK, ID: S | 7032528D, Tel | +65982064 | 21, Er | mail: TUC | CK_CHUA@ | YAHOO.COM.SG | | | |
| Vehicle Reg No.: | SBR448 | Z | | | Date | of Loss: | | 19 13:00 - :59 ths and 14 Days i | From LTA | leg Date (| Man Yr)] |
| Claim Type: OD / 3572816051SG Policy/Cover Note No.: 1800064901 (Compre | | 901 (Comprehens | ehensive) | | | | | | | | |
| | | | | | Exces | 151 | 5\$1,000.00 | | | | |
| Repairer: | Premium | Automobiles Pte | Ltd (UBI) 55 t | Jbi Road 1, 40 | 8699 | Ubi - Tel: | 67689828 | 8/9827/9911 | | | |
| Handling Insurer: | | Pacific Insurance jeetkaur. Mithoosin | |) - Tel: 65-64 | 19-300 | 0 [Ha | ndled by N | Aitheo Singh, Ai | shweenj | eet Kaur] | |
| Adjuster: | LKK Auto | Consultants Pte | Ltd (HQ) - Tel: | 6256-3561 | . [Han | dled by) | KING GUO | QIANG] [Fit | nal Rpt | due 18/0 | 9/2019] |
| Driver/Cust dian: | CHUA SWI | EE TUCK (48 / Mail | e), NRIC: S70 | 32528D, Te | 1: +65 | 9820642 | 1 Email: T | UCK_CHUA@YAH | 00.COM.S | G | |
| ASSOCIAT | ED MAIL RE | CEIVED | | | | | | | View All | Compose | Case Mail |
| | | : Alert - Adj Man : SBR448Z / OD | | | | | | andler: Mithoo | Sing | | |
| ALL ASSO | CIATED TAS | sks⊟ | | | | | View All | Search Tasks | Create N | ew.Task | Complete |
| Due Date | Priority | Type Task | Group Subj | ect Hand | lane | Assign | met Blue | Completed Or | | ated On | Done? |

Claim Documents

*SBR448Z (35728160515G) OD Sep 3 2019 1:00PM [CHUA SWEE TUCK] Premium Automobiles Pte Ltd

| Uplos | ad Documents Uplo | ad Photos Compose New Letter Upload Video Upload Audio | View | View in Brow | ser Y |
|---------------|---|--|--------|--------------|-------|
| Asse | ssment Reports | | 1 per | page v | 100 |
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 09/09/19 12:38 | Adjuster Immediate Advice | 0 | Load HTM | _ |
| Photo | os/Images | | 3 per | page ¥ | 88 |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnail | Print |
| 1 | 09/09/19 11:28 | General View | 0 | Load JPG | 8 |
| 2 | 09/09/19 11:28 | General View | 0 | Load JPG | 8 |
| 3 | 09/09/19 11:28 | General View | 0 | Load JPG | 8 |
| 4 | 09/09/19 11:28 | General View | 0 | Load 3PG | Ø |
| 5 | 09/09/19 11:28 | General View | 0 | Load 3PG | 8 |
| 6 | 09/09/19 11:28 | General View | 0 | Load JPG | 8 |
| 7 | 09/09/19 11:28 | General View | 0 | Load JPG | 88 |
| В | 09/09/19 11:28 | General View | 0 | Load JPG | 100 |
| 9 | 09/09/19 11:28 | General View | 0 | Load JPG | 80 |
| 10 | 09/09/19 11:28 | General View | 0 | Load JPG | 8 |
| 11 | 09/09/19 11:28 | General View | 0 | Load JPG | 8 |
| 12 | 09/09/19 11:28 | General View | 0 | Load JPG | 160 |
| 13 | 09/09/19 11:28 | General View | 0 | Load JPG | 8 |
| 14 | 09/09/19 11:28 | General View | 0 | Load JPG | 8 |
| 15 | 09/09/19 11:28 | General View | 0 | Load JPG | 2 |
| 16 | 09/09/19 11:28 | General View | 0 | Load JPG | 8 |
| 17 | 09/09/19 11:28 | General View | 0 | Load JPG | 2 |
| 18 | 09/09/19 11:28 | General View | 0 | Load JPG | 10 |
| 19 | 09/09/19 11:28 | General View | 0 | Load JPG | 2 |
| 20 | 09/09/19 11:28 | General View | 0 | Load JPG | 80 |
| 21 | 16/01/20 10:19 | Reinspection Photo | 0 | Load JPG | 8 |
| 22 | 16/01/20 10:19 | Reinspection Photo | 0 | Load JPG | 8 |
| 23 | 16/01/20 10:19 | Reinspection Photo | 0 | Load JPG | 80 |
| Danie | mentation | | Tt nee | page ¥ | 2 |
| - | 7-10-10 (100 (100 (100 (100 (100 (100 (10 | LVV Auto Consultanta Dto Ltd (UC) | 1 per | Thumbnail | |
| - | Relabel/Reorder 09/09/19 12:03 | LKK Auto Consultants Pte Ltd (HQ) Singapore Accident Statement | 0 | Load PDF | Frinc |
| _ | 09/09/19 12:03 | Insured's Driving License | ŏ | Load PDF | |
| $\overline{}$ | 09/09/19 12:04 | INTERVIEW FORM | ŏ | Load PDF | |
| | 09/09/19 12:04 | UNDERTAKING | ŏ | Load PDF | |
| | 09/09/19 12:04 | MARK ESTIMATE | Ŏ | Load PDF | |
| | 09/09/19 16:07 | Certificate of Insurance | Õ | Load PDF | |
| _ | 19/02/20 15:13 | Workshop Invoice | Ö | Load PDF | |
| | 19/02/20 15:13 | Discharge Voucher | Ö | Load PDF | |

Linked Accident Report Documents

| | | View In Bo | | wser Y | |
|--------------------|--------------|-----------------------------------|--------------|--------|--|
| Assessment Reports | | s | 1 per page ▼ | | |
| No | Finalized On | Premium Automobiles Pte Ltd (UBI) | Thumbnail | Print | |

| Ass | essment Reports | | 1 per | page 🔻 | 8 |
|-----|-----------------|-----------------------------------|-------|-----------|----------|
| Nο | Finalized On | Premium Automobiles Pte Ltd (UBI) | | Thumbnail | Print |
| 1 | 04/09/19 14:22 | Accident Statement | 0 | Load HTM | |
| Pho | tos/Images | | 3 per | page v | 2 |
| No | Finalized On | Premium Automobiles Pte Ltd (UBI) | | Thumbnail | Print |
| 1 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 8 |
| 2 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 2 |
| 3 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 8 |
| 4 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 8 |
| 5 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | • |
| 6 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 80 |
| 7 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 8 |
| 8 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 8 |
| 9 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | € |
| 10 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 8 |
| 11 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | Ø |
| 12 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 8 |
| 13 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 8 |
| 14 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 23 |
| 15 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 8 |
| 16 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 83 |
| 17 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 80 |
| 18 | 04/09/19 14:19 | Accident Photo | 0 | Load JPG | 8 |
| Doc | cumentation | | 1 per | page T | 8 |
| No | Finalized On | Premium Automobiles Pte Ltd (UBI) | | Thumbnail | Print |
| 1 | 04/09/19 14:20 | Sketch Plan | 0 | Load JPG | • |
| 2 | 04/09/19 14:20 | Sketch Plan #2 | 0 | Load JPG | 82 |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset Save Print |
|--|------------------|
| There are no document checklists configured. | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | |
| Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties. | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #08-16

Singapore 079120

Our File No:

CC3/AIG19015879/GVF3N2

Date:

20/02/2020

REFERENCE

Date of Loss:

Insured/Claimant:

CHUA SWEE TUCK

03/09/2019

Policy No:

1800064901

Nature of Claim:

OD

Claim No:

3572816051SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SBR448Z

Make & Model:

AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A) 20/06/2018 (Man. Year: 2018)

Engine No: Chassis No:

Odometer:

DAX035185

Reg. Date: Colour:

Blue

WAUZZZFYXJ2153860

Engine Capacity:

1984 cc

Market Value/New Car Price:

S\$171,000.00

Market Value/New Car Price

24212 km

Sum Insured (S\$): General Condition:

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Steering (Serviceable):

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

235/55 R19

Rear Tyre Size:

235/55 R19

Front Left Side: Front Right Side:

Continental 6 mm Continental 6 mm Rear Left Side: Rear Right Side: Continental 6 mm Continental 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------------|------------|------------|------------|--------|
| Parts | | 15,704.00 | 8,598.64 | 7,105.36 | 45.25 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 18,232.00 | 10,732.00 | 7,500.00 | 41.14 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Calculated Gross Total (S\$) | 33,936.00 | 19,330.64 | 14,605.36 | 43.04 |
| | - Excess (S\$) | 1,000.00 | 1,000.00 | 0.00 | 0.00 |
| | (S\$) | 32,936.00 | 18,330.64 | 14,605.36 | 44.34 |
| | + GST 7.00/7.00% (S\$) | 2,305.52 | 1,283.14 | 1,022.38 | 44.34 |
| | Nett Amount (S\$) | 35,241.52 | 19,613.78 | 15,627.74 | 44.34 |

INSPECTION

Date Inspected:

Date of Assignment:

09/09/2019

06/09/2019

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

12.0 days

XING GUO QIANG Adjuster:

Manager:

VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| 7 1 2 2 2 | Commende Qty Part No. | | Condition | Repairer's | Amount |
|-----------|--------------------------|-------------------------------------|-------------------|-------------|--------------|
| 1 | 1 | *REAR UPPER BUMPER | Repair | 1,571.00 FS | *-FS |
| 2 | 1 | *REAR LOWER BUMPER | Not Necessary | 1,077.00 FS | *-FS |
| 3 | 1 | *REAR BUMPER TOWING EYE COVER - LH | Not Necessary | 43.00 FS | *-FS |
| 4 | 1 | *REAR BUMPER TOWING EYE COVER - RH | Not Necessary | 26.00 FS | *-FS |
| 5 | 1 | *TAIL LIGHT LH | Not Necessary | 627.00 FS | *-FS |
| 6 | 1 | *REAR BUMPER GUIDE SECTION - LH | Not Necessary | 76.00 FS | *-FS |
| 7 | 1 | *REAR BUMPER FOAM FILLER PIECE - LH | Not Necessary | 56.00 FS | *-FS |
| 8 | 1 | *REAR FENDER - SIDE PANEL - LH | Buckled | 4,072.00 FS | *3,257.60 FS |
| 9 | 1 | *1/4 GLASS | Necessary | 750.00 FS | *599.60 FS |
| 10 | 1 | *REAR DOOR - LH | Dented | 2,829,00 FS | *2,263.20 FS |
| 11 | 1 | *DOOR SEAL BRACKET | Necessary | 39.00 FS | *31.76 FS |
| 12 | 1 | *OUTER DOOR SEAL - LH REAR | Necessary | 190.00 FS | *152.00 FS |
| 13 | 1 | *BONDING AGENT | Not Necessary | 45.00 FS | *-FS |
| 14 | 1 | *CLEANING SOLUTION | Not Necessary | 65.00 FS | *-FS |
| 15 | 1 | *DOOR SEALING STRIP | Not Necessary | 15.00 FS | *-FS |
| 16 | 1 | *OUTER DOOR SEAL - LH REAR | Necessary | 201.00 FS | *160.80 FS |
| 17 | 1 | *DOOR CATCH | Not Necessary | 132.00 FS | *-FS |
| 18 | 1 | *REAR DOOR ATTACHMENT PARTS | Not Necessary | 201.00 FS | *-FS |
| 19 | 1 | *DOOR HANDLE TRIM PLATE - LH | Repair | 250.00 FS | *-FS |
| 20 | 1 | *DOOR HANDLE SENSOR - LH | Not Necessary | 208.00 FS | *-FS |
| 21 | 1 | *EXTERIOR DOOR HANDLE - LH | Not Necessary | 35.00 FS | *-FS |
| 22 | 1 | *DOOR HANDLE HOUSING | Not Necessary | 16.00 FS | *-FS |
| 23 | 1 | *DOOR HANDLE TRIM | Not Necessary | 149.00 FS | *-FS |
| 24 | 1 | *REAR DOOR COVER - LH | Necessary | 577.00 FS | *461.20 FS |
| 25 | 2 | *REAR WHEEL COVER - LH / RH | Necessary | 974.00 FS | *779.20 FS |
| 26 | 1 | *ACRYLIC SEALANT | Necessary | 180.00 FS | *180.00 FS |
| 27 | 1 | *CAVITY WAX | Necessary | 140.00 FS | *140.00 FS |
| 28 | 1 | *STONE CHIP | Necessary | 180.00 FS | *180.00 FS |
| 29 | 1 | *METAL FILLER POWDER | Necessary | 280.00 FS | *280.00 FS |
| 30 | 1 | *1/4 GLASS SEALANT | Necessary | 100.00 FS | *100.00 FS |
| 31 | 1 | *SUNDRIES | Necessary | 600.00 FS | *13.28 FS |
| F=Fr | anchise part. S=Spc | Nett. | Total Parts (S\$) | 15,704.00 | 8,598.64 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

| Recomi | mended | Labour | r |
|----------|--------|--------|---|
| LOCULIII | nended | Labou | |

| Particulars | Lab.Type | Repairer's | Amount |
|---|--|--|--|
| our Items | | | |
| TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR, CHECK FUNCTION | New | 360.00 | 360.00 |
| TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL | New | 300.00 | 300.00 |
| TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES, INSPECT FOR DAMAGES | New | 280.00 | 280.00 |
| TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAY, ELECTRICAL AND AUDIO COMPONENTS | New | 1,400.00 | 1,400.00 |
| TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BAG | New | 1,400.00 | 1,400.00 |
| TO DISMANTLE REAR BUMPER, REAR LID AND LHS REAR DOOR. CUT OUT AND WELD LHS REAR FENDER. RENEW REAR BUMPER AND LHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New | 7,200.00 | 3,500.00 |
| TO RESPRAY REAR UPPER BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLES, LHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL, END PANELLING, DOOR COVER AND BOTH REAR WHEEL ARCH TRIMS. TO CARRY OUT STONE SHIPMENT AND JOINT SEALER WORKS | New | 7,100.00 | 3,300.00 |
| TO CARRY OUT DIAGNOSTIC CHECKS | New | 192.00 | 192.00 |
| Gross Labour | Cost (S\$) | 18,232.00 | 10,732.00 |
| | TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAY, ELECTRICAL AND AUDIO COMPONENTS TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BAG TO DISMANTLE REAR BUMPER, REAR LID AND LHS REAR DOOR. CUT OUT AND WELD LHS REAR FENDER. RENEW REAR BUMPER AND LHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED TO RESPRAY REAR UPPER BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLES, LHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL, END PANELLING, DOOR COVER AND BOTH REAR WHEEL ARCH TRIMS. TO CARRY OUT STONE SHIPMENT AND JOINT SEALER WORKS TO CARRY OUT DIAGNOSTIC CHECKS | TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR, CHECK FUNCTION TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAY, ELECTRICAL AND AUDIO COMPONENTS TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BAG TO DISMANTLE REAR BUMPER, REAR LID AND LHS REAR DOOR. CUT OUT AND WELD LHS REAR FENDER. RENEW REAR BUMPER AND LHS REAR DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED TO RESPRAY REAR UPPER BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLES, LHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL, END PANELLING, DOOR COVER AND BOTH REAR WHEEL ARCH TRIMS. TO CARRY OUT STONE SHIPMENT AND JOINT SEALER WORKS | TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID New 360.00 KICK SENSOR, CHECK FUNCTION TO RENEW LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL New 300.00 TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAY, ELECTRICAL AND AUDIO COMPONENTS TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIR BAG TO DISMANTLE REAR BUMPER, REAR LID AND LHS REAR DOOR. CUT OUT AND WELD LHS REAR FENDER. RENEW REAR BUMPER AND LHS REAR DOOR, RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED TO RESPRAY REAR UPPER BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR HANDLES, LHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL, END PANELLING, DOOR COVER AND BOTH REAR WHEEL ARCH TRIMS. TO CARRY OUT STONE SHIPMENT AND JOINT SEALER WORKS TO CARRY OUT DIAGNOSTIC CHECKS New 192.00 |

< END OF ESTIMATES >