

ASS. REC. BY:

REP: OS/CTI/9015887/Kyd3/12

Special Instruction:

Supervisor: KennethASSIGNMENT (Office)From (Person): Chang Boon Senof CTIDate/Time: 6/9/19 @ 2:19pm

Estimated Cost: _____

Bill to: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: _____

SKR 2259HInsured: SLK 98004

at Workshop, n/a

3 Three AutomotiveTel: 6284 1542

of _____

Blk 8 Sin Ming Ind. Est. #01-64/66

Policy No: _____

Claim No: SNM19D204173

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 3/9/2019CA / REV / REP. / REV 24 HRS sup

H.O.D. Endorsement: _____

Date/Time: 9:40am @ 9/9/19

Person Contacted: _____

MichelleVehicle IN ☒ OUT

Date/Time

Action/Instruction

Schedule /SKR 2259H - XSLK 98004 - X26/9 11pm 8490d email & confirm (Red 10,217.70, 679)

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 6 September 2019 2:19 PM
To: zul
Cc: assignments
Subject: RE: OUR REF: SNM19D204173-SLK9008U-CBS - FW: Accident involving SKR2259H & SLK9008U on 03.09.2019 O ref: JEQ/190917/0919/S3 (zl)

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: zul [mailto:zul@juseq.com.sg]
Sent: Friday, 6 September, 2019 2:17 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D204173-SLK9008U-CBS - FW: Accident involving SKR2259H & SLK9008U on 03.09.2019 O ref: JEQ/190917/0919/S3 (zl)

Dear Sir,

We refer to your Email.

Our client is agreeable to appoint (**LKK - KENNETH**) as a single joint expert.

Please be informed that our client's motor vehicle is available for inspection at the under-stated workshop: -

S THREE AUTOMOTIVE RECOVERY PTE LTD
Blk 8 Sin Ming Industrial Estate #01 – 64 /66,
Singapore 575643
Tel : 6284 1542; Fax : 64875315

Regards,

Zul
JusEquity Law Corporation
171 Chin Swee Road #02-06, CES Centre
Singapore 169877
Tel: 6536 9339
Fax: 6536 5368
E-mail: zul@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]
Sent: Thursday, 5 September, 2019 5:01 PM
To: zul@juseq.com.sg
Subject: RE: OUR REF: SNM19D204173-SLK9008U-CBS - FW: Accident involving SKR2259H & SLK9008U on 03.09.2019 O ref: JEQ/190917/0919/S3 (zl)

Without prejudice

Dear Sir,

LKK
STA
LBS

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: zul [<mailto:zul@juseq.com.sg>]
Sent: Thursday, 5 September, 2019 12:56 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Accident involving SKR2259H & SLK9008U on 03.09.2019 O ref: JEQ/190917/0919/S3 (zl)

Dear Sir/Madam,

Please refer to our notice of accident.

Regards,

Zul
JusEquity Law Corporation

171, Chin Swee Road #02-06, CES Centre
Singapore 169877
Tel: 6536 9339
Fax: 6536 5368
E-mail: zul@juseq.com.sg

This message (and all its attachments) is intended only for the use of the individual or entity to whom it is addressed and is privileged and confidential. If you are not the intended recipient, please notify us immediately by return electronic mail, delete this message and you should not disseminate, distribute or copy any information contained herein.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	809D
Vehicle Details	
Vehicle No.:	SKR2259H
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Sep 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	OUTLANDER 2.4 CVT ABS D/AIRBAG AWD S/R
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	4B12PG8183
Chassis No.:	JMYXTGF3WFZ001595
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$17,651.00
Original Registration Date:	26 Jan 2015
First Registration Date:	26 Jan 2015
Transfer Count:	1
Actual ARF Paid:	\$17,651.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jan 2025
PARF Rebate Amount:	\$13,238.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jan 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$75,289.00
COE Rebate Amount:	\$40,295.00
Total Rebate Amount:	\$53,533.00

The information contained herein is correct as at 18 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/09/2019 14:15
Date Of Accident	03/09/2019 18:30
Exact Location Of Accident	ANGULLIA PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR2259H
Insured/Policyholder	
Name Of Registered Owner	CHUA LAI MENG
NRIC No	S7324809D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81895456
Alternative Phone No	OFFICE-81895456

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ19-000855
Cover Note Number	

Driver

Name of Driver	CHUA LAI MENG
NRIC No	S7324809D
Date Of Birth	10/07/1973
Occupation	INDOOR
Date Of Driving Pass	28/02/2008
Driving Experience	11 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81895456
Fax Number	
Contact Number	OFFICE-81895456
EMail Address	NOEMAIL

Address	-
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	MR CAM
Phone Number	91195648
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK9008U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false report may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Ministry of Transport of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 5/9/2019

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PRN No.:

SKETCH PLAN

Refer Attachment -

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- while driving straight on the extreme right lane along Angellia Park, vehicle B which was exiting the carpark of wheellock place trying to overtake a lorry in front of him cut into my lane hit and grazed the left portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature

Date & Time:

5/9/2019

Driver's Signature


(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRC/IRI No.:





S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Authorised
11 Sep 8?
Recovery After Painting

TO CHINA TAIPING
ATTN MOTOR CLAIM DEPT.

T/P VEHL NO. SLK9008U

ESTIMATE REPORT 1st QUOTATION

JOB NO. _____

OWNER'S PARTICULAR

NAME: CHUA LAI MENG

CONTACT: _____

ADDRESS: _____

LICENSE NO.: SKR2259H

CHASSIS NO.: JBMOTGF3WFE001800

MAKE / MODEL: MITSUBISHI OUTLANDER

ENGINE NO.: _____

OWNER'S INSURER: EQ

JOB-CODE: TP

S/A: _____

ACCIDENT DATE: 03-Sep-19

CLAIM DETAIL

MATERIALS

Can Cap 19/9/19

	QTY	QUO-PRICE	DISC. %	DISC. PRICE	SUR. DISP	REV. PRICE
1 HEADLAMP LH	<i>cm</i> 1.00	\$ 2,280.00	10.00	\$ 2,052.00	Y	<i>✓</i>
2 FRONT BUMPER	<i>n</i> 1.00	\$ 1,900.00	10.00	\$ 1,710.00	Y	<i>7</i>
3 FRONT BUMPER RETAINER RH	<i>sm</i> 1.00	\$ 28.00	10.00	\$ 25.20	Y	<i>X</i>
4 FRONT BUMPER RETAINER LH	<i>sm</i> 1.00	\$ 25.00	10.00	\$ 22.50	Y	<i>X</i>
5 FRONT BUMPER BRACKET	<i>n</i> 1.00	\$ 45.00	10.00	\$ 40.50	Y	<i>X</i>
6 FRONT FENDER LH	<i>n</i> 1.00	\$ 1,150.00	10.00	\$ 1,035.00	Y	<i>✓</i>
7 FRONT FENDER INNER SHIELD	<i>sm</i> 1.00	\$ 280.00	10.00	\$ 252.00	Y	<i>X</i>
8 FRONT FENDER WHEEL PROTECTOR LH	<i>Red</i> 1.00	\$ 295.00	10.00	\$ 265.50	Y	<i>✓</i>
9 WING MIRROR ASSY LH	<i>sm</i> 1.00	\$ 1,375.00	10.00	\$ 1,237.50	Y	<i>X</i>
10 FRONT SPORT RIM LH <i>P-7</i>	<i>Red</i> 1.00	\$ 1,644.00	10.00	\$ 1,479.60	Y	<i>✓</i>
11 FRONT LOWER ARM LH	1.00	\$ 750.00	10.00	\$ 675.00	Y	<i>7</i>
12 FRONT SHOCK ABSORBER LH	1.00	\$ 680.00	10.00	\$ 612.00	Y	<i>7</i>
13 FRONT KNUCKLE ARM LH	1.00	\$ 895.00	10.00	\$ 805.50	Y	<i>7</i>
14 FRONT KNUCKLE BEARING LH	1.00	\$ 495.00	10.00	\$ 445.50	Y	<i>7</i>
<i>X</i> 15 ROCKER PANEL GARNISH	<i>sm</i> 1.00	\$ 895.00	10.00	\$ 805.50	Y	<i>X</i>

Wheel Alignment

TOTAL (PARTS):

12737.00

11463.30

SPECIAL NET ITEM

1 FRONT BUMPER CLIPS 1SET	1.00	50.00	0.00	50.00	Y	<i>?</i>
2 FRONT TYRE LH	<i>sm</i> 1.00	380.00	0.00	380.00	Y	<i>X</i>
3 FRONT FENDER INNER SHIELD CLIPS	<i>sm</i> 1.00	100.00	0.00	100.00	Y	<i>X</i>
4 ROCKER PANEL CLIPS	<i>sm</i> 1.00	80.00	0.00	80.00	Y	<i>X</i>

TOTAL (PARTS):

610.00

610.00

LABOUR

1 STRAIGHTEN & PANEL BEAT ACCIDENT AREAS - FRONT	1.00	800.00	0.00	800.00	Y	<i>400</i>
2 SPRAY PAINTING ON ACCIDENT AREAS - FRONT	1.00	800.00	0.00	800.00	Y	<i>600</i>
3 RESET AND CLIBRATION HEADLAMP SYSTEM	1.00	180.00	0.00	180.00	Y	<i>200</i>

4	RESPRAY TUFF KOTE ON ACCIDENT AREAS	1.00	120.00	0.00	<i>nn</i> 120.00	Y	<u>X</u>
5	CONDUCT CHASSIS ALIGNMENT	1.00	380.00	0.00	<i>nn</i> 380.00	Y	<u>λ</u>
6	R&R CARPET & INNER TRIM TO ASSIST REPAIR	1.00	120.00	0.00	<i>nn</i> 120.00	Y	<u>X</u>
7	CHECKING WIRING SYSTEM	1.00	80.00	0.00	80.00	Y	<u>206</u>
8	R&R FRONT SUSPENSION LH	1.00	280.00	0.00	280.00	Y	<u>?</u>

TOTAL (LABOUR) :	2760.00	2760.00
TOTAL PARTS & LABOUR	16107.00	14833.30

ACCESS : S\$ _____

Q. OF DAY : 04

E-SURVEY : BEFORE / AFTER PAINTING

☒ PART-BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : 17/9/19

SURVEY BY : Hennerth

CONTACT NO : 96910663

FAX NO : 62564315

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED



S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Authorized
11 Sep @ 4900h
Recovery After Paint

TO CHINA TAIPING
ATTN MOTOR CLAIM DEPT. T/P VEH. NO. : SLK9008U

ESTIMATE REPORT 1st QUOTATION JOB NO :
OWNER'S PARTICULAR
NAME : CHUA LAI MENG CONTACT :
ADDRESS :
LICENSE NO. : SKR2259H CHASSIS NO. : JMYXTGF3WVF2001000
MAKE / MODEL : MITSUBISHI OUTLANDER ENGINE NO :
OWNER'S INSURER : EQ
JOB-CODE : TP S/A ACCIDENT DATE : 03-Sep-19

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR. DISP	REV. PRICE
1 HEADLAMP LH → 1852	1.00	\$ 2,280.00	10.00	\$ 2,052.00	Y	✓
2 FRONT BUMPER → 1036	1.00	\$ 1,900.00	10.00	\$ 1,710.00	Y	✓
3 FRONT BUMPER RETAINER RH	1.00	\$ 28.00	10.00	\$ 25.20	Y	X
4 FRONT BUMPER RETAINER LH	1.00	\$ 25.00	10.00	\$ 22.50	Y	X
5 FRONT BUMPER BRACKET	1.00	\$ 45.00	10.00	\$ 40.50	Y	X
6 FRONT FENDER LH	1.00	\$ 1,150.00	10.00	\$ 1,035.00	Y	✓
7 FRONT FENDER INNER SHIELD	1.00	\$ 280.00	10.00	\$ 252.00	Y	X
8 FRONT FENDER WHEEL PROTECTOR LH	1.00	\$ 295.00	10.00	\$ 265.50	Y	✓
9 WING MIRROR ASSY LH	1.00	\$ 1,375.00	10.00	\$ 1,237.50	Y	X
10 FRONT SPORT RIM LH P-7 → 1102	1.00	\$ 1,644.00	10.00	\$ 1,479.60	Y	✓
11 FRONT LOWER ARM LH	1.00	\$ 750.00	10.00	\$ 675.00	Y	X
12 FRONT SHOCK ABSORBER LH	1.00	\$ 680.00	10.00	\$ 612.00	Y	✓
13 FRONT KNUCKLE ARM LH	1.00	\$ 895.00	10.00	\$ 805.50	Y	✓ 610
14 FRONT KNUCKLE BEARING LH	1.00	\$ 495.00	10.00	\$ 445.50	Y	✓ 305
15 ROCKER PANEL GARNISH	1.00	\$ 895.00	10.00	\$ 805.50	Y	X
TOTAL (PARTS) :	108	12737.00		11463.30		

SPECIAL NETT ITEM

1 FRONT BUMPER CLIPS 1SET	1.00	50.00	0.00	50.00	Y	✓
2 FRONT TYRE LH	1.00	380.00	0.00	380.00	Y	X
3 FRONT FENDER INNER SHIELD CLIPS	1.00	100.00	0.00	100.00	Y	X
4 ROCKER PANEL CLIPS	1.00	80.00	0.00	80.00	Y	✓
TOTAL (PARTS) :		610.00		610.00		

LABOUR

1 STRAIGHTEN & PANEL BEAT ACCIDENT AREAS - FRONT	1.00	800.00	0.00	800.00	Y	400
2 SPRAY PAINTING ON ACCIDENT AREAS - FRONT	1.00	800.00	0.00	800.00	Y	600
3 RESET AND CLIBRATION HEADLAMP SYSTEM	1.00	180.00	0.00	180.00	Y	200

4	RESPRAY TUFF KOTE ON ACCIDENT AREAS	1.00	120.00	0.00	nn	120.00	Y	X
5	CONDUCT CHASSIS ALIGNMENT	1.00	380.00	0.00	nn	380.00	Y	X
6	R&R CARPET & INNER TRIM TO ASSIST REPAIR	1.00	120.00	0.00	nn	120.00	Y	X
7	CHECKING WIRING SYSTEM	1.00	80.00	0.00		80.00	Y	20%
8	R&R FRONT SUSPENSION LH	1.00	280.00	0.00		280.00	Y	50% X

TOTAL (LABOUR) : 2760.00 2760.00

TOTAL PARTS & LABOUR 16107.00 14833.30 15,117.70

EXCESS : S\$

NO. OF DAY : 04

RE-SURVEY : BEFORE / AFTER PAINTING

PART-BY-PART OR LUMP-SUM : S\$

DATE OF SURVEY 17/9/19

SURVEY BY Kenneth

CONTACT NO: 96910663

FAX NO: 62564315

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

L&C Auto Consulting hereby notify the Vendor of the following:

- To provide an estimate of repair
- To provide a written estimate of repair
- To provide a written estimate of repair
- To provide a written estimate of repair
- To provide a written estimate of repair
- To provide a written estimate of repair
- To provide a written estimate of repair
- To provide a written estimate of repair

Authorised by Supplier

Signature

Date



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO : CHINA TAIPING
ATTN : MOTOR CLAIM DEPT. T/P VEH. NO. : SLK9008U

ESTIMATE REPORT 1st QUOTATION JOB NO :
OWNER'S PARTICULAR
NAME : CHUA LAI MENG CONTACT :
ADDRESS :
LICENSE NO. : SKR2259H CHASSIS NO. : JMYXTGF3WF2001000
MAKE / MODEL : MITSUBISHI OUTLANDER ENGINE NO. :
OWNER'S INSURER : EQ
JOB-CODE : TP S/A :
SUPPLEMENTARY ACCIDENT DATE : 03-Sep-19
CLAIM DETAIL

MATERIALS	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR-DISP	REV. PRICE
1 LH BUMPER PROTECTOR 	1.00	\$ 168.00	10.00	\$ 151.20	Y	
2 LH ANTI ROLL BAR LINK 	1.00	\$ 148.00	10.00	\$ 133.20	Y	

EXCESS : S\$
NO. OF DAY :
RE-SURVEY : BEFORE / AFTER PAINTING
PART-BY-PART OR LUMP-SUM : S\$
DATE OF SURVEY :
SURVEY BY :
CONTACT NC : FAX NO :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

Gua Q. L.
19/9/19



Mitsubishi : Outlander/Airtrek : 2013- (GF/GG) : Front Wheel Drive
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-3°00'	-3°01'	-0°10' 0°50'
5°06'	5°06'	2°05' 3°05'
0°21'	0°19'	-0°02' 0°06'
11°15'	11°15'	11°15' 14°15'
9°29'	9°29'	11°05' 15°05'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°18'	-0°18'	-0°10' 0°50'
4°59'	4°59'	2°05' 3°05'
0°02'	0°02'	-0°02' 0°06'
9°54'	9°54'	11°15' 14°15'
9°36'	9°36'	11°05' 15°05'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-2°42'	-2°43'	-0°30' 0°30'
0°21'	0°21'	-0°30' 0°30'
2°35'	2°35'	
0°24'	0°23'	-0°04' 0°12'

Rear : Left

Actual	Before	Specified Range
-1°37'	-1°38'	-1°15' 0°15'
0°38'	0°39'	0°02' 0°12'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°12'	-1°12'	-1°15' 0°15'
-0°13'	-0°16'	0°02' 0°12'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°23'	0°23'	-0°30' 0°30'
0°25'	0°25'	0°04' 0°24'
0°26'	0°27'	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119015887/KVD3N2

Date: 02/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN31248318011
Claimant Vehicle No :	SKR2259H	Insured Vehicle No :	SLK9800U
Date of Loss:	03/09/2019	Nature of Claim:	TP
		Claim No:	SNM19D204173C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR2259H	Engine No:	4B12PG8183
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	JMYXTGF3WFZ001595
Reg. Date:	26/01/2015 (Man. Year: 2014)	Odometer:	104232 km
Colour:	Metallic Red		
Engine Capacity:	2360 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,357.70	5,108.00	7,249.70	58.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,040.00	1,720.00	62.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,117.70	6,148.00	8,969.70	59.33
Approved Total (Overridden) (S\$)		4,900.00		
(S\$)	15,117.70	4,900.00	10,217.70	67.59
+ GST 7.00/7.00% (S\$)	1,058.24	343.00	715.24	67.59
Nett Amount (S\$)	16,175.94	5,243.00	10,932.94	67.59

INSPECTION

Date of Assignment:	27/09/2019	
Date Inspected:	17/09/2019 Inspected At:	S Three Automotive & Recovery Pte Ltd - Sin Ming (HQ) BLK 8 SIN MING IND EST #01-64/66 Singapore 575643

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2019)
Parts:	M1-SUV	mitsubishi OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR2259H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Cracked	2,280.00 FL	*1,852.00 FL
2	1		*FRONT BUMPER	Mtg Cracked	1,900.00 FL	*1,036.00 FL
3	1		*FRONT BUMPER RETAINER RH	Serviceable	28.00 FL	*- FL
4	1		*FRONT BUMPER RETAINER LH	Serviceable	25.00 FL	*- FL
5	1		*FRONT BUMPER BRACKET	Repair	45.00 FL	*- FL
6	1		*FRONT FENDER LH	Repair	1,150.00 FL	*- FL
7	1		*FRONT FENDER INNER SHIELD	Serviceable	280.00 FL	*- FL
8	1		*FRONT FENDER WHEEL PROTECTOR LH	Dented	295.00 FL	*295.00 FL
9	1		*WING MIRROR ASSY LH	Serviceable	1,375.00 FL	*- FL
10	1		*FRONT SPORT RIM LH	Dented	1,644.00 FL	*1,102.00 FL
11	1		*FRONT LOWER ARM LH	Serviceable	750.00 FL	*- FL
12	1		*FRONT SHOCK ABSORBER LH	Bent	680.00 FL	*420.00 FL
13	1		*FRONT KNUCKLE ARM LH	Bent	895.00 FL	*610.00 FL
14	1		*FRONT KNUCKLE BEARING LH	Necessary	495.00 FL	*305.00 FL
15	1		*ROCKER PANEL GARNISH	Serviceable	895.00 FL	*- FL
16	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
17	1		*FRONT TYRE LH	Serviceable	380.00 FS	*- FS
18	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	100.00 FS	*- FS
19	1		*ROCKER PANEL CLIPS	Not Necessary	80.00 FS	*- FS
20	1		*LH BUMPER PROTECTOR	Serviceable	168.00 FL	*- FL
21	1		*LH ANTI ROLL BAR LINK	Serviceable	148.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,663.00	5,670.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,305.30	562.00
Total Parts (\$\$)	12,357.70	5,108.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS-FRONT	New	800.00	400.00
2	SPRAY PAINTING ON ACCIDENT AREAS-FRONT	New	800.00	600.00
3	RESET AND CALIBRATION HEADLAMP SYSTEM	New	180.00	20.00
4	RESPRAY TUFF KOTE ON ACCIDENT AREAS	New	120.00	0.00
5	CONDUCT CHASSIS ALIGNMENT	New	380.00	0.00
6	R&R CARPET & INNER TRIM TO ASSIST REPAIR	New	120.00	0.00
7	CHECKING WIRING SYSTEM	New	80.00	20.00
8	R&R FRONT SUSPENSION LH	New	280.00	0.00
Gross Labour Cost (\$\$)			2,760.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >