

SJE : \_\_\_\_\_ Vehicle Nos : **SKW 9841 D**  
Date of Survey : \_\_\_\_\_ Made : Mazda  
Date of ReSurvey : \_\_\_\_\_ After-Paint: \_\_\_\_\_ Model : 5  
Contacts : \_\_\_\_\_ Chassis No : \_\_\_\_\_

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_ Working Day: \_\_\_\_\_

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bonnet	1	\$ 995.80	\$ <del>995.80</del>
2	Front bumper	1	\$ 977.50	\$ <del>977.50</del> 689.90
3	Front bumper side retainer	1	\$ 35.80	\$ <del>35.80</del> ✓ 35.80
4	Front bumper bracket RH	1	\$ <del>50.60</del> 40.20	\$ <del>50.60</del> 40.20
5	Front bumper fog lamp	1	\$ 156.00	\$ <del>156.00</del>
6	Front bumper fog lamp cover	1	\$ 38.20	\$ <del>38.20</del>
7	Front bumper fog lamp garnish	1	\$ 78.30	\$ <del>78.30</del> ✓ 78.30
8	Headlamp	1	\$ 1,145.70	\$ <del>1,145.70</del> ✓ 1,145.70
9	Headlamp lower bracket	1	\$ 67.50	\$ <del>67.50</del>
10	Front fender	1	\$ 968.30	\$ <del>968.30</del>
11	Front fender inner trim	1	\$ 105.60	\$ <del>105.60</del> ✓ 105.60
12	Front fender inner shield	1	\$ 115.30	\$ <del>115.30</del>
13	Front knuckle arm	1	\$ 347.90	\$ <del>347.90</del>
14	Front knuckle arm bearing	1	\$ 266.80	\$ <del>266.80</del>
15	Front lower arm	1	\$ 311.60	\$ <del>311.60</del> ✓ 311.60
16	Front shock absorber	1	\$ 220.80	\$ <del>220.80</del>
Parts Sub Total :				\$ 5,889.70
20% Discount :				\$ 1,177.94
<b>PARTS TOTAL :</b>				<b>\$ 4,711.76</b>

NNX  
CRAV ✓  
NECV ✓  
CRAV ✓  
NNX  
BRV RPTX  
BRV ✓  
CRAV ✓  
BRV NNX  
RX  
TN ✓  
NA X  
NNX  
NNX  
BT ✓  
NNX  
2407.10  
481.42  
1925.68

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ <del>80.00</del>
2	Front bumper clips	1	\$ 50.00	\$ <del>50.00</del> 30.00
3	Headlamp seal	1	\$ 40.00	\$ <del>40.00</del>
4	Front sport rim	1	\$ 352.00	\$ <del>352.00</del>
5	Front fender inner shield clips	1	\$ 50.00	\$ <del>50.00</del> 30.00
<b>SPECIAL NETT TOTAL :</b>				<b>\$ 572.00</b>

NNX  
NECV ✓  
NNX  
NNX  
NECV ✓  
60.00

Nos.	LABOUR	S\$
1	To dismantle/renew accident damaged. To panel beat, reshape, align and replace parts	\$ <del>3,000.00</del> 600.00
2	To disconnect wire harness of electrical component to facilitate repair n reconnect check function	\$ <del>80.00</del> 30.00
3	To apply undercoating on the accident repair and replaced for rust proofing	\$ <del>100.00</del> 30.00
4	To supply paint materials and nessary items to respray accident damaged	\$ <del>1,000.00</del> 400.00
5	To remove & refit front under carriage for check and replace parts	\$ <del>80.00</del> 80.00
6	Apply sealant	\$ <del>80.00</del>
<b>LABOUR TOTAL :</b>		<b>\$ 2,560.00</b>

NNX  
NNX  
1060.00

PARTS TOTAL :	\$ 4,711.76
SPECIAL NETT TOTAL :	\$ 572.00
LABOUR TOTAL :	\$ 2,560.00
<b>GRAND TOTAL :</b>	<b>\$ 7,843.76</b>

1925.68 Resurvey on 11/9/19  
60.00  
1060.00  
3045.68  
609.14  
2436.54  
1545 hrs

Survey on 9/9/19  
Lump sum repair  
Repair days 4  
TTCim Min  
1515hrs

HS 2,400/2

TTCim Min  
11/10/19