



**Bill To:**

DATE:

9 July, 2016

**INVOICE #**

NAP 15980

Vehicle Make/Model/Colour: Honda Shuttle White

Vehicle Registration Number: SLE 664 R

TERM: C.O.D

Account Name: New Age Polish Pte. Ltd.  
Bank Name / Code: OCBC / 7339  
Bank Account Number: 6896 3411 1001  
Branch Code: 689  
Swift Code: OCBCSGSG  
Bank Address: 65 Chulia Street #01-00 Singapore 049513

# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD  
 143 Cecil Street #01-01 GB Building  
 069542

Attention : Motor Claim Department  
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000953

Date : 03/12/2016  
 Vehicle Num. : SLE 664R  
 Make/Model : HONDA SHUTTLE  
 Chassis/Eng# :  
 Accident Date : 01/12/2016  
 Claim No. :  
 Reference :  
 Policy No. :

*Not Authorized*  
*1131*  
*Resurvey B & paint*

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|                       |    |                                               |               |   |
|-----------------------|----|-----------------------------------------------|---------------|---|
| LIST ITEMS :          |    |                                               |               |   |
| 1.                    | 1  | REAR BOOTLID                                  | 1,850.00      | ✓ |
| 2.                    | 1  | REAR BOOTLID LOCK                             | 550.00        | ✓ |
| 3.                    | 1  | REAR BOOTLID LOCK CATCH                       | 158.00        | X |
| 4.                    | 1  | REAR BOOT LID INNER TRIM COVER                | 565.00        | ? |
| 5.                    | 12 | REAR BOOT LID INNER TRIM COVER CLIP           | 9.80 117.60   | ? |
| 6.                    | 1  | REAR BOOT LID INNER TRIM COVER HANDGRIP COVER | 85.00         | ✓ |
| 7.                    | 1  | REAR BOOT WEATHER STRIP                       | 380.00        | ✓ |
| 8.                    | 1  | REAR BOOT SPARE TYRE COMPARTMENT BOX          | 420.00        | ? |
| 9.                    | 1  | REAR END PANEL                                | 950.00        | ✓ |
| 10.                   | 1  | REAR END PANEL TOP GARNISH                    | 260.00        | ✓ |
| 11.                   | 6  | REAR END PANEL TOP GARNISH CLIPS              | 9.80 58.80    | ✓ |
| 12.                   | 1  | REAR BUMPER                                   | 1,350.00      | ✓ |
| 13.                   | 2  | REAR BUMPER SIDE RETAINER                     | 128.00 256.00 | X |
| 14.                   | 2  | REAR BUMPER REFLECTOR LENS                    | 178.00 356.00 | X |
| 15.                   | 2  | REAR BUMPER REFLECTOR LENS GARNISH            | 168.00 336.00 | ? |
| 16.                   | 1  | REAR BUMPER TOW EYE COVER                     | 68.00         | X |
| 17.                   | 10 | REAR BUMPER CLIP                              | 9.80 98.00    | ✓ |
| 18.                   | 1  | REAR WINDSCREEN GLASS MOULDING                | 195.00        | ✓ |
| List Total S\$ :      |    |                                               | 8,053.40      |   |
| 20.00% Discount S\$ : |    |                                               | 1,610.68      |   |
|                       |    |                                               | 6,442.72      |   |

|                          |   |                       |        |   |
|--------------------------|---|-----------------------|--------|---|
| SPECIAL NETT ITEMS :     |   |                       |        |   |
| 1.                       | 1 | WINDSCREEN SEALANT    | 80.00  | ✓ |
| 2.                       | 1 | REVERSE SENSOR        | 280.00 | ? |
| 3.                       | 1 | NUMBER PLATE & CASING | 40.00  | X |
| Special Nett Total S\$ : |   |                       | 400.00 |   |

CONTINUE / ...

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**AXA INSURANCE SINGAPORE PTE LTD**  
 143 Cecil Street #01-01 GB Building  
 069542

Attention : Motor Claim Department  
 Contact : 338 7288 Fax No. : 880 4838

**Estimate : ES000953**

Date : 03/12/2016  
 Vehicle Num. : SLE 664R  
 Make/Model : HONDA SHUTTLE  
 Chassis/Eng# :  
 Accident Date : 01/12/2016  
 Claim No. :  
 Reference :  
 Policy No. :

| S/N | Quantity | Particular                                                                                                                                                     | Unit Price | Amount S\$ |
|-----|----------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|------------|
|     |          | LABOUR :                                                                                                                                                       |            |            |
|     |          | REMOVE & REFIT REAR WINDSCREEN GLASS                                                                                                                           | 180.00     | 1201       |
|     |          | TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES                                                                                                                | 120.00     | 601        |
|     |          | WIRINGS CHECK AND RECTIFY WHERE NECESSARY                                                                                                                      | 80.00      | 201        |
|     |          | REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE<br>REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN<br>CHASSIS WHERE NECESSARY, AND REPLACE ABOVE PARTS | 1,800.00   | 8001       |
|     |          | PUTTY AND SPRAY PAINT ALL AFFECTED AREAS<br>(IN/OUTSIDE, PEARL WHITE)                                                                                          | 1,500.00   | 9001       |
|     |          | Labour Total S\$ :                                                                                                                                             |            | 3,680.00   |

E. &amp; O.E.

Total S\$ : 10,522.72

for WORLD AUTO PTE LTD