

Re: MARKET VALUE, Re: RE: FBM9403U AUTHORIZATION TO REPAIR

Sbk E <sbk5643e@yahoo.com>

Thu 12/9/2019 10:45 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Dear Shirley,

We are agreeable to accept at \$3,300.00 before Excess and GST. Please kindly authorise. Thanks.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

On Thursday, September 12, 2019, 10:37:03 AM GMT+8, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Wendy,

As spoken, kindly confirm that you are able to undertake the repair cost not exceeding \$ 3,300.00 on lump sum basis.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sbk E <sbk5643e@yahoo.com>

Sent: Thursday, 12 September 2019 10:06 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Subject: RE: MARKET VALUE, Re: RE: FBM9403U AUTHORIZATION TO REPAIR

Dear Shirley,

The market value is around \$10,100.00. Therefore, maximum repair limit is \$3,900.00. I will like to highlight that we are not trying to repair to the maximum limit. Thanks.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

On Tuesday, September 10, 2019, 8:48:47 AM GMT+8, Sbk E <sbk5643e@yahoo.com> wrote:

Dear Navita,

Please assist to upload the necessary documents. Thanks.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

On Monday, September 9, 2019, 6:59:05 PM GMT+8, Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com> wrote:

Hi Both,

No revise estimate or bike damaged photos being upload onto Merimen for me to view. As such, cannot be authorize.

Regards,
Thaddaeus Ng
AIG

Motor Claims Surveyor
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1929 | Fax +(65) 6835 7416 Hp +(65) 8876 5433
Thaddaeus-HC.Ng@AIG.com | www.AIG.com.sg

From: Sbk E <sbk5643e@yahoo.com>
Sent: Monday, September 9, 2019 6:22 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>
Cc: SUR <sur@lkkauto.com>
Subject: [EXTERNAL] RE: FBM9403U AUTHORIZATION TO REPAIR

This message is from an external sender; be cautious with links and attachments.

Dear Navita

Please seek permission from AIG to authorise repair for FBM9403U. I have included Thadd from AIG in this email. Thank you very much for your attention.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.