

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: NEO KIAM KIAT
 TP INSURER: AIG Asia Pacific Insurance Pte Ltd
 POLICY NO: 5109906975
 REFERENCE: TP CLAIM
 DOA: 07/09/2019

Vic

REPAIR ESTIMATE

Est. No. : E19090003
 Date : 10/09/2019
 Vehicle Num. : SJR529D
 Make/Model : TOYOTA, AXIO 1.5X A
 Chassis/Eng# : NZE1416115659
 Yr. of Manu : 2009

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	Front Bumper <i>Rehd</i>	1.00	657.00	657.00 ✓
2	Front Bumper Side Retainer <i>new</i>	1.00	66.10	66.10 ✓
3	LH Front Fender <i>Dented</i>	1.00	606.10	606.10 ✓
4	LH Front Fender Inner Shield <i>Rehd</i>	1.00	124.10	124.10 ✓
5	LH Headlamp <i>cut</i>	1.00	785.40	785.40 ✓
6	Sports Rim <i>cut</i>	1.00	700.00	700.00 ✓ 480(SW)
7	LH Front Lower Arm <i>Rehd new</i>	1.00	168.95	168.95 ✓
8	LH Front Shock Absorber <i>Rehd new</i>	1.00	435.10	435.10 ✓
9	LH Front Wheel Bearing <i>Rehd new</i>	1.00	210.10	210.10 ✓
10	LH Front Knuckle Arm <i>Rehd new</i>	1.00	495.10	495.10 ✓
				Amt S\$ 4,247.95
				Discount (25.00%) S\$ 999.99
				Subtotal S\$ 3,185.96

Section: LABOUR				
11	To Panel Beat on Necessary Damaged Part	1.00	650.00	650.00 ✓ 500
12	To Sand Down, Putty and Spray Paint on Necessary Damaged Part	1.00	580.00	580.00 ✓ 400
13	To Dismantle & Replace Undercarriage	1.00	250.00	250.00 ✓ 980
14	To Do 4 Wheel Alignment	1.00	120.00	120.00 ✓ 80

Amt S\$ 1,600.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 1,600.00

total: 3139.02
 h/s: 2.5k.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 3,185.96
LABOUR Subtotal S\$ 1,600.00
Total S\$ 4,785.96

Adrian Ling
 h/s 11/09/19
 050421