

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

9-Sep-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6202 J

1 pc	Front bumper emblem <i>- nec</i>	\$ 44.00
1 pc	Front bumper <i>- con</i>	\$ 531.00
1 pc	Front bumper sponge <i>X su</i>	\$ 110.00
1 pc	Front bumper reinforcement <i>X su</i>	\$ 328.00
1 pc	Front bumper n/s fog lamp cover <i>- con</i>	\$ 66.00
1 pc	Front bumper n/s protector <i>- con</i>	\$ 51.00
1 pc	Support panel <i>X su</i>	\$ 645.00
1 pc	n/s headlamp <i>X su</i>	\$ 1,028.00
1 pc	Front bumper n/s side retainer <i>X su</i>	\$ 16.00
1 pc	Bonnet grille <i>- con</i>	\$ 386.00
		\$ 3,205.00
Less 10%		\$ 320.50
		\$ 2,884.50

S/NETT

1 pc	Front bumper clips <i>- nec</i>	\$ 48.00
1 pc	Front n/s fender sticker <i>X su</i>	\$ 30.00
1 set	Front n/s fender inner shield clips <i>X 47</i>	\$ 28.00
Sundry		
	To check front n/s wheel alignment	\$ 50.00 <i>X su</i>
	To top up aircon gas	\$ 80.00 <i>X su</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 120.00 <i>X su</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same bonnet, front n/s chassis, front n/s fender	\$ 180.00 <i>X su</i>
	To putty and spray painting on front bumper, front n/s fender, bonnet <i>grille</i>	\$ 200 750.00
	To apply rustproofing on the repaired and replaced panels.	\$ 360 600.00
		\$ 120.00 <i>X su</i>
		\$ 4,890.50

... plaintiffs hence notify
... the following:
 • To be resurveyed after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary (pm/s) must be resurveyed and approved by the Insurance Company

Acknowledged by Repairer

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

13/9/19 *che 4/5 \$1250 / 2 days.*

Kahin 10/19
11/9/19 10/19
2 pm.
4/5
After Repair