



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0068271 / NTUC INCOME INS
Chassis No: MRHFC5650JT001303
License No: SMD2338M
Mileage: 7204
Engine No: R16B25501498

Document No: SVO19058635
Printed By: JACKNG
Order Date: 10. September 2019
Order Time: 3:59:34 PM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:TU JINHUO OWNER INSURER:TOKIO MARINE ACC DATE:28/08/2019 SURVEYED BY: DATE: REF NO: TP INSURER:NTUC INCOME TP VEH:FBE 481 U						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40	25	27.30	1.91	29.21
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
68500-TEA-N00ZZ	LID COMP TRUNK	0	486.20	25	0.00	0.00	0.00
	SUM PARTS:				519.51	36.35	555.86
BOSUN	0669 SUNDRIES	1	50.00		50.00	3.50	53.50
BML02I	0669 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	280.00		280.00	19.60	299.60
BA02R	0669 REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)	1	380.00		380.00	26.60	406.60
BC011R	0669 RESET & CALIBRATE SMART ENTRY SYSTEM(N)	1	450.00		450.00	31.50	481.50
BKBU02R	0669 REMOVE & RENEW RR BUMPER. RENEW ALL DAMAGE PARTS ATTACHMENT ITEMS	1	560.00		560.00	39.20	599.20
BP04R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(4P)	1	450.00		450.00	31.50	481.50
	SUM LABOUR:				2,170.00	151.90	2,321.90
	TOTAL SGD				2,689.51	188.25	2,877.76

Total Payable (SGD)

2,877.76

GST Amount is calculated from individual line(s)