

ASS. REC. BY:

Surveyor: Tau AhREF: 25/INC/9016056/T1xd3m2

Special Instruction:

ASSIGNMENT (Office)From (Person): Annie Kohof INCDate/Time: 12:24 pm @ 10/9/19

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 2338M

Insured:

FBE 481 U

at Workshop m/s

Koh Motor

Tel:

8288 6309

of

No 255 Alexandria Road

Policy No:

Claim No:

MT/1059976-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsed:

Date/Time:

12:50 pm @ 10/9/19

Person Contacted:

Juek

Vehicle:

IN/OUT

Date/Time

Action/Instruction

Estimate (✓)SMD 2338M - XFBE 481U - X3/10/19Final fig \$ 2689.51 confirmed by email (Ref 5645.45, 679)

Surveyor *Tamara*

REF:

INC

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Sick

Veh No:

SMD2338M

Regn: 2018 Aug

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Horade Civic 1.6 cc 1597

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

128/6

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC 5650 JT 001303

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/35 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Haruh

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

10/9/19

Survey held at

Kan Motor Alexander 3.46

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 3 OCT 2019

Date/Time, File Pass to?



: Proli. Report

1)



: Final Report

Date/Time, File Return to?

2) *3/10 - typist*

Report Format :

TP

Lump Sum / I.B.I.: (\$

2689.51

Days Of Repair: *3*

Resurvey No. of Trip: *1*

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RT \$

Photos

Others

TOTAL

250

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 10 September 2019 12:24 PM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/09/2019

From: Annie Koh
Sent: Tuesday, 10 September 2019 11:58 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/09/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Tuesday, 10 September 2019 9:24 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 10/09/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Charlotte Chew	MT/1060673-002	5GJ6583J	ACCORD AUTO SERVICES PTE LTD	BLK 1009 BUKIT MERAH LANE 3 #01-80	cella lai / 92740999		SJT2613U	31/8/19	
2	Juliana Lee	MT/1061610-001	5GR3518B	ACCORD AUTO SERVICES PTE LTD	BLK 1009 BUKIT MERAH LANE 3 #01-80	cella lai / 92740999		SJM2951E	7/9/19	
3	Charlotte Chew	MT/1060994-002	SKT3638E	EUROKARS HABITAT PTE LTD	NO.27A TANJONG PENJURU SINGAPORE 609042	JOBI THOMAS / 63310682	14:00-16:00	SHB8048E	4/9/19	
4	Serene Lim	MT/1061249-002	5LE1509A	HITACHI CAPITAL (S) PTE LTD	8 FOURTH LOK YANG ROAD SINGAPORE 629705	ng jiong how / 68336282	14:00-16:00	GBE3833T	5/9/19	
5	Helena Tan	MT/1059976-001	5MD2338M	KAH MOTOR CO SDN BHD	255 ALEXANDRA ROAD BODY REPAIR & PAINT CENTRE SINGAPORE 159937	Jack ng / 82886309	10:00-12:00	FBE481U	28/8/19	
6	Azhari	MT/1053928-001	5MD5182	PERFORMANCE MOTORS LTD	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941	caroline / 63190174	10:00-12:00	SMH5415H	17/7/19	
7	Alice Low	MT/1061272-002	5LW9079B	PREMIUM AUTOMOBILES PTE LTD	281 ALEXANDRA ROAD SINGAPORE 159938	GEORGE WONG / 63662323	10:00-12:00	SLM6686X	5/9/19	

8	Jared Liu	MT/1061679-001	PA9876K	SERVE YOU MOTOR SERVICE	8 # JALAN PAPAN SINGAPORE 619418	ELAINE CHIA / 92393188	XE4372P	6/9/19	
9		To be advise	XD8408A	VFIX AUTO PTE LTD	26 CHIA PING ROAD SINGAPORE 619977	weng sheng / 64552957		14:00-16:00	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Veron Chen (LKKAUTO)

From: Jack Ng <jackng@honda.com.sg>
Sent: Wednesday, 25 September 2019 4:39 PM
To: Veron Chen (LKKAUTO)
Subject: RE: SMD 2338M-DOA: 28/8/2019

Hi Veron,

Repair done recently, not yet finalize. Still in Q-ing for finalize.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Wednesday, 25 September 2019 4:35 PM
To: Jack Ng <jackng@honda.com.sg>
Subject: SMD 2338M-DOA: 28/8/2019

Dear Jack,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 3 October 2019 2:05 PM
To: Jack Ng; Taufikh (LKKAUTO)
Cc: Asher Sng (LKKAUTO); Hsiao Tong (LKKAUTO); Shiau Chan (LKKAUTO); SUR
Subject: RE: FINALIZATION FOR SMD 2338M

Dear Jack,

WITHOUT PREJUDICE

Confirmed amount \$2689.51 before GST @ 3 working days.

Kindly send Final invoice and all supporting documents directly to NTUC INCOME

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jack Ng <jackng@honda.com.sg>
Sent: Wednesday, 2 October 2019 5:32 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: FINALIZATION FOR SLW 3680 D
Importance: High

Dear Taufikh,

We enclosed the total final repair costs for,

Vehicle No.	SMD 2338 M
Final Repair Costs (exclude GST)	S\$2,689.51
Repair Period* (Days)	3 WORKING DAYS

*Note: Repair period does NOT include Sunday and Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you and have a great days ahead

Cheers !!!

Best Regards,

Jack Ng

Hp: 8288 6309

Email: Jackng@honda.com.sg

BODY REPAIR AND PAINT CENTRE

255 Alexandra Road Singapore 159937

DID : +65 6514 5481 FAX : +65 6362 5015

Kah Motor Co. Sdn. Bhd.

(A MEMBER OF ORIENTAL HOLDING BERHAD)

Website: www.honda.com.sg



BLOK BUKIT FOR
OUR CHILDREN



Visit our
Facebook page



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/08/2019 18:08
Date Of Accident	28/08/2019 07:40
Exact Location Of Accident	ENTRY TO AYE FROM CLEMENTI AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD2338M
Insured/Policyholder	
Name Of Registered Owner	TU JIN HUO
NRIC No	S2676931J
Email Address	TUZJH@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98245725
Alternative Phone No	OFFICE-98245725

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO

Policy Number
Cover Note Number

Driver

Name of Driver	TU YAN ALISE
NRIC No	S9271939A
Date Of Birth	26/12/1992
Occupation	INDOOR
Date Of Driving Pass	19/10/2012
Driving Experience	6 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98245725
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK449B BUKIT BATOK WEST AVE 9 #15-98
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBE481U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

Vehicle Number: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

7.40 AM - 28/8/19
Motorcycle hit my car from behind when I was slowing to a stop.
Heavy rain and heavy slow moving traffic (about 30 km/h)
I heard a bump and felt the car jerk then I realize I was hit.

DECLARATION

I/We declare the foregoing particulars are true in every respect,

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

27/8/19 5.18 PM

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : NTUC INCOME INS CO-OPERATIVE LTD
1 MARITIME SQUARE
HARBOURFRONT CENTRE
SINGAPORE 099253
Registration No : SMD2338M
Chassis No : MRHFC5650JT001303
Model : CIVIC 1.6 VTI YM2018
Owner's Name : TU JINHUO
Ins Policy No. :
Date of Accident : 28/8/2019

Document No. : SQT19003852
Date : 2. Sep 2019
Customer No. : WZN008
Svc Advisor : JACK NG
Engine No : R16B25501498
Date | Time : 2. Sep 2019 2:05:18 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:TU JINHUO OWNER INSURER:TOKIO MARINE ACC DATE:28/08/2019 SURVEYED BY: DATE: REF NO: TP INSURER:NTUC INCOME TP VEH:FBE 481 U						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20 <i>de</i>	25	462.90 ✓	32.40	495.30
33505-TEA-T01	REFLECTOR ASSY,RR.	1	7.20 <i>x nm</i>	25	5.40	0.38	5.78
33555-TEA-T01	REFLECTOR ASSY,L.RR.	1	7.20 <i>x nm</i>	25	5.40	0.38	5.78
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40 <i>de</i>	25	27.30 ✓	1.91	29.21
71593-TEA-T01	SPACER,RR.BUMPER SIDE	1	11.50 <i>de</i>	25	8.62 ✓	0.60	9.22
71598-TEA-T01	SPACER,L.RR.BUMPER SIDE	1	11.50 <i>nm</i>	25	8.62 ✓	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.30 <i>de</i>	25	12.07 ✓	0.84	12.91
68500-TEA-N00ZZ	LID COMP TRUNK	1	486.20 <i>x nm</i>	25	364.65	25.53	390.18
Sum Item					894.96	62.64	957.60
BOSUN	SUNDRIES	1	100.00 <i>50</i>	✓ <i>rel</i>	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	380.00 <i>280</i>	✓	380.00	26.60	406.60
BA02R	REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)	1	380.00 ✓	✓	380.00	26.60	406.60
BC011R	RESET & CALIBRATE SMART ENTRY SYSTEM(N)	1	450.00 ✓	✓	450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00 <i>x nm</i>	✓	450.00	31.50	481.50
BKBU02R	REMOVE & RENEW RR BUMPER. RENEW ALL DAMAGE PARTS	1	3500.00 <i>560</i>	✓	3500.00	245.00	3745.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	2000.00 <i>450</i>	✓	2000.00	140.00	2140.00
Sum Labor					7260.00	506.20	7,766.20

Printed on 3/9/2019 9:36:22 AM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 96203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : NTUC INCOME INS CO-OPERATIVE LTD
1 MARITIME SQUARE
HARBOURFRONT CENTRE
SINGAPORE 099253

Registration No : SMD2338M
Chassis No : MRHFC5650JT001303
Model : CIVIC 1.6 VTI YM2018
Owner's Name : TU JINHUO
Ins Policy No. :
Date of Accident : 28/8/2019

Document No. : SQT19003852
Date : 2. Sep 2019
Customer No. : WZN008
Svc Advisor : JACK NG
Engine No : R16B25501498
Date | Time : 2. Sep 2019 2:05:18 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	Tan Jie 17495147						
Date & Time	10/9/19 2:330						
Excess							
Status	UP						
Signature	Jie						

Total Amount 8,154.96 570.84 8,725.80

Total (Inclusive of GST) 8,725.80

Resurvey before paint
= 3 days
src kuantan.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 3/9/2019 9:36:22 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0068271 / NTUC INCOME INS
Chassis No: MRHFC5650JT001303
License No: SMD2338M
Mileage: 7204
Engine No: R16B25501498

Document No: SVO19058635
Printed By: JACKNG
Order Date: 10. September 2019
Order Time: 3:59:34 PM
Service Advisor: JACK NG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:TU JINHUO OWNER INSURER:TOKIO MARINE ACC DATE:28/08/2019 SURVEYED BY: DATE: REF NO: TP INSURER:NTUC INCOME TP VEH:FBE 481 U						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40	25	27.30	1.91	29.21
71593-TEA-T01	SPACERR,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71596-TEA-T01	SPACERL,RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
68500-TEA-N00ZZ	LID COMP TRUNK	0	486.20	25	0.00	0.00	0.00
	SUM PARTS:				519.51	36.35	555.86
BOSUN	0669 SUNDRIES	1	50.00		50.00	3.50	53.50
BML02I	0669 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	280.00		280.00	19.60	299.60
BA02R	0669 REMOVE & REINSTALL REVERSE SENSORS-4 PCS (N)	1	380.00		380.00	26.60	406.60
BC011R	0669 RESET & CALIBRATE SMART ENTRY SYSTEM(N)	1	450.00		450.00	31.50	481.50
BKB02R	0669 REMOVE & RENEW RR BUMPER. RENEW ALL DAMAGE PARTS ATTACHMENT ITEMS	1	560.00		560.00	39.20	599.20
BP04R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(4P)	1	450.00		450.00	31.50	481.50
	SUM LABOUR:				2,170.00	151.90	2,321.90
	TOTAL SGD				2,689.51	188.25	2,877.76
	Total Payable (SGD)						2,877.76

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19016056/T1vd3n2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 07-10-2019



ATTN: HELENA TAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBE 481U	Veh. Inspected	SMD 2338M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1059976-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	10/09/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC 1.6	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MRHFC5650JT001303	Colour	GREY
Odometer	12816 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R16	HANKOOK	6 mm
L/H Front Tyre	215/55 R16	HANKOOK	6 mm
R/H Rear Tyre	215/55 R16	HANKOOK	6 mm
L/H Rear Tyre	215/55 R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/08/2019	Inspect Date / Time	10/09/2019 (03:46 PM)
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 2338M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FACE ASSY,RR BUMPER (SN)	DEFORMED	462.90	462.90
1	REFLECTOR ASSY,RR (SN)	NOT NECESSARY	5.40	-
1	REFLECTOR ASSY,L,RR (SN)	NOT NECESSARY	5.40	-
1	GARNISH,RR.BUMPER LOWER (SN)	DEFORMED	27.30	27.30
1	SPACER,RR.BUMPER SIDE (SN)	NECESSARY	8.62	8.62
1	SPACER,L,RR.BUMPER SIDE (SN)	NECESSARY	8.62	8.62
7	CLIP,BUMPER (SN)	NECESSARY	12.07	12.07
1	LID COMP TRUNK (SN)	NOT NECESSARY	364.65	-
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
			994.96	569.51
LABOUR				
	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER.		380.00	280.00
	REMOVE & REINSTALL REVERSE SENSOR-4 PCS.		380.00	380.00
	RESET & CALIBRATE SMART ENTRY SYSTEM.		450.00	450.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.	NOT NECESSARY	450.00	-
	REMOVE & RENEW RR BUMPER.RENEW ALL DAMAGE PARTS.		3,500.00	560.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (4P).		2,000.00	450.00
			7,160.00	2,120.00
GRAND TOTAL			8,154.96	2,689.51
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,689.51

Report Ref No. CS/INC19016056/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEM,MAEME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.