

ALG CC3/A1G190/6099/A1f30r

Minimum

ASSIGNMENT

From: 10/09/2019 Date: 10/09/2019

Estimated Cost: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SBP 7771 D

at Workshop m/s: premium Automobile

of: 55 ubi Road 1

Insured: 2100500420

Policy No: 163649929356

Claims No: 163649929356

Sum Insured: 18A \$1000

(Client's Record)

Make of Veh: 3pm (writing)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 143K.

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SBP 7771 D. Reg: 2017, Feb.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q5 C.C. 1989

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 33038. T/Radio: Insured / Std / NI / NA

Eng/No: WAU 2228 R7HA 075401

C/No: WAU 2228 R7HA 075401

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/60 R18.

R: 235/60 R18.

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 06 mm R/Bal: 06 mm

L/Bal: 06 mm

D.O.A: 10/09/19

Survey held at: Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: 00 ALG.

Action / Instruction: SBP 7771 D - N/A / 1109000000 / 51

RECEIVED 02 MAR 2020

11/9 @ 11:30 seek mandate approval.

11/9 @ 14:37 - mandate approval by victor kan

12/9 @ 12:09 pm - email premium authorise repair

Part by Part: \$2815.68 (Red: 613332: 68%)

Date/Time, File Pass to: 28/2/2020

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee: 200

Transportation: 11

3 + PS: 24

Plains: 11

Other: 24

1 + 131

Repeat Form: OD

Lump Sum / 2815.68

Add Fee: ☐ Site Insp. (\$) ☐ Interview (\$) ☐ Tech. Insp. (\$) ☐ Weekend

Nivitha (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Monday, 9 September 2019 4:26 PM
To: 'Admin-D (LKKAuto)'; 'Admin A'; 'SUR'
Cc: 'Claims'
Subject: OD CLAIM FOR SBP 7771 D ON 28/8/2019
Attachments: SBP 7771 D - 30082019 - OD CLAIM.PDF; SAftersales19090916290_0001.jpg; SAftersales19090916290_0002.jpg

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report for your reference.

We will forward you the estimate once it is available.

Please arrange survey on 10/9/2019, 3pm. Owner waiting.

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 12 September 2019 12:09 PM
To: Claims Dept; Admin-D (LKKAUTO); SUR
Subject: RE: OD CLAIM FOR SBP 7771 D ON 28/8/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SBP 7771D (Excess \$1000/-)**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Tuesday, 10 September 2019 3:59 PM
To: 'Claims' <claims@premiumauto.com.sg>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SBP 7771 D ON 28/8/2019

Dear SUR team,

Attached revise estimate for your kind reference.

Kindly assist follow up repair approval

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Singapore 408699

p. +65 6366 2323, d. +65 67689911

e.<mailto:claims@premiumauto.com.sg> w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

View Received Message

This mail is associated with :

***SBP7771D (1636499293SG)**
OD
Aug 28 2019 8:00AM
[TERENCE WEE JIN ZOO]
Premium Automobiles Pte Ltd

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From AIG Asia Pacific Insurance Pte. Ltd, (AIG_SG), sent on 11/09/2019 14:37 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3090.00) - SBP7771D - Claim Handler: Gan, Hunchung

Approved:3090.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gan, Hunchung

Date: 11 Sep 2019

Preliminary Advice

Vehicle No	: SBP7771D	Accident Date	: 28/08/2019
Make	: AUDI Q5	Policy No.	: 2100500420
Assignment Date	: 11/09/2019	Excess	: S\$0.00
Date of Inspection	: 10/09/2019	Est. Duration of Repair	: 3.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,949.00
Revised Amount	:S\$	3,090.00
Check Items (Estimated)	:S\$	300.00
Total	:S\$	3,390.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	143,000.00
COE / PARF Rebate	:S\$	66,823.00
Salvage Value	:S\$	
Margin for Repair	:S\$	77,177.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	083A
Vehicle Details	
Vehicle No.:	SBP7771D
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Sep 2019
Vehicle Make:	AUDI
Vehicle Model:	Q5 2.0 TFSI QU (180 BHP)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	CNC181521
Chassis No.:	WAUZZZ8R7HA075401
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$35,276.00
Original Registration Date:	14 Feb 2017
First Registration Date:	14 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$41,387.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Feb 2027
PARF Rebate Amount:	\$31,040.00
Intended COE Rebate Details	
COE Expiry Date:	13 Feb 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,209.00
COE Rebate Amount:	\$35,783.00
Total Rebate Amount:	\$66,823.00

The information contained herein is correct as at 11 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/08/2019 11:10
Date Of Accident	28/08/2019 08:25
Exact Location Of Accident	TIONG BAHRU MARKET CARPARK RAMP (SENG POH RD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBP7771D
Insured/Policyholder	
Name Of Registered Owner	TERENCE WEE JIN ZOO
NRIC No	S1662083A
Email Address	TERENCE_WEE@ROCKETMAIL.COM
Mobile Phone No	(LOCAL) +65-90621881
Alternative Phone No	OFFICE-90621881

Vehicle Particulars

Manufacturer	AUDI
Model	Q5-2.0 TFSI QUATTRO (180BHP) (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100500420-02
Cover Note Number	

Driver

Name of Driver	TERENCE WEE JIN ZOO
NRIC No	S1662083A
Date Of Birth	30/12/1964
Occupation	INDOOR
Date Of Driving Pass	29/07/1985
Driving Experience	34 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90621881
Fax Number	
Contact Number	OFFICE-90621881
E-Mail Address	TERENCE_WEE@ROCKETMAIL.COM

Address	31 CHENG SOON GARDEN
Postcode	599807
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO ACCIDENT REPORT STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCH8009X
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GOH SOOK MUI
NRIC/Passport Number	S7012455F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

30/8/19

Driver's Signature

(If driver is not the policyholder)

Date & Time: 30/8/19

Reporting Centre Personnel's Signature

Name:

Toy Fong

NRIC/FIN No:

870461871



Sketch Plan #2

SKETCH PLAN



A = SBP 7771J

B = SCH 8004X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer to the Accident
Report Statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 30/01/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Tony Tye
NRIC/PRN No: 67040108

Sketch Plan #3

Accident report for SBP7771D

Reference No: WSVCL9001840
Date of accident: 28 Aug 2019
Time of accident: 8:25am
Location: Up the car park ramp of Tiong Bahru Market (Seng Poh Road)
Vehicle: SBP7771D
Driver: Terence Wee (S1662083A)
Contact #: 90621881
Email: Terence_Wee@rocketmail.com

Other vehicle: SCH8009X
Other driver: Goh Sook Mui (S7012455F)
Other contact #: 91906827

Incident Report

1. I frequent the Tiong Bahru Market for breakfast. On that morning, I entered the carpark and drove up along the spiral carpark ramp.
2. I was the only car driving up the ramp and the downward lane was empty too.
3. Three quarter of the way up the ramp, I spotted a car coming down from the other side.
4. I slowed down to allow for better control and navigation.
5. When I noticed the car coming down the slope was a bit fast and a bit close, I slowed my car to a near halt, to allow it navigate clearer.
6. Unfortunately, the oncoming car struck mine.
7. The contact point was the bottom of my Right-Rear passenger door, just in front of the right-rear wheel. The damage was to the door as well as the skirting below the door. As shown in Picture #1.
8. The other car had sustained damage to its front right bumper. It was scratch and displaced about 1cm downwards. As shown in Pictures #2 and #3.
9. Subsequent to the accident, the other car reversed backwards, to allow the drivers to alight. Picture #4.
10. A picture of the scene (picture #5, #6) showed where my car was at the point of the accident (unmoved). The right rear wheel is on the middle line. The point of contact of the accident, is on the line and within the lane.

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : WEE JIN ZOO TERENCE
 Period of Insurance : 14 Feb 2019 To 13 Feb 2020
 Engine No. : CNC181521
 Chassis No. : WAUZZZ8R7HA075401

Vehicle No. : SBP7771D
 Policy No. : 2100500420-02
 Endorsement No. :
 Issued Date : 08 Jan 2019

ABOUT THE COVER

Make/Model : AUDI Q5 2.0 TFSI (180 bhp) Qu
 Engine Capacity/Tonnage : 1,984.00 CC Sum Insured : Market Value First Year of Registration : 2017
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PAF : Yes
 Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$1000 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

WEE JIN ZOO TERENCE - \$1000 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125211

PREMIUM LEASING - NC
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


 AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10950

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1081/2019/NS
Date	:	9-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Terrence Wee Jin Zoo
Address	:	31 Cheng Soon Garden Singapore 599807
Telephone	:	HP +65 90621881
Type of Claim	:	Own Damage Claim
Policy No.	:	2100500420-02
Vehicle No	:	SBP 7771 D
Model Code	:	Audi Q5 SPORT 2.0 TFSI QU
Model / Year	:	14/2/2017
Engine No	:	CNC 181521
Chassis No	:	WAUZZZ8R7HA075401
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-Aug-19
Place of Accident	:	Tiong Bahru Market Carpark Ramp (Seng Poh Rd)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBP 7771 D

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs rear door multi-lock system and power window devices. Check function and renew if necessary.	S/N \$ 280.00 x.	
2	To dismantle and renew rhs rear door. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00 500	✓
3	To respray rhs rear door and door cover,	\$ 1,600.00 750	✓
4	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓ ✓
5	To carry out diagnostic checks.	S/N \$ 192.00	✓ ✓
SUB TOTAL LABOUR CHARGES		: \$ <u>3,552.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBP 7771 D

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	REAR DOOR - RH <i>Repair</i>	\$	2,829.00	x
2	OUTER DOOR SEAL <i>3</i>	NEC \$	193.00	x
3	BONDING AGENT <i>2</i>	NEC \$	45.00	x
4	CLEANING SOLUTION <i>1</i>	NEC \$	65.00	x
5	STONE CHIP PROTECTION FILM - RH INNER <i>2</i>	\$	71.00	56.48
6	REAR DOOR ATTACHMENT PARTS <i>2</i>	\$	112.00	x
7	REAR DOOR CATCH <i>1</i>	\$	132.00	x
8	REAR DOOR COVER - RH <i>1</i>	\$	374.00	298.80
9	WHEEL HOUSING LINER - RH <i>2</i>	\$	246.00	x
10	WHEEL HOUSING LINER ATTACHMENT PARTS <i>2</i>	\$	94.00	x
11	REAR ALUMINIUM RIM - RH <i>1</i>	\$	923.00	738.40
12	ALUMINIUM RIM RUBBER VALVE <i>4</i>	\$	13.00	x
13	SUNDRIES <i>Not NEC</i>	\$	300.00	x
TOTAL SPARE PARTS		:	\$ 5,397.00	
TOTAL LABOUR CHARGES		:	\$ 3,552.00	
GRAND TOTAL		:	\$ 8,949.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 10/09/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10950

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1081/2019/NS
Date : 9-Sep-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

3 days - ok - Jy - 26 Dec 2019

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Terrence Wee Jin Zoo
Address : 31 Cheng Soon Garden
Singapore 599807
Telephone : HP +65 90621881
Type of Claim : Own Damage Claim
Policy No. : 2100500420-02
Vehicle No : **SBP 7771 D**
Model Code : Audi Q5 SPORT 2.0 TFSI QU
Model / Year : 14/2/2017
Engine No : CNC 181521
Chassis No : WAUZZZ8R7HA075401
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-Aug-19
Place of Accident : Tiong Bahru Market Carpark Ramp (Seng Poh Rd)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBP 7771 D

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs rear door multi-lock system and power window devices. Check function and renew if necessary.	S/N \$ 280.00	
2	To dismantle and renew rhs rear door. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00	\$ 500.00
3	To respray rhs rear door and door cover.	\$ 1,600.00	\$ 750.00
4	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
5	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
SUB TOTAL LABOUR CHARGES		: \$ 3,552.00	\$ 1,722.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBP 7771 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR DOOR - RH	\$ 2,829.00	
2	OUTER DOOR SEAL	NEC \$ 193.00	
3	BONDING AGENT	NEC \$ 45.00	
4	CLEANING SOLUTION	NEC \$ 65.00	
5	STONE CHIP PROTECTION FILM - RH INNER	\$ 71.00	\$ 56.48
6	REAR DOOR ATTACHMENT PARTS	\$ 112.00	
7	REAR DOOR CATCH	\$ 132.00	
8	REAR DOOR COVER - RH	\$ 374.00	\$ 298.80
9	WHEEL HOUSING LINER - RH	\$ 246.00	
10	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 94.00	
11	REAR ALUMINIUM RIM - RH	\$ 923.00	\$ 738.40
12	ALUMINIUM RIM RUBBER VALVE	4 \$ 13.00	
13	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		: \$ 5,397.00	\$ 1,093.68
TOTAL LABOUR CHARGES		: \$ 3,552.00	\$ 1,722.00
GRAND TOTAL		: \$ 8,949.00	\$ 2,815.68

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SBP 7771 D

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1081/2019/NH

25th February 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SBP 7771 D, Audi Q5 2.0 TFSI QUATTRO.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SBP 7771 D**, claimant, **Mr. Terence Wee Jin Zoo**, please find the related document per attached.

1. A copy of the Original invoice no. 85014880 – S\$ 1,942.78.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SBP 7771 D

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6386 2323
24-hour Breakdown Service 9825 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:35

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014880 Date : 21/02/2020 Order : SBP7771D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SBP7771D (V 32419)	Regn Date: 14/02/2017	Mileage: 34611	WIP No.: 10950
Model: Q5 2.0 TFSI quattro (180 bhp)	Chassis: WAUZZZ8R7HA075401	Engine: CNC 181521	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1000.00	1.00	-1,000.00
S	BODYWORK	M: TO DISMANTLE AND RENEW RHS REAR DOOR. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY RHS REAR DOOR AND DOOR COVER	750.00	1.00	750.00
S	BODYWORK	M: TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	ASR0839982C	(SK) FOIL Less 020%	1.00	70.60	56.48
X	ASR0601025CG	007445/(V) (GER) WHEEL Less 020%	1.00	923.00	738.40
X	ASR0853970L GRU	(A) (SK) COVER 27/9/19 Less 020%	1.00	373.50	298.80

Parts 1,093.68
Labour 0.00
Sublet 1,722.00
Menus 0.00
Lubricant 0.00

Sub-Total 1,815.68

7% GST 127.10

Grand Total 1,942.78



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SBP7771D

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1081/2019/TF
8 Nov 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q5 2.0 TFSI quattro
Vehicle Chassis No. : WAUZZZ8R7HA075401
Vehicle Regn No. : **SBP7771D**
Vehicle Mileage : 34611KM
Vehicle Owner : Mr. Terence Wee Jin Zoo
Certificate No : 2100500420-02
Own Damage Excess : S\$1070.00 (Inclusive 7% GST)
Accident Date : 28/08/2019
Place : Tiong Bahru Market Carpark Ramp
Repair Cost : \$ 1942.78
WIP No. : 10950
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 

Time :

Date : 8/11/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Aug 2019		11 Sep 2019 09:52 Edit Adj Rpt	S\$2,815.68 Edit Estimates	S\$2,815.68 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TERENCE WEE JIN ZOO, ID: S1662083A, Tel: +6590621881, Email: TERENCE_WEE@ROCKETMAIL.COM								
Vehicle Reg. No.:	SBP7771D	Date of Loss:	28/08/2019 08:00 - :59 [30 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 1636499293SG	Policy/Cover Note No.:	2100500420 (Comprehensive)						
		Excess:	S\$1,000.00						
Repairer:	Premium Automobiles Pte Ltd (UB1) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/09/2019]								
Driver/Custodian:	TERENCE WEE JIN ZOO (S4 / Male) ; NRIC: S1662083A, Tel: +6590621881 Email: TERENCE_WEE@ROCKETMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (11/09/2019): Alert - Adj Mandate Approved (S\$3090.00) - SBP7771D - Claim Handler: Gan, Hunchu... - AIG_SG (11/09/2019): SBP7771D / OD / 28/08/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SBP7771D (1636499293SG)**
OD

Aug 28 2019 8:00AM
[TERENCE WEE JIN ZOO]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Assessment Reports															1 per page		☐	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	11/09/19 11:28	Adjuster Immediate Advice												1	Load HTM			
Photos/Images															3 per page		☐	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	11/09/19 11:06	General View												1	Load JPG	☒		
2	11/09/19 11:06	General View												1	Load JPG	☒		
3	11/09/19 11:06	General View												1	Load JPG	☒		
4	11/09/19 11:06	General View												1	Load JPG	☒		
5	11/09/19 11:06	General View												1	Load JPG	☒		
6	11/09/19 11:06	General View												1	Load JPG	☒		
7	11/09/19 11:06	General View												1	Load JPG	☒		
8	11/09/19 11:06	General View												1	Load JPG	☒		
9	11/09/19 11:06	General View												1	Load JPG	☒		
10	11/09/19 11:06	General View												1	Load JPG	☒		
11	11/09/19 11:06	General View												1	Load JPG	☒		
12	11/09/19 11:06	General View												1	Load JPG	☒		
13	11/09/19 11:06	General View												1	Load JPG	☒		
14	11/09/19 11:06	General View												1	Load JPG	☒		
Documentation															1 per page		☐	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	11/09/19 11:06	Driver's Driving License / NIRC												1	Load PDF			
2	11/09/19 11:06	ESTIMATE												1	Load PDF			
3	11/09/19 11:06	Singapore Accident Statement												1	Load PDF			
4	11/09/19 11:06	Certificate of Insurance												1	Load PDF			
5	04/03/20 15:19	Workshop Invoice												1	Load PDF			
6	04/03/20 15:19	Discharge Voucher												1	Load PDF			

Linked Accident Report Documents

										View		View in Browser					
Assessment Reports										1 per page				☒			
No	Finalized On	Premium Automobiles Pte Ltd (UBI)										Thumbnail		Print			
1	30/08/19 11:23	Accident Statement								1		Load HTM					
2	30/08/19 17:19	Addendum Sheet								1		Load JPG		☒			
3	30/08/19 17:20	Accident Statement								1		Load HTM					
4	03/09/19 11:39	Addendum Sheet								1		Load JPG		☒			
5	03/09/19 11:39	Accident Statement								1		Load HTM					
Photos/Images										3 per page				☒			
No	Finalized On	Premium Automobiles Pte Ltd (UBI)										Thumbnail		Print			
1	30/08/19 11:17	Accident Photo								1		Load JPG					

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
				☒
2	30/08/19 11:17	Accident Photo	 Load JPG	☒
3	30/08/19 11:17	Accident Photo	 Load JPG	☒
4	30/08/19 11:17	Accident Photo	 Load JPG	☒
5	30/08/19 11:17	Accident Photo	 Load JPG	☒
6	30/08/19 11:17	Accident Photo	 Load JPG	☒
7	30/08/19 11:17	Accident Photo	 Load JPG	☒
8	30/08/19 11:17	Accident Photo	 Load JPG	☒
9	30/08/19 11:17	Accident Photo	 Load JPG	☒
10	30/08/19 11:17	Accident Photo	 Load JPG	☒
11	30/08/19 11:17	Accident Photo	 Load JPG	☒
12	30/08/19 11:17	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	30/08/19 11:21	Sketch Plan	 Load JPG	☒
2	30/08/19 11:21	Sketch Plan #2	 Load JPG	☒
3	30/08/19 11:21	Sketch Plan #3	 Load JPG	☒
4	30/08/19 11:21	Sketch Plan #4	 Load JPG	☒
5	30/08/19 11:21	Sketch Plan #5	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19016099/ATF3E2

Date: 04/03/2020

REFERENCE

Insured/Claimant: TERENCE WEE JIN ZOO Policy No: 2100500420
Date of Loss: 28/08/2019 Nature of Claim: OD Claim No: 1636499293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBP7771D**
Make & Model: AUDI Q5, 2.0 TFSI Quattro (180BHP) (A) Engine No: CNC181521
Reg. Date: 14/02/2017 (Man. Year: 2016) Chassis No: WAUZZZ8R7HA075401
Colour: White Odometer: 33038 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$143,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,397.00	1,093.68	4,303.32	79.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,552.00	1,722.00	1,830.00	51.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,949.00	2,815.68	6,133.32	68.54
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	7,949.00	1,815.68	6,133.32	77.16
+ GST 7.00/7.00% (S\$)	556.43	127.10	429.33	77.16
Nett Amount (S\$)	8,505.43	1,942.78	6,562.65	77.16

INSPECTION

Date of Assignment: 11/09/2019
Date Inspected: 10/09/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - RH	Repair	2,829.00 FS	*- FS
2	1		*OUTER DOOR SEAL	Not Necessary	193.00 FS	*- FS
3	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
5	1		*STONE CHIP PROTECTION FILM - RH INNER	Necessary	71.00 FS	*56.48 FS
6	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	112.00 FS	*- FS
7	1		*REAR DOOR CATCH	Not Necessary	132.00 FS	*- FS
8	1		*REAR DOOR COVER - RH	Cut	374.00 FS	*298.80 FS
9	1		*WHEEL HOUSING LINER - RH	Not Necessary	246.00 FS	*- FS
10	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	94.00 FS	*- FS
11	1		*REAR ALUMINIUM RIM - RH	Cut	923.00 FS	*738.40 FS
12	4		*ALUMINIUM RIM RUBBER VALVE	Not Necessary	13.00 FS	*- FS
13	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
Total Parts (S\$)					5,397.00	1,093.68

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. CHECK FUNCTION AND RENEW IF NECESSARY	New	280.00	0.00
2	TO DISMANTLE AND RENEW RHS REAR DOOR. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY RHS REAR DOOR AND DOOR COVER	New	1,600.00	750.00
4	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			3,552.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >