

ASS. REC. BY:

Surveyor: Kenneth

REP: CS/U01 19016102/kgf302

Special Instruction:

ASSIGNMENT (Office)

From (Person): Jenny Lew

of

UOI

Date/Time: 10/9/2019 @ 430pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

EN 222T

Insured:

at Workshop n/a

Lai Hwee Meng Kee

Tel:

6453 8110

of

160 Sin Ming Drive # 04-01/02

Policy No:

Claim No:

M1208071909

Sum Insured:

Excess:

TBA NIL

Make of Veh:

(Client's Record)

D.O.A. 05/09/2019

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:06pm @ 11/9/19

Person Contacted:

Jenny

Vehicle IN/OUT

MV: D92K

Date/Time	Action/Instruction
	Estimate 1 ✓
	EV 222T - X
11/9/19 @ 2:13pm	revert to Jenny Lew by email.
11/9/19 @ 5:26pm	Jenny Lew informed C/A & ex: NIL by email.
11/9/19 @ 5:37pm	Informed Jenny Lin C/A & ex: NIL by email.
20/2	\$19064.80 Cash (Red to 1216, 6%)

ASS. REC. BY:

REF:

U02/CS/U01 1906102/19f3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / RES / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

24 days

Res.: Yes or No

Lum Sum:

1-B-1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 File pass to

20/02/20 @ 1.12pm not revert to Jenny Law by email. (supplementary)

25/2/20 @ 1.04pm Josephine Wong informed they agreed our revised preli. advice of added supplementary & check items. then email.

RECEIVED 25 FEB 2020

Date/Time, File Pass to?

☐

: Preli. Report

1) 25/2/20

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

24

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S-RS-SI

Fees

Others

TOTAL

10 x 24 = 240

300 + 240

60

80 + 80

81

81

81

81

81

81

Report Format:

60

Lump Sum / I.B.I. (\$

19064.80

Nivitha (LKK Auto)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Tuesday, 10 September 2019 4:30 PM
To: Jenny Lim; assignments; SUR
Cc: LEE KATIE
Subject: RE: Request for Survey (OD) - EN 222T / Toyota Estima
Attachments: 10092019154109.zip

Dear Jenny,

As requested, we will appoint LKK to survey the vehicle.

Dear Shiau Chan,

Please arrange to survey the vehicle at Lai Huat.
Excess: nil

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Jenny Lim [<mailto:jenny.lim@laihuat.com.sg>]
Sent: Tuesday, 10 September, 2019 3:48 PM
To: LEW JENNY <jennylew@uoi.com.sg>
Subject: Request for Survey (OD) - EN 222T / Toyota Estima

Dear Jenny

We refer to the above matter.

Please can you arrange to survey our client's vehicle no. EN 222T?

Supporting documents are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

Shiau Chan (LKKAUTO)

From: WONG JOSEPHINE <josephinewong@uoi.com.sg>
Sent: Tuesday, 25 February 2020 11:04 AM
To: Shiau Chan (LKKAUTO); assignments
Cc: LEE KATIE
Subject: RE: Request for Survey (OD) - EN 222T / Toyota Estima Our ref: M11D08071909

Without Prejudice

Dear Shiau Chan

We agree with your revise preliminary of added supplementary and check items.

Our reference no is M11D08071909.

Thanks

Josephine Wong

Executive
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • josephinewong@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Thursday, February 20, 2020 1:12 PM
To: LEW JENNY <jennylew@uoi.com.sg>; assignments <assignments@lkkauto.com>; WONG JOSEPHINE <josephinewong@uoi.com.sg>
Cc: LEE KATIE <katielee@uoi.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: Request for Survey (OD) - EN 222T / Toyota Estima

Dear Sir/Madam,

Enclosed herewith 2nd preliminary advice of EN 222T.
Kindly approve on supplementary & check items and advise us the claim reference.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Wednesday, 11 September 2019 5:26 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 20 February 2020 1:12 PM
To: LEW JENNY; assignments; WONG JOSEPHINE
Cc: LEE KATIE; SUR
Subject: RE: Request for Survey (OD) - EN 222T / Toyota Estima
Attachments: CSUOI19016102Kqf3(2).pdf, EN222 SUPP.pdf

Dear Sir/Madam,

Enclosed herewith 2nd preliminary advice of EN 222T.
Kindly approve on supplementary & check items and advise us the claim reference.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Wednesday, 11 September 2019 5:26 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: Request for Survey (OD) - EN 222T / Toyota Estima

Dear Shiau Chan,

Please proceed with repair authorisation at S\$18,809.80
Excess: Nil

Enclose the discharge voucher for client due execution.

The claim yet to registered.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #26-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Shiau Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]
Sent: Wednesday, 11 September, 2019 2:14 PM
To: LEW JENNY <jennylew@uoi.com.sg>; assignments <assignments@lkkauto.com>



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 20th February 2020

Our Ref: CS/UOI19016102/Kqd3

The Motor Claims Department
United Oversea Insurance

Attn: Jenny

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. EN 222T.


We thank you for the instruction on 10/09/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/09/2019 at the premises of M/s LAI HUAT (MENG KEE) and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 20,280.80 (EST \$19,389.80 + SUPP \$891.00)</u>
Revised Estimate Amount	: <u>S\$ 19,064.80 (INCLUSIVE CHECK & SUPP)</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ 82,000.00</u>
LTA Reimbursement Value	: <u>S\$ 58,686.00</u>
Nett Value	: <u>S\$ 23,314.00</u>

Description of Damage:

The vehicle sustained damages at the rear and front portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

The vehicle repair on part by part basis.

Recommendation days of repair: 24 days.

Kindly approve on supplementary & check items.

Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 11 September 2019 5:37 PM
To: Jenny Lim
Cc: SUR
Subject: OD VEHICLE EN 222T (DOA: 05/09/2019)

Dear Jenny,

As spoken with you.

As instructed by our client, please proceed to repair the insured vehicle **EN 222T (Excess NIL)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Wednesday, 11 September 2019 5:26 PM
To: Shiau Chan (LKKAUTO); assignments
Cc: LEE KATIE; SUR
Subject: RE: Request for Survey (OD) - EN 222T / Toyota Estima
Attachments: OD Template.zip

Dear Shiau Chan,

Please proceed with repair authorisation at S\$18,809.80
Excess: Nil

Enclose the discharge voucher for client due execution.

The claim yet to registered.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Shiau Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]
Sent: Wednesday, 11 September, 2019 2:14 PM
To: LEW JENNY <jennylew@uoi.com.sg>; assignments <assignments@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: Request for Survey (OD) - EN 222T / Toyota Estima

Dear Jenny,

Kindly provide us the claim reference of above mentioned.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Wednesday, 11 September 2019 2:13 PM
To: 'LEW JENNY' <jennylew@uoi.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'LEE KATIE' <katielee@uoi.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: Request for Survey (OD) - EN 222T / Toyota Estima

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 11 September 2019 2:13 PM
To: 'LEW JENNY'; assignments
Cc: 'LEE KATIE'; SUR
Subject: RE: Request for Survey (OD) - EN 222T / Toyota Estima
Attachments: CSUOI19016102Kqf3.pdf; EN222 EST.pdf

Dear Jenny,

Enclosed herewith preliminary advice of EN 222T.
The vehicle repair on part by part basis.

We have not authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 11 September 2019 10:52 AM
To: 'LEW JENNY' <jennylew@uoi.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'LEE KATIE' <katielee@uoi.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: Request for Survey (OD) - EN 222T / Toyota Estima

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: LEW JENNY [<mailto:jennylew@uoi.com.sg>]
Sent: Tuesday, 10 September 2019 4:30 PM
To: Jenny Lim <jenny.lim@laihuat.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: LEE KATIE <katielee@uoi.com.sg>
Subject: RE: Request for Survey (OD) - EN 222T / Toyota Estima

Dear Jenny,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 11th September 2019

Our Ref: CS/UOI19016102/Kqd3

The Motor Claims Department
United Oversea Insurance

Attn: Jenny

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. EN 222T


We thank you for the instruction on 10/09/2019.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/09/2019 at the premises of M/s LAI HUAT (MENG KEE) and have the following to report:-

Workshop Estimate Amount	: S\$ <u>19,389.80</u>
Revised Estimate Amount	: S\$ <u>17,051.00</u>
"Check" Items Amount	: S\$ <u>1,758.80</u>
Market Value	: S\$ <u>82,000.00</u>
LTA Reimbursement Value	: S\$ <u>58,686.00</u>
Nett Value	: S\$ <u>23,314.00</u>

Description of Damage:

The vehicle sustained damages at the rear and front portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

The vehicle repair on part by part basis.

Recommendation days of repair: 24 days.

We have not authorize repair.

Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/09/2019 13:49
Date Of Accident	05/09/2019 13:20
Exact Location Of Accident	BKE (WOODLANDS) TOWARDS KRANJI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EN222T
Insured/Policyholder	
Name Of Registered Owner	LIN TING
NRIC No	S8200729F
Email Address	TINGLT@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92730273
Alternative Phone No	OTHERS-92730273
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ESTIMA AERAS-2.4 PREMIUM (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DHOM110137351405
Cover Note Number	
Driver	
Name of Driver	LIN TING
NRIC No	S8200729F
Date Of Birth	16/01/1982
Occupation	INDOOR
Date Of Driving Pass	03/06/2003
Driving Experience	16 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92730273
Fax Number	
Contact Number	OTHERS-92730273
Email Address	TINGLT@GMAIL.COM

Address	27 CLAYMORE ROAD #07-02
Postcode	229544
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JPR4455 (PRIVATE CAR)
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JPR4455
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SH7335X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 06/09/19
1:00 pm

Driver's Signature


(If driver is not the policyholder)

Date & Time: 06/09/19
1:00 pm

Reporting Centre Personnel's Signature

Name: Jenny Lim
NRIC/FIN No.: S6927273H

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Was driving along Bke (Woodlands) towards Kranji, and near part 315, the extreme right lane was cordoned off so I started to signal and change to the left lane. There ~~was~~ was a queue of cars slowly changing lane as well.

Suddenly, driver in front driving Mitsubishi Sport (JPR 4455) jam break and I had to quickly floor my break as well ^{and hit the car in front}. A few seconds later, I felt an impact from the back as well.

A taxi driver (confort SH 7335X) had jam break and hit my rear.

According to the ~~account~~ account of the driver driving JPR 4455, a car in front of him had jam break causing him to jam break, but I was unable to get his details as he had driven off.

Car A: JPR 4455, Mitsubishi ^{even} Sport, minimal damage
driver details - name: Adin ^{013 7434435}

Car B: EN222T, Toyota Estima, damage to front and back, owner car: S82007294, LINTING


Car C: SH 7335X, confort taxi, kang Jue ON
S1419019H

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time: 06/09/19
1:00pm


Driver's Signature
(If driver is not the policyholder)
Date & Time: 06/09/19
1:00pm


Reporting Centre Personnel's Signature
Name: Jenny Lim
NRIC/FIN No.: S6927273H



**SINGAPORE
POLICE FORCE**



T/20190905/2128

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No. 1800-7359999

1 of 4

Report No. T/20190905/2128

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 06/09/2019 16:53		Vide Report No :		Station Diary No 127	
Informant's Particulars					
Name of Informant LIN TING			Address 27 CLAYMORE ROAD #07-02 SINGAPORE 229544		
ID Type / ID No : NRIC NO / S8200729F			Contact No : Home/Office : Mobile: 92730273		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 37	Date of Birth: 16/01/1982	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Housewife			Driving Licence Information: Class 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 05/09/2019 13:20	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY Along Bukit Timah Expressway (Woodlands) near lamppost number 315 Along the 2nd lane of BKE as the 1st lane just started to cordon off Lamp Post Number: 315				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
EN222T	Car	TOYOTA	ESTIMA AERAS PREMIUM 2.4 A	Purple	Seriously Damaged	0
JPR4455	Car	MITSUBISHI	Ruero Sport	White	Slightly Damaged	0
SH7335X	Car	HYUNDAI	Comfort Delgro Cab	Blue	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20190906/2128

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

2 of 4

Report No: T/20190906/2128

CONTINUATION OF REPORT

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
EN222T	UNITED OVERSEAS INSURANCE LIMITED	DHOM110137351405	08/07/2019	07/07/2020

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

Driver

Name	LIN TING	ID No.	S8200729F
Related Vehicle	EN222T (Car)	Contact No.	92730273
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Driver

Name	A Dini	ID No.	NIL
Related Vehicle	JPR4455 (Car)	Contact No.	0137454455
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Driver

Name	Kong Swee On	ID No.	S14190191
Related Vehicle	SH7335X (Car)	Contact No.	91292112
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20190906/2128

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999

3 of 4

Report No. T/20190906/2128

CONTINUATION OF REPORT

Brief Details.

On the above mentioned date, time and location, I was driving along the BKE in my car (EN222T, purple coloured Toyota) and attempting to change lanes from lane 1 to lane 2 due to the cordoning off of lane 1 (near Lamp post 315). At that instance, the foreign Johor car (JPR4455, white coloured Mitsubishi) suddenly jam braked and I could not stop my car in time and therefore bang into the rear of the foreign Johor vehicle. Subsequently, the taxi behind me (SH7335X, Comfort Delgro Taxi) banged into the rear of my vehicle as well.

As a result, the front and back of my car was seriously damaged and had to call for the tow company to tow it away.

I am therefore lodging this report for insurance claiming purposes.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Orchard N.P.C
51 Killiney Road SINGAPORE 239572
Tel No: 1800-7359999



T/20190906/2128

4 of 4

Report No. T/20190906/2128

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan



IMPORTANT Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
E /
ASP SIM WEI WEN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case
TP / AEIT /
Sr Staff Sgt ONG YONG HOCK
Contact No: 65476436

Authentication Stamp
NP158

Signature Of Informant

Date/Time
06/09/2019 16:53

Classification Of Case:



MEMBER OF THE UOI GROUP

United Overseas Insurance Limited
1 Raffles Road
#12-01 Springhill Tower
Singapore 079909
Tel: 651 6222 7734
Fax: 651 6327 3641 / 6327 3605
Email: Claims@uoi.com.sg
uoi.com.sg
Co. Reg. No. N01500026

Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE NO.	DHQM110137351405	Excess:	\$0/-NOT APPLICABLE
Type of Cover	COMPREHENSIVE		
Vehicle Number	EN222T		
Name of Insured	LIN TING		
Restricted Driver(s)	NOT APPLICABLE		

Period of Insurance 8 July 2019 to 7 July 2020

Engine# 2AZJ021785
Chassis# ACR500167501

PRIVATE CAR - INDIVIDUAL OWNERSHIP [MX 1]
AUTHORISED DRIVER

- (1) The Insured
- (2) Any other person who is driving on the Insured's order or with his permission
- (3) In the event of the death of the Insured
 - (a) any member of the Insured's family or a paid driver who has been driving the car during the lifetime of the Insured and permission to drive had not been withdrawn prior to the death of Insured and
 - (b) any other person who has been given permission to drive the vehicle prior to the death and such permission had not been withdrawn by the Insured

LIMITATIONS AS TO USE

Use only for social domestic and pleasure purposes and for the Insured's business

THE POLICY DOES NOT COVER

Use for hire or reward or racing pace-making reliability trial or speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purposes in connection with the Motor Trade

The carriage of passengers pursuant to car pooling arrangements and payments or any of them made by the passengers thereunder towards the running expenses of any vehicle described in the Schedule shall not be deemed to constitute use for hire or reward

Provided that the person is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

*Limitation rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and part IV of the Road Transport Act, 1987 (Malaysia).

UNITED OVERSEAS INSURANCE LTD

FCTTS Date : 27/06/2019

For the Company

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 729F

Vehicle Details

Vehicle No.: EN222T
Vehicle to be Exported: Yes
Intended Deregistration Date: 06 Sep 2019
Vehicle Make: TOYOTA
Vehicle Model: ESTIMA AERAS PREMIUM 2.4 A
Primary Colour: Purple
Manufacturing Year: 2013
Engine No.: 2AZJ021785
Chassis No.: ACR500167501
Maximum Power Output: 125.0 kW (167 bhp)
Open Market Value: \$32,393.00
Original Registration Date: 08 Jul 2014
First Registration Date: 08 Jul 2014
Transfer Count: 0
Actual ARF Paid: \$37,351.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 07 Jul 2024
PARF Rebate Amount: \$26,145.00

Intended COE Rebate Details

COE Expiry Date: 07 Jul 2024
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$67,290.00
COE Rebate Amount: \$32,541.00
Total Rebate Amount: \$58,686.00

The information contained herein is correct as at 06 Sep 2019

OK

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No: EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Page: 1 of 7
Your ref: DHDM110137351405
Job No: 70846
Our ref: 19.09.08
Payment:
Date: 10/9/2019

Attn:

Vehicle No: EN 222T
Vehicle Model: Toyota Estima
Accident on: 5/9/2019



Not Withheld

Runny Bypain

Rea & FH

24 days

Ref 62564315

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts:					
1.00	Set	Rear windscreen mouldings	38.00		38.00
1.00	Pc	Rear bumper	240.00		240.00
1.00	Pc	Rear bumper tow hook cover LH	12.00		12.00
1.00	Pc	Rear bumper tow hook cover RH	12.00		12.00
1.00	Pc	Rear bumper reflector LH	18.00		18.00
1.00	Pc	Rear bumper corner sponge LH	35.00		35.00
1.00	Pc	Rear bumper corner sponge RH	35.00		35.00
1.00	Pc	Rear tailgate	650.00		650.00
1.00	Pc	Rear tailgate Estima emblem	30.00		30.00
1.00	Pc	Rear tailgate Aeras emblem	20.00		20.00
1.00	Pc	Rear Toyota logo emblem	20.00		20.00
1.00	Pc	Rear tailgate lock mechanism	130.00		130.00
1.00	Pc	Rear end panel assy	230.00		230.00
1.00	Pc	Rear end panel trim garnish (upp)	90.00		90.00
1.00	Pc	Rear end panel trim garnish (lower)	100.00		100.00
4.00	Pcs	Rear end panel trim garnish clips	3.50		14.00
1.00	Pc	Rear luggage trim (fabric)	380.00		380.00
1.00	Pc	Rear fender inner trim garnish LH	580.00		580.00

Rea 38.00 ✓
Ry 240.00 ✓
MIS 12.00 ✓
Rea 12.00 ✓
Rea 18.00 ✓
CM 35.00 ✓
CM 35.00 ✓
Rea 650.00 ✓
Rea 30.00 ✓
Rea 20.00 ✓
Rea 20.00 ✓
Rea 130.00 ✓
Rea 230.00 ✓
CM 90.00 ✓
Rea 100.00 ✓
Rea 14.00 ✓
Rea 380.00 ✓
Rea 580.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Page 2 of 7
Your ref DHOM110137351405
Job No 70846
Our ref 19.09.08
Payment
Date 10/9/2019

Attn

Vehicle No EN 222T
Vehicle Model Toyota Estima
Accident on 5/9/2019

Quantity	Unit	Description	Unit price	Disc. pct	Amount
1.00	Pc	Rear fender inner trim garnish RH	580.00	Reform	580.00
1.00	Pc	Rear tailgate weatherstrip	110.00	Reform	110.00
1.00	Pc	Rear luggage panel	290.00	Re	290.00
1.00	Pc	Bonnet	190.00	Re	190.00
1.00	Pc	Bonnet hinge LH	25.00	Re	25.00
1.00	Pc	Bonnet hinge RH	25.00	Re	25.00
1.00	Pc	Bonnet lock	35.00	Re	35.00
1.00	Pc	Bonnet rubber seal	25.00	CM	25.00
1.00	Pc	Bonnet insulation	100.00	Reform	100.00
1.00	Pc	Radiator top cover	80.00	CM	80.00
5.00	Pcs	Radiator top cover clips	2.00	Re	10.00
1.00	Pc	Front bumper	210.00	CM	210.00
1.00	Pc	Front bumper reinforcement	140.00	Re	140.00
1.00	Pc	Front bumper sponge	35.00	CM	35.00
4.00	Pcs	Front bumper clips	1.50	Re	6.00
1.00	Pc	Front bumper lower grille (centre)	120.00	CM	120.00
1.00	Pc	Front bumper tow hook cover LH	22.00	Re	22.00
1.00	Pc	Front bumper side trim LH	22.00	CM	22.00
1.00	Pc	Front radiator grille	170.00	CM	170.00
1.00	Pc	Front radiator grille logo emblem	30.00	Re	30.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079900

Page 3 of 7
Your ref DHOM110137351405
Job No 70846
Our ref 19.09.08
Payment
Date 10/9/2019

Attn

Vehicle No EN 222T
Vehicle Model Toyota Estima
Accident on 5/9/2019

Quantity	Unit	Description	Unit price	Disc. pct	Amount
1.00	Pc	Signal lamp socket + bulb LH	20.00		Bu 20.00 ✓
1.00	Pc	Headlamp LH	600.00		Brv 600.00 ✓
1.00	Pc	Headlamp RH	600.00		my Br 600.00 ✓
1.00	Pc	HID bulb LH	150.00		Br 150.00 ✓
1.00	Pc	HID control unit LH	260.00		DD 260.00 ✓
1.00	Pc	Front fender LH	170.00		Bu 170.00 ✓
1.00	Pc	Front support panel	400.00		Br 400.00 ✓
1.00	Pc	Front brace panel	45.00		Br 45.00 ✓
1.00	Pc	Air con air guide upp LH	20.00		CM 20.00 ✓
1.00	Pc	Air con air guide upp RH	20.00		CM 20.00 ✓
1.00	Pc	Radiator top bracket LH	32.00		Di 32.00 ✓
1.00	Pc	Radiator top bracket RH	32.00		Di 32.00 ✓
1.00	Pc	Radiator top frame	40.00		CM 40.00 ✓
1.00	Pc	Radiator	500.00		Pu 500.00 ✓
1.00	Pc	Air con condenser	350.00		Br/Pu 350.00 ✓
1.00	Pc	Battery bracket	20.00		Br 20.00 ✓
1.00	Pc	Battery insulation cover	40.00		CM 40.00 ✓
1.00	Pc	Air cleaner box	320.00		CM 320.00 ✓
1.00	Pc	Fan shroud	105.00		CM 105.00 ✓
1.00	Pc	Air con fan motor	170.00		JM 170.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械。可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Page 4 of 7
Your ref DH0M110137351405
Job No 70846
Our ref 19 09 08
Payment
Date 10/9/2019

Attn

Vehicle No EN 222T
Vehicle Model Toyota Estima
Accident on 5/9/2019

Quantity	Unit	Description	Unit price	Disc. pct	Amount	
1.00	Pc	Radiator fan motor	170.00		7M 170.00	✓
1.00	Pc	Air con fan blade	85.00		OKA 85.00	✓
1.00	Pc	Radiator fan blade	75.00		CM 75.00	✓
1.00		Coolant (Original - 4 litres)	22.00		me 22.00	✓
1.00	Pc	Exhaust manifold cover	85.00		nd 85.00	✓
1.00	Pc	Engine mounting LH	85.00		svc 85.00	7X
1.00	Pc	Engine mounting RH	110.00		svc 110.00	7X
1.00	Pc	Radiator bottom hose	22.00		plc 22.00	7✓
1.00	Pc	Radiator upp hose	22.00		cut 22.00	7✓
1.00	Pc	Wiper garnish	220.00		CM 220.00	✓
4.00	Pcs	Wiper garnish clips	2.50		me 10.00	✓
1.00	Pc	Wiper panel	95.00		135 95.00	7✓
1.00	Pc	Brake reservoir tank	75.00		nd 75.00	✓
1.00	Pc	Brake reservoir tank bracket	40.00		R 40.00	✓
1.00	Pc	Wiper panel heat insulation	85.00		80 CM 85.00	✓
1.00	Pc	Front windscreen c/w moulding	600.00		CM 600.00	✓

Total amount of parts supplied -
S\$10,554.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267

GST No: M2-0128609-3

UEN: 199407592C

ESTIMATE

EST. No: EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Page: 5 of 7
Your ref.: DHOM110137351405
Job No.: 70846
Our ref.: 19-09-08
Payment:
Date: 10/9/2019

Attn:

Vehicle No: EN 222T
Vehicle Model: Toyota Estima
Accident on: 5/9/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		20% of parts supplied.	2,110.80		2,110.80
		Special nett item			
1.00	Set	Rear reversing sensor with installation	200.00		200.00 ✓
1.00	Pc	Front number plate	35.00		35.00 ✓
1.00		Brake fluid	15.00		15.00 ✓
1.00	Pc	IU bracket	15.00		15.00 ✓
		Labour & Misc:			
		Towing fee			
1.00		To dismantle + refix rear windscreen	120.00		120.00 ✓
1.00		To dismantle + renew front windscreen	140.00		140.00 120.00
1.00		To supply windscreen sealant (x2)	80.00		80.00 ✓
1.00		To supply front UV film + installation	350.00		350.00 280.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 109407592C

ESTIMATE

EST. No EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Page 5 of 7
Your ref DHOM110137351405
Job No 70846
Our ref 19.09.08
Payment
Date 10/9/2019

Attn

Vehicle No EN 222T
Vehicle Model Toyota Estima
Accident on 5/9/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To dismantle + renew rear fender, end panel trim garnish (x3), to remove + refix 3rd seat, etc	180.00		180.00 1500
1.00		To apply underbody undercoating (tuff coat)	250.00		250.00 2100
1.00		To dismantle + renew air con condenser + refill gas	100.00		100.00 ✓
1.00		To check wiring + repair	40.00		40.00 ✓
1.00		To dismantle + renew engine mountings (x2)	80.00		80.00 ?/N
1.00		To check/erase fault codes using diagnostic	60.00		60.00 ✓
1.00		To remove + refix reverse camera + cable	60.00		60.00 ✓
1.00		To straighten rear body including cutting & welding, to knock dents on rear tail lamp	1,600.00		1,600.00 1500

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No: EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079900

Page: 7 of 7
Your ref: DH0M110137351405
Job No: 70846
Our ref: 19.09.08
Payment:
Date: 10/9/2019

Attn:

Vehicle No: EN 222T
Vehicle Model: Toyota Estima
Accident on: 5/9/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		panels LH & RH, rear fender LH & RH and renew of parts			
1.00		To spray paint (rear portion only)	1,600.00		1,600.00 <i>1500</i>
1.00		To supply sound insulation + cut + paste (luggage panel)	100.00		100.00 ✓
1.00		To straighten front body including cutting & welding, to knock dents on front fender RH and renew of parts	800.00		800.00 <i>700</i>
1.00		To spray paint (front portion only)	900.00		900.00 <i>800</i>

20400.80

Sub-Total: 19,389.80
GST 7.00%: 1,357.29
Total: S\$ 20,747.09

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。此外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明 記) 摩 哆 有 限 公 司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

SUPPLEMENTARY

EST. No: EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Page: 1 of 1
Your ref.: DH0M110137351405
Job No.: 70846
Our ref.: 19.09.08
Payment:
Date: 30/9/2019

Attn

Vehicle No ...: EN 222T
Vehicle Model: Toyota Estima
Accident on ...: 5/9/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
SUPPLEMENTARY ITEM:					
Supply of Parts:					
1.00	Pc	Wiper motor	250.00		250.00 ✓ <i>LM</i>
1.00	Pc	Rear luggage panel reinforce	95.00		95.00 ✓ <i>LM</i>
1.00	Pc	Rear luggage panel floor member	110.00		110.00 ✓ <i>LM</i>
5.00	Pcs	Rear end panel clip grommets	1.50		7.50 ✓ <i>LM</i>
1.00	Pc	Rear hook cover RH	30.00		30.00 ✓ <i>LM</i>
Total amount of parts supplied - S\$492.50					
1.00		20% of parts supplied:	98.50		98.50
Labour & Misc:					
1.00		To cut + weld, to renew above parts	300.00		300.00 ✓ <i>LM</i>
Sub-Total					891.00
GST 7.00%					62.37
Total					S\$ 953.37

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the suppo dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAIC Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Page 7 of 7
Your ref. DH0M110137351405
Job No 70846
Our ref. 19 09 08
Payment
Date 10/9/2019

Attr:

Vehicle No EN 222T
Vehicle Model Toyota Estima
Accident on 5/9/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		panels LH & RH, rear fender LH & RH and renew of parts			1500
1.00		To spray paint (rear portion only)	1,600.00		1,600.00
1.00		To supply sound insulation + cut + paste (luggage panel)	100.00		100.00 ✓
1.00		To straighten front body including cutting & welding, to knock dents on front fender RH and renew of parts	800.00		800.00 ✓
1.00		To spray paint (front portion only)	900.00		900.00 ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total 19,389.80
GST 7.00% 1,357.29
Total S\$ 20,747.09

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大修修理
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the suppo
dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAIC
Deluxe oven heater for re-spraying all motor vehicles."

Shiau Chan (LKKAUTO)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Thursday, 13 February 2020 4:37 PM
To: Kenneth Kong (LKKAUTO)
Cc: SUR
Subject: Finalisation - EN 222T / Toyota Estima
Attachments: EN 222T-Estimate.pdf; EN 222T-Supplier Bill.pdf

Dear Sir

For your confirmation, please:

- Parts: \$10,566.50 (include supplementary)
- 20%: \$2,113.30
- SN: \$265.00
- L&M: \$6,120.00 (include supplementary)
- Sub-total: \$19,064.80
- Less XC: -
- Total: \$19,064.80

Supporting documents are enclosed for your reference.

We look forward to hearing from you soon.

Thank you.

Kind regards
Jenny Lim
Lai Huat (Meng Kee) Motor Pte Ltd
Sin Ming Autocity
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Singapore 575722
Tel: 64538110 Fax: 64596267

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Page 1 of 7
Your ref. DH0M110137351405
Job No. 70846
Our ref. 19.09.08
Payment
Date 10/9/2019

Attn

Vehicle No EN 222T
Vehicle Model Toyota Estima
Accident on 5/9/2019



Not Authorized
Penny Bypam

Pen & Ink

24 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts					
1.00	Set	Rear windscreen mouldings	38.00	✓	38.00 ✓
1.00	Pc	Rear bumper	240.00	✓	240.00 ✓
1.00	Pc	Rear bumper tow hook cover LH	12.00	✓	12.00 ✓
1.00	Pc	Rear bumper tow hook cover RH	12.00	✓	12.00 ✓
1.00	Pc	Rear bumper reflector LH	18.00	✓	18.00 ✓
1.00	Pc	Rear bumper corner sponge LH	35.00	✓	35.00 ✓
1.00	Pc	Rear bumper corner sponge RH	35.00	✓	35.00 ✓
1.00	Pc	Rear tailgate	650.00	✓	650.00 ✓
1.00	Pc	Rear tailgate Estima emblem	30.00	✓	30.00 ✓
1.00	Pc	Rear tailgate Aeras emblem	20.00	✓	20.00 ✓
1.00	Pc	Rear Toyota logo emblem	20.00	✓	20.00 ✓
1.00	Pc	Rear tailgate lock mechanism	130.00	✓	130.00 ✓
1.00	Pc	Rear end panel assy	230.00	✓	230.00 ✓
1.00	Pc	Rear end panel trim garnish (upp)	90.00	✓	90.00 ✓
1.00	Pc	Rear end panel trim garnish (lower)	100.00	✓	100.00 ✓
4.00	Pcs	Rear end panel trim garnish clips	3.50		14.00 ✓
1.00	Pc	Rear luggage trim (fabric)	580.00		580.00 X
1.00	Pc	Rear fender inner trim garnish LH	580.00	✓	580.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多辆汽车进行维修及保养。此外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Page 2 of 7
Your ref DHOM110137351405
Job No 70846
Our ref 19 00 08
Payment
Date 10/9/2019

Attn

Vehicle No EN 222T
Vehicle Model Toyota Estima
Accident on 5/9/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Rear fender inner trim garnish RH	580.00 ✓	Deform	580.00 ✓
1.00	Pc	Rear tailgate weatherstrip	110.00 ✓	Deform	110.00 ✓
1.00	Pc	Rear luggage panel	290.00 ✓	B ₁	290.00 ✓
1.00	Pc	Bonnet	190.00 ✓	B ₂	190.00 ✓
1.00	Pc	Bonnet hinge LH	25.00 ✓	B ₃	25.00 ✓
1.00	Pc	Bonnet hinge RH	25.00 ✓	B ₃	25.00 ✓
1.00	Pc	Bonnet lock	35.00 ✓	B ₃	35.00 ✓
1.00	Pc	Bonnet rubber seal	25.00 ✓	C ₁	25.00 ✓
1.00	Pc	Bonnet insulation	100.00 ✓	Deform	100.00 ✓
1.00	Pc	Radiator top cover	80.00 ✓	C ₁	80.00 ✓
5.00	Pcs	Radiator top cover clips	2.00 ✓	A ₂	10.00 ✓
1.00	Pc	Front bumper	210.00 ✓	C ₁	210.00 ✓
1.00	Pc	Front bumper reinforcement	140.00 ✓	B ₃	140.00 ✓
1.00	Pc	Front bumper sponge	35.00 ✓	C ₁	35.00 ✓
4.00	Pcs	Front bumper clips	1.50 ✓	A ₂	6.00 ✓
1.00	Pc	Front bumper lower grille (centre)	120.00 ✓ + 60% ✓	C ₁	180.00 ✓
1.00	Pc	Front bumper tow hook cover LH	22.00 ✓	A ₁	22.00 ✓
1.00	Pc	Front bumper side trim LH	22.00 ✓	C ₁	22.00 ✓
1.00	Pc	Front radiator grille	170.00 ✓	C ₁	170.00 ✓
1.00	Pc	Front radiator grille logo emblem	30.00 ✓	A ₁	30.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079000

Page 3 of 7
Your ref DH0M110137351405
Job No 70846
Our ref 19 09 08
Payment
Date 10/9/2019

Attn:

Vehicle No EN 222T
Vehicle Model Toyota Estima
Accident on 5/9/2019

Quantity	Unit	Description	Unit price	Disc pct	Amount
1.00	Pc	Signal lamp socket + bulb LH	20.00 ✓		<i>Bu</i> 20.00 ✓
1.00	Pc	Headlamp LH	600.00 ✓		<i>Bu</i> 600.00 ✓
1.00	Pc	Headlamp RH	600.00 ✓		<i>Ref Bu</i> 600.00 ✓
1.00	Pc	HID bulb LH	150.00 ✓		<i>Bu</i> 150.00 ✓
1.00	Pc	HID control unit LH	260.00 ✓		<i>Ref</i> 260.00 ✓
1.00	Pc	Front fender LH	170.00 ✓		<i>Bu</i> 170.00 ✓
1.00	Pc	Front support panel <i>(105 + 105 + 105 + 85)</i>	400.00 ✓		<i>Bu</i> 400.00 ✓
1.00	Pc	Front brace panel	45.00 ✓		<i>Bu</i> 45.00 ✓
1.00	Pc	Air con air guide upp LH	20.00 ✓		<i>CM</i> 20.00 ✓
1.00	Pc	Air con air guide upp RH	20.00 ✓		<i>CM</i> 20.00 ✓
1.00	Pc	Radiator top bracket LH	32.00 ✓		<i>D11</i> 32.00 ✓
1.00	Pc	Radiator top bracket RH	32.00 ✓		<i>D11</i> 32.00 ✓
1.00	Pc	Radiator top frame	40.00 ✓		<i>CM</i> 40.00 ✓
1.00	Pc	Radiator	500.00 ✓		<i>Pu</i> 500.00 ✓
1.00	Pc	Air con condenser	350.00 ✓		<i>B1/Pu</i> 350.00 ✓
1.00	Pc	Battery bracket	20.00 ✓		<i>Bu</i> 20.00 ✓
1.00	Pc	Battery insulation cover	40.00 ✓		<i>CM</i> 40.00 ✓
1.00	Pc	Air cleaner box	320.00 ✓		<i>CM</i> 320.00 ✓
1.00	Pc	Fan shroud	105.00 ✓		<i>CM</i> 105.00 ✓
1.00	Pc	Air con fan motor <i>photo</i>	170.00 ✓		<i>Tr</i> 170.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Page 4 of 7
Your ref DH0M110137351405
Job No 70846
Our ref 19 00 08
Payment
Date 10/9/2019

Attn:

Vehicle No EN 222T
Vehicle Model Toyota Estima
Accident on 9/9/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Radiator fan motor	170.00 ✓		170.00 ✓
1.00	Pc	Air con fan blade	85.00 ✓		85.00 ✓
1.00	Pc	Radiator fan blade	75.00 ✓		75.00 ✓
1.00		Coolant (Original - 4 litres)	22.00 ✓		22.00 ✓
1.00	Pc	Exhaust manifold cover	85.00 ✓		85.00 ✓
1.00	Pc	Engine mounting LH	85.00		85.00
1.00	Pc	Engine mounting RH	110.00		110.00
1.00	Pc	Radiator bottom hose	22.00 ✓		22.00 ✓
1.00	Pc	Radiator upp hose	22.00 ✓		22.00 ✓
1.00	Pc	Wiper garnish	220.00 ✓		220.00 ✓
4.00	Pcs	Wiper garnish clips	2.50		10.00 ✓
1.00	Pc	Wiper panel	95.00 135 ✓		95.00 135 ✓
1.00	Pc	Brake reservoir tank	75.00 ✓		75.00 ✓
1.00	Pc	Brake reservoir tank bracket	40.00 ✓		40.00 ✓
1.00	Pc	Wiper panel heat insulation	85.00 80 ✓		85.00 80 ✓
1.00	Pc	Front windscreen c/w moulding	600.00 ✓		600.00 ✓

Total amount of parts supplied
S\$10,584.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理除外。还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No. EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Page 5 of 7
Your ref. DH0M110137351405
Job No. 70846
Our ref. 19 09 08
Payment
Date 10/9/2019

Attn:

Vehicle No. EN 222T
Vehicle Model Toyota Estima
Accident on 5/9/2019

Quantity	Unit	Description	Unit price	Disc. pct	Amount
1.00		20% of parts supplied.	2,110.80		2,110.80
		Special nett item:			
1.00	Set	Rear reversing sensor with installation	200.00		200.00 ✓
1.00	Pc	Front number plate	35.00		35.00 ✓
1.00		Brake fluid	15.00		15.00 ✓
1.00	Pc	IU bracket	15.00		15.00 ✓
		Labour & Misc:			
		Towing fee			
1.00		To dismantle + refix rear windscreen	120.00		120.00 ✓
1.00		To dismantle + renew front windscreen	140.00		140.00 ✓
1.00		To supply windscreen sealant (x2)	50.00		50.00 ✓
1.00		To supply front UV film + installation	350.00		350.00 ✓

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No: EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Page 5 of 7
Your ref: DH0M110137351405
Job No: 70846
Our ref: 19.09.08
Payment Date: 10/9/2019

Attn: Mr. Lim

Vehicle No: EN 222T
Vehicle Model: Toyota Estima
Accident on: 5/9/2019

Quantity	Unit	Description	Unit price	Disc. pct	Amount
1.00		To dismantle + renew rear fender, end panel trim garnish (x3), to remove + refix 3rd seat etc	180.00		180.00 15
1.00		To apply underbody undercoating (tuff coat)	250.00		250.00 21
1.00		To dismantle + renew air con condenser + refill gas	100.00		100.00 ✓
1.00		To check wiring + repair	40.00		40.00 ✓
1.00		To dismantle + renew engine mountings (x2)	60.00		60.00 ✗
1.00		To check/erase fault codes using diagnostic	60.00		60.00 ✓
1.00		To remove + refix reverse camera + cable	60.00		60.00 ✓
1.00		To straighten rear body including cutting & welding to knock dents on rear tail lamp	1,600.00		1,600.00 1500

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理除外。还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the suppo dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAIC Deluxe oven heater for re-spraying all motor vehicles."

來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0023222
United Overseas Insurance Ltd
3 Anson Road
#28-01 Springleaf Tower
Singapore 079200

Page 7 of 7
Your ref. DH0M110137351405
Job No 70846
Our ref 19 09 08
Payment
Date 10/9/2019

Attn:

Vehicle No EN 222T
Vehicle Model Toyota Estima
Accident on 5/9/2019

Quantity	Unit	Description	Unit price	Disc. pct	Amount
		panels LH & RH, rear fender LH & RH and renew of parts			
1.00		To spray paint (rear portion only)	1,600.00		1,600.00 <i>1500</i>
1.00		To supply sound insulation + cut + paste (luggage panel)	100.00		100.00 ✓
1.00		To straighten front body including cutting & welding, to knock dents on front fender RH and renew of parts	800.00		800.00 <i>700</i>
1.00		To spray paint (front portion only)	900.00		900.00 <i>800</i>

Sub-Total 19,389.80
GST 7.00% 1,357.29
Total S\$ 20,747.09

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949632
Fax: 62992158, 62942354, 62935021
Email: ftrpnet@imbox3.singnet.com.sg
RCB Reg No.: 198301435R

NISSAN **TOYOTA** **OPEL**
Genuine Parts GENUINE PARTS GENUINE PA

mazda
Genuine Parts

GENUINE PARTS

Ford

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426888 62949632 67479292
67426878 62985333 67455824

MITSUBISHI/PROTON

TEL: 62954551
67496954

HONDA/HYUNDAI DIV

TEL: 62970688 64542288
67493588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67495997



TAX INVOICE

TAX INVOICE NO.: CL404149

INVOICE DATE : 12/09/2015

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 1

INVOICE TO: LAI HUAT (MENG KEE) MOTOR PTE LTD
160 SIN MING DRIVE
#04-01/#04-02 SIN MING AUTO CITY
SINGAPORE 575722

GST Reg. No.: M2-0059747-8

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE
				(SIN)
T53301-28110	HOOD		1	190.000✓
T53420-28130	HOOD HINGE		1 PCS	25.000✓
T53410-28060	HOOD HINGE		1	25.000✓
T53510-28090	HOOD LOCK		1	35.000✓
T53381-28090	SEAL HOOD		1	25.000✓
T53341-28050	HOOD INSULATOR		1 PCS	100.000✓
T53292-28070	SEAL RADIATOR		1	80.000✓
T55346-47010	CLIP INSTRUMENT		5	2.000✓ 5/0
T52119-2J940	F/BUMPER		1	210.000✓
T52029-28060	F/B REINFORCEMENT		1 PCS	140.000✓
T52611-28080	F/B ABSORBER		1	35.000✓

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

AUTHORISED SIGNATURE

SIGNATURE



豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949632
Fax: 62992158, 62942354, 62935021
Email: ftrpnet@imbox3.singnet.com.sg
RCB Reg No.: 198301435R

AUTHORISED STOCKISTS:

NISSAN
Genuine Parts

TOYOTA
GENUINE PARTS

OPEL
GENUINE PA

mazda
Genuine Parts

GENUINE PARTS

Ford

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426888 62949632 67479292
67426878 62985333 67455824

MITSUBISHI/PROTON

TEL: 62954551
67496954

HONDA/HYUNDAI DIV

TEL: 62970688 64542288
67493588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67495997



TAX INVOICE

TAX INVOICE NO.: CL404149

INVOICE DATE : 12/09/2015

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 2

INVOICE TO: LAI HUAT (MENG KEE) MOTOR PTE LTD
160 SIN MING DRIVE
#04-01/#04-02 SIN MING AUTO CITY
SINGAPORE 575722

GST Reg. No.: M2-0059747-8

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE
				(SIN)
T52161-16010	BUMPER CLIP		4	1.500✓ 36
T53112-28210	F/B CENTER GRILLE		1	120.000✓
T52128-28902	F/B TOWING COVER		1	22.000✓
T52128-28440	F/B COVER HOLE		1	22.000✓
T52711-28150	MLDG F/BUMPER		1	60.000✓
T53101-28381-A0	GRILLE		1	170.000✓
T81178-28C10	CORD, HEADLAMP, NO. 2		1	20.000✓
T81185-28F40	HEADLAMP UNIT		1 PCS	600.000✓
T81145-28F40	HEADLAMP UNIT		1	600.000✓
T53812-28091	F/FENDER		1	170.000✓
T53202-28140	H/LAMP PANEL		1 PCS	105.000✓

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

TOTAL

豐達汽車私人有限公司 ONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490680, 67477481 Website: www.ongtat.com
Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftgprnet@mbx3.singnet.com.sg
Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
SIN MING DRIVE
01/#04-02 SIN MING AUTO CITY
APORE 575722

GST Reg. No.: M2-0059747-8


NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD DIV
TEL: 62935722
67420366

HONDA/HYUNDAI DIV
TEL: 62970688 64542288
67493588

MAZDA/FORD DIV
TEL: 62935722
67420366

AIRCON/W/S GLASS
TEL: 62952336
67495997



TAX INVOICE

TAX INVOICE NO.: CL404149
INVOICE DATE : 12/09/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 5



DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
20-28140 WIPER PANEL		1	135.000	135.00	✓
20-58020 B/RESERVOIR		1 PCS	75.000	75.00	✓
39-80082 COOLANT 3.785L		1 PCS	22.000	22.00	✓
2T (ACR50) JASON					
GST Excl Amount :				5726.00	
Special Discount :					
GST @ 7 % :				400.82	

OTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

6126.82

PRINT BY :
YKN 12/09/2019 14:28:29

SIGNATURE

NATURE

豐達汽車私人有限公司 ONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490680, 67477481 Website: www.ongtat.com
Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftgprnet@mbx3.singnet.com.sg
Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
SIN MING DRIVE
-01/#04-02 SIN MING AUTO CITY
APORE 575722

GST Reg. No.: M2-0059747-8


NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD DIV
TEL: 62935722
67420366

HONDA/HYUNDAI DIV
TEL: 62970688 64542288
67493588

MAZDA/FORD DIV
TEL: 62935722
67420366

AIRCON/W/S GLASS
TEL: 62952336
67495997



TAX INVOICE

TAX INVOICE NO.: CL405100
INVOICE DATE : 13/09/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 1



DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
005-28C80 R/BOOT		1	650.000	650.00	✓
23949 EN222T JASON					
GST Excl Amount :				650.00	
Special Discount :					
GST @ 7 % :				45.50	

OTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

695.50

REPRINT BY :
LHK 02/12/2019 09:02:33

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62948632
Fax: 62992158, 62942354, 62935021
Email: ftrpnet@mbx3.singnet.com.sg
CB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
SIN MING DRIVE
-01/#04-02 SIN MING AUTO CITY
GAPORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MITSUBISHI/PROTON

TEL: 62954551
67486954

HONDA/HYUNDAI DIV

TEL: 62970688 64542288
67483588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67486997

AUTHORISED STOCKISTS:



TAX INVOICE

TAX INVOICE NO.: CL404196

INVOICE DATE : 13/09/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 1



	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
				(SIN)	(SIN)
311-28240	EMBLEM,RADIATOR		1 ✓	30.000	30.00 ✓
981-20028	HID BULD		1 ✓	150.000	150.00 ✓
107-30031	COMPUTER HEDALAMP		1 PCS ✓	260.000	260.00 ✓
209-28060	BRACE PANEL		1 PCS ✓	45.000	45.00 ✓
533-28040	SUPPORT RADIATOR		2 PCS ✓	32.000	64.00 ✓
410-28010	BATTERY CARRIER (1)		1 PCS ✓	190.000	190.00 ✓
431-02280	BATTERY TRAY		1 ✓	32.000	32.00 ✓

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

SIGNATURE

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62948632
Fax: 62992158, 62942354, 62935021
Email: ftrpnet@mbx3.singnet.com.sg
CB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
SIN MING DRIVE
-01/#04-02 SIN MING AUTO CITY
GAPORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MITSUBISHI/PROTON

TEL: 62954551
67486954

HONDA/HYUNDAI DIV

TEL: 62970688 64542288
67483588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67486997

AUTHORISED STOCKISTS:



TAX INVOICE

TAX INVOICE NO.: CL404196

INVOICE DATE : 13/09/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 2



	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
				(SIN)	(SIN)
22T (ACR50)	JASON				
				GST Excl Amount :	711.00
				Special Discount :	
				GST @ 7 % :	49.77

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

760.77

PRINT BY :

YKN 13/09/2019 12:39:20

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 Fax: 62992158, 62942354, 62935021
 Mail: ftrpnet@inbox3.singnet.com.sg
 CB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
 SIN MING DRIVE
 -01/#04-02 SIN MING AUTO CITY
 SINGAPORE 575722

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
573-28030		1	38.000	38.000	38.00 ✓
159-28920		1	240.000	240.000	240.00 ✓
162-28050-C0		2	12.000	24.000	24.00 ✓
920-13020		1	18.000	18.000	18.00 ✓
516-28020		1 PCS	35.000	35.000	35.00 ✓
515-28050		1	35.000	35.000	35.00 ✓
441-28710		1 PCS	30.000	30.000	30.00 ✓
442-28540		1	20.000	20.000	20.00 ✓
975-02072		1	20.000	20.000	20.00 ✓
350-28160		1	130.000	130.000	130.00 ✓
307-28110		1 PCS	230.000	230.000	230.00 ✓

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

SIGNATURE

4:30

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 Fax: 62992158, 62942354, 62935021
 Mail: ftrpnet@inbox3.singnet.com.sg
 CB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
 SIN MING DRIVE
 -01/#04-02 SIN MING AUTO CITY
 SINGAPORE 575722

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
935-28090-C0		1	90.000	90.000	90.00 ✓
939-28040-C0		1 PCS	100.000	100.000	100.00 ✓
771-28130-C0		4 PCS	3.500	14.000	14.00 ✓
381-28120		1	110.000	110.000	110.00 ✓
311-2J870		1	290.000	290.000	290.00 ✓

22T (ACR50) JASON

GST Excl Amount : 1424.00
 Special Discount :
 GST @ 7 % : 99.68

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

1523.68

PRINT BY :
 YKN 13/09/2019 15:14:10

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL OEM PARTS
 TEL: 67426888 62949832 67479292
 67426878 62985333 67455824

MITSUBISHI/PROTON
 TEL: 62954551
 67490954

HONDA/HYUNDAI DIV
 TEL: 62970688 64542288
 67493588

MAZDA/FORD DIV
 TEL: 62935722
 67420368

AIRCON/W/S GLASS
 TEL: 62952336
 67495997

TAX INVOICE

TAX INVOICE NO.: CL404220

INVOICE DATE : 13/09/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 1

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL OEM PARTS
 TEL: 67426888 62949832 67479292
 67426878 62985333 67455824

MITSUBISHI/PROTON
 TEL: 62954551
 67490954

HONDA/HYUNDAI DIV
 TEL: 62970688 64542288
 67493588

MAZDA/FORD DIV
 TEL: 62935722
 67420368

AIRCON/W/S GLASS
 TEL: 62952336
 67495997

TAX INVOICE

TAX INVOICE NO.: CL404220

INVOICE DATE : 13/09/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 2

豐達汽車私人有限公司 FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490880, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 216115 Tel: 62965333, 62948832
Fax: 62992168, 62942354, 62905021
Email: ftgprnet@mbbox3.singnet.com.sg
ICB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
SIN MING DRIVE
-01/#04-02 SIN MING AUTO CITY
GAPORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD DIV

TEL: 62954551
67496954

HYUNDAI/HYUNDAI DIV

TEL: 62970688 64542288
67493588

MAZDA/FORD DIV

TEL: 62935722
67420366

AIRCON/W/S GLASS

TEL: 62952336
67496997

AUTHORISED STOCKISTS:



TAX INVOICE

TAX INVOICE NO.: CL404388

INVOICE DATE : 17/09/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 1

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
656-28060	MEMBER,RR FLOOR CROSS,N05		1 PCS	(SIN) 110.000	(SIN) 110.00✓
205-28020	REINFORCEMENT SUB-ASSY,RR		1 PCS	95.000	95.00✓
22 (ACR50)	JASON				
				GST Excl Amount :	205.00
				Special Discount :	
				GST @ 7 % :	14.35

MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

PRINT BY :

YKN 17/09/2019 16:45:28

TOTAL

219.35

SIGNATURE

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 Fax: 62992158, 62942354, 62935021
 Email: ftrpnet@mbox3.singnet.com.sg
 ICB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
 SIN MING DRIVE
 -01/#04-02 SIN MING AUTO CITY
 GAPORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS
 TEL: 67426889 62949832 67479292
 67426878 62985333 67455824

MITSUBISHI/PROTON
 TEL: 62954551
 67498954

HONDA/HYUNDAI DIV
 TEL: 62970688 64542288
 67493588

MAZDA/FORD DIV
 TEL: 62935722
 67420368

AIRCON/W/S GLASS
 TEL: 62952336
 67495997



TAX INVOICE

TAX INVOICE NO.: CL404319
 INVOICE DATE : 17/09/2019
 CREDIT TERMS : 30 DAYS
 SALES ORDER NO.:
 SALESMAN : YKN
 PAGE(S) : 1



DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
581-28051 CLAMP, HOSE		1 PCS	10.000	10.00	
22 (ACR50) JASON					
GST Excl Amount :				10.00	
Special Discount :					
GST @ 7 % :					0.70

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

PRINT BY :
 YKN 17/09/2019 08:14:52

TOTAL

10.70

SIGNATURE

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 Fax: 62992158, 62942354, 62935021
 Email: ftrpnet@mbox3.singnet.com.sg
 ICB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
 SIN MING DRIVE
 -01/#04-02 SIN MING AUTO CITY
 GAPORE 575722

GST Reg. No.: M2-0059747-8


NISSAN TOYOTA OPEL OEM PARTS
 TEL: 67426889 62949832 67479292
 67426878 62985333 67455824

MITSUBISHI/PROTON
 TEL: 62954551
 67498954

HONDA/HYUNDAI DIV
 TEL: 62970688 64542288
 67493588

MAZDA/FORD DIV
 TEL: 62935722
 67420368

AIRCON/W/S GLASS
 TEL: 62952336
 67495997



TAX INVOICE

TAX INVOICE NO.: CL404322
 INVOICE DATE : 17/09/2019
 CREDIT TERMS : 30 DAYS
 SALES ORDER NO.:
 SALESMAN : YKN
 PAGE(S) : 1



DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
101-28550 FR W/S GLASS		1 PCS	600.000	600.00	
22 (ACR50) JASON					
GST Excl Amount :				600.00	
Special Discount :					
GST @ 7 % :					42.00

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

PRINT BY :

TOTAL

642.00

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftgprnet@mbbox3.singnet.com.sg
ICB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
SIN MING DRIVE
-01/#04-02 SIN MING AUTO CITY
GAPORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426888 62949832 67479292
67426878 62985333 67455824

MITSUBISHI/PROTON

TEL: 62954551

67498954

HONDA/HYUNDAI DIV

TEL: 62970688 64542288

67493588

MAZDA/FORD DIV

TEL: 62935722


67420368

AIRCON/W/S GLASS

TEL: 62952336

67498997

AUTHORISED STOCKISTS:



TAX INVOICE

TAX INVOICE NO.: CL405185

INVOICE DATE : 04/10/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 1

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
899-28070	INSULATOR BATTERY		1 PCS	40.000	40.00	✓
234-28190	BRACKET RESERVOIR		1 PCS	40.000	40.00	✓
742-28080	WIPER PANEL INSULATOR		1 PCS	80.000	80.00	✓
715-28040-00	COVER, LUGGAGE		1 PCS	55.000	55.00	✓
730-28761-00	R/FENDER GARNISH R		1 PCS	580.000	580.00	✓
740-28791-00	R/FENDER GARNISH L		1 PCS	580.000	580.00	✓
848-28040-00	COVER BACK DOOR GRANISH		1 PCS	20.000	20.00	✓

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

SIGNATURE

10:00

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftgprnet@mbbox3.singnet.com.sg
ICB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
SIN MING DRIVE
-01/#04-02 SIN MING AUTO CITY
GAPORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426888 62949832 67479292
67426878 62985333 67455824

MITSUBISHI/PROTON

TEL: 62954551

67498954

HONDA/HYUNDAI DIV

TEL: 62970688 64542288

67493588

MAZDA/FORD DIV

TEL: 62935722


67420368

AIRCON/W/S GLASS

TEL: 62952336

67498997

AUTHORISED STOCKISTS:



TAX INVOICE

TAX INVOICE NO.: CL405185

INVOICE DATE : 04/10/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 2

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
22T (ACR50)	JASON					
				GST Excl Amount :		1395.00
				Special Discount :		
				GST @ 7 % :		97.65

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

1492.65

PRINT BY :

YKN 04/10/2019 09:15:26

豐達汽車私人有限公司 FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62936021
Email: ftrpnet@mbca3.singnet.com.sg
CB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
SIN MING DRIVE
#01/#04-02 SIN MING AUTO CITY
GAPORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL OEM PARTS

TEL: 67426888 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD DIV

TEL: 62954551
67496954


HONDA/HYUNDAI DIV

TEL: 62970688 64542288
67493588

AIRCON/W/S GLASS

TEL: 62982336
67495997

AUTHORISED STOCKISTS:



TAX INVOICE

TAX INVOICE NO.: CL405186

INVOICE DATE : 04/10/2019

CREDIT TERMS : 30 DAYS

SALES ORDER NO.:

SALESMAN : YKN

PAGE(S) : 1



	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
310-30011-C0	R/HOOK COVER		1 PCS	(SIN) 30.000	(SIN) 30.00 ✓
22T (ACR50) JASON					
				GST Excl Amount :	30.00
				Special Discount :	
				GST @ 7 % :	2.10

MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

PRINT BY :
YKN 04/10/2019 09:17:56

TOTAL

32.10

SIGNATURE

10:10

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62965333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftrpnet@mbx3.singnet.com.sg
ICB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
SIN MING DRIVE
01/#04-02 SIN MING AUTO CITY
IGAPORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL GEM PARTS

TEL: 67426888 62949832 67479292
67426878 62965333 67455824

MITSUBISHI/PROTON

TEL: 62954551
67496854

HONDA/HYUNDAI DIV

TEL: 62970688 64542288
67490588


MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67495997

AUTHORISED STOCKISTS:



TAX INVOICE

TAX INVOICE NO.: CL405502
INVOICE DATE : 11/10/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 1

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
130-28080 MOTOR ASSY REAR WIPER		1 PCS	(SIN) 250.000	(SIN) 250.00 ✓
22T (ACR50) JASON				
GST Excl Amount :				250.00
Special Discount :				
GST @ 7 % :				17.50

MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

PRINT BY :
YKN 11/10/2019 09:27:22

TOTAL

267.50

SIGNATURE

SIGNATURE

豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62965333, 62949832
Fax: 62992158, 62942354, 62935021
Email: ftrpnet@mbx3.singnet.com.sg
ICB Reg No.: 198301435R

LAI HUAT (MENG KEE) MOTOR PTE LTD
SIN MING DRIVE
01/#04-02 SIN MING AUTO CITY
APORE 575722

GST Reg. No.: M2-0059747-8

NISSAN TOYOTA OPEL GEM PARTS

TEL: 67426888 62949832 67479292
67426878 62965333 67455824

MITSUBISHI/PROTON

TEL: 62954551
67496854

HONDA/HYUNDAI DIV

TEL: 62970688 64542288
67490588

MAZDA/FORD DIV

TEL: 62935722
67420368

AIRCON/W/S GLASS

TEL: 62952336
67495997

AUTHORISED STOCKISTS:



TAX INVOICE

TAX INVOICE NO.: CL405481
INVOICE DATE : 10/10/2019
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 1

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	
72-20021 R/C/GRANISH CLIP (6) INNER		5	(SIN) 1.500	(SIN) 7.50 ✓
2T (ACR50) JASON				
GST Excl Amount :				7.50
Special Discount :				
GST @ 7 % :				0.53

MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

PRINT BY :
YKN 10/10/2019 14:57:22

TOTAL

8.03



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI19016102/Kqf3e2

3 ANSON ROAD #28-01
SPRINGLEAF TOWER SINGAPORE 079909

Date : 02-03-2020



Code : UOI2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	EN 222T
Policy No.	DHOM110137351405	Coverage (\$)	0.00
Claim No.	M11D08071909	Excess (\$)	0.00
Assign From	JENNY LEW	Assign Date	10/09/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ESTIMA (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	ACR500167501	Colour	METALLIC DARK MAROON
Odometer	47235	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R18	MICHELIN	7 mm
L/H Front Tyre	225/50 R18	MICHELIN	7 mm
R/H Rear Tyre	225/50 R18	MICHELIN	7 mm
L/H Rear Tyre	225/50 R18	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/09/2019	Inspection Date	11/09/2019
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE MARKET VALUE IS S\$82,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	24 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EN 222T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDINGS	NECESSARY	38.00	38.00
1	REAR BUMPER	BENT	240.00	240.00
1	REAR BUMPER TOW HOOK COVER LH	MISSING	12.00	12.00
1	REAR BUMPER TOW HOOK COVER RH	DENTED	12.00	12.00
1	REAR BUMPER REFLECTOR LH	BROKEN	18.00	18.00
1	REAR BUMPER CORNER SPONGE LH	CRACKED	35.00	35.00
1	REAR BUMPER CORNER SPONGE RH	CRACKED	35.00	35.00
1	REAR TAILGATE	BENT	650.00	650.00
1	REAR TAILGATE ESTIMA EMBLEM	NECESSARY	30.00	30.00
1	REAR TAILGATE AERAS EMBLEM	NECESSARY	20.00	20.00
1	REAR TOYOTA LOGO EMBLEM	NECESSARY	20.00	20.00
1	REAR TAILGATE LOCK MECHANISM	DENTED	130.00	130.00
1	REAR END PANEL ASSY	BENT	230.00	230.00
1	REAR END PANEL TRIM GARNISH (UPP)	CRACKED	90.00	90.00
1	REAR END PANEL TRIM GARNISH (LOWER)	BUCKLED	100.00	100.00
4	REAR END PANEL TRIM GARNISH CLIPS @\$3.50	NECESSARY	14.00	14.00
1	REAR LUGGAGE TRIM (FABRIC)	SERVICEABLE	380.00	-
1	REAR FENDER INNER TRIM GARNISH LH	BUCKLED	580.00	580.00
1	REAR FENDER INNER TRIM GARNISH RH	DEFORMED	580.00	580.00
1	REAR TAILGATE WEATHERSTRIP	DENTED / DISTORTED	110.00	110.00
1	REAR LUGGAGE PANEL	BENT	290.00	290.00
1	BONNET	BENT	190.00	190.00
1	BONNET HINGE LH	BENT	25.00	25.00
1	BONNET HINGE RH	BENT	25.00	25.00
1	BONNET LOCK	BENT	35.00	35.00
1	BONNET RUBBER SEAL	CUT	25.00	25.00
1	BONNET INSULATION	DEFORMED	100.00	100.00
1	RADIATOR TOP COVER	CRACKED	80.00	80.00
5	RADIATOR TOP COVER CLIPS @\$2.00	NECESSARY	10.00	10.00
1	FRONT BUMPER	CRACKED	210.00	210.00
1	FRONT BUMPER REINFORCEMENT	BENT	140.00	140.00
1	FRONT BUMPER SPONGE	CRACKED	35.00	35.00
4	FRONT BUMPER CLIPS @\$1.50	NECESSARY	6.00	6.00

Report Ref No. CS/UOI19016102/Kqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER LOWER GRILLE (CENTRE)	CRACKED	180.00	180.00
1	FRONT BUMPER TOW HOOK COVER LH	MISSING	22.00	22.00
1	FRONT BUMPER SIDE TRIM LH	CRACKED	22.00	22.00
1	FRONT RADIATOR GRILLE	CRACKED	170.00	170.00
1	FRONT RADIATOR GRILLE LOGO EMBLEM	NECESSARY	30.00	30.00
1	SIGNAL LAMP SOCKET + BULB LH	BROKEN	20.00	20.00
1	HEADLAMP LH	BROKEN	600.00	600.00
1	HEADLAMP RH	MTG BROKEN	600.00	600.00
1	HID BULB LH	BROKEN	150.00	150.00
1	HID CONTROL UNIT LH	DENTED	260.00	260.00
1	FRONT FENDER LH	BUCKLED	170.00	170.00
1	FRONT SUPPORT PANEL	BENT	400.00	400.00
1	FRONT BRACE PANEL	BENT	45.00	45.00
1	AIR CON AIR GUIDE UPP LH	CRACKED	20.00	20.00
1	AIR CON AIR GUIDE UPP RH	CRACKED	20.00	20.00
1	RADIATOR TOP BRACKET LH	DISTORTED	32.00	32.00
1	RADIATOR TOP BRACKET RH	DISTORTED	32.00	32.00
1	RADIATOR TOP FRAME	CRACKED	40.00	40.00
1	RADIATOR	PUNCTURE	500.00	500.00
1	AIR CON CONDENSER	BENT / PUNCTURE	350.00	350.00
1	BATTERY BRACKET	BENT	20.00	20.00
1	BATTERY INSULATION COVER	CRACKED	40.00	40.00
1	AIR CLEANER BOX	CRACKED	320.00	320.00
1	FAN SHROUD	CRACKED	105.00	105.00
1	AIR CON FAN MOTOR	JAMMED	170.00	170.00
1	RADIATOR FAN MOTOR	JAMMED	170.00	170.00
1	AIR CON FAN BLADE	CRACKED	85.00	85.00
1	RADIATOR FAN BLADE	CRACKED	75.00	75.00
1	COOLANT (ORIGINAL - 4 LITRES)	NECESSARY	22.00	22.00
1	EXHAUST MANIFOLD COVER	DENTED	85.00	85.00
1	ENGINE MOUNTING LH	SERVICEABLE	85.00	-
1	ENGINE MOUNTING RH	SERVICEABLE	110.00	-
1	RADIATOR BOTTOM HOSE	PUNCTURE	22.00	22.00
1	RADIATOR UPP HOSE	CUT	22.00	22.00
1	WIPER GARNISH	CRACKED	220.00	220.00
4	WIPER GARNISH CLIPS @\$2.50	NECESSARY	10.00	10.00

Report Ref No. CS/UOI19016102/Kqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WIPER PANEL	DENTED	135.00	135.00
1	BRAKE RESERVOIR TANK	DENTED	75.00	75.00
1	BRAKE RESERVOIR TANK BRACKET	BENT	40.00	40.00
1	WIPER PANEL HEAT INSULATION	CRACKED	85.00	80.00
1	FRONT WINDSCREEN C/W MOULDING	CRACKED	600.00	600.00
1	WIPER MOTOR (ADDITIONAL)	JAMMED	250.00	250.00
1	REAR LUGGAGE PANEL REINFORCE (ADDITIONAL)	BENT	95.00	95.00
1	REAR LUGGAGE PANEL FLOOR MEMBER (ADDITIONAL)	BENT	110.00	110.00
5	REAR END PANEL CLIP GROMMETS @\$1.50 (ADDITIONAL)	NECESSARY	7.50	7.50
1	REAR HOOK COVER RH (ADDITIONAL)	CRACKED	30.00	30.00
	COST PLUS 20%		2,229.30	2,113.30
			13,375.80	12,679.80
	SPECIAL NETT ITEMS			
1	SET REAR REVERSING SENSOR WITH INSTALLATION (SN)	CRACKED	200.00	200.00
1	FRONT NUMBER PLATE (SN)	MISSING	35.00	35.00
1	BRAKE FLUID (SN)	NECESSARY	15.00	15.00
1	IU BRACKET (SN)	NECESSARY	15.00	15.00
			265.00	265.00
	LABOUR			
	TOWING FEE. (NPA)		-	-
	TO DISMANTLE + REFIX REAR WINDSCREEN.		120.00	120.00
	TO DISMANTLE + RENEW FRONT WINDSCREEN.		140.00	120.00
	TO SUPPLY WINDSCREEN SEALANT (X2).		80.00	80.00
	TO SUPPLY FRONT UV FILM + INSTALLATION.		350.00	280.00
	TO DISMANTLE + RENEW REAR FENDER, END PANEL TRIM GARNISH (X3), TO REMOVE + REFIX 3RD SEAT, ETC.		180.00	150.00
	TO APPLY UNDERBODY UNDERCOATING (TUFF COAT).		250.00	210.00
	TO DISMANTLE + RENEW AIR CON CONDENSER + REFILL GAS.		100.00	100.00
	TO CHECK WIRING + REPAIR.		40.00	40.00
	TO DISMANTLE + RENEW ENGINE MOUNTINGS (X2).	NOT NECESSARY	80.00	-
	TO CHECK / ERASE FAULT CODES USING DIAGNOSTIC.		60.00	60.00
	TO REMOVE + REFIX REVERSE CAMERA + CABLE.		60.00	60.00

Report Ref No. CS/UOI19016102/Kqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO STRAIGHTEN REAR BODY INCLUDING CUTTING & WELDING, TO KNOCK DENTS ON REAR TAIL LAMP PANEL LH & RH, REAR FENDER LH & RH AND RENEW OF PARTS.		1,600.00	1,500.00
	TO SPRAY PAINT (REAR PORTION ONLY).		1,600.00	1,500.00
	TO SUPPLY SOUND INSULATION + CUT + PASTE (LUGGAGE PANEL).		100.00	100.00
	TO STRAIGHTEN FRONT BODY INCLUDING CUTTING & WELDING, TO KNOCK DENTS ON FRONT FENDER RH AND RENEW OF PARTS.		800.00	700.00
	TO SPRAY PAINT (FRONT PORTION ONLY).		900.00	800.00
	TO CUT + WELD, TO RENEW ABOVE PARTS. (ADDITIONAL)		300.00	300.00
			6,760.00	6,120.00
GRAND TOTAL			20,400.80	19,064.80
RECOMMENDED COST OF REPAIRS				19,064.80

Report Ref No. CS/UOI19016102/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.