

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 13 Sep 2019

Preliminary Advice

Insured Vehicle No	:	SLD3917Y			
TP Vehicle No	:	SJN3963J	Accident Date	:	08/09/2019
Make	:	AUDI A3	Assignment Date	:	10/09/2019
Date of Inspection	:	11/09/2019	Est. Duration of Repair	:	7 days
Inspection At	:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722			

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 19,198.68
Revised Amount	:	S\$ 9,009.68
Check Items (Estimated)	:	S\$ 8,353.60
Total	:	S\$ 17,363.28
Lump Sum Repair	:	S\$

Total Loss Consideration

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. Some parts items still pending parts prices.