

Minim

ASSIGNMENT

Front

Date

11/9/19

Estimated Cost

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKX1153D

at Workshop n/s: premium

of 55 ubi Road

Insured

Policy No

Claims No

Sum Insured

Excess

78A \$100/-

(Client's Record)

Make of Veh:

10am (waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Est. or Market Value: 80K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SKX1153D

Yr Regd

2015 NOV

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4

C.C

1798

Colour

White

A/C

Insured / Std / NI / NA

Sp Reading

60563

T/Radio

Insured / Std / NI / NA

Eng No:

C/No:

WAU2228K6FA181239

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R18

R:

245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

06

mm

R/Bal

06

mm

L/Bal

06

mm

L/Bal

06

mm

D.O.A.

D.O.I.

11/09/19

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

DD ALG.

SKX 1153D - (4 TP 19016117) Asf3n2

DOA - 03/04/2019

RECEIVED 18 DEC 2019

12/09/19 @ 13:38 pm noted PA to Alan, Sycardona via minim

12/09/19 @ 13:39 pm mandate requested authority upon to ALG via minim

12/09/19 @ 17:22 pm mandate approved by Victor Koh via minim

12/09/19 @ 18:11 pm inform CLA to Troy (Gepard) via email

05/11/19 Confirmed P/P \$ 7,661.68 @ 5 days with Adrian

(\$ 11,258.32 Red - 60%)

Use / Item, File Path (1)

☐

Prel. Report

Days Of Repair:

5

18/12/19

☐

Final Report

Resurvey No. of Trip:

1

1) Tip: 4

End/Time, File Path (1)

3

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Work end (\$

Survey Fee:

Transportation:

3 - P/L \$

1 Hour

1 Hour

1 Hour

TOTAL

200

11

211

Report Form:

Long Sum:

G

\$ 7,661.68 P/P

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 12 Sep 2019

Preliminary Advice

Vehicle No	: SKX1153D	Accident Date	: 06/09/2019
Make	: AUDI A4	Policy No.	: 2100439686
Assignment Date	: 11/09/2019	Excess	: S\$0.00
Date of Inspection	: 11/09/2019	Est. Duration of Repair	: 5 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,920.00
Revised Amount	:S\$	8,675.00
Check Items (Estimated)	:S\$	772.00
Total	:S\$	9,447.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	59,089.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,911.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Nivitha (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Saturday, 7 September 2019 11:38 AM
To: 'Admin-D (LKKAuto)'; 'Admin A'; 'SUR'
Cc: 'Claims'
Subject: OD CLAIM FOR SKX 1153 D ON 7/9/2019
Attachments: SAftersales19090711400_0001.jpg; SAftersales19090711400_0002.jpg; SAftersales19090711400_0003.jpg; SAftersales19090711400_0004.jpg; SKX 1153 D - 07092019.PDF

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report for your reference.

We will forward you the estimate once it is available.

Please arrange survey on 11/9/2019 10am. Owner waiting.

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This e-mail, including any attachments, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply e-mail and then delete this message from your system.
Please do not copy, re-use or use it for any purpose, or disclose its contents or any attachments to any other person. Thank you

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 5 November 2019 1:36 pm
To: jiajee.yap@premiumauto.com.sg; Adrian Ling (LKKAuto)
Cc: 'Boo seng yak'; 'Chang Chee Sing'; 'Carrine Leong'; SUR
Subject: RE: FINAL REVISION - SKX1153D - OD AIG - SURVEYED 11 SEP 19

Dear Jia Yee,

Confirmed final fig \$7,661.68 @ 5 days of repairs before excess \$ 800/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jiajee.yap@premiumauto.com.sg <jiajee.yap@premiumauto.com.sg>
Sent: Thursday, 31 October 2019 5:13 pm
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Chang Chee Sing' <claims@premiumauto.com.sg>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>
Subject: FINAL REVISION - SKX1153D - OD AIG - SURVEYED 11 SEP 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$7661.68 @ 5 days of repair.

Your early closure is well appreciated.

Thanks & Best Regard
JiaYee Yap
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699

Re: OD CLAIM FOR SKX 1153 D ON 7/9/2019

Shirley Hiew (LKK Auto)

Thu 12/9/2019 6:11 PM

To: Claims <claims@premiumauto.com.sg>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>

1 attachments (785 KB)

ESTIMATE.pdf

Hi Troy,

As instructed by our client, please proceed to repair the insured vehicle **SKX 1153D** (Excess S 800/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>

Sent: Wednesday, 11 September 2019 12:56 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: RE: OD CLAIM FOR SKX 1153 D ON 7/9/2019

Dear all,

Survey was just done earlier by Adrian, herein attached with the estimate with marking for your reference.

Kindly assist to advise the claim for approval and how much of the excess.

Thanks

Best Regards,

Troy Goh

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 109902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

View Received Message

This mail is associated with :

***SKX1153D (6702615494SG)**

OD

Sep 6 2019 8:00PM

[WANG MIN]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/09/2019 17:22 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$8675.00) - SKX1153D - Claim Handler: Azlan, Syazairdina

Approved:8675.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	335H
Vehicle Details	
Vehicle No.:	5KX1153D
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8 TFSI MU ATTRACTION
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	CJE114348
Chassis No.:	WAUZZZ8K6FA181239
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$29,466.00
Original Registration Date:	26 Nov 2015
First Registration Date:	26 Nov 2015
Transfer Count:	0
Actual ARF Paid:	\$28,253.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2025
PARF Rebate Amount:	\$21,189.00
Intended COE Rebate Details	
COE Expiry Date:	25 Nov 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,103.00
COE Rebate Amount:	\$37,900.00
Total Rebate Amount:	\$59,089.00

The information contained herein is correct as at 12 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/09/2019 11:01
Date Of Accident	06/09/2019 20:10
Exact Location Of Accident	PASIR RIS INDUSTRIAL DRIVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX1153D
Insured/Policyholder	
Name Of Registered Owner	WANG MIN
NRIC No	S7382335H
Email Address	WANGMIN_WENDY@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96329657
Alternative Phone No	OFFICE-64091496

Vehicle Particulars

Manufacturer	AUDI
Model	A4 1.8T FSI MU 8K203
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	XU GUOBIN
NRIC No	S2711382F
Date Of Birth	25/03/1967
Occupation	INDOOR
Date Of Driving Pass	09/01/2013
Driving Experience	6 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91835756
Fax Number	
Contact Number	

Address	20C DUCHESS ROAD
	#04-14
Postcode	269033
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WANG MIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS I WAS DRIVING ON PASIR RIS INDUSTRIAL DRIVE 1, IN FRONT OF MY LANE HAVING AN RENOVATION OF LANE, AS I TRYING CHANGING TO ANOTHER LANE, SUDDENLY ANOTHER CAR BEHIND OF ME BANG MY FRONTAL BUMPER, HEADLIGHT, FENDER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



A → SKX 1153 D
B → JALAN 11

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As I was driving on the road via industrial area 1, in front of my lane
having an intention of lane, as I trying changing to another lane, suddenly
another car behind of me bang my frontal bumper, headlight, bumper.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Officer's Signature
Name: [Signature]
NRIC/TIN No: 62522416

Accident Photo





GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 5 Raffles Quay #12-00 Singapore 048080
 Tel (65) 6224 0020 Fax (65) 6224 0030
 Operating Hours: Monday to Friday: 09:00 - 17:00
 LHM: 64250200 / 227 Reg. No.: 640001770

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MPA 119118595 Vehicle Registration No: SKX 1153 D
 Name (as shown in NRIC): Ms. Wang Min NRIC/FIN/Passport No: ST382335H
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address: 20C Duchess Road #04-14 Singapore (268033)
 Contact (Tel): _____ Mobile No.: +65 95320657
 Email Address: wangmin_wendy@yahoo.com
 Date of Accident: 06/09/2019 Time of Accident: 08.10pm
 Place of Accident: Pasir Ris Industrial Drive 1
 Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

TO CHANGE THE ACCIDENT DATE AND TIME.

Policyholder / Driver's Signature
 Date

Reporting Centre Personnel's Signature
 Name: Poh Li Hae, Tan
 NRIC/FIN/No: G1547752
 Date: 9/9/2019

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : WANG MIN
 Period of Insurance : 26 Nov 2018 To 25 Nov 2019
 Engine No. : CJE114348
 Chassis No. : WAUZZZ8K6FA181239

Vehicle No. : SKX1153D
 Policy No. : 2100439686-03
 Endorsement No. :
 Issued Date : 06 Oct 2018

ABOUT THE COVER

Make/Model : AUDI A4 1.8 TFSI MU ATTRACTION (WBW)
 Engine Capacity/Tonnage : 1,798.00 CC Sum Insured : Market Value First Year of Registration : 2015
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

WANG MIN - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).)

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

AIGSGMOBILEAPP

UNDERTAKING

I, Xu Guobin, (NRIC No. S2711382F), hereby confirm that the Singapore Accident Statement lodged by me on 7/09/2019 at 8:00 hours pertaining to the accident involving motor car Reg. No: SKX1153D, in which I was the driver are true and accurate to the best of my knowledge, information and belief.

I acknowledge that my insurers are not liable under the contract of insurance if there is a breach of policy terms and conditions.

In the event that an unrelated/unreported third party property or injury claim arises or there is evidence emerges that there is a breach of policy terms and conditions, I irrevocably undertake to absolve my insurer from all liability under the contract of insurance and I undertake to re-pay any sums paid by my insurers pursuant to the contract of insurance upon receipt of written demand by my insurers.

Signature : 
Name of Insured / Driver : Xu Guobin
Nric No. : S2711382F
Date : 07/09/2019

Signature : 
Name of Policyholder : WANG MIN
Nric No. : S7382335H
Date : 7/9/2019



AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME : Xu Guobin
VEHICLE NUMBER : SKX1153D
DATE/ TIME OF ACCIDENT : 6/09/2019
PLACE OF ACCIDENT : Pasir Ris Ind Pr 1
THIRD PARTY VEHICLE (IF ANY) : NA

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

From Pasir Ris Ind Pr 1 heading back to home.

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT WAS THE RESULTS?


I didn't drink any alcohol during driving.

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

side swipe.

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

NO one injured.


NAME: Xu Guobin.

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 11594

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1084/2019/NS
Date : 10-Sep-19

Vehicle NOT IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 62564315

Owner's Name : Ms Wang Min
Address : Blk 32 Marine Crescent
#13-117
Singapore 440032
Telephone : (HP)+65 96329657
Type of Claim : Own Damage Claim
Policy No. : 2100439686-03
Vehicle No : **SKX 1153 D**
Model Code : Audi A4 1.8T FSI MU 8K203
Model / Year : 26/11/2015
Engine No : CJE 114348
Chassis No : WAUZZZ8K6FA181239
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Sep-19
Place of Accident : Pasir Ris Industrial Drive 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 1153 D

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, rhs front fender, bonnet and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 3,150.00 1250	
3	To respray front bumper, rhs front fender and bonnet.	\$ 3,000.00 1650	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ <u>6,702.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 1153 D

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
1	FRONT BUMPER <i>Deformed</i>	\$	2,100.00 ✓	1680
2	FRONT BUMPER FIXING PARTS <i>Not in</i>	\$	234.00 ✗	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not in</i>	\$	207.00 ✗	
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>Not in</i>	\$	123.00 ✗	
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>Not in</i>	\$	177.00 ✗	
6	FRONT BUMPER SUPPORT ELEMENT - UPPER <i>Not in</i>	\$	54.00 ✗	
7	FRONT BUMPER VENT GRILLE - RH <i>Not in</i>	\$	123.00 ✗	
8	FRONT WHEEL SPOILER - RH <i>Not in</i>	\$	45.00 ✗	
9	FRONT BUMPER SIDE REINFORCEMENT <i>Not in</i>	\$	802.00 ✗	
10	FRONT BUMPER FOAM FILLER PIECE <i>Not in</i>	\$	113.00 ✗	
11	FRONT BUMPER SUPPORT <i>Not Nec</i>	2 \$	23.00 ? ✗	
12	FRONT BUMPER GUIDE SECTION - RH <i>Not in</i>	\$	33.00 ✗	
13	SIGNAL HORN - RH LOW TONE <i>Not in</i>	\$	184.00 ✗	
14	SIGNAL HORN SPRING SHACKLE - RH LOW TONE <i>Not in</i>	\$	23.00 ✗	
15	FRONT FENDER - RH <i>Dented</i>	\$	904.00 ✓	722.80
16	FRONT FENDER ATTACHMENT PARTS <i>Not Nec</i>	\$	52.00 ? ✗	
17	FRONT FENDER BRACKET - RH <i>Not Nec</i>	\$	48.00 ? ✗	
18	REAR DEFORMATION ELEMENT BRACKET <i>Not in</i>	\$	45.00 ✗	
19	FRONT FENDER BRACE - RH LOWER <i>Not Nec</i>	\$	107.00 ? ✗	
20	STONE CHIP GUARD <i>Not in</i>	\$	67.00 ✓	52.96
SUB TOTAL SPARE PARTS		:	<u>\$ 5,464.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 1153 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	ADHESIVE TAPE <i>not nec</i>	\$ 50.00	<i>X</i>
22	WHEEL HOUSING LINER <i>not nec</i>	\$ 223.00	<i>X</i>
23	WHEEL HOUSING LINER ATTACHMENT PARTS <i>not nec</i>	\$ 41.00	<i>X</i>
24	BONNET <i>Repair</i>	\$ 2,549.00	<i>X</i>
25	BONNET PROTECTIVE FILM - FRONT	\$ 42.00	<i>X</i>
26	BONNET ATTACHMENT PARTS	\$ 152.00	<i>X</i>
27	BONNET EDGE PROTECTION - FRONT	\$ 25.00	<i>X</i>
28	BONNET CATCH HOOK	\$ 127.00	<i>X</i>
29	BONNET LID LOCK	\$ 196.00	<i>X</i>
30	BONNET LOCK COVER	\$ 21.00	<i>X</i>
31	MAIN BEAM HEADLIGHT MOUNTING	\$ 107.00	<i>X</i>
32	HEADLAMP BRACKET - RH	\$ 96.00	<i>X</i>
33	GAS DISCHARGE LAMP HEADLIGHT - RH <i>cracked</i>	\$ 2,152.00	<i>✓ 1721.60</i>
34	HALOGEN FOG LAMP - RH <i>not nec</i>	\$ 242.00	<i>X</i>
35	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - RH <i>not nec</i>	\$ 192.00	<i>X</i>
36	HEADLIGHT WASHER HOSE <i>not nec</i>	\$ 170.00	<i>X</i>
37	LIFT CYLINDER ELBOW FITTING	\$ 24.00	<i>X</i>
38	RADIATOR AIR GUIDE - RH	\$ 24.00	<i>X</i>
39	RADIATOR SEALING STRIP - LOWER	\$ 21.00	<i>X</i>
40	SUNDRIES <i>Nec</i>	\$ 300.00	<i>32.32</i>

TOTAL SPARE PARTS	\$ 12,218.00
TOTAL LABOUR CHARGES	\$ 6,702.00
GRAND TOTAL	\$ 18,920.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 11/09/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 11594

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1084/2019/NS
Date	:	10-Sep-19

Vehicle NOT IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

5 days - ok - Jy - 31 Oct 2019

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 62564315

Owner's Name	:	Ms Wang Min
Address	:	Blk 32 Marine Crescent #13-117 Singapore 440032
Telephone	:	(HP)+65 96329657
Type of Claim	:	Own Damage Claim
Policy No.	:	2100439686-03
Vehicle No	:	SKX 1153 D
Model Code	:	Audi A4 1.8T FSI MU 8K203
Model / Year	:	26/11/2015
Engine No	:	CJE 114348
Chassis No	:	WAUZZZ8K6FA181239
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	6-Sep-19
Place of Accident	:	Pasir Ris Industrial Drive 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 1153 D

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew front bumper, rhs front fender, bonnet and rhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 3,150.00	\$ 1,250.00
3	To respray front bumper, rhs front fender and bonnet.		\$ 3,000.00	\$ 1,650.00
4	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
SUB TOTAL LABOUR CHARGES		:	<u>\$ 6,702.00</u>	<u>\$ 3,452.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 1153 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,100.00	\$ 1,680.00
2	FRONT BUMPER FIXING PARTS	\$ 234.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 207.00	
4	FRONT BUMPER GRILLE - LOWER CENTRE	\$ 123.00	
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	\$ 177.00	
6	FRONT BUMPER SUPPORT ELEMENT - UPPER	\$ 54.00	
7	FRONT BUMPER VENT GRILLE - RH	\$ 123.00	
8	FRONT WHEEL SPOILER - RH	\$ 45.00	
9	FRONT BUMPER SIDE REINFORCEMENT	\$ 802.00	
10	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	
11	FRONT BUMPER SUPPORT	2 \$ 23.00	
12	FRONT BUMPER GUIDE SECTION - RH	\$ 33.00	
13	SIGNAL HORN - RH LOW TONE	\$ 184.00	
14	SIGNAL HORN SPRING SHACKLE - RH LOW TONE	\$ 23.00	
15	FRONT FENDER - RH	\$ 904.00	\$ 722.80
16	FRONT FENDER ATTACHMENT PARTS	\$ 52.00	
17	FRONT FENDER BRACKET - RH	\$ 48.00	
18	REAR DEFORMATION ELEMENT BRACKET	\$ 45.00	
19	FRONT FENDER BRACE - RH LOWER	\$ 107.00	
20	STONE CHIP GUARD	\$ 67.00	\$ 52.96
SUB TOTAL SPARE PARTS		\$ 5,464.00	\$ 2,455.76

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 1153 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
			\$ 2,455.76
21	ADHESIVE TAPE	\$ 50.00	
22	WHEEL HOUSING LINER	\$ 223.00	
23	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 41.00	
24	BONNET	\$ 2,549.00	
25	BONNET PROTECTIVE FILM - FRONT	\$ 42.00	
26	BONNET ATTACHMENT PARTS	\$ 152.00	
27	BONNET EDGE PROTECTION - FRONT	\$ 25.00	
28	BONNET CATCH HOOK	\$ 127.00	
29	BONNET LID LOCK	\$ 196.00	
30	BONNET LOCK COVER	\$ 21.00	
31	MAIN BEAM HEADLIGHT MOUNTING	\$ 107.00	
32	HEADLAMP BRACKET - RH	\$ 96.00	
33	GAS DISCHARGE LAMP HEADLIGHT - RH	\$ 2,152.00	\$ 1,721.60
34	HALOGEN FOG LAMP - RH	\$ 242.00	
35	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - RH	\$ 192.00	
36	HEADLIGHT WASHER HOSE	\$ 170.00	
37	LIFT CYLINDER ELBOW FITTING	\$ 24.00	
38	RADIATOR AIR GUIDE - RH	\$ 24.00	
39	RADIATOR SEALING STRIP - LOWER	\$ 21.00	
40	SUNDRIES	\$ 300.00	\$ 32.32
TOTAL SPARE PARTS :		\$ 12,218.00	\$ 4,209.68
TOTAL LABOUR CHARGES		\$ 6,702.00	\$ 3,452.00
GRAND TOTAL		\$ 18,920.00	\$ 7,661.68

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKX 1153 D

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1084/2019/NH

12 Dec 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SKX 1153 D, Audi A4 1.8T FSI MU.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SKX 1153 D**, claimant, **Ms. Wang Min**, please find the related document per attached.

1. A copy of the Original invoice no. 85014590 – S\$ 7,342.00.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SKX 1153 D

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:25

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014590 Date : 10/12/2019 Order : SKX1153D Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SKX1153D (V 27897) Regn Date: 26/11/2015 Mileage: 61186 WIP No.: 11594

Model: A4 1.8T FSI MU 8M203H-NEW ATTR Chassis: WAUZZZ8K6FA181239 Engine: CJE 114348 Dept: U

You have been assisted by :- UB-Tony Poong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,RHS FRONT FENDER AND BONNET	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8K0941044D	(A) (SK)HEADLAMP 13/9	Less 020%	1.00	2152.00
X	A8K0821106J	FENDER	Less 020%	1.00	903.50
X	A8K0807065C GRU	(A) (SK)COVER 13/9/19	Less 020%	1.00	2100.00
X	A8K0853824C	STONEGUARD	Less 020%	1.00	66.20
X	A3C0973737	HOUSING	Less 020%	1.00	28.40
X	AM 0161857	POP-RIVET	Less 020%	4.00	3.00

Parts 4,209.68
Labour 0.00
Sublet 3,452.00
Menus 0.00
Lubricant 0.00



Sub-Total 6,861.68

7% GST 480.32

Grand Total 7,342.00

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKX 1153 D

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1084/2019/TG
09 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 1.8 TFSI MU 8K203
Vehicle Chassis No. : WAUZZZ8K6FA181239
Vehicle Regn No. : SKX 1153 D
Vehicle Mileage : 61186 KM
Vehicle Owner : Ms. Wang Min
Certificate No : 2100439686-03
Own Damage Excess : S\$ 856.00 (Inclusive 7% GST)
Accident Date : 06/09/2019
Place : Pasir Ris Industrial Drive 1
Repair Cost : \$ 7,342.00
WIP No. : 11594
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 17.56pm
Date : 9/10/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth ed	Status
Main	12 Sep 2019		11 Sep 2019 14:31 Edit Adj Rpt	S\$7,661.68 Edit Estimates	S\$7,661.68 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS **[Created by insurer]**

Insured: **WANG MIN**, ID: S7382335H, Tel: +6599999999

Vehicle Reg. No.: **SKX1153D** Date of Loss: 06/09/2019 20:00 - :59
[45 Months and 11 Days From LTA Reg Date (Man Yr)]

Claim Type: **OD / 6702615494SG** Policy/Cover Note No.: (Comprehensive)

Excess: S\$800.00

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Azian, Syazairdina**] syazairdina.azian@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... **[Final Rpt due 20/09/2019]**

Driver/Custodian: **XU GUOBIN (52 / Male)**, NRIC: S2711382F, Tel: +6591835756 Email: EVERYYEAR888@YAHOO.COM.SG

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (12/09/2019): **Alert - Adj Mandate Approved (S\$8675.00) - SKX1153D - Claim Handler: Azian, Syaz...**
- AIG_SG (12/09/2019): **SKX1153D / OD / 06/09/2019 / Coverage & Excess update**

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKX1153D (6702615494SG)**
OD
Sep 6 2019 8:00PM
[WANG MIN]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▾		
Assessment Reports															1 per page ▾			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	12/09/19 13:38		Adjuster Immediate Advice													Load HTM				
Photos/Images															3 per page ▾			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	12/09/19 13:31		General View													Load JPG		☒		
2	12/09/19 13:31		General View													Load JPG		☒		
3	12/09/19 13:31		General View													Load JPG		☒		
4	12/09/19 13:31		General View													Load JPG		☒		
5	12/09/19 13:31		General View													Load JPG		☒		
6	12/09/19 13:31		General View													Load JPG		☒		
7	12/09/19 13:31		General View													Load JPG		☒		
8	12/09/19 13:31		General View													Load JPG		☒		
9	12/09/19 13:31		General View													Load JPG		☒		
10	12/09/19 13:31		General View													Load JPG		☒		
11	12/09/19 13:31		General View													Load JPG		☒		
12	12/09/19 13:31		General View													Load JPG		☒		
13	12/09/19 13:31		General View													Load JPG		☒		
14	12/09/19 13:31		General View													Load JPG		☒		
15	12/09/19 13:31		General View													Load JPG		☒		
16	12/09/19 13:31		General View													Load JPG		☒		
17	12/09/19 13:31		General View													Load JPG		☒		
18	12/09/19 13:31		General View													Load JPG		☒		
19	12/09/19 13:31		General View													Load JPG		☒		
20	12/09/19 13:31		General View													Load JPG		☒		
21	04/11/19 15:03		Reinspection Photo													Load JPG		☒		
22	04/11/19 15:03		Reinspection Photo													Load JPG		☒		
23	04/11/19 15:03		Reinspection Photo													Load JPG		☒		
Documentation															1 per page ▾			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	12/09/19 13:30		SKX 1153D GIA.pdf													Load PDF				
2	12/09/19 13:30		DRIVING.pdf													Load PDF				
3	12/09/19 13:30		INS. CERT.pdf													Load PDF				
4	12/09/19 13:30		UNDERTAKING & INTERVIEW FORM.pdf													Load PDF				
5	12/09/19 13:30		ESTIMATE.pdf													Load PDF				
6	05/11/19 13:21		ESTIMATE MARKED.pdf													Load PDF				
7	30/12/19 09:08		WORKSHOP INVOICE													Load PDF				
8	30/12/19 09:08		DISCHARGE VOUCHER													Load PDF				

Linked Accident Report Documents

										View		View in Browser ▾	
Assessment Reports										1 per page ▾			
No	Finalized On	Premium Automobiles Pte Ltd (UBI)							Thumbnail	Print			

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&objid=864043&extid=316573&carole... 2/2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19016117/ASF3N2

Date: 30/12/2019

REFERENCE

Insured/Claimant: WANG MIN Policy No:
Date of Loss: 06/09/2019 Nature of Claim: OD Claim No: 6702615494SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX1153D
Make & Model: AUDI A4, 1.8 TFSI (A) Engine No: CJE114348
Reg. Date: 26/11/2015 (Man. Year: 2015) Chassis No: WAUZZZ8K6FA181239
Colour: White Odometer: 60563 km
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$80,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40R18 Rear Tyre Size: 245/40R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,218.00	4,209.68	8,008.32	65.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,702.00	3,452.00	3,250.00	48.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,920.00	7,661.68	11,258.32	59.50
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	18,120.00	6,861.68	11,258.32	62.13
+ GST 7.00/7.00% (S\$)	1,268.40	480.32	788.08	62.13
Nett Amount (S\$)	19,388.40	7,342.00	12,046.40	62.13

INSPECTION

Date of Assignment: 11/09/2019
Date Inspected: 11/09/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,100.00 FS	*1,680.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	234.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	207.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-LOWER CENTRE	Not Necessary	123.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-UPPER CENTRE	Not Necessary	177.00 FS	*- FS
6	1		*FRONT BUMPER SUPPORT ELEMENT-UPPER	Not Necessary	54.00 FS	*- FS
7	1		*FRONT BUMPER VENT GRILLE-RH	Not Necessary	123.00 FS	*- FS
8	1		*FRONT WHEEL SPOILER-RH	Not Necessary	45.00 FS	*- FS
9	1		*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	802.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
11	2		*FRONT BUMPER SUPPORT	Not Necessary	23.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	33.00 FS	*- FS
13	1		*SIGNAL HORN-RH LOW TONE	Not Necessary	184.00 FS	*- FS
14	1		*SIGNAL HORN SPRING SHACKLE-RH LOW TONE	Not Necessary	23.00 FS	*- FS
15	1		*FRONT FENDER-RH	Dented	904.00 FS	*722.80 FS
16	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	52.00 FS	*- FS
17	1		*FRONT FENDER BRACKET-RH	Not Necessary	48.00 FS	*- FS
18	1		*REAR DEFORMATION ELEMENT BRACKET	Not Necessary	45.00 FS	*- FS
19	1		*FRONT FENDER BRACE-RH LOWER	Not Necessary	107.00 FS	*- FS
20	1		*STONE CHIP GUARD	Necessary	67.00 FS	*52.96 FS
21	1		*ADHESIVE TAPE	Not Necessary	50.00 FS	*- FS
22	1		*WHEEL HOUSING LINER	Not Necessary	223.00 FS	*- FS
23	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	41.00 FS	*- FS
24	1		*BONNET	Repair	2,549.00 FS	*- FS
25	1		*BONNET PROTECTIVE FILM-FRONT	Not Necessary	42.00 FS	*- FS
26	1		*BONNET ATTACHMENT PARTS	Not Necessary	152.00 FS	*- FS
27	1		*BONNET EDGE PROTECTION-FRONT	Not Necessary	25.00 FS	*- FS
28	1		*BONNET CATCH HOOK	Not Necessary	127.00 FS	*- FS
29	1		*BONNET LID LOCK	Not Necessary	196.00 FS	*- FS
30	1		*BONNET LOCK COVER	Not Necessary	21.00 FS	*- FS
31	1		*MAIN BEAM HEADLIGHT MOUNTING	Not Necessary	107.00 FS	*- FS
32	1		*HEADLAMP BRACKET-RH	Not Necessary	96.00 FS	*- FS
33	1		*GAS DISCHARGE LAMP HEADLIGHT-RH	Cracked	2,152.00 FS	*1,721.60 FS
34	1		*HALOGEN FOG LAMP-RH	Not Necessary	242.00 FS	*- FS
35	1		*HEADLIGHT WASHER SYSTEM LIFT CYLINDER-RH	Not Necessary	192.00 FS	*- FS
36	1		*HEADLIGHT WASHER HOSE	Not Necessary	170.00 FS	*- FS
37	1		*LIFT CYLINDER ELBOW FITTING	Not Necessary	24.00 FS	*- FS
38	1		*RADIATOR AIR GUIDE-RH	Not Necessary	24.00 FS	*- FS
39	1		*RADIATOR SEALING STRIP-LOWER	Not Necessary	21.00 FS	*- FS
40	1		*SUNDRIES	Necessary	300.00 FS	*32.32 FS

F=Franchise part, S=SpcNett.

Total Parts (\$\$)	12,218.00	4,209.68
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER,BONNET AND RHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,150.00	1,250.00
3	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER AND BONNET	New	3,000.00	1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			6,702.00	3,452.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >