## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building

51 Ubi Ave 1 #01-25 78 Shenton Way #08-16 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Attn: Khoo, Kay-Eng Date: 12 Sep 2019

# **Preliminary Advice**

Vehicle No : SLT7955B **Accident Date** : 07/09/2019

Make : AUDI A4 Policy No.

**Assignment Date** : 12/09/2019 **Excess** : S\$0.00 Date of Inspection : 12/09/2019 Est. Duration of Repair : 13 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,153.00
Revised Amount	:S\$	18,231.00
Check Items (Estimated)	:S\$	1,025.00
Total	:S\$	19,256.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

110,000.00 Pre-Accident Value :S\$ COE / PARF Rebate :S\$ 67,089.00

Salvage Value :S\$

Margin for Repair :S\$ 42,911.00

### Remarks

X	( )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
	)	Other comments: