



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

MOTOR CLAIMS DEPT

VEHICLE NO. : FBK4430J
MAKE/MODEL : BMW / R1200RT

NO. : 34772

DATE : 10/09/2019

CLAIM NO. : 11422

POLICY NO. :

FROM : RAYMOND

Not Authorised
1/5/19
5 day
Whepleto AAR up
12/9/19

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AIR HOSE INLET	REPLACE	1.00	\$140.00	140.00 ?
2	ARM TRAIL <i>Fork stem</i>	REPLACE	1.00	\$1,635.00 <i>but</i>	1,635.00 ✓
3	AXLE FRONT WHEEL	REPLACE	1.00	\$265.00	265.00 ?
4	AXLE SHAFT SUSPENSION FRONT	REPLACE	1.00	\$256.00	256.00 ?
5	BALL JOINT	REPLACE	1.00	\$319.00	319.00 ?
6	BUSH P/N: 54127	REPLACE	2.00	\$17.00	34.00 ?
7	CAP ARM SUSPENSION FRONT	REPLACE	2.00	\$13.00	26.00 ?
8	COVER FRONT WHEEL	REPLACE	1.00	\$469.00 <i>3 no</i>	469.00 ✓
9	COVER GRID LUGGAGE	REPLACE	1.00	\$582.00	582.00 ?
10	COVER INSTRUMENT	REPLACE	1.00	\$306.00	306.00 ?
11	CRASH BAR SET	REPLACE	1.00	\$1,083.00 <i>3 set</i>	1,083.00 ✓
12	CROWN HANDLE	REPLACE	1.00	\$1,184.00 <i>3 set</i>	1,184.00 ✓
13	CROWN HANDLE LOWER	REPLACE	1.00	\$1,068.00	1,068.00 ?



bizSAFE₃



CERT NO: 2002-1-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
14	FORK LH ASSY	REPLACE	1.00	\$1,884.00	1,884.00
15	FORK RH ASSY	REPLACE	1.00	\$1,884.00	1,884.00
16	HEADLAMP ASSY	REPLACE	1.00	\$1,388.00	1,388.00
17	LABOUR P/N: 06766	REPLACE	20.00	\$35.00	700.00
18	MIRROR LH	REPLACE	1.00	\$1,387.00	1,387.00
19	MUDGUARD FRONT	REPLACE	1.00	\$344.00	344.00
20	RIM SPORT FRONT	REPLACE	1.00	\$1,835.00	1,835.00
21	SCREW	REPLACE	4.00	\$9.00	36.00
22	SPRAY PAINT LH SIDEBOX	Spray	1.00	\$150.00	150.00
23	SPRAY PAINT RH SIDEBOX	Spray	1.00	\$150.00	150.00
24	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED P/N: 45837 - FOR COLLECTION OF ACCIDENT BIKE.		1.00	\$70.00	70.00
25	TYRE 120/70-17 (METZELER)ROADTEC01 HWM P/N: 61288	REPLACE	1.00	\$231.00	231.00
SUB TOTAL					\$17,426.00
GST @ 7 %					\$1,219.82
GRAND TOTAL					\$18,645.82

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LLK Auto Consultants Seng Guan
Acknowledged & Accepted By
The Repairer of the following:

- To be surveyed before/after spray painting
- To supply damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

