

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO : SXXX8913E

ALEX YEO SIAK TEONG
BLK 9 YISHUN STREET 51
07-18
SINGAPORE 767970
TEL: FAX:
PH: 97201102
ATTN:

ESTIMATE BILL

Number : EB00005258
Date : 02/09/2019
Case No : AD00010643
Vehicle No : SGG850T
Chassis: JNABBU32Z0000583
Year of Mfr 2008
Policy No 5058925228-01
Model : NISSAN TEANA 2.5

Term:

Cost price.

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	HEADLAMP RH <i>SCR</i>	1.0	2,188.60	10	1,969.74
2	FRONT BUMPER <i>Deep cut ✓</i>	1.0	720.00	10	648.00
3	FRONT BUMPER RETAINER RH <i>11</i>	1.0	55.50	10	49.95
4	FRONT BUMPER RETAINER LH <i>11</i>	1.0	55.50	10	49.95
5	FRONT BUMPER CHROME RH <i>here</i>	1.0	121.20	10	109.08
6	FRONT BUMPER CHROME LH <i>11</i>	1.0	121.20	10	109.08
7	FRONT FENDER SHIELD RH <i>11</i>	1.0	99.40	10	89.46
Nett Price - Parts Sub Total					3,025.26
8	HEADLAMP LOWER BRACKET RH <i>11</i>	1.0	30.00	0	30.00
9	HEADLAMP NOZZLE RH <i>?</i>	1.0	233.90	0	233.90
10	HEADLAMP NOZZLE COVER RH <i>cut</i>	1.0	75.60	0	75.60
11	FRONT FENDER RH - REPAIR <i>2x</i>	1.0			
12	BONNET - REPAIR <i>2x</i>	1.0			
Special Nett Price - Parts Sub Total					339.50
Parts Total					3,364.76
13	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	<i>300</i> 600.00	0	600.00
14	SPRAY PAINT ON THE AFFECTED AREAS	1.0	<i>800</i> 800.00	0	800.00
15	ANTI-RUST COATING	1.0	<i>180</i> 180.00	0	180.00
16	WIRING	1.0	<i>20</i> 40.00	0	40.00
Labour 1 Sub Total					1,620.00
SINGAPORE DOLLARS : FIVE THOUSAND THREE HUNDRED THIRTY-THREE AND CENTS SIXTY-NINE ONLY					
Less Excess					0.00
SUBTOTAL					4,984.76
GST 7.00%					348.93
TOTAL					5,333.69

Date of accident : 02/08/2019 08:40 AM Place: CARPARK OF 419A YISHUN AVE 11

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

HOCK WAH MOTOR WORKSHOP PTE LTD

AUTHORISED SIGNATURE

CUSTOMER SIGNATURE