

ASS. REC. BY:

REF: CS/SMO19016319/ At f3

n2

Special Instruction:

Surveyor: Adrian ASSIGNMENT (Office)

From (Person): Gmoh Pau Long of SMO Date/Time: 16.9.19 15.29pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLM 6280H Insured: GBJ 444 B

at Workshop n/z: Zero Gravity Tel: 67412845

of 2 Kati Bukit Ave 2 #01-15

Policy No: D19MTHCRG 000226 Claim No: CMD1904336

Sum Insured: Excess:

Make of Veh: D.O.A. 14.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 16.9.19 3.39pm Person Contacted: Mei Yi Vehicle: IN OUT

Date/Time Action/Instruction (✓) Estimate

SLM 6280H - x

GBJ 444 B - 1A1 A16 CRK222/24 D.O.A. 14/09/2019

H/A @ 14.16 - Menmen composed mail pending estimate.

Lump Sum \$2300/- (Red: 4280.30, 65%)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Sep 2019		16 Sep 2019 15:29 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS		[Created by insurer]		
Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H			
Main Claimant:	UNKNOWN4336			
Vehicle Reg. No.:	SLM6280H	Date of Loss:	14/09/2019 00:00 - :59	
Claim Type:	TP / CMTD1904336	Policy/Cover Note No.:	D19MTHCVE000226 (Third Party Only)	
Vehicle Reg. No. (Insured):	GBJ444B	Policy No. (Claimant):		
Repairer:	Zero Gravity (Kaki Bukit) 2 Kaki Bukit Ave 2, #01-25 Kaki Bukit Autohub, 417921 Kaki Bukit - Tel:			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/09/2019]			
Adj Asg. Remarks:	Please assign to Mr Marcus Chua and to conduct survey on a without prejudice basis.			
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail		
There are no mail for this case.				
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?				
No results.				

View Sent Message

This mail is associated with :

***SLM6280H (CMTD1904336)**
[GBJ4448]

TP
UNKNOWN4336
Sep 14 2019 12:00AM
[ETHOZ GROUP LTD]
Zero Gravity

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 17/09/2019 14:16 PM.
To pauloong.gnoh@sompo.com.sg
Subject SLM6280H (CMTD1904336) [GBJ4448] TP

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLM 6280H on 17/9/2019
We are pending estimate from repairer.

Regards,
Denise
LKK Auto

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/09/2019 11:48
Date Of Accident	14/09/2019 13:05
Exact Location Of Accident	PIE TWDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM6280H
Insured/Policyholder	
Name Of Registered Owner	GOO FONG YONG
NRIC No	S1765098Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97110006
Alternative Phone No	OFFICE-97110006

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER EX 1.6 AT LED TAIL LAMP
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100504665-02
Cover Note Number	

Driver

Name of Driver	GOO FONG YONG
NRIC No	S1765098Z
Date Of Birth	01/10/1966
Occupation	INDOOR
Date Of Driving Pass	05/07/1988
Driving Experience	31 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97110006
Fax Number	
Contact Number	OFFICE-97110006
Email Address	NOEMAIL

Address	BLK 462 CLEMENTI AVENUE 3 #18-622
Postcode	120462
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ444B
Vehicle Make/Model/Colour	ISUZU NHR
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	GOO FONG YONG
------	---------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

NECK

SLM6280H

YES

NO

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 14/09/2019


Driver's Signature
(If driver is not the policyholder)

Reporting Centre Person's Signature
Name:

Accident Sketch Plan

SKETCH PLAN

THAS



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TRAVELING ALONG PIE TOWARDS TEAR
 AS I DRIVING PASS LOANE ROAD.
 SUDDENLY THIS VEHICLE B (GRILLER) HIT ONTO
 MR REAR.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time: 14/09/2009

Driver's Signature
 (If driver is not the policyholder)
 Date & Time

Reporting Centre Personnel's Signature
 Name:
 Policy/Till No.



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Buss.Reg.No.: 5288887X

Quotation : QT-000192

SOMPO INSURANCE SINGAPORE PTE LTD

50 RAFFLES PLACE

#05-01/06 SINGAPORE LAND TOWER

SINGAPORE 048623

Attn: Motor Claims Department

TEL : 64616555

FAX : 52213302

Date In : 16/09/2019

Vehicle No. : SLM6280H

Make/Model : MIT LANCER EX

Mileage(KM) : 96,937

Ref./Remark :

Devisé

S/N	Quantity	Particular	Qty	U/ Price S\$	Amount S\$
1	1.0	PCS REAR BUMPER <i>new</i>	1.0 PCS	724.00	✓ 724.00
2	1.0	PCS BUMPER CAP <i>new</i>	1.0 PCS	22.00	✓ 22.00
3	1.0	SET BUMPER CLIP <i>new</i>	1.0 SET	38.00	✓ 38.00
4	1.0	PCS BUMPER SIDE RETAINER (L/H/R) <i>new</i>	1.0 PCS	34.00	✓ 34.00
5	1.0	PCS BUMPER SIDE RETAINER (R/H/R) <i>new</i>	1.0 PCS	34.00	✓ 34.00
6	1.0	PCS REAR BUMPER REINFORCEMENT <i>Bent</i>	1.0 PCS	167.00	✓ 167.00
7	1.0	PCS REAR BUMPER TOP RETAINER <i>new</i>	1.0 PCS	63.00	✓ 63.00
8	1.0	PCS REAR BUMPER REFLECTOR (L/H) <i>new</i>	1.0 PCS	19.00	✓ 19.00
9	1.0	PCS REAR BUMPER REFLECTOR (R/H) <i>new</i>	1.0 PCS	19.00	✓ 19.00
10	1.0	PCS REAR BOOT <i>new</i>	1.0 PCS	763.00	✓ 763.00
11	1.0	PCS LOGO <i>new</i>	1.0 PCS	36.00	✓ 36.00
12	1.0	PCS LOGO "C&C" <i>new</i>	1.0 PCS	18.00	✓ 18.00
13	1.0	PCS EMBLEM "MIVEV" <i>new</i>	1.0 PCS	62.00	✓ 62.00
14	1.0	PCS EMBLEM "LANCER" <i>new</i>	1.0 PCS	62.00	✓ 62.00
15	1.0	PCS REAR BOOT WEATHERSTRIP <i>new</i>	1.0 PCS	186.00	✓ 186.00
16	1.0	PCS REAR BOOT INNER LOCK <i>new</i>	1.0 PCS	87.00	✓ 87.00
17	1.0	PCS REAR BOOT LOCK STRIKER <i>new</i>	1.0 PCS	32.00	✓ 32.00
18	1.0	PCS REAR END PANEL <i>new</i>	1.0 PCS	403.00	✓ 403.00
19	1.0	PCS REAR END PANEL GARNISH <i>new</i>	1.0 PCS	169.00	✓ 169.00
20	1.0	PCS SPARE TYRE BOARD <i>new</i>	1.0 PCS	195.00	✓ 195.00
21	2.0	PCS LAMP (NUMBER PLATE) <i>new</i>	2.0 PCS	42.00	✓ 84.00
22		Discount 10 %			-321.70
23		SubTotal (L)			2,895.30
24	1.0	SET REVERSE SENSOR <i>Damaged</i>	1.0 SET	280.00	✓ 280.00
25	1.0	PCS REVERSE CAMERA <i>new</i>	1.0 PCS	450.00	✓ 450.00
26	1.0	BTL REAR END PANEL SEALANT <i>new</i>	1.0 BTL	50.00	✓ 50.00

1597

143730



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
 Tel: +65 67412845 Fax No: +65 67412170
 Email: zero_gravity@singnet.com.sg
 Buss.Reg.No.: 5268887X

Quotation : QT-000192**SOMPO INSURANCE SINGAPORE PTE LTD****50 RAFFLES PLACE****#05-01/06 SINGAPORE LAND TOWER****SINGAPORE 048623****Attn: Motor Claims Department****TEL : 64616555****FAX : 62213302**

Date In : 16/09/2019
 Vehicle No. : SLM6230H
 Make/Model : MIT LANCER EX
 Mileage(KM) : 96,937
 Ref./Remark :

S/N	Quantity	Particular	Qty	U/ Price S\$	Amount S\$
27	1.0	PCS REAR NUMBER PLATE <i>Best</i>	1.0	35.00	✓ 35.00
28	1.0	PCS REAR SPOILER <i>Rpr</i>	1.0	450.00	+ 450.00
29		SubTotal (S)			1,265.00
30	1.0	X PANEL BEAT & REPAIR REAR DAMAGE	1.0	X	<i>600</i> 1,000.00
31	1.0	X TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0	X	<i>600</i> 900.00
32	1.0	X TO PROVIDE UNDER TURFCOAT	1.0	X	<i>30</i> 420.00
33	1.0	X TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0	X	<i>1290</i> 30 450.00
34	1.0	X TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0	X	<i>30</i> 80.00
35	1.0	X TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0	X	X 50.00
36	1.0	X TO TRANSFER REAR BOOT FITTING	1.0	X	+ 120.00
37		SubTotal (Labour)			2,420.00

*total 2962.30**4/21 2.3k**0.5 days*

LKK Auto Consultants hence notify
 the Repairer of the following:

SINGAPORE DOLLAR SIX THOUSAND FIVE HUNDRED EIGHTY AND CENTS THIRTY ONLY

- E. & O.E.** Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Customer's Signature/Co. Stamp
 Date:

ZERO GRAVITY

Total S\$ 6,580.30
Discount S\$ 0.00
Net Total S\$ 6,580.30

Terms: C.O.D.

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made within (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.

2.3k

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19016319/ATF3N2
Date: 17/01/2020

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTHCVE000226
Claimant Vehicle No : SLM6280H **Insured Vehicle No :** GBJ444B
 Date of Loss: 14/09/2019 Nature of Claim: TP Claim No: CMTD1904336

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM6280H
 Make & Model: MITSUBISHI LANCER, 1.6 EX AT LED TAIL LAMP (A) Engine No: 4A92CN6270
 Reg. Date: 03/04/2017 (Man. Year: 2016) Chassis No: JMYSRCY1AGU006471
 Colour: Red Odometer: 96938 km
 Engine Capacity: 1590 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,160.30	1,672.30	2,488.00	59.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	1,290.00	1,130.00	46.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,580.30	2,962.30	3,618.00	54.98
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	6,580.30	2,300.00	4,280.30	65.05

INSPECTION

Date of Assignment: 16/09/2019
 Date Inspected: 17/09/2019 Inspected At: Zero Gravity (Kaki Bukit)
 2 Kaki Bukit Ave 2, #01-25 Kaki Bukit Autohub
 Singapore 417921
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jan 2020)

Parts: 143 MITSUBISHI LANCER 1.6 EX AT LED TAIL LAMP (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLM6280H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	724.00 FL	*724.00 FL
2	1		*BUMPER CAP	Not Necessary	22.00 FL	*- FL
3	1		*SET BUMPER CLIP	Necessary	38.00 FL	*38.00 FL
4	1		*BUMPER SIDE RETAINER (L/H/R)	Necessary	34.00 FL	*34.00 FL
5	1		*BUMPER SIDE RETAINER (R/H/R)	Necessary	34.00 FL	*34.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	167.00 FL	*167.00 FL
7	1		*REAR BUMPER TOP RETAINER	Not Necessary	63.00 FL	*- FL
8	1		*REAR BUMPER REFLECTOR (L/H)	Cracked	19.00 FL	*19.00 FL
9	1		*REAR BUMPER REFLECTOR (R/H)	Not Necessary	19.00 FL	*- FL
10	1		*REAR BOOT	Repair	763.00 FL	*- FL
11	1		*LOGO	Necessary	36.00 FL	*36.00 FL
12	1		*LOGO C&C	Necessary	18.00 FL	*18.00 FL
13	1		*EMBLEM MIVEC	Necessary	62.00 FL	*62.00 FL
14	1		*EMBLEM LANCER	Necessary	62.00 FL	*62.00 FL
15	1		*REAR BOOT WEATHERSTRIP	Not Necessary	186.00 FL	*- FL
16	1		*REAR BOOT INNER LOCK	Not Necessary	87.00 FL	*- FL
17	1		*REAR BOOT LOCK STRIKER	Not Necessary	32.00 FL	*- FL
18	1		*REAR END PANEL	Dented	403.00 FL	*403.00 FL
19	1		*REAR END PANEL GARNISH	Not Necessary	169.00 FL	*- FL
20	1		*SPARE TYRE BOARD	Not Necessary	195.00 FL	*- FL
21	2		*LAMP (NUMBER PLATE)	Not Necessary	84.00 FL	*- FL
22	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
23	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
24	1		*BTL REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
25	1		*REAR NUMBER PLATE	Bent	35.00 FS	*35.00 FS
26	1		*REAR SPOILER	Repair	450.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	4,482.00	1,832.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	321.70	159.70
Total Parts (\$\$)	4,160.30	1,672.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT & REPAIR REAR DAMAGE	New	1,000.00	600.00
2	TO PUTTY AND RE-SPRAY AFFECTED PORTION	New	900.00	600.00
3	TO PROVIDE UNDER TURFCOAT	New	120.00	30.00
4	TO REMOVE AND REFIT COMPONENTS/FACILITATE THE REPAIR	New	150.00	30.00
5	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	New	80.00	30.00
6	TO CHECK WIRING SYSTEM,FOCUS LIGHTINGS	New	50.00	0.00
7	TO TRANSFER REAR BOOT FITTING	New	120.00	0.00
Gross Labour Cost (S\$)			2,420.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >