



Co. Reg: 200922097K GST Reg.No: 200922097K  
 Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883  
 • Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date : 13/9/2019

*Xico Tay* Total Pages : 1

TO: India International Insurance Pte Ltd  
 64 Cecil Street  
 IOB Building  
 Singapore 049711

Our Customer : VINODTHAN S/O MURUGAYA  
 Vehicle No : **SLK1106Y**  
 Model : BMW 116I AT ABS  
 Manufacture Year : 2011  
 Date of Accident : 11/9/2019  
 Total Estimate Repair Days : 3

Attn : Motor Claim Department  
 Email :

Re: Repair Estimate For Third Party Claim against : SHC2163P

| No.   | Item Descriptions  | Qty | Unit Price | Amount                   | Remarks From Surveyor |
|---|--|-----|------------|--------------------------|-----------------------|
| <b>A. Spare Parts</b>                           |  |     |            |                          |                       |
| 1   | Rear Bumper <i>Repr</i>  | 1   | \$1,300.00 | \$1,300.00               | X                     |
| 2   | Rear bumper RH retainer <i>Men</i>   | 1   | \$70.00    | \$70.00                  | X                     |
| 3   | RH Rear Fender <i>Repr</i>   | 1   | \$1,800.00 | \$1,800.00               | X                     |
|   |  |     |            | <b>Sub Total</b>         | <b>\$3,170.00</b>     |
|   |  |     |            | Less 10%                 | \$317.00              |
|   |  |     |            | <b>Sub Total 1</b>       | <b>\$2,853.00</b>     |
| <b>B. Spare Parts (S/Nett)</b>                  |  |     |            |                          |                       |
| 1   | RH rear tyre rim <i>ht</i>   | 1   | \$1,024.80 | \$1,024.80               | 750 (SN)              |
| 2   | Rear windscreen seal   | 1   | \$15.00    | \$15.00                  | X                     |
| 3   | Rear windscreen sealant <i>Men</i>   | 2   | \$25.00    | \$50.00                  | X                     |
| 4   | Rear windscreen primer   | 1   | \$15.00    | \$15.00                  | X                     |
|   |  |     |            | <b>Sub Total 2</b>       | <b>\$1,104.80</b>     |
|   |  |     |            | <b>Total Spare Parts</b> | <b>\$1,104.80</b>     |
| <b>C. Labour</b>                                |  |     |            |                          |                       |
| 1   | To knock and straighten rear portion. To remove and renew necessary parts. Cut and weld damaged panel. Adjust and realign the same |     |            | \$800.00                 | 200                   |
| 2   | To putty and spray damaged panel   |     |            | \$800.00                 | 400                   |
| 3   | To remove and refit rear windscreen glass  |     |            | \$120.00                 | X                     |
| 4   | To check wiring and lighting   |     |            | \$60.00                  | X                     |
|   |  |     |            | <b>Total Labour</b>      | <b>\$1,780.00</b>     |
|   |  |     |            | <b>Total Repair Cost</b> | <b>\$4,633.00</b>     |
| <b>* The above quoted are exclusive of GST.</b> |  |     |            |                          |                       |

Yours faithfully,

Ekynn  
 f Auto N Cars Services Pte Ltd

*total: 1350  
 h/s: 1050*

| Surveyor's Details |                                      |
|--------------------|--------------------------------------|
| Name               | <i>Adrian Ling</i>                   |
| Contact            | <i>96853733</i>                      |
| Survey Date        | <i>19/09/19</i>                      |
| Recommend          | Authorize / <del>Not Authorize</del> |
| Before Paint       | Yes / <del>No</del>                  |
| Signature          | <i>[Signature]</i>                   |

*03 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Adrian Ling*