

ASS. REC. BY:

REF:

CS/FCI 19016398/T1+3

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Marina Chian San San of FCI

Date/Time: 17.9.19 2.55p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GT 6990P

Insured: SHB 3408H

at Workshop m/s Sng Ah Tee

Tel: 62186183

of BLK 3 Pioneer Road North #01-18

Policy No:

Claim No:

D19005827MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 7.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 17.9.19 2.58p.m

Person Contacted:

Joyce Tan

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GT 6990P - CC31 AIC 10024934/bbn ROA - 06/12/2010
	SHB 3408H - x
19/9@ 2:47pm	- email preli advise to FCI
	lump sum \$4050f cred: 2311-49 :3670)

Tanjong

REF: F01

ASS. REV. BY:

ASSIGNMENT

From: Date 18-9-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GT 6990P

at Workshop m/s Sng Ah Tee

of BLK 3 Pioneer Road North #01-18

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh: 2.00pm - 3.00pm Dinner waly

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GT6990P Yr Regn: 2015, Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV200 c.c. 1461

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 104703 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VSKYBAM 207.0106832

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65 R14

R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 12 NOV 2019

Date/Time, File Pass to?

1) W/L Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / U/C: 40501

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (%)

Survey Fee:

Transportation:

S + RS, SA

Photos:

Others:

TOTAL

145

50

50

31

276

MOTOR SURVEY ASSIGNMENT

Date 09-09-2019 **Our Ref No.** D19005827MFSH

Accident Date 07-09-2019 **Claim Type.** Third Party

Insured Vehicle SHB3408H **Third Party Vehicle.** GT6990P

Survey Location BLK 3 PIONEER ROAD NORTH #01-18

Contact Person. JOYCE TAN

Contact No. 62686183/0 **Fax No.** 62681429

Survey Type DIRECT SETTLEMENT:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA

Contact Number. NA **Fax No.** 68416315

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop SNG AH TEE MOTOR & PANEL SERVICE PTE LTD **Attention.** NIL

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge MERINA CHIA SAN SAN

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 19 September 2019 2:47 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR
Cc: 'Merina Chia'
Subject: RE: SURVEY ASSESSMENT - D19005827MFSH/1
Attachments: PRELI ADVISED OF GT 6990P.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **GT 6990P**
Number of days (estimated) : 5 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 17 September 2019 3:00 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005827MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAUTO)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Friday, 8 November 2019 5:06 PM
To: Taufikh (LKKAUTO); Denise Tay (LKKAUTO)
Subject: FW: GT 6990P / TP / DOA: 7/9/2019
Attachments: img-191108161453.pdf; IMG_20190927_105956.jpg; IMG_20190927_110026.jpg; IMG_20190927_110130.jpg; IMG_20190927_110158.jpg; IMG_20190927_110206.jpg; IMG_20190927_110215.jpg; IMG_20190923_093104.jpg; IMG_20190923_093257.jpg

asking for 7 days for repair.
thanks.

From: Sharon Sng
Sent: Friday, November 8, 2019 5:05 PM
To: 'Denise Tay (LKKAUTO)' <denisetay@lkkauto.com>; 'Taufikh (LKKAUTO)' <Taufikh@lkkauto.com>
Subject: RE: GT 6990P / TP / DOA: 7/9/2019

Hi

pls refer to attachment for finalising.

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-

From: Denise Tay (LKKAUTO)
Sent: Thursday, November 7, 2019 10:18 AM
To: Janice Chang <janice@sngahtee.com>; SAMANTHA TAN <sam@sngahtee.com>
Cc: 'Sharon Sng' <sharon@sngahtee.com>
Subject: GT 6990P / TP / DOA: 7/9/2019

Dear Sir,

Would like check this case status. If any repair done

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 11 November 2019 4:52 PM
To: Sharon Sng; Taufikh (LKKAuto)
Subject: RE: GT 6990P / TP / DOA: 7/9/2019

Dear Sharon,

Confirm lump sum \$4050/-, 7days.

Please submit your relevant document to First Capital directly.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Friday, 8 November 2019 5:06 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: FW: GT 6990P / TP / DOA: 7/9/2019

asking for 7 days for repair.
thanks.

From: Sharon Sng
Sent: Friday, November 8, 2019 5:05 PM
To: 'Denise Tay (LKKAuto)' <denisetay@lkkauto.com>; 'Taufikh (LKKAuto)' <Taufikh@lkkauto.com>
Subject: RE: GT 6990P / TP / DOA: 7/9/2019

Hi

pls refer to attachment for finalising.

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005827MFSH

Date: 19/09/2019

Our Ref: CS/FCI19016398/T1tf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GT 6990P

Please be informed that we had conducted the inspection of the abovementioned vehicle 18/09/2019 at the premises of M/s Sng Ah Tee have the following to report: -

Workshop Estimate Amount	: S\$ <u>6,307.49</u>
Revised Estimate Amount	: S\$ <u>4,557.56</u>
"Check" Items Amount	: S\$ <u>420.21</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2019 09:56
Date Of Accident	07/09/2019 08:40
Exact Location Of Accident	SENGKANG EAST ROAD TOWARDS TPE(SLE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GT6990P
Insured/Policyholder	
Name Of Registered Owner	B K S CATERING
Co Reg No	31025900B
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93657976 — MR JANK.

Vehicle Particulars

Manufacturer	NISSAN
Model	NV200-1.5 (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5084398706-02
Cover Note Number	COMPREHENSIVE

Driver

Name of Driver	PANG SENG SAN
NRIC No	S1717275A
Date Of Birth	25/09/1965
Occupation	INDOOR
Date Of Driving Pass	12/11/1984
Driving Experience	34 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93657976
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 250B COMPASSVALE STREET #07-75
Postcode	542250
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I STOPPED AT THE SLIP ROAD AND WAS CHECKING FOR VEHICLES ON THE MAIN ROAD. VEHICLE B COULD NOT STOP IN TIME AND HIT INTO THE REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB3408H
Vehicle Make/Model/Colour	YELLOW TAXI
Details Of Properties	FRONT PORTION
Vehicle Category	TAXI
Name of Driver	MISS LIM
NRIC/Passport Number	
Contact Number	98190838
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

NTUC Income Motor Service Centre

Report No: MT

D.O.A.

Vehicle No:

Make / Model:

Report Date: 9/9/2019 Start Time: 9:50 AM

Reporting Type: R

End Time:

IMPORTANT NOTICE

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims/collectively the "Purposes";
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, law or court orders.

BKS CATERING

9/9/2019 9:54


Policyholder's Signature
Date & Time:

Driver's Signature (If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: S992753

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I STOPPED AT THE SLIP ROAD AND WAS CHECKING FOR VEHICLES ON THE MAIN ROAD. VEHICLE B COULD NOT STOP IN TIME AND HIT INTO THE REAR PORTION OF MY VEHICLE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

BKS CATERING

9/9/2019 9:54

Policyholder's Signature
Date & Time:

9/9/2019 9:54

Driver's Signature (If driver is not the policyholder)
Date & Time:

BKS CATERING

9/9/2019 9:54

Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: S992753

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	900B
Vehicle Details	
Vehicle No.:	GT6990P
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Sep 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	K9KC400D054710
Chassis No.:	VSKYBAM20Z0106832
Maximum Power Output:	-
Open Market Value:	\$20,050.00
Original Registration Date:	22 Oct 2015
First Registration Date:	22 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$1,003.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Oct 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$43,185.00
COE Rebate Amount:	\$26,178.00
Total Rebate Amount:	\$26,178.00

The information contained herein is correct as at 12 Sep 2019

OK

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ005175

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

DATE : 16/09/2019
ACCIDENT DATE : 07/09/2019
VEHICLE NO : GT6990P
CHASSIS/ENG.NO : VSKYBAM20Z0106832
VEHICLE MODEL : NISSAN NV200
CLAIM NO :
POLICY NO :
REMARK : 6990 TP AGST FIRST
CAP SHB3408H

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
							SUB-TOTAL: 0.00
** NETT PRICE **							
1	1	PC	REAR BUMPER	740.00	10	666.00	666.00 ✓
2	2	PC	REAR BUMPER RETAINER	33.30	10	29.97	59.94 nn X
3	6	PC	REAR BUMPER CLIPS	4.40	10	3.96	23.76 nn X
4	1	PC	REAR BUMPER REFLECTOR(LH)	55.00	10	49.50	49.50 nn X
5	1	PC	REAR BOOT LID LH	1,381.10	10	1,242.99	1,242.99 bt ✓
6	1	PC	REAR BOOT LID LOCK LH	116.70	10	105.03	105.03 bt ✓
7	1	PC	REAR BOOT LID TRIMBOARD LH	184.80	10	166.32	166.32 nn X
8	1	PC	REAR BOOT LID RUBBER	96.40	10	86.76	86.76 nn X
9	1	PC	REAR BOOT LID RH	960.90	10	864.81	864.81 bt ✓
10	1	PC	REAR BOOT LID RUBBER RH	67.20	10	60.48	60.48 nn X
11	1	PC	REAR BOOT LID LOCK RH	116.70	10	105.03	105.03 nn X
12	1	PC	REAR BOOT LID TRIMBOARD RH	118.40	10	106.56	106.56 nn X
13	1	PC	REAR END PANEL TOP GARNISH	69.90	10	62.91	62.91 nn X ✓
							SUB-TOTAL 3,600.09
** SPECIAL NETT PRICE **							
1	1	PC	REAR BOOT GLASS SEALANT	40.00		40.00	40.00 nn ✓
2	1	PC	REAR NUMBER PLATE	35.00		35.00	35.00 nn X nn ✓
3	1	PC	REAR BOOT GLASS SEALANT	40.00		40.00	40.00 nn ✓
4	1	PC	REAR END PANEL	152.40		152.40	152.40 nn X ✓

JOYCE

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com.sg

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ005175

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

DATE : 16/09/2019
ACCIDENT DATE : 07/09/2019
VEHICLE NO : GT6990P
CHASSIS/ENG.NO : VSKYBAM20Z0106832
VEHICLE MODEL : NISSAN NV200
CLAIM NO :
POLICY NO :
REMARK : 6990 TP AGST FIRST
CAP SHB3408H

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
5	1	PC	REAR PARKING SENSOR	280.00		280.00 <i>200nw</i>	280.00
6	1	PC	6PAX STICKER	20.00		20.00 <i>nr</i>	20.00
7	1	PC	70KM STICKER	20.00		20.00 <i>nr</i>	20.00
SUB-TOTAL							587.40

** WORK LABOUR **

TO KNOCK,WELD,REMOVE & REPLACE ABOVE PARTS
TO REMOVE & REFIX REAR WINDSCREEN
TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS
TO APPLY ANTI RUST COAT
TO CHECK WIRING

850.00 *600 750* 850.00
120.00 *120* 240.00
850.00 *800* 850.00
150.00 *40* 150.00
30.00 *✓* 30.00
SUB-TOTAL 2,120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanfer 97495749
WP 0704 days
18/9/19 @ 220pm
Lumpsum
Resurvey after repair
sure/hkano.com

JOYCE

PAGE: 2 of 2

SUB-TOTAL : S\$ 6,307.49
ADD 7% GST. S\$ 441.52
GRAND TOTAL : S\$ 6,749.01

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

6356.09

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ005175

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE 16/09/2019

ACCIDENT DATE : 07/09/2019

VEHICLE NO : GT6990P

CHASSIS/ENG.NO : VSKYBAM20Z0106832

VEHICLE MODEL : NISSAN NV200

CLAIM NO :

POLICY NO :

REMARK : 6990 TP AGST FIRST
CAP SHB3408H

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
							SUB-TOTAL: 0.00
** NETT PRICE **							
1	1	PC	REAR BUMPER	740.00	10	666.00	de 666.00
2	2	PC	REAR BUMPER RETAINER	33.30	10	29.97	X 59.94
3	6	PC	REAR BUMPER CLIPS	4.40	10 26.4	3.96	net 23.76
4	1	PC	REAR BUMPER REFLECTOR(LH)	55.00	10	49.50	X 49.50
5	1	PC	REAR BOOT LID LH	1,381.10	10	1,242.99	bt 1,242.99
6	1	PC *	REAR BOOT LID LOCK LH	116.70	10	105.03	? 105.03 ✓
7	1	PC	REAR BOOT LID TRIMBOARD LH	184.80	10	166.32	X 166.32
8	1	PC	REAR BOOT LID RUBBER	96.40	10	86.76	? 86.76
9	1	PC	REAR BOOT LID RH	960.90	10	864.81	bt 864.81
10	1	PC	REAR BOOT LID RUBBER RH	67.20	10	60.48	? 60.48
11	1	PC	REAR BOOT LID LOCK RH	116.70	10	105.03	? 105.03
12	1	PC	REAR BOOT LID TRIMBOARD RH	118.40	10	106.56	X 106.56
13	1	PC *	REAR END PANEL TOP GARNISH missing	69.90	10	62.91	? 62.91
							SUB-TOTAL 3,600.09
							NCC 3,296.50
** SPECIAL NETT PRICE **							
1	1	PC	REAR BOOT GLASS SEALANT	40.00		40.00	net 40.00
2	1	PC	REAR NUMBER PLATE	35.00		35.00	X 35.00
3	1	PC	REAR BOOT GLASS SEALANT	40.00		40.00	net 40.00
4	1	PC	REAR END PANEL	152.40		152.40	Rp 152.40

JOYCE

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB, Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ005175

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE: 16/09/2019
ACCIDENT DATE: 07/09/2019
VEHICLE NO: GT6990P
CHASSIS/ENG.NO: VSKYBAM20Z0106832
VEHICLE MODEL: NISSAN NV200
CLAIM NO:
POLICY NO:
REMARK: 6990 TP AGST FIRST
CAP SHB3408H

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
5	1	PC	REAR PARKING SENSOR	280.00		280.00 <i>200nw</i>	280.00
6	1	PC	6PAX STICKER	20.00		20.00 <i>net</i>	20.00
7	1	PC	70KM STICKER	20.00		20.00 <i>net</i>	20.00
SUB-TOTAL							587.40

** WORK LABOUR **

TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS (Floor panel needs to knock)	<i>\$750 ↑</i>	850.00	<i>600</i>	850.00
TO REMOVE & REFIX REAR WINDSCREEN		120.00	<i>120</i>	240.00
TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS	<i>\$800 ↑</i>	850.00	<i>650</i>	850.00
TO APPLY ANTI RUST COAT		150.00	<i>40</i>	150.00
TO CHECK WIRING		30.00	<i>✓</i>	30.00
SUB-TOTAL				2,120.00

**
Total \$5074.10
(587.40) = \$4486.70
~ \$4000 Us
ok? 1st time
Shawn 8/11/2019*

*Tanpin 97495749 \$1140
WP 05 days
18/9/19 @ 220pm
Lumpsum
Resumey after repair
sure@hkant.com*

JOYCE

PAGE: 2 of 2

SUB-TOTAL: SS 6,307.49
ADD 7% GST. SS 441.52
GRAND TOTAL: SS 6,749.01

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3 Pioneer Road North #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Our Ref:

Date : 7/9/2019

ATTN:THE MOTOR CLAIMS DEPT
FIRST CAPITAL INSURANCE LTD

SUPPLEMENTARY ESTIMATE COST OF REPAIR

Vehicle Reg No.	GT6990P	Model / Year	NISSAN NV200
Date of Accident	07-Sep-19	Policy No.	
Type of Claim	THIRD PARTY	Prepared By	SHARON
Survey By		Chassis No.	

S/NO Description

Qty Unit Price Amount

1 REAR END PANEL TOP GARNISH CLIP

6	\$ 9.00	\$ 54.00	(A) ALL ✓
	LESS 10%	\$ 5.40	
		<u>\$ 48.60</u>	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19016398/T1tf3s2

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 19-11-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 3408H	Veh. Inspected	GT 6990P
Policy No.		Coverage (\$)	0.00
Claim No.	D19005827MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA SAN SAN	Assign Date	17/09/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VSKYBAM20Z0106832	Colour	WHITE
Odometer	104703	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R14	LING LONG	6 mm
L/H Front Tyre	175/65 R14	LING LONG	6 mm
R/H Rear Tyre	175/65 R14	LING LONG	6 mm
L/H Rear Tyre	175/65 R14	LING LONG	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/09/2019	Inspection Date	18/09/2019
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GT 6990P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (N)	DEFORMED	740.00	740.00
2	REAR BUMPER RETAINER @ \$33.30 (N)	NOT NECESSARY	66.60	-
6	REAR BUMPER CLIPS @ \$4.40 (N)	NECESSARY	26.40	26.40
1	REAR BUMPER REFLECTOR (LH) (N)	NOT NECESSARY	55.00	-
1	REAR BOOT LID LH (N)	BENT	1,381.10	1,381.10
1	REAR BOOT LID LOCK LH (N)	BENT	116.70	116.70
1	REAR BOOT LID TRIMBOARD LH (N)	NOT NECESSARY	184.80	-
1	REAR BOOT LID RUBBER (N)	NOT NECESSARY	96.40	-
1	REAR BOOT LID RH (N)	BENT	960.90	960.90
1	REAR BOOT LID RUBBER RH (N)	NOT NECESSARY	67.20	-
1	REAR BOOT LID LOCK RH (N)	NOT NECESSARY	116.70	-
1	REAR BOOT LID TRIMBOARD RH (N)	NOT NECESSARY	118.40	-
1	REAR END PANEL TOP GARNISH (N)	MISSING	69.90	69.90
6	REAR END PANEL TOP GARNISH CLIP @ \$9.00 (N) (ADDITIONAL)	NECESSARY	54.00	54.00
	LESS 10% DISCOUNT		-405.41	-334.90
			3,648.69	3,014.10
SPECIAL NETT ITEMS				
1	REAR BOOT GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	35.00	-
1	REAR BOOT GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	REAR END PANEL (SN)	TO REPAIR SEE LABOUR	152.40	-
1	REAR PARKING SENSOR (SN)	NOT WORKING	280.00	200.00
1	6PAX STICKER (SN)	NECESSARY	20.00	20.00
1	70KM STICKER (SN)	NECESSARY	20.00	20.00
			587.40	320.00
LABOUR				
	TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		850.00	750.00
	TO REMOVE & REFIX REAR WINDSCREEN.		240.00	120.00

Report Ref No. CS/FCI19016398/T1tf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS.		850.00	800.00
	TO APPLY ANTI RUST COAT.		150.00	40.00
	TO CHECK WIRING.		30.00	30.00
			2,120.00	1,740.00
GRAND TOTAL			6,356.09	5,074.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,050.00

Report Ref No. CS/FCI19016398/T1tf3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.