



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 18/19/19/VP05/022382

Date: 08th May 2020

Our Ref: CC4/LPC19016413/Eda3s2

M/s Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMF 5888L
INSURED VEHICLE: SKQ 1307P ACCIDENT DATE: 13/09/2019**

We thank you for your instruction on 17/09/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMF 5888L from M/s C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SMF 5888L and SKQ 1307P.
- c) Colour damaged vehicle photographs of SMF 5888L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMF 5888L
Make & Model	: B.M.W 520I
Year of Registration	: 2019
Chassis Number	: WBAJA12030BJ21370
Engine Capacity	: 1998 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.