

AUTO BOLT BODY AND PAINT PTE LTD

8 Kaki Bukit Avenue 4 #03-01 Premier @ Kaki Bukit Singapore 415875

Email : autoboltsvc@singnet.com.sg

Tel : 6384 1066 Fax : 6384 1067

17 September 2019

Reg No.: SJJ 8092 K
Model: HONDA STREAM

TPAIG
Vic

QTY	DESCRIPTION	AMT \$
<u>List Items</u>		
1	Rear windscreen moulding <i>new</i>	\$ 118.50 ✓
1	Rear tailgate <i>Dented</i>	\$ 1,285.00 <i>202</i>
1	Rear tailgate inner lock <i>new</i>	\$ 303.20 +
1	Rear tailgate inner trim board <i>cracked</i>	\$ 489.50 <i>245</i>
1	Rear tailgate weatherstrip <i>cut</i>	\$ 189.60 ✓
1	Rear tailgate "STREAM" emblem <i>new</i>	\$ 68.50 ✓
1	Rear taillamp -L/H <i>cut</i>	\$ 585.90 <i>385</i>
1	Rear end panel <i>Dented</i>	\$ 685.00 ✓
1	Rear end panel inner garnish <i>replaced</i>	\$ 212.60 <i>2</i>
1	Rear bumper <i>Dented</i>	\$ 1,185.00 <i>689</i>
1	Rear bumper lower bracket <i>Bent</i>	\$ 58.50 ✓
2	Rear bumper side retainers <i>new</i>	\$ 97.00 ✓
1	Rear bumper towing cover <i>replaced</i>	\$ 15.60 ✓
1	Rear fender -L/H <i>Repair</i>	\$ 981.60 +
1	Rear fender inner trim garnish <i>new</i>	\$ 628.50 +
1	Rear fender quarter glass moulding <i>new new</i>	\$ 182.60 +
		\$ 7,086.60
	Less 20%	\$ 1,417.32
		\$ 5,669.28

3575.30

2860.24

Special Nett Items

1	Rear windscreen sealant <i>new</i>	\$ 80.00 <i>60</i>
1	Rear bumper clip (1 set) <i>new</i>	\$ 45.00 <i>30</i>
1	Rear reverse sensor (1 set) <i>Dented</i>	\$ 350.00 <i>200</i>
1	Rear reverse camera <i>new new</i>	\$ 480.00 +
1	Rear fender quarter glass sealant -L/H <i>new</i>	\$ 80.00 +
		\$ 1,035.00

290

S/N. Labour Charges

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 <i>30</i>
2	To remove and refit inner garnishes.	\$ 150.00 <i>60</i>
3	To remove and refit rear reverse sensor and camera.	\$ 150.00 <i>80</i>
4	To transfer rear tailgate mechanism and wiring assembly.	\$ 120.00 <i>80</i>
5	To remove and refit rear windscreen glass.	\$ 180.00 <i>120</i>
6	To apply undercoating.	\$ 200.00 <i>160</i>
7	Panel heating.	\$ 1,800.00 <i>800</i>
8	To respray painting on the affected areas.	\$ 1,600.00 <i>800</i>
		\$ 4,280.00

2030

Grand Total : \$ 10,984.28

06 Days

total: 5180.24
h/s: 4.1K

LKK Auto Consultants hereby notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No legal proceedings shall be initiated on the basis of the above
Supplementary item(s) must be resurveyed and approved by the Repairer before final approval from Insurance Company is subject to final approval from Insurance Company