

Z001

NC

Khonchne

REG NO.:

GBH 1185 C

MAKE/MODEL: TOYOTA DYNA

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

The second secon	
DESCRIPTION	
LIST ITEMS	
Rear tailgate	
Rear tailgate lower pan	el
Rear tailgate lower stopper rubbers	
Rear tailgate lower stopper brackets	
Rear taillamps	305-10
Rear taillamp panels	107.10
	el
Rear exhaust pipe	415:10
Rear exhaust mounting	
Front wiper panel	
Front headlamps	
Front panel	
Front panel "DYNA" stic	ker
Front grille	
Front grille clip set	
Front grille logo	
Front bumper	
Front bumper brackets	
Front chassis crossmem	ber
	Rear tailgate Rear tailgate lower pan Rear tailgate lower stop Rear tailgate lower stop Rear tailgate lower stop Rear tailgate "TOYOTA" Rear taillamps Rear taillamp panels Rear number plate pan Rear exhaust pipe Rear exhaust mounting Front wiper panel Front headlamps Front panel Front grille Front grille clip set Front grille logo Front bumper Front bumper

PAGE 1 OF 2

75 . + B:093.74* 75 % 30 - + 80.4

1,049 ==

LIS\$ 8,000