

ASS. REC. BY:

REF: CS/INC19016431/Rlv324

Special Instruction:

Survey: RASU

ASSIGNMENT (Office)

From (Person): Annie Koh

of INC

Date/Time: 9/18/2019 17/11/19

Estimated Cost:

Bill to:

OD / IT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKC 878M

Insured:

FBG 1984T

at Workshop m/s

Indente Automobile

Tel:

6475 2168. 86933065

of

30 lang kee Road #01-02

Policy No:

Claim No:

MT/106 2510-001

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9/9/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10/31/2019 17/11/19

Person Contacted:

Joseph

Vehicle IN

OUT

Date/Time	Action/Instruction	Valued
	SKC 878M - (13/ATU) 3017552/Rep3g2	Don: 10/11/19
	FBG 1984T - X.	
20/11/19	@ 1155am Joseph said Vehicle still under repairing	
29/11/19	Final fig \$ 23,482 confirmed by email (Ref 21,267-TI, 4819)	

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 17 September 2019 11:43 AM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Subject: RE: TP CASES FARMED OUT TO LKK ON 17/09/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Tuesday, 17 September 2019 9:48 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 17/09/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
----	-----	-----------	---------	---------------	------------------	------------------	-------------	--------	-----	--------------------

1	Quek Swee Keng	MT/1062704-001	SHC7550Y	DING AUTOMOTIVE PTE LTD	31 CORPORATION ROAD SINGAPORE 649825	vadivelan mohan / 96891857		FBK5883D	16/9/19	
2	Cyndie Yong	MT/1062707-001	SHB4588P	DING AUTOMOTIVE PTE LTD	31 CORPORATION ROAD SINGAPORE 649825	vadivelan mohan / 96891857		GZ4035D	16/9/19	avoid lunch time 12-1pm OWNER WANT VEH TO BE SURVEYED AT 10AM.
3	Jared Liu	MT/1053631-001	SLK9697E	EUROKARS SERVICES PTE LTD	27A TANJONG PENJURU SINGAPORE 609042	samuel / 63310697	10:00-12:00	SMD1685S	6/7/19	
4	David Phua	MT/1062351-002	GBB3166B	MILLION AUTO SERVICE	4 PENJURU PLACE #01-12 2.8 PENJURU TECH HUB	Ms Chong / 62649091	10:00-12:00	SGU2459D	12/9/19	82285020
5	Alice Low	MT/1062478-001	SLL7112J	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	KALA / 65137748	10:00-12:00	GBJ4486D	14/9/19	

6	Jared Liu	MT/1062601- 001	SLJ2693S	PEGASUS ENGINEERING & TRADING PTE LTD	74 KIAN TECK ROAD SINGAPORE 628800	chern /	SGT4453L	14/9/19	
7	Serene Lim	MT/1062510- 001	SKC378M	TRIDENTE AUTOMOBILI PTE LTD	30 LENG KEE ROAD, UNIT 01-02	JOSEPH TEE / 64752168	FBG1984T	9/9/19	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg

income
more different



Veron Chen (LKKAUTO)

From: Tee Yong Seng Joseph <joseph.tee@tridenteautomobili.com.sg>
Sent: Monday, 14 October 2019 4:07 PM
To: Veron Chen (LKKAUTO)
Subject: RE: SKC 878M-DOA: 9/9/2019

Hi Veron,

We will order the parts now,
And we received the Email the case will be in charge by NTUC in-house surveyor?

RE: 3rd party claim for SKC878M againsts FBG1984T

Lim Serene (MT) <lim.serene@income.com.sg>

Sent: Mon 10/14/2019 9:40 AM

To: Tee Yong Seng Joseph

"WITHOUT PREJUDICE"

Dear Joseph

Liability is clear for your client and you can direct settle with us after you finalised Cost of Repair with our in-house surveyor.

Please note that LOU/LOR is strictly to our surveyor's recommendation on the duration of repairs, Saturdays included.

When the repair/claim is complete, kindly forward all your invoice, bill and receipt to mtrd@income.com.sg, quoting our reference for the OIC to compute your claim.

We will follow up with a letter of offer upon receipt of your final repair bill and other supporting documents on the quantum.

Thank you.

Serene Lim
Senior Claims Executive
Motor Insurance
T +65 6430 7926
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

in with you

Best Regards,



Joseph Tee
Service Advisor
Tridente Automobili Pte Ltd
30 Leng Kee Road, Unit 01-02, Singapore 159100
T(+65) 6475 2168 F(+65) 6472 2928 HP (+65) 86933065
E: joseph.tee@tridenteautomobili.com.sg

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Monday, October 7, 2019 4:29 PM
To: Tee Yong Seng Joseph
Subject: SKC 878M-DOA: 9/9/2019

Dear Joseph,

WITHOUT PREJUDICE

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Tee Yong Seng Joseph <joseph.tee@tridenteautomobili.com.sg>
Sent: Monday, 7 October 2019 5:30 PM
To: Veron Chen (LKKAuto)
Subject: RE: SKC 878M-DOA: 9/9/2019

Hi, we still not starter yet, LIABILITY NOT CLEAR

Best Regards,



Joseph Tee
Service Advisor
Tridente Automobili Pte Ltd
30 Leng Kee Road, Unit 01-02, Singapore 159100
T(+65) 6475 2168 F(+65) 6472 2928 HP (+65) 86933065
E: joseph.tee@tridenteautomobili.com.sg

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Monday, October 7, 2019 4:29 PM
To: Tee Yong Seng Joseph
Subject: SKC 878M-DOA: 9/9/2019

Dear Joseph,

WITHOUT PREJUDICE

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

wip 13761

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/09/2019 20:37
Date Of Accident	09/09/2019 13:15
Exact Location Of Accident	PIE TOWARDS CHANGI NEAR THOMSON ROAD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC878M
Insured/Policyholder	
Name Of Registered Owner	TAN MING SHENG
NRIC No	S7800479G
Email Address	MINGSHENG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97623611
Alternative Phone No	OTHERS-97623611

Vehicle Particulars

Manufacturer	MASERATI
Model	GHIBLI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI19V05411
Cover Note Number	N.A

Driver

Name of Driver	TAN MING SHENG
NRIC No	S7800479G
Date Of Birth	02/01/1978
Occupation	INDOOR
Date Of Driving Pass	17/03/1997
Driving Experience	22 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97623611
Fax Number	
Contact Number	OTHERS-97623611
Email Address	MINGSHENG@GMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: ON 9/9/19 AT ABOUT 1315HRS, I WAS DRIVING MY CAR (SKC878M) ALONG PIE TOWARDS CHANGI. WHILE ON THE EXPRESSWAY, THE TRAFFIC WAS HEAVY AND I HAD NOTICED THAT THERE WERE CONSTRUCTION WORKS GOING ON THE FIRST LANE. SUDDENLY I NOTICED THAT THE CARS INFRONT OF ME WERE ALL BRAKING QUITE HARDLY, THUS I FOLLOWED SUIT AND BRAKE ACCORDINGLY, WHEN SUDDENLY I FELT AN IMPACT THAT CAME FROM THE REAR OF MY CAR. I WAS JUST BESIDE THE THOMSON ROAD EXIT. I ALIGHTED MY CAR AND NOTICED THAT A MOTORCYCLE (FBG1984T) HAD HIT ONTO ME. I CALLED FOR POLICE VIDE E/20190909/0072 AND AMBULANCE FOR THIS ACCIDENT, WHICH SUBSEQUENTLY THIS FEMALE RIDER WAS CONVEYED TO THE HOSPITAL DUE TO HER INJURED WRIST. THE IO IN CHARGE IS SHAHRUL. I WASN'T INJURED FROM THIS ACCIDENT, I HAD NOTICED DENTS AND SCRATCHES ON MY REAR BUMPER, WHILE THE MOTORCYCLE WAS SUFFERED SOME DAMAGES THROUGHOUT THE WHOLE MOTORCYCLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBG1984T
Vehicle Make/Model/Colour	HONDA / CBF150 / BLUE
Details Of Properties	N/A
Vehicle Category	MOTORCYCLE
Name of Driver	NUR HAFIZHAH BIBI BINTE HAJI MOHAMED OMAR

NRIC/Passport Number	S9344116H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

DETAILS OF INJURED PERSON 1

Name	NUR HAFIZHAH BIBI BINTE HAJI MOHAMED OMAR
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBG1984T
Were seat belts worn?	NO
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	



**SINGAPORE
POLICE FORCE**



T/20190909/2092

1 of 3

Report No. T/20190909/2092

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/09/2019 15:02		Vide Report No.: E/20190909/0072		Station Diary No.: 87	
Informant's Particulars					
Name of Informant: TAN MING SHENG			Address: 3A STEVENS DRIVE SINGAPORE 257895		
ID Type / ID No.: NRIC NO / S7800479G			Contact No.: Home/Office: Mobile: 97623611		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 41	Date of Birth: 02/01/1978	Type of Informant: Driver		
Race: Chinese		Language:		Institution / School Name:	
Occupation: CIVIL SERVANT		Driving Licence Information: Class: 3		Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 09/09/2019 13:15	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY ALONG PIE TOWARDS CHANGI, BESIDE THOMSON ROAD EXIT				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBG1984T	Motorcycle	HONDA		Blue	Slightly Damaged	0
SKC878M	Car	MASERATI	GHIBLI	Black	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190909/2092

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

2 of 3

Report No. T/20190909/2092

CONTINUATION OF REPORT

Rider			
Name	NUR HAFIZHAH BIBI BINTE HAJI MOHAMED OMAR	ID No.	S9344116H
Related Vehicle	FBG1984T (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN MING SHENG	ID No.	S7800479G
Related Vehicle	SKC878M (Car)	Contact No.	97623611
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 9/9/19 at about 1315hrs, I was driving my car (SKC878M) along PIE towards Changi. While on the expressway, the traffic was heavy and I had noticed that there were construction works going on on the first lane. Suddenly I noticed that the cars in front me were all braking quite hardly, thus I followed suit and brake accordingly, when suddenly I felt an impact that came from the rear of my car. I was just beside the Thomson Road Exit.

I alighted my car and noticed that a motorcycle (FBG1984T) had hit onto me. I called for police vide E/20190909/0072 and ambulance for this accident, which subsequently this female rider was conveyed to the hospital due to her injured wrist. The IO in charge is Shahrul. I wasn't injured from this accident. I had noticed dents and scratches on my rear bumper, while the motorcycle was suffered some damages throughout the whole motorcycle.



**SINGAPORE
POLICE FORCE**



T/20190909/2092

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

3 of 3

Report No. T/20190909/2092

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 LIN XUETONG, TOM

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

09/09/2019 15:02

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI


Contact No.: 65476504

Classification Of Case:

SN 168

Authentication Stamp

NP168





Tridente Automobili Pte Ltd
Official Importer

Tridente Automobili Pte Ltd

30 Leng Kee Road, Unit 01-02, Singapore 159100

Tel: +65 6472 2236 Fax: +65 6472 2928

Company Reg No: 201631819D

GST Reg. No. MR-8500364-4

Quotation

Invoice Name & Address:

NTUC INCOME INSURANCE CO-OPERATIVE
INCOME CENTRE
75 BRAS BASAH ROAD,
SINGAPORE

Customer Name & Address:

Mr Tan Ming Sheng
3A Stevens Drive

Contact: 189557

Singapore 257895

Tel:

Mobile:

Email: mingsheng@gmail.com

Service advisor: Joseph Tee

Contact	Document Number	Date & Tax Point	Order Number	W.I.P. No.	Job No.
N0000001	0	20/09/2019		W 13761	0
Model	Chassis No.	Reg No.	Mileage	Page	
Ghibli 3.0 SOFT V6 2WD 330HP M	ZAMSS57C001112378	SKC878M	0	1	

Description of Goods / Services	Qty.	Unit Price	Unit	Discount	Net Total	V
SVC-MECH LABOUR TO CARRY OUT ACCIDENT REPAIR	1.00	19,800.00	6600	0.00%	19,800.00	S ✓
SVC-MECH SPRAY PAINT 4 PANELS AND 3 INNER PANEL	1.00	9,100.00	5200	0.00%	9,100.00	S ✓
SUN Sundry items	300.00	1.00	150	0.00%	300.00	S ✓
SVC-MECH LABOUR TO CHECK AND CLEAR FAULTS AFTER ACCIDENT REPAIR	1.00	1,200.00		0.00%	1,200.00	S ✓
Subtotal:					30,400.00	
FULL OPT M157 REAR BUMPER	1.00	3,021.00	EACH	0.00%	3,021.00	S ✓
REAR BUMPER SHOCK ABSORBER	1.00	160.00	EACH	0.00%	160.00	S ✓
RH BRACKET UNDER REAR BACKLI	1.00	60.00	EACH	0.00%	60.00	S ✓
UPPER CENTRAL BRACKET	1.00	150.00	EACH	0.00%	150.00	S ✓
LH BRACKET UNDER REAR BACKLI	1.00	60.00	EACH	0.00%	60.00	S ✓
GASKET	6.00	9.00	EACH	0.00%	54.00	S ✓
R.H. BUMPER MOUNTING BRACKET	1.00	98.00	EACH	0.00%	98.00	S ✓
L.H. BUMPER MOUNTING BRACKET	1.00	98.00	EACH	0.00%	98.00	S ✓
SPECIAL SCREW	6.00	5.00	EACH	0.00%	30.00	S ✓
SCREW	2.00	6.00	EACH	0.00%	12.00	S ✓
REAR BUMPER LH LOWER MOULDIN	1.00	600.00	EACH	0.00%	600.00	S ✓
FIXING BUTTON	7.00	5.00	EACH	0.00%	35.00	S ✓
CPL CENTRAL LOWER MOULDING	1.00	550.00	EACH	0.00%	550.00	S ✓
REAR BUMPER RH 'O' TR MOULDIN	1.00	550.00	EACH	0.00%	550.00	S ✓
SCREW	4.00	5.00	EACH	0.00%	20.00	S ✓
BRACKET	2.00	30.00	EACH	0.00%	60.00	S ✓
SCREW	2.00	5.00	EACH	0.00%	10.00	S ✓
RIVET	10.00	5.00	EACH	0.00%	50.00	S ✓
NUTSERTS	4.00	6.00	EACH	0.00%	24.00	S ✓
Subtotal:					5,642.00	
TRUNK LOCK	1.00	150.00	EACH	0.00%	150.00	S ✓
CLOSING STRIKER	1.00	35.00	EACH	0.00%	35.00	S ✓
SCREW	2.00	40.00	EACH	0.00%	80.00	S ✓

The estimate is only valid for 7 days from the date indicated

V	Rate	Service/Goods	GST



Tridente Automobili Pte Ltd
Official Importer

Tridente Automobili Pte Ltd

30 Leng Kee Road, Unit 01-02, Singapore 159100
Tel: +65 6472 2236 Fax: +65 6472 2928
Company Reg No: 201631819D
GST Reg. No. MR-8500364-4

Quotation

Invoice Name & Address:

NTUC INCOME INSURANCE CO-OPERATIVE
INCOME CENTRE
75 BRAS BASAH ROAD,
SINGAPORE

Contact: 189557

Customer Name & Address:

Mr Tan Ming Sheng
3A Stevens Drive

Singapore 257895
Tel:
Mobile:
Email: mingsheng@gmail.com

Service advisor: Joseph Tee

Contact	Document Number	Date & Tax Point	Order Number	W.L.P. No.	Job No.
N0000001	0	20/09/2019		W 13761	0
Model	Chassis No.	Reg No.	Mileage	Page	
Ghibli 3.0 SOFT V6 2WD 330HP M	ZAMSS57C001112378	SKC878M	0	2	

Description of Goods / Services	Qty.	Unit Price	Unit	Discount	Net Total	V
SCREW <i>see - ✓</i>	2.00	40.00	EACH	0.00%	80.00	S
Subtotal:					345.00	
CPL REAR LID <i>51 ✓</i>	1.00	2,998.00	EACH	0.00%	2,998.00	S
SCREW <i>see - ✓</i>	8.00	11.00	EACH	0.00%	88.00	S
BOOT LID COVER <i>X ✓</i>	1.00	300.00	EACH	0.00%	300.00	S
SMALL BLOCK <i>see - ✓</i>	2.00	10.00	EACH	0.00%	20.00	S
FIXING BUTTON <i>see - ✓</i>	9.00	15.00	EACH	0.00%	135.00	S
RUBBER FOR REAR LICENSE PLAT <i>see - ✓</i>	1.00	8.00	EACH	0.00%	8.00	S
RIVET <i>see - ✓</i>	6.00	10.00	EACH	0.00%	60.00	S
PLUG <i>see - ✓</i>	2.00	8.00	EACH	0.00%	16.00	S
PLUG <i>see - ✓ 40.80</i>	10.00	4.08	EACH	0.00%	17.10	S
WATER SHIELD LUGGAGE COMPART <i>see - ✓</i>	1.00	322.00	EACH	0.00%	322.00	S
Subtotal:					3,964.10	
BLACK COVER <i>? X see</i>	1.00	330.40	EACH	0.00%	330.40	S
LUGGAGE C. PROTECTION COVER <i>see - ✓</i>	6.00	8.20	EACH	0.00%	49.20	S
REAR BUMPER RH LOWER MOULDIN <i>? X see</i>	1.00	323.31	EACH	0.00%	323.31	S
PIN <i>see - ✓</i>	2.00	8.00	EACH	0.00%	16.00	S
"GHIBLI" EMBLEM <i>see - ✓</i>	1.00	160.00	EACH	0.00%	160.00	S
R.H. REAR LIGHT FIXED SIDE <i>X X see</i>	1.00	605.00	EACH	0.00%	605.00	S
Subtotal:					1,483.91	
REAR AERODYNAMIC BOTTOM ASSE <i>do ✓</i>	1.00	224.00	EACH	0.00%	224.00	S
REAR CROSS MEMBER ASSEMBLY <i>repair ✓</i>	1.00	490.00	EACH	0.00%	490.00	S
REAR REINFORCEMENT <i>? by ✓</i>	1.00	1,015.00	EACH	0.00%	1,015.00	S
RADIAL PARKING SENSOR <i>modis - ✓</i>	1.00	262.00	EACH	0.00%	262.00	S
SILICON RING <i>see - ✓</i>	4.00	16.50	EACH	0.00%	66.00	S
COMPLETE SPARE WHEEL STEP <i>X X see</i>	1.00	784.00	EACH	0.00%	784.00	S
Subtotal:					2,841.00	

The estimate is only valid for 7 days from the date indicated

V	Rate	Service/Goods	GST



Tridente Automobili Pte Ltd
Official Importer

Tridente Automobili Pte Ltd
30 Leng Kee Road, Unit 01-02, Singapore 159100
Tel: +65 6472 2236 Fax: +65 6472 2928
Company Reg No. 201631819D
GST Reg. No. MR-8500364-4

Quotation

Invoice Name & Address:

NTUC INCOME INSURANCE CO-OPERATIVE
INCOME CENTRE
75 BRAS BASAH ROAD,
SINGAPORE

Contact: 189557

Customer Name & Address:

Mr Tan Ming Sheng
3A Stevens Drive

Singapore 257895
Tel:
Mobile:
Email: mingsheng@gmail.com

Service advisor: Joseph Tee

Contact	Document Number	Date & Tax Point	Order Number	W.I.P. No.	Job No.
N0000001	0	20/09/2019		W 13761	0
Model	Chassis No.	Reg No.	Mileage	Page	
Ghibli 3.0 SOFT V6 2WD 330HP M	ZAMSS57C001112378	SKC878M	0	3	

Description of Goods / Services	Qty.	Unit Price	Unit	Discount	Net Total	V
NOTES TP Claim SKC878M Against FBG1984T DOA:9SEP2019 <i>Rasul</i> <i>Hp 90010068</i> <i>10 days</i> <i>20/09/19 @ 1655</i> <i>Reservy before partet</i> <i>23/9/19</i> Ltd shall immediately notify the Reparer of the following: • To ensure immediate parts pricing • To display damaged parts during recovery. • Third party repairs are not to be undertaken • No stage modifications shall be made • Supplementary repair work is subject to prior approval from insurance company Acknowledged by Reparer Signature: Date:	0.00	0.00		0.00%		0
					44,749.71	

The estimate is only valid for 7 days from the date indicated

V	Rate	Service/Goods	GST	Net	
S	7.00	44676.01	3127.32	GST	44,676.01
				Total	3,127.32
				Paid	47,803.35
				Owing	0.00
					47,803.35



Tridente Automobili Pte Ltd
Official Importer

Tridente Automobili Pte Ltd
30 Leng Kee Road, Unit 01-02, Singapore 159100
Tel: +65 6472 2236 Fax: +65 6472 2928
Company Reg No: 201631819D
GST Reg. No. MR-8500364-4

Pro-Forma Invoice

Invoice Name & Address:

Mr Tan Ming Sheng
3A Stevens Drive

Customer Name & Address:

Mr Tan Ming Sheng
3A Stevens Drive

Singapore 257895
Contact:

Singapore 257895
Tel:
Mobile:
Email: mingsheng@gmail.com

Service advisor: Joseph Tee

Contact	Document Number	Date & Tax Point	Order Number	W.I.P. No.	Job No.
C0000002	900000	27/11/2019		W 13761	3335
Model	Chassis No.	Reg No.	Mileage	Page	
Ghibli 3.0 SOFT V6 2WD 330HP M	ZAMSS57C001112378	SKC878M	58041	1	

Description of Goods / Services	Qty.	Unit Price	Unit	Discount	Net Total	V
M673004365 FULL OPT M157 REAR BUMPER	1.00	3,021.00	EACH	0.00%	3,021.00	S
M670033709 REAR BUMPER SHOCK ABSORBER	1.00	160.00	EACH	0.00%	160.00	S
M670004471 UPPER CENTRAL BRACKET	1.00	150.00	EACH	0.00%	150.00	S
M670034505 SPECIAL SCREW	6.00	5.00	EACH	0.00%	30.00	S
M675000326 SCREW	2.00	6.00	EACH	0.00%	12.00	S
M670017199 REAR BUMPER LH LOWER MOULDIN	1.00	600.00	EACH	0.00%	600.00	S
M670014562 FIXING BUTTON.	7.00	5.00	EACH	0.00%	35.00	S
M670017197 CPL CENTRAL LOWER MOULDING	1.00	550.00	EACH	0.00%	550.00	S
M675000326 SCREW	4.00	5.00	EACH	0.00%	20.00	S
M14368974 BRACKET	2.00	30.00	EACH	0.00%	60.00	S
M675000326 SCREW	2.00	5.00	EACH	0.00%	10.00	S
M675000323 RIVET	10.00	5.00	EACH	0.00%	50.00	S
M675000715 NUTSERTS	4.00	6.00	EACH	0.00%	24.00	S
Subtotal:					4,722.00	
M675000422 SCREW	2.00	40.00	EACH	0.00%	80.00	S
Subtotal:					80.00	
M673004651 CPL REAR LID	1.00	2,998.00	EACH	0.00%	2,998.00	S
M675000113 SCREW	8.00	11.00	EACH	0.00%	88.00	S
M675000287 SMALL BLOCK	2.00	10.00	EACH	0.00%	20.00	S
M670017293 FIXING BUTTON	9.00	15.00	EACH	0.00%	135.00	S
M675000516 RUBBER FOR REAR LICENSE PLAT	1.00	8.00	EACH	0.00%	8.00	S
M670005149 RIVET	6.00	10.00	EACH	0.00%	60.00	S
M675000528 PLUG	2.00	8.00	EACH	0.00%	16.00	S
M675000529 PLUG	10.00	4.08	EACH	0.00%	40.80	S
M670033871 WATER SHIELD LUGGAGE COMPART	1.00	322.00	EACH	0.00%	322.00	S
Subtotal:					3,687.80	
M675000294 PIN	2.00	8.00	EACH	0.00%	16.00	S
M670008315 "GHIBLI" EMBLEM	1.00	160.00	EACH	0.00%	160.00	S

V	Rate	Service/Goods	GST



Tridente Automobili Pte Ltd
Official Importer

Tridente Automobili Pte Ltd
30 Leng Kee Road, Unit 01-02, Singapore 159100
Tel: +65 6472 2236 Fax: +65 6472 2928
Company Reg No: 201631819D
GST Reg. No. MR-8500364-4

Pro-Forma Invoice

Invoice Name & Address:

Mr Tan Ming Sheng
3A Stevens Drive

Customer Name & Address:

Mr Tan Ming Sheng
3A Stevens Drive

Singapore 257895
Contact:

Singapore 257895
Tel:
Mobile:
Email: mingsheng@gmail.com

Service advisor: Joseph Tee

Contact	Document Number	Date & Tax Point	Order Number	W.I.P. No.	Job No.
C0000002	900000	27/11/2019		W 13761	3335
Model	Chassis No.	Reg No.	Mileage	Page	
Ghibli 3.0 SOFT V6 2WD 330HP M	ZAMSS57C001112378	SKC878M	58041	2	

Description of Goods / Services	Qty.	Unit Price	Unit	Discount	Net Total	V
M673005736 LUGGAGE C. PROTECTION COVER	4.00	8.20	EACH	0.00%	32.80	S
M673005736 LUGGAGE C. PROTECTION COVER	2.00	8.20	EACH	0.00%	16.40	S
Subtotal:					225.20	
M670034348 REAR AERODYNAMIC BOTTOM ASSE	1.00	224.00	EACH	0.00%	224.00	S
M673009299 REAR REINFORCEMENT	1.00	1,015.00	EACH	0.00%	1,015.00	S
M675000039 RADIAL PARKING SENSOR	1.00	262.00	EACH	0.00%	262.00	S
M675000044 SILICON RING	4.00	16.50	EACH	0.00%	66.00	S
Subtotal:					1,567.00	
SUN Sundry items	150.00	1.00		0.00%	150.00	S
SVC-MECH LABOUR TO CHECK AND CLEAR FAULTS AFTER ACCIDENT REPAIR	6.00	200.00		0.00%	1,200.00	S
SUB LABOUR TO CARRY OUT ACCIDENT REPAIR	1.00	6,600.00		0.00%	6,600.00	S
SUB SPRAY PAINT 4 PANELS AND 1 INNER PANEL	1.00	5,200.00		0.00%	5,200.00	S
SUB REAR NUMBER PLATE SKC878M	1.00	50.00		0.00%	50.00	S
NOTES SUB:3210 VIN:112378 DO:31865						
NOTES TP Claim SKC878M Against FBG1984T	0.00	0.00		0.00%		O
NOTES DOA:9SEP2019						
NOTES Reference number: MT/1062510 -001						
NOTES Claim Officer: Serene Lim						
NOTES SE:SG0007760	0.00	0.00		0.00%		O
NOTES WW0370:No Open Campaigns for this vehicle						
Subtotal:					13,200.00	

V	Rate	Service/Goods	GST	Net	
S	7.00	23482.00	1643.74	GST	23,482.00
				Total	1,643.74
				Paid	25,125.75
				Owing	0.00
					25,125.75



Tridente Automobili Pte Ltd
Official Importer

Tridente Automobili Pte Ltd
30 Leng Kee Road, Unit 01-02, Singapore 159100
Tel: +65 6472 2236 Fax: +65 6472 2928
Company Reg No: 201631819D
GST Reg. No. M1-8500364-4

Quotation

Invoice Name & Address:

NTUC INCOME INSURANCE CO-OPERATIVE
INCOME CENTRE
75 BRAS BASAH ROAD,
SINGAPORE

189557

Contact:

Customer Name & Address:

Mr Tan Ming Sheng
3A Stevens Drive

Singapore 257895

Tel:

Mobile:

Email: mingsheng@gmail.com

Service advisor: Joseph Tee

Contact	Document Number	Date & Tax Point	Order Number	W.I.P. No.	Job No.
N0000001	0	20/09/2019		W 13761	0
Model	Chassis No.	Reg No.	Mileage	Page	
Ghibli 3.0 SOFT V6 2WD 330HP M	ZAM5557C001112378	SKC878M	0	1	

Description of Goods / Services	Qty.	Unit Price	Unit	Discount	Net Total	V
SVC-MECH LABOUR TO CARRY OUT ACCIDENT REPAIR	1.00	19,800.00	6600	0.00%	19,800.00	S
SVC-MECH SPRAY PAINT 4 PANELS AND 3 INNER PANEL	1.00	9,100.00	5200	0.00%	9,100.00	S
SUN Sundry items	300.00	1.00	150	0.00%	300.00	S
SVC-MECH LABOUR TO CHECK AND CLEAR FAULTS AFTER ACCIDENT REPAIR	1.00	1,200.00		0.00%	1,200.00	S
Subtotal:					30,400.00	13200
673 004 365 FULL OPT M157 REAR BUMPER de 7 de	1.00	3,021.00	EACH	0.00%	3,021.00	S
* 620 333 209 REAR BUMPER SHOCK ABSORBER	1.00	160.00	EACH	0.00%	160.00	S
RH BRACKET UNDER REAR BACKLI	1.00	60.00	EACH	0.00%	60.00	S
* 620 004 171 UPPER CENTRAL BRACKET ? de ?	1.00	150.00	EACH	0.00%	150.00	S
LH BRACKET UNDER REAR BACKLI	1.00	60.00	EACH	0.00%	60.00	S
GASKET ?	6.00	9.00	EACH	0.00%	54.00	S
R.H. BUMPER MOUNTING BRACKET ?	1.00	98.00	EACH	0.00%	98.00	S
L.H. BUMPER MOUNTING BRACKET ?	1.00	98.00	EACH	0.00%	98.00	S
670 034 505 SPECIAL SCREW re	6.00	5.00	EACH	0.00%	30.00	S
675 000 326 SCREW re	2.00	6.00	EACH	0.00%	12.00	S
670 017 199 REAR BUMPER LH LOWER MOULDIN cl	1.00	600.00	EACH	0.00%	600.00	S
670 014 562 FIXING BUTTON. re	7.00	5.00	EACH	0.00%	35.00	S
670 017 197 CPL CENTRAL LOWER MOULDING sel	1.00	550.00	EACH	0.00%	550.00	S
REAR BUMPER RH LOWER MOULDIN X	1.00	550.00	EACH	0.00%	550.00	S
675 000 326 SCREW re	4.00	5.00	EACH	0.00%	20.00	S
114 268 974 BRACKET re	2.00	30.00	EACH	0.00%	60.00	S
675 000 326 SCREW re	2.00	5.00	EACH	0.00%	10.00	S
675 000 323 RIVET re	10.00	5.00	EACH	0.00%	50.00	S
675 000 215 NUTSERTS re	4.00	6.00	EACH	0.00%	24.00	S
Subtotal:					5,642.00	1722
TRUNK LOCK	1.00	150.00	EACH	0.00%	150.00	S
CLOSING STRIKER	1.00	35.00	EACH	0.00%	35.00	S
SCREW	2.00	40.00	EACH	0.00%	80.00	S

The estimate is only valid for 7 days from the date indicated

V	Rate	Service/Goods	GST



Tridente Automobili Pte Ltd
Official Importer

Tridente Automobili Pte Ltd
30 Leng Kee Road, Unit 01-02, Singapore 159100
Tel: +65 6472 2236 Fax: +65 6472 2928
Company Reg No: 201631819D
GST Reg. No. MR-8500364-4

Quotation

Invoice Name & Address:

NTUC INCOME INSURANCE CO-OPERATIVE
INCOME CENTRE
75 BRAS BASAH ROAD,
SINGAPORE

Contact:

189557

Customer Name & Address:

Mr Tan Ming Sheng
3A Stevens Drive

Singapore 257895

Tel:

Mobile:

Email: mingsheng@gmail.com

Service advisor: Joseph Tee

Contact	Document Number	Date & Tax Point	Order Number	W.I.P. No.	Job No.
N0000001	0	20/09/2019		W 13761	0
Model	Chassis No.	Reg No.	Mileage	Page	
Ghibli 3.0 SOFT V6 2WD 330HP M	ZAMSS57C001112378	SKC878M	0	2	

Description of Goods / Services	Qty.	Unit Price	Unit	Discount	Net Total	V
675 000 422 SCREW <i>rec</i>	2.00	40.00	EACH	0.00%	80.00	S
Subtotal:					-345.00	
673 004 651 CPL REAR LID <i>bt</i>	1.00	2,998.00	EACH	0.00%	2,998.00	S
676 000 112 SCREW <i>rec</i>	8.00	11.00	EACH	0.00%	88.00	S
BOOT LID COVER <i>X</i>	1.00	300.00	EACH	0.00%	300.00	S
SMALL BLOCK <i>rec</i>	2.00	10.00	EACH	0.00%	20.00	S
FIXING BUTTON <i>rec</i>	9.00	15.00	EACH	0.00%	135.00	S
RUBBER FOR REAR LICENSE PLAT <i>rec</i>	1.00	8.00	EACH	0.00%	8.00	S
RIVET <i>rec</i>	6.00	10.00	EACH	0.00%	60.00	S
PLUG <i>rec</i>	2.00	8.00	EACH	0.00%	16.00	S
PLUG <i>rec</i>	10.00	4.08	EACH	0.00%	40.80	S
WATER SHIELD LUGGAGE COMPART <i>rec</i>	1.00	322.00	EACH	0.00%	322.00	S
Subtotal:					-3,964.10	
BLACK COVER ?	1.00	330.40	EACH	0.00%	330.40	S
LUGGAGE C. PROTECTION COVER <i>rec</i>	6.00	8.20	EACH	0.00%	49.20	S
REAR BUMPER RH LOWER MOULDIN ?	1.00	323.31	EACH	0.00%	323.31	S
PIN <i>rec</i>	2.00	8.00	EACH	0.00%	16.00	S
"GHIBLI" EMBLEM <i>rec</i>	1.00	160.00	EACH	0.00%	160.00	S
R.H. REAR LIGHT FIXED SIDE <i>X</i>	1.00	605.00	EACH	0.00%	605.00	S
Subtotal:					-1,483.91	
REAR AERODYNAMIC BOTTOM ASSE <i>da</i>	1.00	224.00	EACH	0.00%	224.00	S
REAR CROSS MEMBER ASSEMBLY <i>repair bt</i>	1.00	490.00	EACH	0.00%	490.00	S
REAR REINFORCEMENT <i>bt</i>	1.00	1,015.00	EACH	0.00%	1,015.00	S
RADIAL PARKING SENSOR <i>modis</i>	1.00	262.00	EACH	0.00%	262.00	S
SILICON RING <i>rec</i>	4.00	16.50	EACH	0.00%	66.00	S
COMPLETE SPARE WHEEL STEP <i>X</i>	1.00	784.00	EACH	0.00%	784.00	S
Subtotal:					-2,841.00	

The estimate is only valid for 7 days from the date indicated

V	Rate	Service/Goods	GST



Tridente Automobili Pte Ltd
Official Importer

Tridente Automobili Pte Ltd
30 Leng Kee Road, Unit 01-02, Singapore 159100
Tel: +65 6472 2236 Fax: +65 6472 2928
Company Reg No: 201631819D
GST Reg. No. MR-8500364-4

Quotation

Invoice Name & Address:
NTUC INCOME INSURANCE CO-OPERATIVE
INCOME CENTRE
75 BRAS BASAH ROAD,
SINGAPORE

Contact: 189557

Customer Name & Address:

Mr Tan Ming Sheng
3A Stevens Drive

Singapore 257895
Tel:
Mobile:
Email: mingsheng@gmail.com

Service advisor: Joseph Tee

Contact	Document Number	Date & Tax Point	Order Number	W.I.P. No.	Job No.
N0000001	0	20/09/2019		W 13761	0
Model	Chassis No.	Reg No.	Mileage	Page	
Ghibli 3.0 SOFT V6 2WD 330HP M	ZAM5557C001112378	SKC878M	0	3	

Description of Goods / Services	Qty.	Unit Price	Unit	Discount	Net Total	V
NOTES TP Claim SKC878M Against FBG1984T DOA:9SEP2019	0.00	0.00		0.00%		0
<i>Rasul</i> <i>Hp 90010068</i> <i>10 days</i> <i>20/09/19 @ 1655</i> <i>Reserve before part</i> <i>Email: rasul@1kkauto.com</i> <i>Recy Steve</i> <i>13/11/19</i> <i>Total: \$23482.00</i>						

The estimate is only valid for 7 days from the date indicated

V	Rate	Service/Goods	GST	Net	
S	7.00	44676.01	3127.32	GST	44,676.01
				Total	3,127.32
				Paid	47,803.35
				Owing	0.00
					47,803.35

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 29 November 2019 1:57 PM
To: Tee Yong Seng Joseph; Rasul (LKKAUTO); SUR
Cc: Santhanasamy
Subject: RE: 3rd party claim for SKC878M againsts FBG1984T

Dear Joseph,

WITHOUT PREJUDICE

Confirmed amount \$23,482 @ 10 working days.

Kindly send Final invoice and all supporting documents directly to NTUC INCOME

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tee Yong Seng Joseph <joseph.tee@tridentautomobili.com.sg>
Sent: Wednesday, 27 November 2019 6:57 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Santhanasamy <Santhanasamy@tridentautomobili.com.sg>
Subject: RE: 3rd party claim for SKC878M againsts FBG1984T

Hi Mr Rasul,

Attach the pro-forma invoice and survey quotation for finalize.
Please take note that we have add on \$50 for rear number plate in this invoice.
I need to close it by this week.

Thanks

Best Regards,



Joseph Tee
Service Advisor
Tridente Automobili Pte Ltd
30 Leng Kee Road, Unit 01-02, Singapore 159100

T(+65) 6475 2168 F(+65) 6472 2928 HP (+65) 86933065

E: joseph.tee@tridenteautomobili.com.sg

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]
Sent: Monday, September 23, 2019 8:48 AM
To: Tee Yong Seng Joseph
Subject: RE: 3rd party claim for SKC878M againts FBG1984T

Hi Joseph,

Received with thanks


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

From: Tee Yong Seng Joseph [<mailto:joseph.tee@tridenteautomobili.com.sg>]
Sent: Friday, 20 September, 2019 6:32 PM
To: Rasul (LKKAuto)
Subject: FW: 3rd party claim for SKC878M againts FBG1984T

Hi Rasul,

Attach as per your request

Best Regards,



Joseph Tee

Service Advisor

Tridente Automobili Pte Ltd

30 Leng Kee Road, Unit 01-02, Singapore 159100

T(+65) 6475 2168 F(+65) 6472 2928 HP (+65) 86933065

E: joseph.tee@tridenteautomobili.com.sg

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Tee Yong Seng Joseph
Sent: Saturday, September 14, 2019 3:16 PM
To: 'MTSurvey'; MTCL@income.com.sg

Cc: Santhanasamy

Subject: 3rd party claim for SKC878M againts FBG1984T

Hi Sir/Mdm,

Please refer to the attached quotation for the 3rd party claim.

3rd party claim for SKC878M againts FBG1984T.

DOA: 9SEP2019 13:15

Please let us know the survey time so we can arrange client come in.

Please do not hesitate to contact me for further information.

Best Regards,



Joseph Tee

Service Advisor

Tridente Automobili Pte Ltd

30 Leng Kee Road, Unit 01-02, Singapore 159100

T(+65) 6475 2168 F(+65) 6472 2928 HP (+65) 86933065

E: joseph.tee@tridenteautomobili.com.sg

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19016431/R1vd3e2

73 BRAS BASAH ROAD

Date: 06-12-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : SERENE LIM

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBG 1984T	Veh. Inspected	SKC 878M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1062510-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	17/09/2019

2. Vehicle Particulars & Condition

Make & Model	MASERATI GIBLI	c.c	2979
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZAMSS57C001112378	Colour	BLACK
Odometer	57348 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	PIRELLI	6 mm
L/H Front Tyre	235/50 R18	PIRELLI	6 mm
R/H Rear Tyre	235/50 R18	PIRELLI	6 mm
L/H Rear Tyre	235/50 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/09/2019	Inspect Date / Time	20/09/2019 (04:22 PM)
Survey held at	TRIDENTE AUTOMOBILI PL 30 LENG KEE ROAD SINGAPORE 159100		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 878M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COMPLETE SPARE WHEEL STEP (SN)	SERVICEABLE	784.00	-
1	SUNDRY ITEMS (SN)	NECESSARY	300.00	150.00
1	FULL OPT M157 REAR BUMPER (SN)	DEFORMED	3,021.00	3,021.00
1	REAR BUMPER SHOCK ABSORBER (SN)	CRACKED	160.00	160.00
1	RH BRACKET UNDER REAR BACKLI (SN)	SERVICEABLE	60.00	-
1	UPPER CENTRAL BRACKET (SN)	FABRICATED	150.00	150.00
1	LH BRACKET UNDER REAR BACKLI (SN)	SERVICEABLE	60.00	-
6	GASKET @\$9.00 (SN)	NOT NECESSARY	54.00	-
1	R.H. BUMPER MOUNTING BRACKET (SN)	SERVICEABLE	98.00	-
1	L.H. BUMPER MOUNTING BRACKET (SN)	SERVICEABLE	98.00	-
6	SPECIAL SCREW @\$5.00 (SN)	NECESSARY	30.00	30.00
2	SCREW @\$6.00 (SN)	NECESSARY	12.00	12.00
1	REAR BUMPER LH LOWER MOULDIN (SN)	CUT	600.00	600.00
7	FIXING BUTTON @\$5.00 (SN)	NECESSARY	35.00	35.00
1	CPL CENTRAL LOWER MOULDING (SN)	SCRATCHED	550.00	550.00
1	REAR BUMPER RH LOWER MOULDIN (SN)	SERVICEABLE	550.00	-
4	SCREW @\$5.00 (SN)	SERVICEABLE	20.00	20.00
2	BRACKET @\$30.00 (SN)	NECESSARY	60.00	60.00
2	SCREW @\$5.00 (SN)	NECESSARY	10.00	10.00
10	RIVET @\$5.00 (SN)	NECESSARY	50.00	50.00
4	NUTSERTS @\$6.00 (SN)	NECESSARY	24.00	24.00
1	TRUNK LOCK (SN)	SERVICEABLE	150.00	-
1	CLOSING STRIKER (SN)	SERVICEABLE	35.00	-
2	SCREW @\$40.00 (SN)	REPEATED	80.00	-
2	SCREW @\$40.00 (SN)	NECESSARY	80.00	80.00
1	CPL REAR LID (SN)	BENT	2,998.00	2,998.00
8	SCREW @\$11.00 (SN)	NECESSARY	88.00	88.00
1	BOOT LID COVER (SN)	SERVICEABLE	300.00	-
2	SMALL BLOCK @\$10.00 (SN)	NECESSARY	20.00	20.00
9	FIXING BUTTON @\$15.00 (SN)	NECESSARY	135.00	135.00
1	RUBBER FOR REAR LICENSE PLAT (SN)	NECESSARY	8.00	8.00

Report Ref No. CS/INC19016431/R1vd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
6	RIVET @\$10.00 (SN)	NECESSARY	60.00	60.00
2	PLUG @\$8.00 (SN)	NECESSARY	16.00	16.00
10	PLUG @\$4.08 (SN)	NECESSARY	40.80	40.80
1	WATER SHIELD LUGGAGE COMPART (SN)	NECESSARY	322.00	322.00
1	BLACK COVER (SN)	SERVICEABLE	330.40	-
6	LUGGAGE C.PROTECTION COVER @\$8.20 (SN)	NECESSARY	49.20	49.20
1	REAR BUMPER RH LOWER MOULDIN (SN)	SERVICEABLE	323.31	-
2	PIN @\$8.00 (SN)	NECESSARY	16.00	16.00
1	"GHIBLI" EMBLEM (SN)	NECESSARY	160.00	160.00
1	R.H. REAR LIGHT FIXED SIDE (SN)	SERVICEABLE	605.00	-
1	REAR AERODYNAMIC BOTTOM ASSE (SN)	DEFORMED	224.00	224.00
1	REAR CROSS MEMBER ASSEMBLY (SN)	TO REPAIR SEE LABOUR	490.00	-
1	REAR REINFORCEMENT (SN)	BENT	1,015.00	1,015.00
1	RADIAL PARKING SENSOR (SN)	DISTORTED	262.00	262.00
4	SILICON RING @\$16.50 (SN)	NECESSARY	66.00	66.00
1	REAR NUMBER PLATE SKC 878M (SN) (ADDITIONAL)	NECESSARY	50.00	50.00
			14,649.71	10,482.00
	LABOUR			
	LABOUR TO CHECK AND CLEAR FAULTS AFTER ACCIDENT REPAIR.		1,200.00	1,200.00
	LABOUR TO CARRY OUT ACCIDENT REPAIR. INCLUSIVE OF THE REPAIR OF REAR CROSS MEMBER ASSEMBLY.		19,800.00	6,600.00
	SPRAY PAINT 4 PANELS AND 3 INNER PANEL.		9,100.00	5,200.00
			30,100.00	13,000.00
	GRAND TOTAL		44,749.71	23,482.00
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			23,482.00

Report Ref No. CS/INC19016431/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.