

7/20/2019

ASS. REC. BY:

REF: CS3/FWD19016474/Hcd302

Instruction:

Assigner: Hock Ann

ASSIGNMENT (Office)

From (Person):

venessa chan

of

FWD

Date/Time:

17/9/19 @ 5:02pm

Estimated Cost:

Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JST 3683

Insured:

SQJ 2139K

at Workshop m/s

Equator Brotherhood

Tel:

6384 6939

of

25 kaki Bukit Road 4 #03-79 Synergy

Policy No:

PNP2018-00008379-01

Claim No:

12019 00026857

Sum Insured:

Excess:

Make of Veh:

D.O.A.

09/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:33am @ 18/9/19

Person Contacted:

Mr. Tan

Vehicle IN (OUT)

Date/Time	Action/Instruction
	Vehicle (X)
	JST 3683 X
	SQJ 2139K X
	Dismantle: 15/10/2019
	After repair: 18/10/2019

RECEIVED 8 0:00 2019

REG. REC. BY: H-PNN


REF: FWO

PRS

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: JST 3683
at Workshop m/s Work Equator Brotherhood
of 25 Kalia Bldg Road 4 #03-79
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: JST 3683 Yr Regn: 5/51/2018
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Yamaha LC 135 cc 134
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 16541 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: PMYUG0810J0022382
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modl: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 80/90-17
R: 90/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: PIR Rear: PIR
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. _____ mm L/Bal. _____ mm
D.O.A. 9/7/17 D.O.I. 14/10/19
Survey held at work Equator
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	* JST 3683 (PRS) car
	NON completed file
	workshop inspection person
	4 times requested workshop
	mv - 1900 hp = 90/13391 - willie
	Handler not giving
	1.8K - 2.3K All document, many reasons
	Range -> 1.8K
	Sum cover RM 5900 upon days -> 3 days
	convert to sig \$1900

Days Of Repair: 3
Resurvey No. of Trip: 0
Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Wash and ... (\$)
Survey Fee: 80
Transportation: 90
S + RS: 90
Pinsus
Others
Total: 180

Date/Time, File Pass to? ☐ : Prel. Report
Date/Time, File Return to? ☐ : Final Report

Request Feedback: PRS
Escap Date / REF: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Sep 2019 Edit Reg		18 Sep 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Choi Kein Cheng David, ID: S75038561								
Main Claimant:	-								
Vehicle Reg. No.:	JST3683	Date of Loss:	09/09/2019 00:00 - :59						
Claim Type:	TP / 1201900026857	Policy/Cover Note No.:	PNPV2018-00008379-01 (Comprehensive) Coverage: 04/07/2019 - 03/07/2020						
Vehicle Reg. No. (Insured):	SGJ2139K	Policy No. (Claimant):							
		Excess:							
Repairer:	Equator Brotherhood (KAKI BUKIT) 25 Kaki Bukit Road 4, #03 -79 Synergy @ KB, 417800 Kaki Bukit - Tel: 63846939 / h/p 90113391								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 27/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Tuesday, 17 September 2019 5:02 PM
To: admin-d@lkkauto.com; admin-a@lkkauto.com
Cc: clara.li@fwd.com; motorclaims.sg@fwd.com
Subject: ACCIDENT INVOLVING MOTOR VEHICLES NO: JST 3683 AND SGJ 2139K ON 09.09.2019 OUR CLAIM REF: 1201900026857
Attachments: 17092019160916.pdf

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen & I will upload the documents accordingly.

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Venessa Chan - SGUser

Sent: Tuesday, September 17, 2019 5:00 PM

To: 'Hui Ling'

Cc: Clara Li Zirong - SGUser; Motor Claims SG - SG Common

Subject: ACCIDENT INVOLVING MOTOR VEHICLES NO: JST 3683 AND SGJ 2139K ON 09.09.2019
OUR CLAIM REF: 1201900026857

WITHOUT PREJUDICE

Dear Sir/Madam,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s **LKK Auto Consultant Pte Ltd**, to conduct the pre-repair survey (PRS) on your client's vehicle, JST3683. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.*

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Hui Ling [<mailto:riaz@justice.com.sg>]

Sent: Tuesday, September 17, 2019 4:53 PM

To: Venessa Chan - SGUser

Cc: Clara Li Zirong - SGUser; Motor Claims SG - SG Common

Subject: RE: ACCIDENT INVOLVING MOTOR VEHICLES NO: JST 3683 AND SGJ 2139K ON 09.09.2019 OUR CLAIM REF: 1201900026857

WITHOUT PREJUDICE

Dear sirs,

We refer to your fax on even date.

On behalf of our client, we disagree your list of surveyor.

Please choose one out of the surveyor from the list below:-

1. Chang Fuh Keong, Dave
2. Ho Joo Loong, Danny
3. Dennis Yap Teck Wee
4. Michael Yap
5. Lee Kok Weng
6. Winson Goh
7. Ong Ah Keng, Kent
8. Ong Poh Meng
9. Seah Kwang Boon
10. Thor Teck Soon, David

Thanks & Best Regards,

Hailing

RIAZ LLC
Advocates and Solicitors
133 NEW BRIDGE ROAD
09-09 CHINATOWN POINT
SINGAPORE 059413
TEL : 6534-0110 FAX : 6534-0220

Disclaimer: This message is privileged and confidential and is intended solely for the named recipient. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is strictly prohibited. If this e-mail has reached you in error, please delete the e-mail immediately and inform us of the error by sending an e-mail to riaz@justice.com.sg, though internet communications cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost or infected with viruses, we have scanned this message to minimise the possibility of corruption.

From: venessa.chan@fwd.com <venessa.chan@fwd.com>

Sent: Tuesday, September 17, 2019 4:36 PM

To: riaz@justice.com.sg

Cc: clara.li@fwd.com; motorclaims.sg@fwd.com

Subject: ACCIDENT INVOLVING MOTOR VEHICLES NO: JST 3683 AND SGJ 2139K ON 09.09.2019
OUR CLAIM REF: 1201900026857

WITHOUT PREJUDICE

Dear Hui Ling,

Meanwhile, we refer to your email dated on 17.09.2019 of the PRI Notice of your client's vehicle JST3683.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.

Thank you.

Best Regards,

Venessa Chan




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Hui Ling [<mailto:riaz@justice.com.sg>]

Sent: Tuesday, 17 September, 2019 4:11 PM

To: SG Corporate Contact <contact.sg@fwd.com>; Clara Li Zirong - SGUser <clara.li@fwd.com>; Josey Loh Kah Wai - SGUser <josey.loh@fwd.com>; Lionel Tan Tian Pei - SGUser <lionel.tan@fwd.com>

Subject: ACCIDENT INVOLVING MOTOR VEHICLES NO: JST 3683 AND SGJ 2139K ON 09.09.2019

WITHOUT PREJUDICE

Dear sirs,

Please find the enclosed notice of accident for your immediate action.

Thanks & Best Regards,

Hui Ling

RIAZ LLC

Advocates and Solicitors

133 NEW BRIDGE ROAD

09-09 CHINATOWN POINT

SINGAPORE 059413

TEL : 6534-0110 FAX : 6534-0220

Disclaimer: This message is privileged and confidential and is intended solely for the named recipient. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is strictly prohibited. If this e-mail has reached you in error, please delete the e-mail immediately and inform us of the error by sending an e-mail to riaz@justice.com.sg. though internet communications cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost or infected with viruses, we have scanned this message to minimise the possibility of corruption.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT

been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

RIA Z
L.L.C
ADVOCATES AND SOLICITORS
COMMISSIONER FOR OATHS

ACRA NUMBER : 200911678H

GST REGISTRATION NUMBER : 200911678H

17/09/2019

Our Ref: JST 3683 (V) EQUATOR

Your Ref: SGJ 2139K

RIAZ QAYYUM CHARTERED ACCOUNTANT
DIRECTOR

ABDUL HALIM BIN ROSALAN CHARTERED ACCOUNTANT
ASSOCIATE

MUHD RIDHWAN ABDEL RAHMAN CHARTERED ACCOUNTANT
ASSOCIATE

TO: FWD Singapore Pte Ltd
6 Temasek Boulevard,
#18-01 Suntec Tower Four,
Singapore 038986
Attn: Motor Claims Department

BY EMAIL ONLY
contact.sg@fwd.com

NOTICE OF ACCIDENT

Dear Sir

We are instructed by our client to *notify* you of a road traffic accident on **09.09.2019** at about **0830** hours along **PIE** involving our client's vehicle registration number **JST 3683** and vehicle registration number **SGJ 2139K** driven by you or your authorized driver at the material time. A copy of Singapore accident statement / traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

BIKE MAKE & MODELS: YAMAHA LC 135

Please be informed that the said vehicle can be inspected at:

Name of workshop : EQUATOR BROTHERHOOD

Address : 25 KAKI BUKIT ROAD 4
#03-79 SYNERGY @ KB
SINGAPORE 417800

Telephone no. : 6384 6939/9011 3391 (Wille)

Please let us hear from you by the stipulated time.

Yours faithfully


encs

cc Client

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor
(Name & signature)

Date & time of inspection



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

SFMZSSSEI

No. Pendaftaran	: JST3683
No. ID	: 900823015961
Nama Pemunya Berdaftar	: MOHAMMAD RIDUWAN BIN SUROSO
Alamat	: NO 106 JLN BAHAGIA KAMPUNG SUNGAI RINTING B 81750 MASAI JOHOR
No. Chasis/No. Enjin	: PMYUG0810J0022382 / G3G5E-022402
Buatan/Nama Model	: YAMAHA / YAMAHA 135LC
Keupayaan Enjin	: 134
Bahan Bakar	: PETROL
Status Asai	: PEMASANGAN TEMPATAN
Kelas Kegunaan	: MOTOSIKAL
Jenis Badan/Tahun Dibuat	: MOTOSIKAL / 2018
Tarikh Pendaftaran	: 05/05/2018
B. D. M/B. G. K/BTM	: -
Syarat Pendaftaran 1	: -
Syarat Pendaftaran 2	: -
Syarat Pendaftaran 3	: -

LESEN KENDERAAN MOTOR

ROAD TRANSPORT ACT 1987 MOTOR VEHICLES (REGISTRATION AND LICENSING) RULES 1958

MOTOSIKAL No.SIRI: **AR 996702**

04 MEI 2020

JST3683

021117 05052019

JST3683

RM2.00

0101181 KADHA 04052020

134 SP AA

Gutdpdu

INS1 : T63327E-19001744

INS2 :

VEL02010

LESEN INI TIDAK SAH KECUALI ADA CAP MESIN PENERIMAAN JABATAN PENGANGKUTAN JALAN



POST FREE AD



YAMAHA LC 135

Kuala Lumpur

RM 6,868 NEGOTIABLE PRICE

CONTACT SELLER

VISIT STORE

Brand	Yamaha	Model	135LC
Type	Moped	Year	2019
Color	Blue	Engine	135 Cc
Gearbox	Manual	Engine Type	Petrol
Warranty	1 Year(S)		

Loan Option

RM 450
DOWN PAYMENT

24 months	RM 390
36 months	RM 282
48 months	RM 228
60 months	RM 195

More info

RM 700
DOWN PAYMENT

24 months	RM 370
36 months	RM 268
48 months	RM 216
60 months	RM 185

More info

RM 1,000
DOWN PAYMENT

24 months	RM 350
36 months	RM 253
48 months	RM 204
60 months	RM 175

More info

RM 2,000
DOWN PAYMENT

24 months	RM 300
36 months	RM 217

More info

Description

Yamaha LC 135- Auto Clutch

Colors Available: Yellow, Black, Red, Blue

Basic Selling Price RM 6,868

Technical Spec:

Engine Displacement: 134 cm3

Engine Type : Single Cylinder

Maximum Power: 8.93kW (8,500rpm)

Maximum Torque: 11.79N.m (5,500rpm)

Fuel Tank: 4.0 litres

Kerb Weight: 105 kg

sum cost RM 3900



convert to

SG \$1900



Zurich General Takaful Malaysia Berhad
 Level 21A, Menara 1, No. 1, Jalan Bangsar, KL Eco City, 59200 Kuala Lumpur, Malaysia
 Tel: 03 2109 6000 Fax: 03 2109 6000 Toll Centre: 1 800 888 622

CONFIRMATION OF PURCHASE OF TAKAFUL

E-C/Note No: T63327E-19001744
 Issue Date & Time: 28 APR 2019 11:38:05am
 Period of Takaful: From 05 MAY 2019 To 04 MAY 2020
 Vehicle Registration No.: JST3683
 Make of Vehicle: YAMAHA 135 LC
 Engine No.: G3G5E-022402 Chassis No.: PMYUG0810J0022382
 Capacity: 134.00 CC Year of Make: 2018
 Participant Name: MOHD RIDUWAN BIN SUROSO
 Address: NO 106 JLN BAHAGIA KAMPUNG SUNGAI RINTING B.81750,MASAI,JOHOR DARUL TAKZIM
 NRIC/Business Reg No.: 900823-01-5961
 Type of Cover: V-CO MOTOR COMPREHENSIVE
 Use of Vehicle: MOTORCYCLE FOR PRIVATE USE
 HP Owner:
 Sum Covered (RM): 5,900.00
 Transaction Type: New

Sum Covered (RM)	5,900.00	Contribution (RM)	199.53
All Rider (Y/N)	Y	All Rider Amt (RM)	99.77
NCD %	15.000000 %	NCD Amt (RM)	44.90
		Basic Net (RM)	254.40
Tuition Load %	0 %	Tuition Load Amt (RM)	0.00
		Extra Coverage (RM)	0.00
SST	6.00 %	SST (RM)	15.26
		Stamp Duty (RM)	10.00
Act Contribution (RM)	53.47	Payable Contribution (RM)	279.66

<u>Extra Benefits</u>	<u>Extra Covered (RM)</u>	<u>Extra Contribution (RM)</u>
ALL RIDERS	0.00	0.00

Named Drivers
 ALL RIDERS

Agent: T63327E-000 HARI GEMBIRA ENTERPRISE
 Tel No: 03-83200399

THIS IS A COMPUTER GENERATED FORM, SIGNATURE IS NOT REQUIRED

THE SCHEDULE

(SCHEDULE COPY)

JADUAL
(SALINAN ASAL)

Agent Code (Kod Agensi)	T63327E-000 (ZTMB - KUALA LUMPUR) HARI GEMBIRA ENTERPRISE	Date (Tarikh)	28 APR 2019	
Replacing Cover Note No. (Mengantikan Note Lindung No.)	T63327E-19001744	Receipt No. (No. Resit)		
Certificate No. (No. Sijil)	221950054129-00	ACT (AGT)	RM	53.47
The Participant (Peserta)	MOHD RIDUWAN BIN SUROSO	Basic Contribution	RM	199.53
Address (Alamat)	NO 106 JLN BAHAGIA KAMPUNG SUNGAI RINTING B, 81750 MASAI, JOHOR DARUL TAKZIM	All Riders	RM	99.77
Business Reg. No. (No. Sykt)		NCD 15.00%	RM	44.90
I/C No. New (No. K/P Baru)	900823-01-5961	Extra Cover	RM	0.00
Old I/C No. (No. K/P Lama)		Gross Contribution	RM	254.40
Business / Profession (Perniagaan / Pekerjaan)	OTHERS	SST 6.00%	RM	15.26
Hire Purchase Owners (Pemilik Sewa Beli)	-	Stamp Duty (DUTI SETEM)	RM	10.00
Employer / Lessors (Majikan / Pemajak)		Total Contribution (JUMLAH)	RM	279.66
Period of Coverage (Tempoh Perlindungan)	(a) From (Dari) 05 MAY 2019 To (Hingga) 04 MAY 2020 Time 12:01AM To Midnight 11:59:59 pm (b) Any subsequent period for which you shall pay and we shall agree to accept a renewal contribution Sebarang tempoh selanjutnya untuk mana anda membayar dan kami bersetuju menerima sumbangan pembaharuan			

The Motor Vehicle

Any of the following (Manapun yang berikut):

Kenderaan Motor

Registration No. (No. Pendaftaran)	Make (Buat dan Jenis Badan)	Type of Body (Jenis Badan)	Cubic Capacity (Keupayaan Enjin)	Year of Manufacture (Tahun Diperbuat)	Seating Capacity Including Driver (Muatan Tempat Duduk termasuk Pemandu)	Your Estimate of Value Including Accessories (Nilai Anggaran Anda termasuk Aksesori)
JST3683	YAMAHA 135 LC	MOTORCYCLE	134.00 CC	2018	2	RM5,900.00

Date of Signature of Proposal and Declaration
(Tarikh Cadangan dan Pernyataan Ditandatangani)

EXCESS : RM100.00
(LEBIHAN)

Engine (Enjin) : G3G5E-02Z40Z
CHASSIS (KASIS) : PMYUG0810J002238Z

Subject to the terms and conditions of the Certificate and endorsement as numbered below :
(Tertakluk kepada peraturan - peraturan dan syarat - syarat Sijil dan pengendornan seperti disenaraikan di bawah)

Named Driver : 1) ALL RIDERS

Include Endorsement No. 03.94.107

Additional Extra Coverage/Endorsements :

Code Description

03 ALL RIDERS

Value
0.00

Contribution
99.77

LEGISLATION :-

Road Transport Act 1987 (Malaysia) Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore Motor Vehicles (Third Party Risks and Compensation) Rules (Republic of Singapore) Motor Vehicles Takaful (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam (the reference to legislation under the heading "Avoidance of Certain Terms and Right of Recovery" is limited to Section 94, 95 and 96 of the Road Transport Act 1987 (Malaysia) Section 7, 8 and 9 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and Section 7 of the Motor Vehicles Takaful (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam)

UNDANG - UNDANG :-

Akta Pengangkutan Jalan Raya 1987 (Malaysia) Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura Peraturan Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) 1990 (Republik Singapura) Akta Takaful Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam (rujukan kepada undang - undang di bawah tajuk "Pengelakan Peraturan - Peraturan Dan Hak Turutan Tertentu" adalah terhad kepada Seksyen 94, 95 dan 96 Akta Pengangkutan Jalan Raya 1987 (Malaysia) Seksyen 7, 8 dan 9 Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura dan Seksyen 7 Akta Takaful Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam)

Limit of Liability :-

Had Tanggungan :-

Limit of the amount of the Company's Liability under Section 11 (a)
(Had jumlah tanggungan Syarikat di bawah Seksyen 11 (a))

RM50.00

Limit of the amount of the Company's Liability under Section 11 (b)
(Had jumlah tanggungan Syarikat di bawah Seksyen 11 (b))

Unlimited

Limit of the amount of the Company's Liability under Section 11 (c)
(Had jumlah tanggungan Syarikat di bawah Seksyen 11 (c))

RM3,000,000.00

Limitation as to Use
(Had Penggunaan)

As shown in the Certificate of Takaful
(Seperti ditunjukkan dalam Sijil Takaful)


Geographical Area
(Had Wilayah)

Malaysia, Republic of Singapore and Negara Brunei Darussalam
(Malaysia, Republik Singapura dan Negara Brunei Darussalam)

Authorized Driver
(Peserta Yang Diperuntukkan)

As shown in the Certificate of Takaful
(Seperti ditunjukkan dalam Sijil Takaful)

For and on behalf of : Untuk dan bagi pihak
ZURICH GENERAL TAKAFUL MALAYSIA
BERHAD



ZUHAIRI ISMAIL

JPJL6

26469918

A	Kenderaan Orang Cacat (Motorsikal) BTM tidak melebihi 450 kg <i>Invalid Searriage (Motor Cycle) unladen weight not exceeding 450 kg</i>	F	Traktor/Jentera Bergerak Ringan (Beroda) BTM tidak melebihi 5000 kg <i>Tractor/Mobile Machinery Light (Wheeled) unladen weight not exceeding 5000 kg</i>
A1	Kenderaan Orang Cacat (Motokar) BTM tidak melebihi 3500 kg <i>Invalid Carriage (Motor Car) unladen weight not exceeding 3500 kg</i>	G	Traktor/Jentera Bergerak Ringan (Berantai) BTM tidak melebihi 5000 kg <i>Tractor/Mobile Machinery Light (Tracked) unladen weight not exceeding 5000 kg</i>
B	Motosikal melebihi 500 sp <i>Motor Cycle exceeding 500 cc</i>	H	Traktor/Jentera Bergerak Berat (Beroda) BTM melebihi 5000 kg <i>Tractor/Mobile Machinery Heavy (Wheeled) unladen weight 5000 kg</i>
B1	Motosikal tidak melebihi 500 sp <i>Motor Cycle not exceeding 500 cc</i>	I	Traktor/Jentera Bergerak Berat (Berantai) BTM melebihi 5000 kg <i>Tractor/Mobile Machinery Heavy (Tracked) unladen exceeding 5000 kg</i>
B2	Motosikal tidak melebihi 250 sp <i>Motor Cycle not exceeding 250 cc</i>	M	Hukuman Mahkamah <i>Court Conviction</i>
C	Motosikal Tiga Roda <i>Three Wheels Motor Cycle</i>		
D	Motokar BTM tidak melebihi 3500 kg <i>Motor Car unladen weight not exceeding 3500 kg</i>		
DA	Motokar Tanpa Pedal Klac BTM tidak melebihi 3500 kg <i>Motor Car Without Clutch Pedal unladen weight not exceeding 3500 kg</i>		
E	Motokar Berat BTM melebihi 7500 kg <i>Heavy Motor Car unladen weight exceeding 7500 kg</i>		
E1	Motokar Berat BTM tidak melebihi 7500 kg <i>Heavy Motor Car unladen weight not exceeding 7500 kg</i>		
E2	Motokar Berat BTM tidak melebihi 5000 kg <i>Heavy Motor Car unladen weight not exceeding 5000 kg</i>		

0101181 vxrHIHj7




Ketua Pengarah Pengangkutan Jalan



SINGAPORE POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190910/2070

1 of 3

Report No. T/20190910/2070

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/09/2019 13:09		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: MOHAMMAD RIDUWAN BIN SUROSO			Address: 108 JALAN BAHAGIA KAMPUNG SUNGAI RINTING B 81750 MASAI JOHOR		
ID Type / ID No.: FIN NO / G3401765X			Contact No.: Home/Office: 011 3665 0659 Mobile: 87517963		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 29	Date of Birth: 23/08/1990	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name:
Occupation: IT CONSULTANT			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 09/09/2019 08:30	Type of Location:
Location: Along Road 1 PAN ISLAND EXPRESSWAY ALONG BKE RD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
JST3683	Motorcycle					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190910/2070

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190910/2070

CONTINUATION OF REPORT

Rider			
Name	MOHAMMAD RIDUWAN BIN SUROSO	ID No.	G3401765X
Related Vehicle	JST3683 (Motorcycle)	Contact No.	87517963
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	09/09/2019	Date Discharge	09/09/2019
No. of Days granted Medical Leave	05	Degree of Injury	NIL

Brief Details.

ON THE STATED DATE, TIME AND LOCATION

I WAS TRAVELLING ALONG BKE ROAD ON THE MIDDLE LANE WHEN A CAR OF (UNKNOWN NUMBER PLATE) CHANGE LANE IMMEDIATELY AND HIT ONTO ME. I FELL DOWN AND WAS CONVEYED TO NG TENG FONG HOSPITAL. I WAS DISCHARGED ON THE SAME DAY. THAT ALL



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20190910/2070

3 of 3

Report No. T/20190910/2070

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
EUGENE AW WEI XUAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI
Contact No.: 65476904

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
10/09/2019 13:09

Classification Of Case:

Eugene

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Sep 2019 Edit Reg		17 Sep 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	Choi Kein Cheng David, ID: S75038561								
Main Claimant:	-								
Vehicle Reg. No.:	JST3683	Date of Loss:	09/09/2019 00:00 - :59 [16 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900026857	Policy/Cover Note No.:	PNPV2018-00008379-01 (Comprehensive) Coverage: 04/07/2019 - 03/07/2020						
Vehicle Reg. No. (Insured):	SGJ2139K	Policy No. (Claimant):							
		Excess:							
Repairer:	Equator Brotherhood (KAKI BUKIT) 25 Kaki Bukit Road 4, #03 -79 Synergy @ KB, 417800 Kaki Bukit - Tel: 63846939 / h/p 90113391								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 27/09/2019]								
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All	Search Tasks						
Create New Task	Complete								
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JST3683 (1201900026857)

[SGJ2139K]

TP

Sep 9 2019 12:00AM

[Choi Kein Cheng David]

Equator Brotherhood

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	22/10/19 09:32	Chassis Number						Load JPG	☒	
2	22/10/19 09:33	Odometer Reading						Load JPG	☒	
3	22/10/19 09:33	General View						Load JPG	☒	
4	22/10/19 09:33	General View						Load JPG	☒	
5	22/10/19 09:33	General View						Load JPG	☒	
6	22/10/19 09:33	General View						Load JPG	☒	
7	22/10/19 09:33	General View						Load JPG	☒	
8	22/10/19 09:33	General View						Load JPG	☒	
9	22/10/19 09:33	General View						Load JPG	☒	
10	22/10/19 09:33	General View						Load JPG	☒	
11	22/10/19 09:34	General View						Load JPG	☒	
12	22/10/19 09:34	General View						Load JPG	☒	
13	22/10/19 09:34	General View						Load JPG	☒	
14	22/10/19 09:34	General View						Load JPG	☒	
15	22/10/19 09:34	General View						Load JPG	☒	
16	22/10/19 09:34	General View						Load JPG	☒	
17	22/10/19 09:34	General View						Load JPG	☒	
18	22/10/19 09:34	General View						Load JPG	☒	
19	22/10/19 09:34	General View						Load JPG	☒	
20	22/10/19 09:34	General View						Load JPG	☒	
21	22/10/19 09:34	General View						Load JPG	☒	
22	22/10/19 09:34	General View						Load JPG	☒	
23	22/10/19 09:34	General View						Load JPG	☒	
24	22/10/19 09:34	General View						Load JPG	☒	
25	22/10/19 09:34	General View						Load JPG	☒	
26	22/10/19 09:34	General View						Load JPG	☒	
27	22/10/19 09:34	General View						Load JPG	☒	
28	22/10/19 09:34	General View						Load JPG	☒	
29	22/10/19 09:34	General View						Load JPG	☒	
30	22/10/19 09:34	General View						Load JPG	☒	
31	22/10/19 09:34	General View						Load JPG	☒	
32	22/10/19 09:34	General View						Load JPG	☒	
33	22/10/19 09:34	General View						Load JPG	☒	
34	22/10/19 09:34	General View						Load JPG	☒	
35	22/10/19 09:34	General View						Load JPG	☒	
36	22/10/19 09:34	General View						Load JPG	☒	
37	22/10/19 09:34	General View						Load JPG	☒	
38	22/10/19 09:34	General View						Load JPG	☒	
39	22/10/19 09:34	General View						Load JPG	☒	
40	22/10/19 09:34	General View						Load JPG	☒	
41	22/10/19 09:34	General View						Load JPG	☒	
42	22/10/19 09:34	General View						Load JPG	☒	
43	22/10/19 09:34	General View						Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	22/10/19 09:34	General View	 Load JPG	☒
45	22/10/19 09:34	General View	 Load JPG	☒
46	22/10/19 09:34	General View	 Load JPG	☒
47	22/10/19 09:34	General View	 Load JPG	☒
48	22/10/19 09:34	General View	 Load JPG	☒
49	22/10/19 09:34	General View	 Load JPG	☒
50	22/10/19 09:34	General View	 Load JPG	☒
51	22/10/19 09:35	General View	 Load JPG	☒
52	22/10/19 09:35	General View	 Load JPG	☒
53	22/10/19 09:35	General View	 Load JPG	☒
54	22/10/19 09:35	General View	 Load JPG	☒
55	22/10/19 09:35	General View	 Load JPG	☒
56	22/10/19 09:35	General View	 Load JPG	☒
57	22/10/19 09:35	General View	 Load JPG	☒
58	22/10/19 09:35	General View	 Load JPG	☒
59	22/10/19 09:35	General View	 Load JPG	☒
60	22/10/19 09:35	General View	 Load JPG	☒
61	22/10/19 09:35	General View	 Load JPG	☒
62	22/10/19 09:35	General View	 Load JPG	☒
63	22/10/19 09:35	General View	 Load JPG	☒
64	22/10/19 09:35	General View	 Load JPG	☒
65	22/10/19 09:35	General View	 Load JPG	☒
66	22/10/19 09:35	General View	 Load JPG	☒
67	22/10/19 09:35	General View	 Load JPG	☒
68	22/10/19 09:35	General View	 Load JPG	☒
69	22/10/19 09:35	General View	 Load JPG	☒
70	22/10/19 09:35	General View	 Load JPG	☒
71	22/10/19 09:35	General View	 Load JPG	☒
72	22/10/19 09:35	General View	 Load JPG	☒
73	22/10/19 09:35	General View	 Load JPG	☒
74	22/10/19 09:35	General View	 Load JPG	☒
75	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
76	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
77	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
78	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
79	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
80	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
81	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
82	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
83	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
84	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
85	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
86	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
87	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
88	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
89	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
90	22/10/19 09:36	Reinspection Photo	Load JPG	☒
91	22/10/19 09:36	Reinspection Photo	Load JPG	☒
92	22/10/19 09:36	Reinspection Photo	Load JPG	☒
93	22/10/19 09:36	Reinspection Photo	Load JPG	☒
94	22/10/19 09:36	Reinspection Photo	Load JPG	☒
95	22/10/19 09:36	Reinspection Photo	Load JPG	☒
96	22/10/19 09:36	Reinspection Photo	Load JPG	☒
97	22/10/19 09:36	Reinspection Photo	Load JPG	☒
98	22/10/19 09:36	Reinspection Photo	Load JPG	☒
99	22/10/19 09:36	Reinspection Photo	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
101	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
102	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
103	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
104	22/10/19 09:36	Reinspection Photo	 Load JPG	☒
105	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
106	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
107	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
108	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
109	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
110	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
111	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
112	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
113	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
114	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
115	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
116	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
117	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
118	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
119	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
120	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
121	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
122	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
123	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
124	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
125	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
126	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
127	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
128	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
129	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
130	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
131	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
132	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
133	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
134	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
135	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
136	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
137	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
138	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
139	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
140	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
141	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
142	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
143	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
144	22/10/19 09:37	Reinspection Photo	 Load JPG	☒
145	22/10/19 09:38	Reinspection Photo	 Load JPG	☒
146	22/10/19 09:38	Reinspection Photo	 Load JPG	☒
147	22/10/19 09:38	Reinspection Photo	 Load JPG	☒
148	22/10/19 09:38	Reinspection Photo	 Load JPG	☒
149	22/10/19 09:38	Reinspection Photo	 Load JPG	☒
150	22/10/19 09:38	Reinspection Photo	 Load JPG	☒
151	22/10/19 09:38	Reinspection Photo	Load JPG	☒
152	22/10/19 09:38	Reinspection Photo	Load JPG	☒
153	22/10/19 09:38	Reinspection Photo	Load JPG	☒
154	22/10/19 09:38	Reinspection Photo	Load JPG	☒
155	22/10/19 09:39	Reinspection Photo	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
156	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
157	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
158	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
159	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
160	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
161	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
162	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
163	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
164	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
165	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
166	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
167	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
168	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
169	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
170	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
171	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
172	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
173	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
174	22/10/19 09:39	Reinspection Photo	 Load JPG	☒
175	22/10/19 09:39	After Repair Photo	 Load JPG	☒
176	22/10/19 09:39	After Repair Photo	 Load JPG	☒
177	22/10/19 09:39	After Repair Photo	 Load JPG	☒
178	22/10/19 09:39	After Repair Photo	 Load JPG	☒
179	22/10/19 09:39	After Repair Photo	 Load JPG	☒
180	22/10/19 09:39	After Repair Photo	 Load JPG	☒
181	22/10/19 09:39	After Repair Photo	 Load JPG	☒
182	22/10/19 09:39	After Repair Photo	 Load JPG	☒
183	22/10/19 09:39	After Repair Photo	 Load JPG	☒
184	22/10/19 09:39	After Repair Photo	 Load JPG	☒
185	22/10/19 09:40	After Repair Photo	 Load JPG	☒
186	22/10/19 09:40	After Repair Photo	 Load JPG	☒
187	22/10/19 09:40	After Repair Photo	 Load JPG	☒
188	22/10/19 09:40	After Repair Photo	 Load JPG	☒
189	22/10/19 09:40	After Repair Photo	 Load JPG	☒
190	22/10/19 09:40	After Repair Photo	 Load JPG	☒
191	22/10/19 09:40	After Repair Photo	 Load JPG	☒
192	22/10/19 09:40	After Repair Photo	 Load JPG	☒
193	22/10/19 09:40	After Repair Photo	 Load JPG	☒
194	22/10/19 09:40	After Repair Photo	 Load JPG	☒
195	22/10/19 09:40	After Repair Photo	 Load JPG	☒
196	22/10/19 09:40	After Repair Photo	 Load JPG	☒
197	22/10/19 09:40	After Repair Photo	 Load JPG	☒
198	22/10/19 09:40	After Repair Photo	 Load JPG	☒
199	22/10/19 09:40	After Repair Photo	 Load JPG	☒
200	22/10/19 09:40	After Repair Photo	 Load JPG	☒
201	22/10/19 09:40	After Repair Photo	 Load JPG	☒
202	22/10/19 09:40	After Repair Photo	 Load JPG	☒
203	22/10/19 09:40	After Repair Photo	 Load JPG	☒
204	22/10/19 09:40	After Repair Photo	 Load JPG	☒
205	22/10/19 09:40	After Repair Photo	 Load JPG	☒
206	22/10/19 09:40	After Repair Photo	 Load JPG	☒
207	22/10/19 09:40	After Repair Photo	 Load JPG	☒
208	22/10/19 09:40	After Repair Photo	 Load JPG	☒
209	22/10/19 09:40	After Repair Photo	 Load JPG	☒
210	22/10/19 09:40	After Repair Photo	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	19/09/19 17:02	SGJ2139K OI GIA		Load PDF
2	19/09/19 17:12	PRI - RIAZ LLC		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD19016474/HCD3E2

Date: 31/10/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00008379-01

Claimant

Vehicle No : JST3683

Insured Vehicle No : SGJ2139K

Date of Loss: 09/09/2019

Nature of Claim: TP

Claim No: 1201900026857

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JST3683

Make & Model: YAMAHA 135LC, 134cc ES

Engine No: G3G5E022402

Reg. Date: 05/05/2018 (Man. Year: 2018)

Chassis No: PMYUG0810J0022382

Colour: Silver

Odometer: 16541 km

Engine Capacity: 134 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 80/90-17

Rear Tyre Size: 90/80-17

Front Left Side: Pirelli 5 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/09/2019

Date Inspected: 14/10/2019 Inspected At:

Equator Brotherhood (KAKI BUKIT)

25 Kaki Bukit Road 4, #03 -79

Synergy @ KB

Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,800.00 - \$2,300.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 31 Oct 2019)

Parts: N/A YAMAHA 135LC 134cc ES (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for JST3683)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >