

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19016507/GGA3Q2

Date: 16/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLU9132R	Insured Vehicle No :	SHC1293D
Date of Loss: 14/09/2019	Nature of Claim: TP	Claim No: MCT19090308

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU9132R		
Make & Model:	TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)	Engine No:	2ZR0A23417
Reg. Date:	18/12/2017 (Man. Year: 2017)	Chassis No:	ZVW400027147
Colour:	Black	Odometer:	186282 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,149.00	632.50	516.50	44.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	760.00	700.00	60.00	7.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	1,909.00	1,332.50	576.50	30.20
Approved Total (Overridden) (\$\$)		1,050.00		
(\$\$)	1,909.00	1,050.00	859.00	45.00
+ GST 7.00/7.00% (\$\$)	133.63	73.50	60.13	45.00
Nett Amount (\$\$)	2,042.63	1,123.50	919.13	45.00
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	17/09/2019	
Date Inspected:	19/09/2019	Inspected At: 24 DEFU LANE 12
		Repairer: Allswell Motor Traders (HQ)
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2020)
Parts:	144	TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU9132R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT DOOR	Buckled	790.00 F	*790.00 FL
2	1		*LH SKIRTING	Repair	319.00 F	*- FL
3	1		*CLIPS /RETAINER STUDS FOR LH FRONT DOOR UPHOLSTERY	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,149.00	830.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	197.50
Total Parts (S\$)	1,149.00	632.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DISMANTLE/ASSEMBLY OF LH FRONT DOOR MOULDING CABLES/WINDW/UPHOLSTERY MECHANISM	New	360.00	300.00
2	SPRAY PAINT OF LH FRONT DOOR INTERIOR/EXTERIOR MOULDING SKIRTING	New	400.00	400.00
Gross Labour Cost (\$\$)			760.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >