

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 24 Sep 2019

Preliminary Advice

Vehicle No	: SKE2565S	Accident Date	: 16/09/2019
Make	: AUDI A3	Policy No.	: DMPCSN1507531904
Assignment Date	: 19/09/2019	Excess	: S\$1,000.00
Date of Inspection	: 23/09/2019	Est. Duration of Repair	: 5 days
Inspection At	: Z-one Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6,, Blk D #01-87, Autobay @ Kaki Bukit Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,370.05
Revised Amount	:S\$	6,260.45
Check Items (Estimated)	:S\$	86.25
Total	:S\$	6,346.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	72,000.00
COE / PARF Rebate	:S\$	44,951.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,049.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer asking for part by part basis due to no second hand parts. Estimate prices change to cost prices.