LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road

51 Ubi Ave 1 #01-25 #16-00 Springleaf Tower Paya Ubi Industrial Park Singapore 079909 Singapore 408933

Attn: Chong Boon Sen Date: 23 Sep 2019

Preliminary Advice

Vehicle No : SKE2565S **Accident Date** : 16/09/2019

: DMPCSN1507531904 Make : AUDI A3 Policy No.

Assignment Date : 19/09/2019 **Excess** : S\$1,000.00 Date of Inspection : 23/09/2019 Est. Duration of Repair : 5 days

Inspection At : Z-one Automotive Pte Ltd (HQ)

1 Kaki Bukit Avenue 6,, Blk D #01-87, Autobay @ Kaki Bukit

Singapore 417883

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,157.67
Revised Amount	:S\$	11,874.20
Check Items (Estimated)	:S\$	225.74
Total	:S\$	12,099.94

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 72,000.00 COE / PARF Rebate :S\$ 44,951.00

Salvage Value :S\$

Margin for Repair :S\$ 27,049.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Repairer asking for part by part basis due to no second hand parts.