



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19016530/Qyf3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 12-05-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8539A	Veh. Inspected	SLS 7014Y
Policy No.		Coverage (\$)	0.00
Claim No.	D19005953MFSH	Excess (\$)	0.00
Assign From	JASON TEA CHEE KIAT	Assign Date	18/09/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA3 SEDAN	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8J0175771	Colour	WHITE
Odometer	29418	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TOYO	5 mm
L/H Front Tyre	205/60 R16	TOYO	5 mm
R/H Rear Tyre	205/60 R16	TOYO	5 mm
L/H Rear Tyre	205/60 R16	TOYO	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/09/2019	Inspection Date	01/10/2019
Survey held at	HUA HONG PTE LTD 25D SUNGEI KADUT STREET 1 SINGAPORE 729332		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------