

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **Lonpac Insurance Bhd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/LONPAC
Policy No:	Z19VP05023282	Date of Loss:	17/09/2019
Vehicle Reg. No.:	SJP3467P	Driveable?	
Driver Age/Info:	44 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HO BEE YEAN		
Driver:	TEW KIAN HOE		
Make/Model:	HONDA STREAM, 1.8 X (A)	Vehicle Reg. Date:	20/03/2009
Vehicle Colour:	SILVER		
Engine No:	R18A1797397	Chassis No:	RN61087909
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	I WAS LOOKING OUT FOR TRAFFIC ON THE RIGHT AND WHEN I TURN BACK TO THE FRONT, WAS SHOCKED TO REALISED THAT MOTOR CAR SJJ8830Y WHO HAD MOVED FORWARD AT THE SLIP ROAD STOPPED INFRONT, AS SUCH I COULDN'T AVOID IN TIME AND HIT ONTO THE REAR OF SJJ8830Y. NO ONE WAS INJURED.		
Remarks:	OWNER ARRANGE HIS VEHICLE TO TOW INTO ANG MO KIO WORKSHOP ON 17/09/2019 EVENING		
Present Location:	CHENG HOE MOTOR PTE LTD (AMK)		

COST OF CLAIMS	Amount
Parts	6,335.35
Miscellaneous Items	70.00
Labour	1,650.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,055.35
+ GST 7.00% (S\$)	563.87
Nett Amount (S\$)	8,619.22

This claim is handled by: **DORLYN LI YAZHU**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Sep 2019)

Parts: M1-MPV HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SJP3467P/19/09/2019 10:08

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front bumper / CRA	0.00	0.00	*390.00 F
2	1		*1 pc front bumper reinforcement / BT.	0.00	0.00	*160.00 F
3	1		*1 pc front bumper lower centre grille / Re	0.00	0.00	*70.00 F
4	1		*2 pcs front bumper side retainers @ \$12/pc / Re.	0.00	0.00	*24.00 F
5	1		*6 pcs front bumper clips \$1.50/pc / MC	0.00	0.00	*9.00 F
6	1		*1 pc bonnet / Bnc	0.00	0.00	*420.00 F
7	1		*1 pc bonnet inner lock / BT	0.00	0.00	*38.00 F
8	1		*2 pc bonnet hinges @ \$32/pc / BT.	0.00	0.00	*64.00 F
9	1		*1 pc front grille / CRA	0.00	0.00	*150.00 F
10	1		*1 pc front grille moulding chrome / Cut.	0.00	0.00	*145.00 F
11	1		*1 pc front grille logo / Cut	0.00	0.00	*18.00 F
12	1		*4 pcs front grille clips @ \$2/pc / MC.	0.00	0.00	*8.00 F
13	1		*1 pc front LH fender / BT.	0.00	0.00	*310.00 F
14	1		*6 pcs front LH fender clips @ \$2/pc / MC.	0.00	0.00	*12.00 F
15	1		*1 pc front RH fender inner top garnish / Re.	0.00	0.00	*35.00 F
16	1		*3 pcs front RH fender inner top garnish clips \$2/pc / MC.	0.00	0.00	*6.00 F
17	1		*2 pcs horns @ \$35/pc / Cut.	0.00	0.00	*70.00 F
18	1		*1 pc front support panel / BT.	0.00	0.00	*330.00 F
19	1		*1 pc front support panel inner top garnish / BR.	0.00	0.00	*45.00 F
20	1		*6 pcs front support panel inner top garnish clips @ \$1/pc / MC.	0.00	0.00	*6.00 F
21	1		*1 pc aircon condenser / BT.	0.00	0.00	*510.00 F
22	1		*1 pc aircon condenser fan motor ?	0.00	0.00	*190.00 F
23	1		*1 pc aircon condenser fan blade ?	0.00	0.00	*50.00 F
24	1		*1 pc aircon condenser fan cowling / Re ?	0.00	0.00	*60.00 F
25	1		*1 pc radiator / BT	0.00	0.00	*830.00 F
26	1		*1 pc radiator fan cowling / Re.	0.00	0.00	*80.00 F
27	1		*1 pc radiator fan motor ?	0.00	0.00	*190.00 F
28	1		*1 pc radiator fan blade ?	0.00	0.00	*50.00 F
29	1		*1 pc radiator spare tank ?	0.00	0.00	*45.00 F
30	1		*2 pcs headlamps (HID) @ \$460/pc / CRA.	0.00	0.00	*920.00 F
31	1		*2 pcs headlamp lower brackets @ \$32/pc / BT.	0.00	0.00	*64.00 F
32	1		*1 pc LH HID bulb / NW.	0.00	0.00	*210.00 F

F=Franchise part.

Sub Total (\$\$)	5,509.00
+ Margin on L,N Items 15.00% (\$\$)	826.35
Total Parts (\$\$)	6,335.35

Cheng Hoe Motor Pte Ltd/SJP3467P/19/09/2019 10:08. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
----	-----	-------------	--------

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	1 pc front number plate / <i>scr.</i>	35.00
2	1	1 unit coolant / <i>acc.</i>	35.00
Sub Total (S\$)			70.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Towing (arrange and paid by owner) (Towing fee TBA)	New	-
2	Remove & refix aircon condenser,check,vacuum & refill gas	New	✓ 100.00
3	Remove & refix frt bumper,bonnet & attachments,grille,headlamps,frt LH fender;to curt,weld & renew frt support panel;knocking & repair frt RH fender,chassis frames & realign the same	New	650 750.00
4	Putty & respray frt bumper,bonnet,both fenders,frt support panel & all affected areas	New	700 800.00
Gross Labour Cost (S\$)			1,650.00

Cheng Hoe Motor Pte Ltd/SJP3467P/19/09/2019 10:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5 Days.

Not Authorised.

Excess \$500.

lump sum repair

After repair photos.

Guo Qiang - 82880282.

19/9/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: