

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 1392 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 //	
2	To dismantle and renew lhs rear door. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00 ⁵⁰⁰ /	
3	To respray lhs rear door, door handle, door cover, lhs rear wheel arch trim and lhs rear fender.	\$ 3,000.00 ¹⁴⁷⁵ 925+550	
4	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00 //	
5	To carry out diagnostic checks.	S/N \$ 192.00 //	
SUB TOTAL LABOUR CHARGES		: \$ 4,952.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 1392 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR DOOR - LH <i>bt</i>	\$ 2,829.00	<i>2263.20</i>
2	REAR DOOR SEAL BRACKET <i>? nee</i>	\$ 39.00	<i>30.48 ✓</i>
3	REAR DOOR OUTER SEAL <i>nee</i>	NEC \$ 190.00	<i>152</i>
4	BONDING AGENT <i>ne</i>	NEC \$ 45.00	<i>35.92</i>
5	CLEANING SOLUTION <i>ne Xnn</i>	NEC \$ 65.00	<i>X</i>
6	REAR DOOR SEALING STRIP <i>? Xnn</i>	\$ 15.00	<i>X</i>
7	REAR DOOR ATTACHMENT PARTS <i>? Xnn</i>	\$ 201.00	<i>X</i>
8	REAR DOOR CATCH <i>repair bt</i>	\$ 132.00	<i>105.60 ✓</i>
9	REAR DOOR SEAL - OUTER <i>nee</i>	\$ 201.00	<i>160.80</i>
10	REAR DOOR SEAL - INNER <i>ne Xnn</i>	\$ 190.00	<i>X</i>
11	SILL PANEL SEAL - LH <i>X nn</i>	\$ 234.00	<i>X</i>
12	REAR DOOR HANDLE TRIM PLATE - LH <i>? Xsrl</i>	\$ 250.00	<i>X</i>
13	REAR DOOR HANDLE HOUSING <i>Xsrl</i>	\$ 16.00	<i>X</i>
14	REAR DOOR HANDLE SENSOR - LH <i>Xsrl</i>	\$ 208.00	<i>X</i>
15	REAR DOOR EXTERIOR HANDLE - LH <i>Xsrl</i>	\$ 35.00	<i>X</i>
16	REAR DOOR COVER - LH <i>srl</i>	\$ 577.00	<i>461.20</i>
17	REAR WHEEL COVER - LH <i>srl</i>	\$ 487.00	<i>387.60</i>
18	REAR ALUMINIUM RIM - LH <i>cut</i>	\$ 923.00	<i>738.40</i>
19	ALUMINIUM RIM RUBBER VALVE <i>ne</i>	4 \$ 13.00	<i>9.92</i>
20	SUNDRIES <i>? ne</i>	\$ 300.00	<i>8.40 ✓</i>
TOTAL SPARE PARTS		: \$ 6,950.00	
TOTAL LABOUR CHARGES		: \$ 4,952.00	
GRAND TOTAL		: <u>\$ 11,902.00</u>	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

12702

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax



Name

: Rasul - Hp 90010068

Surveyed Date

: 19/09/19 @ 1600h

Authorised Date

: 3 days

Excess Cost

: EXCESS: TBA

Liability

:

Remarks

: Repair

Resur before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/1128/2019/NS

Date

8-Oct-19

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SLR 1392 A

Model No

Audi Q5 SPORT 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
<u>Labour</u>			
1	To repair lhs rear fender.	\$ 800.00	250 ✓
TOTAL		\$ 800.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Gmo Corp.
08/10/19