


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:44

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85015017 Date: 31/03/2020 Order: SLR1392A Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SLR1392A (V 34637)	Regn Date: 31/07/2017	Mileage: 9484	WIP No.: 12643
Model: Q5 SPORT 2.0 TFSI qu S tronic	Chassis: WAUZZZF1H2027428	Engine: DAX 006478	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1600.00	1.00	-1,600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES.	280.00	1.00	280.00
S	BODYWORK	M: TO DISMANTLE AND RENEW LHS REAR DOOR. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY LHS REAR DOOR,DOOR HANDLE, LHS REAR WHEEL ARCH TRIM AND LHS REAR FENDER	1475.00	1.00	1,475.00
S	BODYWORK	M: TO RENEW LHS REAR RIM AND CARRY OUT DIAGNOSTIC CHECK	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO REPAIR LHS REAR FENDER	250.00	1.00	250.00
X	A80A833051B STL	(A) (SK) DOOR 26/9/19	Less 020%	1.00	2829.00
X	A80A839911B	(A) (SK) SEAL 26/9/19	Less 020%	1.00	190.00
X	AD 355205A2	(SK) BONDAGENT	Less 020%	1.00	44.90
X	A80A839249	CHECK ROD(LAST) AP	Less 020%	1.00	132.00
X	A80A839119B	(A) (SK) DOOR SEAL 26/	Less 020%	1.00	201.00
X	A80A853969A GRU	(A) (SK) COVER 26/9/19	Less 020%	1.00	576.50
X	A80A853817A GRU	(SK) COVER	Less 020%	1.00	487.00
X	A80A601025E	WHEEL (LAST)	Less 020%	1.00	923.00
X	A311601361	RUBBER VAL	Less 020%	4.00	3.10
X	A4B0837491B	PLUG ap	Less 020%	3.00	3.50
X	A80A839151A	(V) (SK) BRACKET AP 10	Less 020%	1.00	38.10

Parts 4,355.52
Labour 0.00
Sublet 2,977.00
Menus 0.00
Lubricant 0.00

Sub-Total 5,732.52

7% GST 401.28

Grand Total 6,133.80



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLR 1392 A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1128/2019/TG
11 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1 total pages

Make & Model : Audi Q5 2.0 TFSI QU
Vehicle Chassis No. : WAUZZZF1H2027428
Vehicle Regn No. : **SLR 1392 A**
Vehicle Mileage : 7805 KM
Vehicle Owner : Premium Leasing Pte Ltd
Certificate No : 100878207
Own Damage Excess : S\$ 1,712.00 (Inclusive 7% GST)
Accident Date : 15/09/2019
Place : 31 St Thomas Walk Singapore 238141
Repair Cost : \$ 6133.80
WIP No. : 12643
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :

