

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 12617**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/1126/2019/NS  
**Date** : 17-Sep-19

**Vehicle NOT in workshop. Kindly arrange for survey.**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Malik Maksudi  
**Address** : Blk 866 Yishun Street 81  
#10-49  
Singapore 760866  
**Telephone** : 81807326  
**Type of Claim** : Own damage Claim  
**Policy No.** : 1700083118-01  
**Vehicle No** : **SCV 3868 S**  
**Model Code** : Audi A4 Sedan 1.4 TFSI S  
**Model / Year** : 27/11/2017  
**Engine No** : CVN 044874  
**Chassis No** : WAUZZZF47JA022047  
**Mileage** :  
**Date In** :  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 14-Sep-19  
**Place of Accident** : Johor Bahru Permas Jaya

# Automobiles

l, Singapore 408699

23 Fax : 6841 1183

elefax

## for Accident Vehicle SCV 3868 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs front door's multi-lock system and power window devices.	S/N \$ 280.00 ✓	
2	To dismantle and renew lhs front door. Inspect lhs wing mirror assy for damages. Reinstall all parts removed.	\$ <del>1,050.00</del> 500	
3	To respray lhs front door and lhs wing mirror cover. ✓ x	\$ <del>1,200.00</del> 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 2,722.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SCV 3868 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT DOOR - LH <i>Dented</i>	\$	2,152.00 ✓
2	FRONT DOOR OUTER SEAL - LH <i>New</i>	NEC \$	185.00 ✓
3	BONDING AGENT <i>?</i>	NEC \$	45.00 <i>?</i>
4	CLEANING SOLUTION <i>?</i>	NEC \$	65.00 <i>?</i>
5	FRONT DOOR ATTACHMENT PARTS <i>?</i>	\$	488.00 <i>?</i>
6	FRONT DOOR CATCH <i>New</i>	\$	96.00 <i>X</i>
7	WINDOW REGULATOR WITHOUT MOTOR - LH <i>New</i>	\$	250.00 <i>X</i>
8	SUNDRIES <i>?</i>	\$	300.00 <i>?</i>
<b>TOTAL SPARE PARTS CHARGES</b>		<b>\$</b>	<b>3,581.00</b>
<b>TOTAL LABOUR CHARGES</b>		<b>\$</b>	<b>2,722.00</b>
<b>GRAND TOTAL</b>		<b>\$</b>	<b>6,303.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name

: Adrian King

Surveyed Date

: 19/09/19.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 03 Days.

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant