

INSURANCE

INS. CASE OWNER:

CC 4/III1901 6568, U

LOC:
IDAC:

Surveyor:

marcus.

DOI:

ASSIGNMENT

30/9/19

Date / Time:

19/11/19

Registered in Merimen:

19/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SH 6433C

Name of Insured:

CTPL

Insured Tel No.:

HP:

Claim No.:

MT1909022

Policy No.:

MEM0005

Make / Model:

LYNNON

Place of Accident:

194 HDB Tampines ST 12

Excess Sec II :\$5

D.O.A:

15/11/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: GUN KOK CHENH.

Driver Tel No.:

(VA: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLV 4509R



INSRS:

WSP:

Tel:

Liability:

RMKS:

SME



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

20/11 - Pending liability approval. (approved).

21/11 - Liability clear send tp.

21/11 - File pass R1 type report.

21/11 - Pending mandate approval of \$1955.73

21/12 - After R1S \$1955 (Pending assessment).

21/12 - TP reject offer. Propose \$1955.73. Send

to \$1955.73 as propose. File pass R1 type report.

STAGE

DATE/ PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

marcus.

Repair Cost:

\$5 1045.60

(2 days) Reduction: \$134.12 = 45

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : H2-15

If NO or B 28, Ass. Lia:

Repair Cost:

\$5 1045.60

OI int auto tpv

Loss of Rental (LOR):

\$5

days

Loss of Use (LOU):

\$5 180.00

(5.60 x 3 days)

Loss of Income (LOI):

\$5

(5 x days)

LOR only ☐

LOU only ☐

LOR + LOI ☐

LOR + LO ☐

(Tick only one)

GIA/LTA Search

\$5 7.45

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$5 1052.95

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

\$5 1055.73

Name 1:

SME Motor Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

COPY SENT
3/2/2020

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Sep 2019)

Parts: M1-SUV HONDA VEZEL 1.5 HYBRID X (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SLV4509R/18/09/2019 13:44

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER	20.00	0.00	*801.00 FL ✓
2	1		*FRT BUMPER RETAINER RH	20.00	0.00	*28.00 FL X
3	10		*FRT BUMPER CLIP	20.00	0.00	*55.00 FL ✓
4	1		*FRT BUMPER LOWER SPOILER	20.00	0.00	*391.00 FL ✓
5	8		*FRT FENDER PROTECTOR CLIP	20.00	0.00	*35.40 FL ✓
6	1		*FRT FENDER EMBLEM HYBRID RH	20.00	0.00	*221.00 FL ✓
7	1		*FRT FENDER RH	20.00	0.00	*387.00 FL ✓
F=Franchise part. L=List Item Disc.						
			Sub Total (S\$)		221.00	1,918.40
			- List Item Discount on L Items (S\$)			383.68
			Total Parts (S\$)			1,534.72

SME Motor Pte Ltd/SLV4509R/18/09/2019 13:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

7-1077
202
P-801.60
S.N 11
L-780
1652.60

82986.72

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRT SPORT RIM RH	250.00
2	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			261.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	20.00
2	LABOUR CHARGE	New	450.00
3	SPRAY PAINTING	New	500.00
Gross Labour Cost (S\$)			970.00

SME Motor Pte Ltd/SLV4509R/18/09/2019 13:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

760

Nett Amount (S\$) 2,959.32

This claim is handled by: CHIA PEI YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Oct 2019)
 Parts: M1-SUV HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLV4S09R)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT FENDER OUTER PROTECTOR RH A00	20.00	0.00	*221.00 FL
Sub Total (\$)						221.00
- List Item Discount on L Items (\$)						44.20
Total Parts (\$)						176.80

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

list 1,077 ✓

-20's 861.60

SN 11

LC 860

1732.60

10/10/2019

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Sep 2019)
 Parts: M1-SUV HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: SME Motor Pte Ltd/SLV4509R/18/09/2019 13:44
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER			*801.00 FL ✓
2	1		*FRT BUMPER RETAINER RH	20.00	0.00	*28.00 FL X
3	10		*FRT BUMPER CLIP	20.00	0.00	*55.00 FL ✓
4	1		*FRT BUMPER LOWER SPOILER	20.00	0.00	*391.00 FL X
5	6		*FRT FENDER PROTECTOR CLIP	20.00	0.00	*35.40 FL ?
6	1		*FRT FENDER EMBLEM HYBRID RH	20.00	0.00	*221.00 FL ?
7	1		*FRT FENDER RH	20.00	0.00	*387.00 FL X
F=Franchise part. L=List Item Disc.						
<i>for fender outer protector RH</i> <i>\$291.</i>						
Sub Total (S\$)						1,918.40
- List Item Discount on L Items (S\$)						383.68
Total Parts (S\$)						1,534.72

SME Motor Pte Ltd/SLV4509R/18/09/2019 13:44. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 FRT SPORT RIM RH \$80 repair

2 1 OD/TP Case (Insurer)

250.00

11.00

Sub Total (S\$)

261.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 WIRE CHECKING

2 LABOUR CHARGE

3 SPRAY PAINTING

New

20.00

New

280

450.00

New

480

500.00

Gross Labour Cost (S\$)

780

970.00

SME Motor Pte Ltd/SLV4509R/18/09/2019 13:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

TP INSURER: India International Insurance Pte Ltd (HQ)

MOHAMMAD SHAM BIN JAMIL

BLK 274B PUNGGOL PLACE #08-824

Singapore 822274

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	19/III/TP-192 (09)
Policy No:		Date of Loss:	15/09/2019
Vehicle Reg. No.:	SLV4509R ←	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	MOHAMMAD SHAM BIN JAMIL	Driver (Insured):	MOHAMMAD SHAM BIN JAMIL

Make/Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Vehicle Reg. Date:	29/12/2017
Vehicle Colour:	RED		
Engine No:	LEB5957578	Chassis No:	RU31257561
Odometer:	0 KM		

Paint Type:	
List Item Discount:	20.00 %
Total Loss?	NO
Est. Duration of Repair 7 (day)	

not Admitted here
30/9/19
The vehicle is going to be repaired.
32.

p/w 1652-60

Description of Accident/Loss	VEHICLE B ENTERING THE CARPARK. AT THE BEND, I SAW VEHICLE B GETTING NEAR MY VEHICLE AND ENTERING MY LANE. I CAME TO A COMPLETE STOP AND HORN HIM. BUT VEHICLE B STILL HIT ONTO MY RIGHT SIDE.
------------------------------	--

Remarks: VEHICLE NOT IN.

Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	1,534.72
Miscellaneous Items	261.00
Labour	970.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,765.72
+ GST 7.00% (\$\$)	193.60

LKK Auto Consultants hence notify the Repairer of the following:

- To ensure transfer of liability
- To ensure damaged part(s) during recovery
- Parts price is subject to confirmation
- Third party recovery is on a "Without Prejudice" basis
- All repair work(s) is allowed
- Any necessary work(s) must be recognised and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Sep 2019)

Parts: M1-SUV HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SLV4509R/18/09/2019 13:44

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER <i>Deepen</i>	20.00	0.00	*801.00 FL ✓
2	1		*FRT BUMPER RETAINER RH <i>11</i>	20.00	0.00	*28.00 FL X
3	10		*FRT BUMPER CLIP <i>101</i>	20.00	0.00	*55.00 FL ✓
4	1		*FRT BUMPER LOWER SPOILER <i>2</i>	20.00	0.00	*391.00 FL X
5	6		*FRT FENDER PROTECTOR CLIP	20.00	0.00	*35.40 FL ?
6	1		*FRT FENDER EMBLEM HYBRID RH	20.00	0.00	*221.00 FL ?
7	1		*FRT FENDER RH <i>2</i>	20.00	0.00	*387.00 FL X
F=Franchise part. L=ListItemDisc						
<i>for fender outer protector RM</i>						
Sub Total (S\$)						1,918.40
- List Item Discount on L Items (S\$)						383.68
Total Parts (S\$)						1,534.72

SME Motor Pte Ltd/SLV4509R/18/09/2019 13:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	837C
Vehicle Details	
Vehicle No.:	SLV4509R
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	LEB5957578
Chassis No.:	RU31257561
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$27,351.00
Original Registration Date:	29 Dec 2017
First Registration Date:	29 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,011.00
COE Rebate Amount:	\$38,726.00
Total Rebate Amount:	\$42,476.00

The information contained herein is correct as at 01 Oct 2019

OK

Print Received Message

This mail is associated with :

SLV4509R (MCT19090322)

[SH6433C]

TP

MOHAMMAD SHAM BIN JAMIL

Sep 15 2019 11:00AM

[COMFORT TRANSPORTATION PTE LTD]

SME Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 21/11/2019 17:44 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1955.73) - SLV4509R - Claim Handler: Sundari Nagarajan

Approved:1955.73:Please request TP WS to raise Tax Invoice for Cost of repairs in III's name

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Sep 2019 Sendback Est	18 Sep 2019 13:44 \$2,765.72	19 Sep 2019 08:40 Edit Adj Rpt	\$1,652.60 Edit Estimates	\$1,652.60 View Rpt		Pending for Survey Report Cancel Case
Supp #1	10 Oct 2019 12:41 Sendback Est	10 Oct 2019 12:43 \$176.80	10 Oct 2019 12:43 Assign			Combine Suppl.	New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R, Tel: +6592996225								
Main Claimant:	MOHAMMAD SHAM BIN JAMIL, ID: S7424837C								
Vehicle Reg. No.:	SLV4509R	Date of Loss:	15/09/2019 11:00 ~ :59 [20 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19090322	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH6433C	Policy No. (Claimant):	5097007036						
		Excess:							
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagaraajan - 6347 6071]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 30/09/2019]								
Driver/Custodian (Insured):	MOHAMMAD SHAM BIN JAMIL (45 / Male), NRIC: S7424837C, Tel: +6592996225 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (21/11/2019): Alert - Adj Mandate Approved (\$1955.73) - SLV4509R - Claim Handler: Sundari Nag... - III_SG (23/09/2019): Alert - Adj Mandate Approved (\$0.00) - SLV4509R - Claim Handler: Sundari Nagara...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLV4509R (MCT19090322)
[SH6433C]
TP
MOHAMMAD SHAM BIN JAMIL
Sep 15 2019 11:00AM
[COMFORT TRANSPORTATION PTE LTD]
SME Motor Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)
View [View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	18/09/19 13:44	Repairer Estimates	Load HTM	
2	10/10/19 12:43	Repairer Estimates Suppl. #1	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/10/19 10:22	General View	Load JPG	☒
2	22/10/19 10:22	General View	Load JPG	☒
3	22/10/19 10:22	General View	Load JPG	☒
4	22/10/19 10:22	General View	Load JPG	☒
5	22/10/19 10:22	General View	Load JPG	☒
6	22/10/19 10:22	General View	Load JPG	☒
7	22/10/19 10:22	General View	Load JPG	☒
8	22/10/19 10:22	General View	Load JPG	☒
9	22/10/19 10:22	General View	Load JPG	☒
10	22/10/19 10:22	General View	Load JPG	☒
11	22/10/19 10:22	General View	Load JPG	☒
12	22/10/19 10:22	General View	Load JPG	☒
13	22/10/19 10:22	General View	Load JPG	☒
14	22/10/19 10:22	General View	Load JPG	☒
15	22/10/19 10:22	General View	Load JPG	☒
16	22/10/19 10:22	General View	Load JPG	☒
17	22/10/19 10:22	General View	Load JPG	☒
18	22/10/19 10:22	General View	Load JPG	☒
19	22/10/19 10:22	General View	Load JPG	☒
20	22/10/19 10:22	General View	Load JPG	☒
21	22/10/19 10:22	General View	Load JPG	☒
22	22/10/19 10:22	General View	Load JPG	☒
23	22/10/19 10:22	General View	Load JPG	☒
24	22/10/19 10:22	General View	Load JPG	☒
25	22/10/19 10:22	General View	Load JPG	☒
26	22/10/19 10:22	General View	Load JPG	☒
27	22/10/19 10:22	General View	Load JPG	☒
28	22/10/19 10:22	General View	Load JPG	☒
29	22/10/19 10:22	General View	Load JPG	☒
30	22/10/19 10:22	General View	Load JPG	☒
31	22/10/19 10:22	General View	Load JPG	☒
32	22/10/19 10:22	General View	Load JPG	☒
33	22/10/19 10:22	General View	Load JPG	☒
34	22/10/19 10:22	General View	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	18/09/19 13:44	E-filed GIA report	Load PDF	
2	18/09/19 13:46	LTA SEARCH	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
1	19/09/19 08:37	SME Motor Pte Ltd (Kaki Bukit)			Load PDF
		Singapore Accident Statement			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/10/19 17:05	TP ESTIMATE- MARKED			Load PDF
2	22/10/19 10:25	LOD AND OTHER DOCUMENTS			Load PDF
3	21/11/19 15:30	LTA SEARCH			Load PDF
4	04/02/20 10:21	WORKSHOP INVOICE			Load PDF
5	04/02/20 10:21	AUTHORISATION TO ACT FORM			Load PDF
6	04/02/20 10:21	DISCHARGE VOUCHER			Load PDF
7	04/02/20 10:21	LOD			Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19016568/UGS3Q2

Date: 04/02/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant
 Vehicle No: SLV4509R Insured Vehicle No: SH6433C
 Date of Loss: 15/09/2019 Nature of Claim: TP Claim No: MCT19090322

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV4509R
 Make & Model: HONDA VEZEL, 1.5 HYBRID X (A) Engine No: LEB5957578
 Reg. Date: 29/12/2017 (Man. Year: 2017) Chassis No: RU31257561
 Colour: Red Odometer: 26388 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,534.72	861.60	673.12	43.86
Miscellaneous Items	261.00	11.00	250.00	95.79
Labour	970.00	780.00	190.00	19.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,765.72	1,652.60	1,113.12	40.25
+ GST 7.00/7.00% (S\$)	193.60	115.68	77.92	40.25
Nett Amount (S\$)	2,959.32	1,768.28	1,191.04	40.25
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,955.73		

INSPECTION

Date of Assignment: 19/09/2019 Present Location: SME Motor Pte Ltd (Kaki Bukit)
 Date Inspected: 30/09/2019 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
 1 Kaki Bukit Ave 6 #02-15, AutoBay @
 Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV4509R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deep Cut	801.00 FL	*801.00 FL
2	1		*FRT BUMPER RETAINER RH	Not Necessary	28.00 FL	*- FL
3	10		*FRT BUMPER CLIP	Necessary	55.00 FL	*55.00 FL
4	1		*FRT BUMPER LOWER SPOILER	Repair	391.00 FL	*- FL
5	6		*FRT FENDER PROTECTOR CLIP	Not Necessary	35.40 FL	*- FL
6	1		*FRT FENDER EMBLEM HYBRID RH	Not Necessary	221.00 FL	*- FL
7	1		*FRT FENDER RH	Repair	387.00 FL	*- FL
8	1		*FRT FENDER OUTER PROTECTOR RH	Distorted	-	*221.00 FL
					Sub Total (S\$)	1,918.40
					- List Item Discount on L Items 20.00/20.00% (S\$)	383.68
					Total Parts (S\$)	1,534.72
						861.60

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT SPORT RIM RH (REPAIR)	250.00	0.00
2	1	OD/TP Case (Insurer) (NECESSARY)	11.00	11.00
Sub Total (S\$)			261.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	20.00	20.00
2	LABOUR CHARGE	New	450.00	280.00
3	SPRAY PAINTING	New	500.00	480.00
Gross Labour Cost (S\$)			970.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >