

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

TP INSURER: India International Insurance Pte Ltd (HQ)

MOHAMMAD SHAM BIN JAMIL

BLK 274B PUNGGOL PLACE #08-824

Singapore 822274

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	19/III/TP-192 (09)
Policy No:		Date of Loss:	15/09/2019
Vehicle Reg. No.:	SLV4509R	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	MOHAMMAD SHAM BIN JAMIL	Driver (Insured):	MOHAMMAD SHAM BIN JAMIL

Make/Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Vehicle Reg. Date:	29/12/2017
Vehicle Colour:	RED		
Engine No:	LEB5957578	Chassis No:	RU31257561
Odometer:	0 KM		

Paint Type:	
List Item Discount:	20.00 %
Total Loss?	NO
Est. Duration of Repair (day)	7

p/28

not Admitted
 here
 30/9/19
 The 1st Surveyor
 3 dy.

Description of Accident/Loss	VEHICLE B ENTERING THE CARPARK. AT THE BEND, I SAW VEHICLE B GETTING NEAR MY VEHICLE AND ENTERING MY LANE. I CAME TO A COMPLETE STOP AND HORN HIM. BUT VEHICLE B STILL HIT ONTO MY RIGHT SIDE.
------------------------------	--

Remarks: VEHICLE NOT IN.

Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS

Parts

Miscellaneous Items

Labour

Paintwork Labour

Towing

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Gross Total (\$\$)**+ GST 7.00% (\$\$)****Amount**

1,534.72

261.00

970.00

0.00

0.00

2,765.72**193.60**

Nett Amount (S\$) 2,959.32

This claim is handled by: CHIA PEI YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 18 Sep 2019)**Parts:** M1-SUV **HONDA VEZEL 1.5 HYBRID X (A)** (Catalogue: Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** SME Motor Pte Ltd/SLV4509R/18/09/2019 13:44**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER	20.00	0.00	*801.00 FL ✓
2	1		*FRT BUMPER RETAINER RH	20.00	0.00	*28.00 FL X
3	10		*FRT BUMPER CLIP	20.00	0.00	*55.00 FL ✓
4	1		*FRT BUMPER LOWER SPOILER	20.00	0.00	*391.00 FL X
5	6		*FRT FENDER PROTECTOR CLIP	20.00	0.00	*35.40 FL ?
6	1		*FRT FENDER EMBLEM HYBRID RH	20.00	0.00	*221.00 FL ?
7	1		*FRT FENDER RH	20.00	0.00	*387.00 FL X
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)						1,918.40
- List Item Discount on L Items (S\$)						383.68
Total Parts (S\$)						1,534.72

SME Motor Pte Ltd/SLV4509R/18/09/2019 13:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRT SPORT RIM RH	<i>rx</i> 250.00
2	1	OD/TP Case (Insurer)	<i>mu</i> 11.00
Sub Total (S\$)			261.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	20.00
2	LABOUR CHARGE	New	<i>280</i> 450.00
3	SPRAY PAINTING	New	<i>480</i> 500.00
Gross Labour Cost (S\$)			970.00

SME Motor Pte Ltd/SLV4509R/18/09/2019 13:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >