

ACT RECORD

REF: 08/11/19016590/Gtd3e2 Special InstructionSurvey: Steve

ASSIGNMENT (Office)

From (Person): Chang Boon Sen of CTF Date/Time: 19/9/19 @ 1:11pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: 8MK 5140J Insured: SJC 9595Gat Workshop in/ Kah Motor Tel: 82886302of 6A Menden estimatePolicy No: DMPCLN30563919011 Claim No: SNM19D20411

Sum Insured: _____ Receipt: _____

Make of Veh: _____ D.O.A. 17/09/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 2:01pm @ 19/9/19 Person Contacted: Anukken Vehicle IN OUT

Date/Time	Action/Instruction
	<u>1. already ✓</u>
	<u>8MK 5140J - X</u>
	<u>SJC 9595G - X</u>
	<u>Part by Part \$20,593.75 (Red: 1385.47; 67%)</u>

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 19 September 2019 1:11 PM
To: Anikka Lai
Cc: assignments
Subject: RE: OUR REF: SNM19D204411-SJC9595G-CBS & YOUR REF: SMK5140J - TP CLAIMS AGAINST SJC9595C DOA: 17/09/2019- TO CONDUCT PRS

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis. Please merimen.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Anikka Lai [mailto:anikkalai@honda.com.sg]
Sent: Thursday, September 19, 2019 12:06 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: OUR REF: SNM19D204411-SJC9595G-CBS & YOUR REF: SMK5140J - TP CLAIMS AGAINST SJC9595C DOA: 17/09/2019- TO CONDUCT PRS
Importance: High

Dear Boon Sen,

Pls assign LKK to survey the vehicle.

Thank you.

Warmest regards
Anikka Lai
6A Mandai Estate
Singapore 729903
DID : 65145248 HP: 82886302
Email add: anikkalai@honda.com.sg

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Thursday, 19 September 2019 12:04 PM

To: Anikka Lai <anikkalai@honda.com.sg>

Subject: RE: OUR REF: SNM19D204411-SJC9595G-CBS & YOUR REF: SMK5140J - TP CLAIMS AGAINST SJC9595C DOA: 17/09/2019- TO CONDUCT PRS

Without prejudice

Dear Sir,

LKK

STA

LBS

Chong Boon Sen

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson

Road #16-00 Springleaf Tower Singapore 079909

DID (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, September 19, 2019 11:46 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; anikkalai@honda.com.sg

Subject: OUR REF: SNM19D204411-SJC9595G-CBS & YOUR REF: SMK5140J - TP CLAIMS AGAINST SJC9595C DOA: 17/09/2019- TO CONDUCT PRS

Importance: High

Dear Boon Sen,

Please conduct PRS-SMK5140J –soonest possible

File with officer-in charge –Chong Boon Sen –DID: 6389 6171

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Tel: 6389 6116

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Anikka Lai [<mailto:anikkalai@honda.com.sg>]

Sent: Wednesday, September 18, 2019 4:34 PM

To: Claims Dept of CTI; Jowyn Tay; Henry, Irene James

Subject: SMK5140J - TP CLAIMS AGAINST SJC9595C DOA: 17/09/2019

Importance: High

Dear Sir / Madam,

Attached pls find the claim documents for your necessary action. Kindly arrange survey at our premises urgently as the vehicle was towed in from the accident scene.

Attached video footage with your insured admitted his mistake. Pls expedite the liability of direct settlement.

Thank you.

Warmest regards

Anikka Lai

6A Mandai Estate

Singapore 729903

DID : 65145248 HP: 82886302

Email add: anikkalai@honda.com.sg

From: Printer Service <printservice@honda.com.sg>

Sent: Wednesday, 18 September 2019 4:27 PM

To: Anikka Lai <anikkalai@honda.com.sg>

Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	722D
Vehicle Details	
Vehicle No.:	SMK5140J
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 CVT
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	L15B34100294
Chassis No.:	JHMGK5850KS204561
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$16,946.00
Original Registration Date:	12 Apr 2019 ✓
First Registration Date:	12 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$16,946.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Apr 2029
PARF Rebate Amount:	\$12,709.00
Intended COE Rebate Details	
COE Expiry Date:	11 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,689.00
COE Rebate Amount:	\$24,565.00
Total Rebate Amount:	\$37,274.00

The information contained herein is correct as at 19 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/09/2019 13:59
Date Of Accident	17/09/2019 12:55
Exact Location Of Accident	BT BATOK RD B4 BT BATOK WEST AVE 5 JCTN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK5140J
Insured/Policyholder	
Name Of Registered Owner	JANE LAZAROO NEE LYN YOKE CHOO
NRIC No	S0187722D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96348892
Alternative Phone No	OFFICE-96348892

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ 1.5 VTI
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	JANE LAZAROO NEE LYN YOKE CHOO
NRIC No	S0187722D
Date Of Birth	03/04/1954
Occupation	INDOOR
Date Of Driving Pass	28/03/1978
Driving Experience	41 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96348892
Fax Number	
Contact Number	OFFICE-96348892
EMail Address	NOEMAIL

Address -
 Postcode -
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BUKIT PANJANG
 Police Station Address ROAD: 1 SEGAR ROAD , POSTCODE: 677738 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-8929999 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS ANNEX D&E POLICE REPORT NO. T/20190918/2026

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: RETAIN BY TP
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJC9595G
 Vehicle Make/Model/Colour TOYOTA CROWN / WHITE
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver JASON KOH
 NRIC/Passport Number
 Contact Number 91687888
 Address
 Postcode
 Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	JANE LAZAROO NEE LYN YOKE CHOO
Approximate Age	
Injuries Sustain	NECK
Injured person in which vehicle?	SMK5140J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Vehicle Number: SMK 5140J

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190918/2026

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

1 of 4

Report No. T/20190918/2026

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/09/2019 09:29		Vide Report No.: J/20190917/0076		Station Diary No.: 21	
Informant's Particulars					
Name of Informant: MRS JANE LAZAROO NEE LYN YOKE CHOO			Address: 28 JALAN LEMPENG #02-03 SINGAPORE 128807		
ID Type / ID No.: NRIC NO / S0187722D			Contact No.: Home/Office: Mobile: 96348892		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 65	Date of Birth: 03/04/1954	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Retiree			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/09/2019 12:55	Type of Location: T-Junction
Location: Along Road 1 BUKIT BATOK ROAD				
T-JUNCTION OF BUKIT BATOK ROAD TOWARDS PIE DIRECTION AND BUKIT BATOK WEST AVE 5				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJC9595G	Car	TOYOTA		White		0
SMK5140J	Car	HONDA	JAZZ 1.5 CVT	Red		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMK5140J	AVIVA LTD	10912689	12/04/2019	11/04/2021



**SINGAPORE
POLICE FORCE**



T/20190918/2026

2 of 4

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20190918/2026

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	JASON KOH	ID No.	NIL
Related Vehicle	SJC9595G (Car)	Contact No.	91687888
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MRS JANE LAZAROO NEE LYN YOKE CHOO	ID No.	S0187722D
Related Vehicle	SMK5140J (Car)	Contact No.	96348892
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	17/09/2019	Date Discharge	17/09/2019
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 17/09/09 at about 1250hrs I was driving my vehicle bearing SMK5140J along Bukit Batok road towards PIE direction. Along a T-junction of Bukit Batok road and Bukit Batok west Ave 5, the traffic light was red hence I stop my vehicle, on lane 2. About 3 to 4 seconds after my vehicle was stationary on the road, I heard a very loud bang coming from the rear left end portion of my vehicle. The impact caused my vehicle to surge forward and swirled towards the right side of the road, approximately 15 feet away from the original location where I stopped my vehicle.

Upon collision, I put my vehicle to park position mode and activated the hand brake. I switched off the engine and I proceed down to make a check. I discovered that SJC9595G had collided onto my vehicle, causing the road traffic accident. Particulars between the driver of SJC9595G and myself were exchanged. The driver of SJC9595G identified himself as Mr Jason Koh HP:91687888. Photos of the scene were taken. Subsequently SCDF, paramedic and police arrive at scene. Subsequently, I was conveyed to Ng Teng Fong hospital by the paramedics as I felt pain on the back of my neck due to the collision. My husband came down to the scene to make a check on me and also to take over the vehicle. There is a in car camera in my vehicle and the SD was hand over to the traffic police officer at scene by my husband. Acknowledgement form was given to my husband by the traffic police officer who took over the SD card from my husband. My vehicle had to be tow as it was not able to drive off.

I was at Ng Teng Fong hospital for medical treatment. I suffered whiplash and after an examination, x-ray and medication was discharged on 17/09/2019 at 1550hrs. On 18/09/19 at about 0842hrs I received a call



**SINGAPORE
POLICE FORCE**



T/20190918/2026

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

3 of 4

Report No. T/20190918/2026

CONTINUATION OF REPORT

from Traffic Police Investigation officer and was advised to lodge a traffic police report.



**SINGAPORE
POLICE FORCE**



T/20190918/2026

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

4 of 4

Report No. T/20190918/2026

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /
Sgt 3 YIM ZI KUEI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /
Sgt 3 RASHIDAH BINTE AZMAN
Contact No: 65476216

SN 117

Authentication Stamp
NP168

Singapore Police Force

Signature Of Informant:

Date/Time:

18/09/2019 09:29

Classification Of Case:



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Classic Offer! Best Deal/Fast Selling! Hurry Down Now!



Flexible Loan, Trade In And
Welcome Refund For
Sapereview Loan
Classic Credit

Lake View Credit Pte Ltd

[view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

11 vehicles

[Advanced Search](#)


Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Jazz	Any	Any	2018	Any	Any	Any	Available
	Honda Jazz 1.5A RS	\$68,800	\$7,290 /yr	09-Jan-2018	1,498 cc	33,000 km	Hatchback	Available
Cheapest Unit, Not A PHV Unit, 5 Years Unlimited Mileage Warranty By Kah Motor, 1 Owner, Keyless Entry, Reverse Camera, Bluetooth, Accident Free, Price Still Negotiable, Showroom Condition, Call For Viewing Now!								
Posted: 19-Sep-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.3A (OPC)	\$53,000	\$5,970 /yr	27-Feb-2018	1,318 cc	16,000 km	Hatchback	Available
OPC Unit, Very Well Maintained Unit. 1 Owner! 3 Years Free Servicing, 5 Years Unlimited Mileage Warranty Package! Conversion To Normal Plate Available, Call Us Now To Enquire More. Trade-In/Flexible Loan Available, Viewing By Appointment Only!								
360 VR Cars								
Posted: 26-Jul-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.3A LX	\$62,800	\$7,020 /yr	09-Apr-2018	1,318 cc	26,000 km	Hatchback	Available
Facelift Model! Attractive Interest Rates! Flexible In-house Loan! Balance 4 Times Free Agent Servicing With 5 Years On-going Warranty! Previously Own By Lady Owner. Lower Fuel Consumption Yet Powerful! Accident Free! Professional Evaluation By STA! Buy It Fro...								
Dickson Automobile								
Posted: 08-Sep-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.3A LX	\$61,888	\$6,900 /yr	12-Apr-2018	1,318 cc	6,200 km	Hatchback	Available
Agent Warranty Till March 2023 For Peace Of Mind! Lowest Mileage And Depreciation In The Market. Most Popular Hot Hatch In Pearl White! Extremely Spacious Cabin For A Hatchback! Engine Revs Is Kept Low With Its 1.3L Intelligent EarthDreams Engine Mated To A C...								
Autocars Premium Pte Ltd								
Posted: 07-Aug-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Precise Auto Service - Specialist for Honda Car repair, servicing & maintenance							
Your Trusted Car Workshop, a one-stop car workshop specialising in Japanese cars.								
More info about this shop								
	Honda Jazz 1.5A RS	\$70,800	\$7,250 /yr	26-Apr-2018	1,498 cc	37,500 km	Hatchback	Available
Lowest Depre In RS Market, Well Maintained By Owner, Warranty Till 2021. Full-Service History With Agent. Sparking Rouge Amethyst Metallic Exterior Couple With Original GKS Mugen Bodykits. Jazz's Airy & Spacious Cabin Easily Fits Five Adults Without Elbow-warfare Br...								
Car Buyers Automotive Pte Ltd								
Posted: 13-Sep-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.5A RS (OPC)	\$61,800	\$6,180 /yr	02-May-2018	1,498 cc	21,000 km	Hatchback	Available
Best Selling Model And Hatchback In The Market, Proven Famous For Fuel Economy Drive, Powerful And Smooth, Hassle Free And Easy Maintenance, Fully Serviced And Maintained By Agent Kah Motors, Agent 5 Year Warranty Vehicle, Flexi Loan Scheme Available, Owner...								
Posted: 05-Sep-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								
	Honda Jazz 1.5A RS	\$78,800	\$7,900 /yr	15-Aug-2018	1,498 cc	15,000 km	Hatchback	Available
1 Owner Low Mileage Unit! Fully Serviced By Kah Motors With 5 Years Warranty And 3 Years Servicing Package. Very Well Taken Care, Sheltered Carpark, Fuel Efficient And Responsive Drive, ECU Tuned, Don't Miss This Unit! Selling To Upgrade. Trade In And Flexible Loan...								
Cars								
Posted: 12-Sep-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda								



Honda Jazz 1.3A **\$63,800** **\$6,830 /yr** **15-Aug-2018** **1,318 cc** **6,900 km** **Hatchback** **Available**

From Kah Motor. 3 Years Free Servicing And 5 Years Warranty (Unlimited Mileage). Under Utilize. Midnight Blue. My Loss Is Your Gain. As Good As New. 100% Accident Free. Spare Vehicle In The House Hold. Just Renewed Road Tax, Higher Loan Quantum Financing And Tra...

Posted: 07-Sep-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda

DIRECT OWNER



Honda Jazz 1.3A LX **\$66,800** **\$7,110 /yr** **12-Sep-2018** **1,318 cc** **11,236 km** **Hatchback** **Available**

Superb Condition. Almost Like A New Car Driven Out From Kah Motor Showroom! Second Car In The Family. Owner Selling Due To Cut Cost. Comes With Branded iRoad V9 Front & Back Recording Cameras. Agent Warranty Until 2023 For Your Peace Of Mind Buy. We Can...

Posted: 17-Aug-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda

PREMIUM CD



Honda Jazz 1.5A RS (OPC) **\$62,800** **\$5,990 /yr** **09-Oct-2018** **1,498 cc** **4,075 km** **Hatchback** **Available**

As Good As Brand New Unit With Only 4K Km Mileage Done! Able To Do Conversion To Normal Plate. Agent Serviced And Still Under Warranty. Don't Miss! Loan And Trade In Options Available. Call For A Viewing Appointment Today!

Mayfair Motoring

Posted: 16-Sep-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda

PREMIUM CD



Insurance renewal at cheaper price!

We'll find you the cheapest car insurance quotes from over 10 insurers. Make your choice on zero excess and own workshop. Everything done at the comfort of your own home. Roadside assistance & claims support completely free.

Find out more!



Honda Jazz 1.3A **\$66,800** **\$7,000 /yr** **08-Nov-2018** **1,318 cc** **16,000 km** **Hatchback** **Available**

1 Owner Agent Unit With Warranty Till 2023. Extremely Spacious Cabin And Very Versatile Rear Seats To Cater To Your Different Carrying Needs. Competitive Trade In. Bank And In House Finance Available. Speak To Our Sales Team Today.

Posted: 24-Aug-2019 Tags: 2018 Honda Jazz, 2018 honda jazz, Honda Jazz, honda jazz, Honda, Jazz, jazz, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Used Eng Cap Mileage Veh Type Show All

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda Jazz, Honda Jazz Singapore, used Honda Jazz Singapore, used Honda Jazz, used vehicles Singapore or even buy used Honda Jazz Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT19004118	Page	1
Registration No	: SMK5140J	Date	: 18. Sep 2019	Customer No.	: WZC008
Chassis No	: JHMGK5850KS204561	Svc Advisor	: ANIKKA LAI SWEE KAM	Engine No	: L15B34100294
Model	: JAZZ 1.5VTIR CVT 19YM (EURO 6)	Date Time	: 18. Sep 2019 2:57:44 PM	Surveyor Name	:
Owner's Name	: MRS JANE LAZAROO NEE LYN YOKE	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 17/9/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: JANE LAZAROO NEE LYN YOKE CHOO OWNER INSURER: AVIVA ACC DATE: 17/09/2019 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: SJC9595G						
04646-TAR-320ZZ	PANEL SET,L.RR.OUTSIDE / DP	1	570.50	5	541.97 /	37.94	579.91
63720-T5A-900ZZ	GUTTER COMP,L.RR.PILLAR LOWER / DP	1	88.60	5	84.17 /	5.89	90.06
65590-T5A-N00ZZ	STIFFENER COMP,L.RR.SIDE ? / DP	1	86.90	5	82.55 /	5.78	88.33
66100-TAR-T10ZZ	PANEL COMPRR. / DP	1	320.40	5	304.38 /	21.31	325.69
68100-T5B-Z50ZZ	TAILGATE COMP / DP	1	730.60	5	694.07 /	48.58	742.65
68210-T5A-J03ZZ	HINGE COMPTAILGATE X NAI	2	30.80	5	58.52	4.10	62.62
74440-T5A-003	WEATHERSTRIPTAILGATE X NAI	1	92.30	5	87.68	6.14	93.82
74800-T5S-K61	LOCK ASSY,TAILGATE X NAI	1	85.50	5	81.22	5.69	86.91
74820-T5C-J01	STAY ASSYR.TAILGATE OPEN X NAI	1	94.00	5	89.30	6.25	95.55
74870-T5C-J01	STAY ASSYL.TAILGATE OPEN X NAI	1	94.00	5	89.30	6.25	95.55
75722-T5L-T01	EMBLEMRR. / DEC	1	10.90	5	10.35 /	0.72	11.07
75723-TE7-K90	EMBLEMRR.RS X DEC NAI	1	17.80	5	16.91	1.18	18.09
74890-T5B-911	GARNISH ASSYRR.LICENSE X NAI	1	200.60	5	190.57	13.34	203.91
75701-T5A-000	EMBLEMH X NAI	1	10.70	5	10.16	0.71	10.87
90301-ST0-003	NUTPUSH 3MM X NAI	2	2.10	5	3.99	0.28	4.27
33550-T5A-J02	TAILLIGHT ASSYL. / SCR	1	223.90	5	212.70 /	14.89	227.59
34155-T5A-J01	LIGHT ASSYL.LID X NAI	1	81.70	5	77.61	5.43	83.04
04715-T5B-J50ZZ	FACE,RR.BUMPER - DP	1	502.50	5	477.37 /	33.42	510.79

Printed on 18/9/2019 4:25:51 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SMK5140J

Chassis No : JHMGK5850KS204561

Model : JAZZ 1.5VTIR CVT 19YM (EURO 6)

Owner's Name : MRS JANE LAZAROO NEE LYN YOKE

Ins Policy No. :

Date of Accident : 17/9/2019

Document No. : SQT19004118 Page 2

Date : 18. Sep 2019

Customer No. : WZC008

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L15B34100294

Date | Time : 18. Sep 2019 2:57:44 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71507-T5A-J60	COVER,L.RR.BUMPER / BR <i>BR</i>	1	20.70	5	19.66	1.38	21.04
71502-T5A-J60	COVER,R.RR.BUMPER X <i>NAI</i>	1	20.70	5	19.66	1.38	21.04
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR <i>DR</i>	1	206.80	5	196.46	13.75	210.21
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE / <i>DR</i>	1	16.90	5	16.05	1.12	17.17
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE / <i>DR</i>	1	16.90	5	16.05	1.12	17.17
91505-TM8-003	CLIP,BUMPER / <i>NOL</i>	9	2.30	5	19.66	1.38	21.04
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER / <i>CR4</i>	1	53.70	5	51.01	3.57	54.58
84441-T5A-003ZB	POCKETTAILGATE LINING PULL X <i>NAI</i>	1	5.10	5	4.84	0.34	5.18
84521-T5A-901ZA	LID ASSYSPARE TIRE X <i>NAI</i>	1	189.80	5	180.31	12.62	192.93
84550-TAS-U00	BOX ASSY,CARGO FLOOR X <i>NAI</i>	1	110.60	5	105.07	7.35	112.42
84651-TAR-Z03ZA	LINING ASSYL,TRUNK / <i>CR4</i>	1	169.00	5	160.55	11.24	171.79
84640-T5A-003ZA	LINING ASSYRR.PANEL X <i>NAI</i>	1	60.80	5	57.76	4.04	61.80
D-185/55R16SP2030	DUNLOP TYRE / <i>TM</i>	1	225.00		225.00	15.75	240.75
42700-TAR-E91	DISK ALUMINIUM WHEEL,16X6 / <i>SCR</i>	1	772.30	5	733.68	51.36	785.04
67550-TAR-306ZZ	PANEL COMPL,RR.DOOR X <i>R</i>	1	689.60	5	655.12	45.86	700.98
73225-TF0-000	RUBBER A WSHIELD DAM / <i>Nec X SVC</i>	1	37.00	5	35.15	2.46	37.61
73226-TF0-000	RUBBER B WSHIELD X <i>Nec X SVC</i>	1	32.10	5	30.49	2.13	32.62
73228-TF0-000	RUBBER D WSHIELD DAM / <i>Nec X SVC</i>	2	4.90	5	9.31	0.65	9.96
75717-SNB-E01	STICKER I-TEC / <i>Nec X SVC</i>	1	12.60	5	11.97	0.84	12.81
91501-S70-003	FASTENER BW/SHIELD / <i>Nec X SVC</i>	4	5.30	5	20.14	1.41	21.55
91502-S70-003	FASTENER B / <i>Nec</i>	2	5.30	5	10.07	0.70	10.77
91536-SS0-J01	FASTENER AW/SHIELD / <i>Nec</i>	2	3.80	5	7.22	0.51	7.73
BO-WS-SEALANT	WINDSCREEN SEALANT (N) / <i>Nec</i>	1	60.00		60.00	4.20	64.20
73450-T5A-000	GLASS ASSYL,RR.DOOR X <i>Nec X NAI</i>	1	219.40	5	208.43	14.59	223.02
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR / <i>Shut (1set)</i>	1	320.00		320.00	22.40	342.40
Sum Item					6286.48	440.05	6,726.53
BOSUN	SUNDRIES	1	100.00	50	100.00	7.00	107.00
BG02R	REPLACE RR, WINDSCREEN.(N)	1	560.00	/	560.00	39.20	599.20

Printed on 18/9/2019 4:25:51 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SMK5140J

Chassis No : JHMGK5850KS204561

Model : JAZZ 1.5VTIR CVT 19YM (EURO 6)

Owner's Name : MRS JANE LAZAROO NEE LYN YOKE

Ins Policy No. :

Date of Accident : 17/9/2019

Document No. : SQT19004118

Date : 18. Sep 2019

Customer No. : WZC008

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L15B34100294

Date | Time : 18. Sep 2019 2:57:44 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	600.00	520	600.00	42.00	642.00
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	600.00	1380	600.00	42.00	642.00
BG21R	REPLACE RR. L DOOR GLASS.(N) include tinted	1	250.00	250	250.00	17.50	267.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00	320	450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00	320	450.00	31.50	481.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00	/	120.00	8.40	128.40
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT LHR FENDER	1	100.00	80	100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	80	100.00	7.00	107.00
GSG96R	INSTALL RIMS & TYRES	1	150.00	80	150.00	10.50	160.50
BKRP21M	CUT OFF & RENEW RR PANEL, LHR FENDERS & DAMAGE PA 11 days	1	4500.00	2800	6100	450.00	4815.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P) 8.5 x 4.50 7.5	1	3500.00	2225	3375	350.00	3745.00
Sum Labor					11780.00	824.60	12,604.60

Survey By : Jave / Pm

Date & Time : 14/09/2019 @ 1.10pm

Excess :

Status : P/P Repair

Signature : Jave

Total Amount 18,066.48 1,264.65 19,331.13

Total (Inclusive of GST) 19,331.13

TP
Without prejudice -
Repair day - 18 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 18/9/2019 4:25:51 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S80FC1380G

Customer: CU0016608 / MRS JANE
Chassis No: JHMGK5850KS204561
License No: SMK5140J
Mileage: 5155
Engine No: L15B34100294

Document No: SVO19060909
Printed By: ANIKKALAI
Order Date: 19. September 2019
Order Time: 6:12:58 PM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount Includ	GST
	SUPPLEMENTARY PARTS & LABOUR :-						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER / <i>APC</i>	1	11.40	25	10.83 8.55 /	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER / <i>APC</i>	2	6.50	25	12.35 9.75 /	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5 / <i>APC</i>	1	8.50	25	8.07 6.37 /	0.45	6.82
65590-T5A-N00ZZ	STIFFENER COMP.LRR.SIDE / <i>RPT</i>	1	86.90	25	81.55 65.17 X	4.56	69.73
65619-T5A-300ZZ	FLANGERR.FRAME END / <i>BO</i>	1	11.00	25	10.45 8.25 /	0.58	8.83
73525-SYY-000	RUBBERRR QTR W/SHIELD / <i>APC</i>	2	9.70	25	18.43 14.55 /	1.02	15.57
91501-T5A-901	CLIP A .QUARTER WINDSHIELD / <i>APC</i>	1	3.40	25	3.23 2.55 /	0.18	2.73
91502-T5A-901	CLIP B .QUARTER WINDSHIELD / <i>APC</i>	1	3.70	25	3.51 2.77 /	0.19	2.96
91503-TD4-003	CLIP C,QUARTER WINDSHIELD / <i>APC</i>	1	2.40	25	2.28 1.80 /	0.13	1.93
74591-T5B-N00	COVER,LRR.FENDER / <i>MIS</i>	1	42.80	25	40.47 31.95 /	2.24	34.19
74592-T5B-003	FENDER,LRR INNER / <i>BO</i>	1	79.00	25	75.05 59.25 /	4.15	63.40
90601-S30-003	GROMMETCOWL TOP / <i>APC</i>	2	2.00	25	3.80 3.00 /	0.21	3.21
91501-T2A-003	CLIPINNER FENDER / <i>APC</i>	2	0.40	25	0.76 0.60 /	0.04	0.64
91501-TR0-003	CLIP INNER FENDER / <i>APC</i>	4	2.80	25	10.64 8.40 /	0.59	8.99
75450-SAA-013	OUTLETRR AIR / <i>OR</i>	1	25.20	25	23.94 18.90 /	1.32	20.22
90650-SZT-003	GROMMETRR.COMBINATION LIGHT / <i>APC</i>	1	2.50	25	2.37 1.87 /	0.13	2.00
93903-25320	SCREWTAPPING 5X16 / <i>APC</i>	2	0.40	25	0.76 0.60 /	0.04	0.64
90103-TA0-000	SCREW TAPPING 5 X 20 / <i>APC</i>	2	4.00	25	7.60 6.00 /	0.42	6.42
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR / <i>RPT</i>	1	206.80	25	196.46 155.10 X	10.86	165.96
84640-T5A-003ZA	LINING ASSYRR.PANEL / <i>APC</i>	1	60.80	25	57.76 45.60 /	3.19	48.79
90667-SWZ-003ZA	CLIPTRIM 7MM / <i>APC</i>	2	2.30	25	4.39 3.45 /	0.24	3.69
64700-TAS-325ZZ	PANEL COMP,LRR.INSIDE / <i>BO</i>	1	520.00	25	494.00 390.00 /	27.30	417.30
65662-T5A-300ZZ	FRAME BL.RR. / <i>BO</i>	1	45.90	25	43.60 34.42 /	2.41	36.83
42200-T5B-N52	BEARING ASSYRR.HUB / <i>jump</i>	1	287.50	25	273.12 15.62 /	15.09	230.71
42100-T5A-J75	BEAM ASSYRR.AXLE / <i>OT</i>	1	911.00	25	865.55 683.25 /	47.83	731.08
	SUM PARTS:				1,777.77	124.45	1,902.22
BMU02R	REMOVE & REPLACE RR UNDERCARRIAGE PARTS. (N)	1	560.00		560.00 /	39.20	599.20
BKOT00A	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT	1	1,200.00		1,200.00 /	84.00	1,284.00
	SUM LABOUR:				1,760.00	123.20	1,883.20
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00 /	12.60	192.60
	SUM EXT SERVICE:				180.00	12.60	192.60
	TOTAL SGD				3,717.77	260.25	3,978.02

Total Payable (SGD)

3,978.02

GST Amount is calculated from individual line(s)

3912-84

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5456 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0016608 / CHINA TAIPING
 Chassis No: JHMGK5850KS204561
 License No: SMK5140J
 Mileage: 5155
 Engine No: L15B34100294

Document No: SVO19060909
 Printed By: ANIKKALAI
 Order Date: 19. September 2019
 Order Time: 6:12:58 PM
 Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: JANE LAZAROO NEE LYN YOKE CHOO						
	OWNER INSURER: AVIVA						
	ACC DATE: 17/09/2019						
	SURVEYED BY: STEVE / LKK						
	DATE: 19/09/2019						
	REF NO:						
	TP INSURER: CHINA TAIPING						
	TP VEH: SJC8595G						
	SUPPLEMENTARY PARTS & LABOUR :-						
04646-TAR-320ZZ	PANEL SET,L,RR.OUTSIDE	1	570.50	5	✓ 541.97	37.94	579.91
63720-T5A-900ZZ	GUTTER COMP,L,RR.PILLAR LOWER	1	88.60	5	✓ 84.17	5.89	90.06
66100-TAR-T10ZZ	PANEL COMPRR.	1	320.40	5	✓ 304.38	21.31	325.69
68100-T5B-Z50ZZ	TAILGATE COMP	1	730.60	5	✓ 694.07	48.58	742.65
75722-T5L-T01	EMBLEMRR.	1	10.90	5	✓ 10.35	0.72	11.07
33550-T5A-J02	TAILLIGHT ASSYL.	1	223.90	5	✓ 212.70	14.89	227.59
04715-T5B-J50ZZ	FACE,RR.BUMPER	1	502.50	5	✓ 477.37	33.42	510.79
71507-T5A-J60	COVER,L,RR.BUMPER	1	20.70	5	✓ 19.66	1.38	21.04
71593-T5A-J50	SPACER,R,RR.BUMPER SIDE	1	16.90	5	✓ 16.05	1.12	17.17
71596-T5A-J50	SPACER,L,RR.BUMPER SIDE	1	16.90	5	✓ 16.05	1.12	17.17
91505-TM8-003	CLIP,BUMPER	9	2.30	5	✓ 19.66	1.38	21.04
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	53.70	5	✓ 51.01	3.57	54.58
84651-TAR-Z03ZA	LINING ASSYL,TRUNK	1	169.00	5	✓ 160.55	11.24	171.79
D-185/55R16SP2030	DUNLOP TYRE	1	225.00		✓ 225.00	15.75	240.75
42700-TAR-E91	DISK ALUMINIUM WHEEL,16X6	1	772.30	5	✓ 733.68	51.36	785.04
91501-T5A-J01	FASTENER C WINDSHIELD	4	0.80	5	✓ 3.04	0.21	3.25
91502-S70-003	FASTENER B	2	5.30	5	✓ 10.07	0.70	10.77
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	5	✓ 7.22	0.51	7.73
BO-W5-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		✓ 60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		✓ 320.00	22.40	342.40
73127-TY0-000	RUBBER C WINDSHIELD DAMPER	1	11.40	5	✓ 10.83	0.76	11.59
73214-T5A-013	RUBBER WINDSHIELD DAMPER	2	6.50	5	✓ 12.35	0.86	13.21
73226-SZW-000	DAMPER STD 5X5	1	8.50	5	✓ 8.07	0.56	8.63
65590-T5A-N00ZZ	STIFFENER COMP,L,RR.SIDE	1	88.90	5	✓ 82.55	5.78	88.33
65619-T5A-300ZZ	FLANGERR.FRAME END	1	11.00	5	✓ 10.45	0.73	11.18
73525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.70	5	✓ 18.43	1.29	19.72
91501-T5A-901	CLIP A ,QUARTER WINDSHIELD	1	3.40	5	✓ 3.23	0.23	3.46
91502-T5A-901	CLIP B ,QUARTER WINDSHIELD	1	3.70	5	✓ 3.51	0.25	3.76
91503-TD4-003	CLIP C,QUARTER WINDSHIELD	1	2.40	5	✓ 2.28	0.16	2.44
74591-T5B-N00	COVER,L,RR.FENDER	1	42.60	5	✓ 40.47	2.83	43.30
74592-T5B-003	FENDER,L,RR.INNER	1	79.00	5	✓ 75.05	5.25	80.30
90601-S30-003	GROMMET COWL TOP	2	2.00	5	✓ 3.80	0.27	4.07
91501-T2A-003	CLIP INNER FENDER	2	0.40	5	✓ 0.76	0.05	0.81
91501-TR0-003	CLIP,INNER FENDER	4	2.80	5	✓ 10.64	0.74	11.38
75450-SAA-013	OUTLETRR AIR	1	25.20	5	✓ 23.94	1.68	25.62
90650-SZT-003	GROMMETRR.COMBINATION LIGHT	1	2.50	5	✓ 2.37	0.17	2.54
93903-25320	SCREW TAPPING 5X16	2	0.40	5	✓ 0.76	0.05	0.81
90103-TA0-000	SCREW TAPPING 5 X 20	2	4.00	5	✓ 7.60	0.53	8.13
71510-T5B-J50ZA	DIFFUSER ASSY,RR.PR	1	206.80	5	✓ 196.46	13.75	210.21

Ruhla



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0016808 / CHINA TAIPING
Chassis No: JHMGK5850KS204561
License No: SMK5140J
Mileage: 5155
Engine No: L15B34100294

Document No: SVO19060909
Printed By: ANIKKALAI
Order Date: 19. September 2019
Order Time: 6:12:58 PM
Service Advisor: ANIKKA LAI SWEE KAM

84640-T5A-003ZA	LINING ASSYRR.PANEL	1	60.80	5	57.76 /	4.04	61.80
90667-SWZ-003ZA	CLIPTRIM 7MM	2	2.30	5	4.37 /	0.31	4.68
64700-TAS-325ZZ	PANEL COMP.LRR.INSIDE	1	520.00	5	494.00 /	34.58	528.58
65662-T5A-300ZZ	FRAME BL.RR.	1	45.90	5	43.60 /	3.05	46.65
42200-T5B-N52	BEARING ASSYRR.HUB	1	287.50	5	273.12 /	19.12	292.24
42100-T5A-J75	BEAM ASSYRR.AXLE	1	911.00	5	865.45 /	60.58	926.03
	SUM PARTS:				6,218.85	435.31	6,654.16
BOSUN		1	50.00		50.00 /	3.50	53.50
	SUNDRIES						
BG02R	1438	1	560.00		560.00 /	39.20	599.20
	REPLACE RR. WINDSCREEN.(N)						
BKTG02R	1729	1	320.00		320.00 /	22.40	342.40
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						
BMF00D	1438	1	380.00		380.00 /	26.60	406.60
	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)						
BG21R	1438	1	250.00		250.00 /	17.50	267.50
	REPLACE RR. L DOOR GLASS.(N)						
BC012R		1	320.00		320.00 /	22.40	342.40
	RESET VEHICLE SMART ENTRY SYSTEM						
BC011R	1438	1	320.00		320.00 /	22.40	342.40
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						
BA02R	1729	1	120.00		120.00 /	8.40	128.40
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BODAMKIT		1	80.00		80.00 /	5.60	85.60
	WINDSCREEN DAM KIT.						
BOJSE	1718	1	80.00		80.00 /	5.60	85.60
	BODY JOINT SEALANT END PANEL						
BOJSE	1718	1	80.00		80.00 /	5.60	85.60
	BODY JOINT SEALANT TAILGATE						
BOJSE	1718	1	80.00		80.00 /	5.60	85.60
	BODY JOINT SEALANT LHR FENDER						
BOBC		1	80.00		80.00 /	5.60	85.60
	BODY UNDERSIDE COATING (N)						
GSG96R		1	80.00		80.00 /	5.60	85.60
	INSTALL RIMS & TYRES						
BKRP21M	1729	1	6,160.00		6,160.00 /	431.20	6,591.20
	CUT OFF & RENEW RR PANEL, LHR FENDERS & DAMAGE PA ALIGN CHASSIS INCLUDING FITTING ON ATTACHMENT ITEM						
BP06R	1718	1	3,375.00		3,375.00 /	236.25	3,611.25
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)						
BO-TOW		1	100.00		100.00 /	7.00	107.00
	TOWING SERVICES (MBBS)						
BMU02R		1	560.00		560.00 /	39.20	599.20
	REMOVE & REPLACE RR UNDERCARRIAGE PARTS. (N)						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0016608 / CHINA TAIPING
Chassis No: JHMGK5850KS204561
License No: SMK5140J
Mileage: 5155
Engine No: L15B34100294

Document No: SVO19060909
Printed By: ANIKKALAI
Order Date: 19. September 2019
Order Time: 6:12:58 PM
Service Advisor: ANIKKA LAI SWEE KAM

BKOT00A	1	1,200.00	1,200.00 /	84.00	1,284.00
PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT					
		SUM LABOUR:	14,195.00	993.65	15,188.65
BO-WHEEL ALIGN X4	1	180.00	180.00 /	12.60	192.60
		SUM EXT SERVICE:	180.00	12.60	192.60
		TOTAL SGD	20,593.85	1,441.56	22,035.41
Total Payable (SGD)					22,035.41

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Oct 2019		14 Oct 2019 15:46 Edit Adj Rpt	S\$20,593.85 Edit Estimates	S\$20,593.85 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: JANE LAZAROO NEE LYN YOKE CHOO , ID: S0187722D									
Vehicle Reg. No.: SMK5140J		Date of Loss: 17/09/2019 12:00 - :59 [5 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D204411C02		Policy/Cover Note No.: DMPCSN30568919011							
Vehicle Reg. No. (Insured): SJC9595G		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: Aviva Ltd (HQ) - Tel: (65) 6827 9966									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 23/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMK5140J (SNM19D204411C02)
 [SJC9595G]
 TP
 JANE LAZAROO NEE LYN YOKE CHOO
 Sep 17 2019 12:00PM
 [-]
 Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser								
Assessment Reports									1 per page			☒								
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)							Thumbnail			Print								
1	18/09/19 14:47	Accident Statement										Load HTML								
Photos/Images															3 per page			☒		
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)							Thumbnail			Print								
1	18/09/19 14:47	Accident Photo [Linked Accident Report Documents]										Load JPG								
2	18/09/19 14:47	Accident Photo [Linked Accident Report Documents]										Load JPG								
3	18/09/19 14:47	Accident Photo [Linked Accident Report Documents]										Load JPG								
4	18/09/19 14:47	Driving License [Linked Accident Report Documents]										Load JPG								
5	18/09/19 14:47	Accident Photo [Linked Accident Report Documents]										Load JPG								
6	18/09/19 14:47	Accident Photo [Linked Accident Report Documents]										Load JPG								
7	18/09/19 14:47	Accident Photo [Linked Accident Report Documents]										Load JPG								
8	18/09/19 14:47	Accident Photo [Linked Accident Report Documents]										Load JPG								
9	18/09/19 14:47	Accident Photo [Linked Accident Report Documents]										Load JPG								
10	18/09/19 14:47	Accident Photo [Linked Accident Report Documents]										Load JPG								
11	18/09/19 14:47	Accident Photo [Linked Accident Report Documents]										Load JPG								
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print								
1	14/10/19 16:20	General View										Load JPG								
2	14/10/19 16:20	General View										Load JPG								
3	14/10/19 16:20	General View										Load JPG								
4	14/10/19 16:20	General View										Load JPG								
5	14/10/19 16:20	General View										Load JPG								
6	14/10/19 16:20	General View										Load JPG								
7	14/10/19 16:20	General View										Load JPG								
8	14/10/19 16:20	General View										Load JPG								
9	14/10/19 16:20	General View										Load JPG								
10	14/10/19 16:20	General View										Load JPG								
11	14/10/19 16:20	General View										Load JPG								
12	14/10/19 16:20	General View										Load JPG								
13	14/10/19 16:20	General View										Load JPG								
14	14/10/19 16:20	General View										Load JPG								
15	14/10/19 16:20	General View										Load JPG								
16	14/10/19 16:20	General View										Load JPG								
17	14/10/19 16:20	General View										Load JPG								
18	14/10/19 16:20	General View										Load JPG								
19	14/10/19 16:20	General View										Load JPG								
20	14/10/19 16:20	General View										Load JPG								
21	14/10/19 16:20	General View										Load JPG								
22	14/10/19 16:20	General View										Load JPG								
23	14/10/19 16:20	General View										Load JPG								
24	14/10/19 16:20	General View										Load JPG								

Assessment Reports				1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
25	14/10/19 16:20	General View		Load JPG	☒
26	14/10/19 16:20	General View		Load JPG	☒
27	14/10/19 16:20	General View		Load JPG	☒
28	14/10/19 16:20	General View		Load JPG	☒
29	14/10/19 16:20	General View		Load JPG	☒
30	14/10/19 16:20	General View		Load JPG	☒
31	14/10/19 16:20	General View		Load JPG	☒
32	14/10/19 16:20	General View		Load JPG	☒
33	14/10/19 16:20	General View		Load JPG	☒
34	14/10/19 16:20	General View		Load JPG	☒
35	14/10/19 16:20	General View		Load JPG	☒
36	14/10/19 16:20	General View		Load JPG	☒
37	14/10/19 16:20	General View		Load JPG	☒
38	14/10/19 16:20	General View		Load JPG	☒
39	14/10/19 16:20	General View		Load JPG	☒
40	14/10/19 16:20	General View		Load JPG	☒
41	14/10/19 16:20	General View		Load JPG	☒
42	14/10/19 16:20	General View		Load JPG	☒
43	14/10/19 16:20	General View		Load JPG	☒
44	14/10/19 16:20	General View		Load JPG	☒
45	14/10/19 16:20	General View		Load JPG	☒
46	14/10/19 16:20	General View		Load JPG	☒
47	14/10/19 16:20	General View		Load JPG	☒
48	14/10/19 16:20	General View		Load JPG	☒
49	14/10/19 16:20	General View		Load JPG	☒
50	14/10/19 16:20	General View		Load JPG	☒
51	14/10/19 16:20	General View		Load JPG	☒
52	14/10/19 16:20	General View		Load JPG	☒
53	14/10/19 16:20	General View		Load JPG	☒
54	14/10/19 16:20	General View		Load JPG	☒
55	14/10/19 16:20	General View		Load JPG	☒
56	14/10/19 16:20	General View		Load JPG	☒
57	14/10/19 16:20	General View		Load JPG	☒
58	14/10/19 16:20	General View		Load JPG	☒
59	14/10/19 16:20	General View		Load JPG	☒
60	14/10/19 16:20	General View		Load JPG	☒
61	14/10/19 16:20	General View		Load JPG	☒
62	14/10/19 16:20	General View		Load JPG	☒
63	14/10/19 16:20	General View		Load JPG	☒
64	14/10/19 16:20	General View		Load JPG	☒
65	14/10/19 16:20	General View		Load JPG	☒
66	14/10/19 16:20	General View		Load JPG	☒
67	14/10/19 16:20	General View		Load JPG	☒
68	14/10/19 16:20	General View		Load JPG	☒
69	14/10/19 16:20	General View		Load JPG	☒
70	14/10/19 16:20	General View		Load JPG	☒
71	14/10/19 16:20	General View		Load JPG	☒
72	14/10/19 16:20	General View		Load JPG	☒
73	14/10/19 16:20	General View		Load JPG	☒
74	14/10/19 16:20	General View		Load JPG	☒
75	14/10/19 16:20	General View		Load JPG	☒
76	14/10/19 16:20	General View		Load JPG	☒
77	14/10/19 16:20	General View		Load JPG	☒
78	14/10/19 16:20	General View		Load JPG	☒
79	14/10/19 16:20	General View		Load JPG	☒
80	14/10/19 16:20	General View		Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
81	14/10/19 16:20	General View		Load JPG	☒
82	14/10/19 16:20	General View		Load JPG	☒
83	14/10/19 16:20	General View		Load JPG	☒
84	14/10/19 16:20	General View		Load JPG	☒
85	14/10/19 16:20	General View		Load JPG	☒
86	14/10/19 16:20	General View		Load JPG	☒
87	14/10/19 16:20	General View		Load JPG	☒
88	14/10/19 16:20	General View		Load JPG	☒
89	14/10/19 16:20	General View		Load JPG	☒
90	14/10/19 16:20	General View		Load JPG	☒
91	14/10/19 16:20	General View		Load JPG	☒
92	14/10/19 16:20	General View		Load JPG	☒
93	14/10/19 16:20	General View		Load JPG	☒
94	14/10/19 16:20	General View		Load JPG	☒
95	14/10/19 16:20	General View		Load JPG	☒
96	14/10/19 16:20	General View		Load JPG	☒
97	14/10/19 16:20	General View		Load JPG	☒
98	14/10/19 16:20	General View		Load JPG	☒
99	14/10/19 16:20	General View		Load JPG	☒
100	14/10/19 16:20	General View		Load JPG	☒
101	14/10/19 16:20	General View		Load JPG	☒
102	14/10/19 16:20	General View		Load JPG	☒
103	14/10/19 16:20	General View		Load JPG	☒
104	14/10/19 16:20	General View		Load JPG	☒
105	14/10/19 16:20	General View		Load JPG	☒
106	14/10/19 16:20	General View		Load JPG	☒
107	14/10/19 16:20	General View		Load JPG	☒
108	14/10/19 16:24	Reinspection Photo		Load JPG	☒
109	14/10/19 16:24	Reinspection Photo		Load JPG	☒
110	14/10/19 16:24	Reinspection Photo		Load JPG	☒
111	14/10/19 16:24	Reinspection Photo		Load JPG	☒
112	14/10/19 16:24	Reinspection Photo		Load JPG	☒
113	14/10/19 16:24	Reinspection Photo		Load JPG	☒
114	14/10/19 16:24	Reinspection Photo		Load JPG	☒
115	14/10/19 16:24	Reinspection Photo		Load JPG	☒
116	14/10/19 16:24	Reinspection Photo		Load JPG	☒
117	14/10/19 16:24	Reinspection Photo		Load JPG	☒
118	14/10/19 16:24	Reinspection Photo		Load JPG	☒
119	14/10/19 16:24	Reinspection Photo		Load JPG	☒
120	14/10/19 16:24	Reinspection Photo		Load JPG	☒
121	14/10/19 16:24	Reinspection Photo		Load JPG	☒
122	14/10/19 16:24	Reinspection Photo		Load JPG	☒
123	14/10/19 16:24	Reinspection Photo		Load JPG	☒
124	14/10/19 16:24	Reinspection Photo		Load JPG	☒
125	14/10/19 16:24	Reinspection Photo		Load JPG	☒
126	14/10/19 16:24	Reinspection Photo		Load JPG	☒
127	14/10/19 16:24	Reinspection Photo		Load JPG	☒
128	14/10/19 16:24	Reinspection Photo		Load JPG	☒
129	14/10/19 16:24	Reinspection Photo		Load JPG	☒
130	14/10/19 16:24	Reinspection Photo		Load JPG	☒
131	14/10/19 16:24	Reinspection Photo		Load JPG	☒
132	14/10/19 16:24	Reinspection Photo		Load JPG	☒
133	14/10/19 16:24	Reinspection Photo		Load JPG	☒
134	14/10/19 16:24	Reinspection Photo		Load JPG	☒
135	14/10/19 16:24	Reinspection Photo		Load JPG	☒
136	14/10/19 16:24	Reinspection Photo		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubl)	Thumbnail	Print
137	14/10/19 16:24	Reinspection Photo		☒
138	14/10/19 16:24	Reinspection Photo		☒
139	14/10/19 16:24	Reinspection Photo		☒
140	14/10/19 16:24	Reinspection Photo		☒
141	14/10/19 16:24	Reinspection Photo		☒
142	14/10/19 16:24	Reinspection Photo		☒
143	14/10/19 16:24	Reinspection Photo		☒
144	14/10/19 16:24	Reinspection Photo		☒
145	14/10/19 16:24	Reinspection Photo		☒
146	14/10/19 16:24	Reinspection Photo		☒
147	14/10/19 16:24	Reinspection Photo		☒
148	14/10/19 16:24	Reinspection Photo		☒
149	14/10/19 16:24	Reinspection Photo		☒
150	14/10/19 16:24	Reinspection Photo		☒
151	14/10/19 16:24	Reinspection Photo		☒
152	14/10/19 16:24	Reinspection Photo		☒
153	14/10/19 16:24	Reinspection Photo		☒
154	14/10/19 16:24	Reinspection Photo		☒
155	14/10/19 16:24	Reinspection Photo		☒
156	14/10/19 16:24	Reinspection Photo		☒
157	14/10/19 16:24	Reinspection Photo		☒
158	14/10/19 16:24	Reinspection Photo		☒
159	14/10/19 16:24	Reinspection Photo		☒
160	14/10/19 16:24	Reinspection Photo		☒
161	14/10/19 16:24	Reinspection Photo		☒
162	14/10/19 16:24	Reinspection Photo		☒
163	14/10/19 16:24	Reinspection Photo		☒
164	14/10/19 16:24	Reinspection Photo		☒
165	14/10/19 16:24	Reinspection Photo		☒
166	14/10/19 16:24	Reinspection Photo		☒
167	14/10/19 16:24	Reinspection Photo		☒
168	14/10/19 16:24	Reinspection Photo		☒
169	14/10/19 16:24	Reinspection Photo		☒
170	14/10/19 16:24	Reinspection Photo		☒
171	14/10/19 16:24	Reinspection Photo		☒
172	14/10/19 16:24	Reinspection Photo		☒
173	14/10/19 16:25	Before Repair Photo		☒
174	14/10/19 16:25	Before Repair Photo		☒
175	14/10/19 16:25	Before Repair Photo		☒
176	14/10/19 16:25	Before Repair Photo		☒
177	14/10/19 16:25	Before Repair Photo		☒
178	14/10/19 16:25	Before Repair Photo		☒
179	14/10/19 16:25	Before Repair Photo		☒
180	14/10/19 16:25	Before Repair Photo		☒
181	14/10/19 16:25	Before Repair Photo		☒
182	14/10/19 16:25	Before Repair Photo		☒
183	14/10/19 16:25	Before Repair Photo		☒
184	14/10/19 16:25	Before Repair Photo		☒
185	14/10/19 16:25	Before Repair Photo		☒
186	14/10/19 16:25	Before Repair Photo		☒
187	14/10/19 16:25	Before Repair Photo		☒
188	14/10/19 16:25	Before Repair Photo		☒
189	14/10/19 16:25	Before Repair Photo		☒
190	14/10/19 16:25	Before Repair Photo		☒
191	14/10/19 16:25	Before Repair Photo		☒
192	14/10/19 16:25	Before Repair Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
193	14/10/19 16:25	Before Repair Photo		☒
194	14/10/19 16:25	Before Repair Photo		☒
195	14/10/19 16:25	Before Repair Photo		☒
196	14/10/19 16:25	Before Repair Photo		☒
197	14/10/19 16:25	Before Repair Photo		☒
198	14/10/19 16:25	Before Repair Photo		☒
199	14/10/19 16:25	Before Repair Photo		☒
200	14/10/19 16:25	Before Repair Photo		☒
201	14/10/19 16:25	Before Repair Photo		☒
202	14/10/19 16:25	Before Repair Photo		☒
203	14/10/19 16:25	Before Repair Photo		☒
204	14/10/19 16:25	Before Repair Photo		☒
205	14/10/19 16:25	Before Repair Photo		☒
206	14/10/19 16:25	Before Repair Photo		☒
207	14/10/19 16:25	Before Repair Photo		☒
208	14/10/19 16:25	Before Repair Photo		☒
209	14/10/19 16:25	Before Repair Photo		☒
210	14/10/19 16:25	Before Repair Photo		☒
211	14/10/19 16:25	Before Repair Photo		☒
212	14/10/19 16:25	Before Repair Photo		☒
213	14/10/19 16:25	Before Repair Photo		☒
214	14/10/19 16:25	Before Repair Photo		☒
215	14/10/19 16:25	Before Repair Photo		☒
216	14/10/19 16:25	Before Repair Photo		☒
217	14/10/19 16:25	Before Repair Photo		☒
218	14/10/19 16:25	Before Repair Photo		☒
219	14/10/19 16:25	Before Repair Photo		☒
220	14/10/19 16:25	Before Repair Photo		☒
221	14/10/19 16:25	Before Repair Photo		☒
222	14/10/19 16:25	Before Repair Photo		☒
223	14/10/19 16:25	Before Repair Photo		☒
224	14/10/19 16:25	Before Repair Photo		☒
225	14/10/19 16:25	Before Repair Photo		☒
226	14/10/19 16:25	Before Repair Photo		☒
Documentation			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	18/09/19 14:43	Sketch Plan [Linked Accident Report Documents]		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/10/19 15:48	Supplementary		☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	18/09/19 14:47	Accident Statement		☒
Photos/Images			3 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	18/09/19 14:47	Accident Photo		☒
2	18/09/19 14:47	Accident Photo		☒
3	18/09/19 14:47	Accident Photo		☒
4	18/09/19 14:47	Driving License		☒
5	18/09/19 14:47	Accident Photo		☒
6	18/09/19 14:47	Accident Photo		☒
7	18/09/19 14:47	Accident Photo		☒

Assessment Reports				1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
8	18/09/19 14:47	Accident Photo		Load JPG	☒
9	18/09/19 14:47	Accident Photo		Load JPG	☒
10	18/09/19 14:47	Accident Photo		Load JPG	☒
11	18/09/19 14:47	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	18/09/19 14:43	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119016590/ETD3E2

Date: 24/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30568919011
Claimant Vehicle No :	SMK5140J	Insured Vehicle No :	SJC9595G
Date of Loss:	17/09/2019	Nature of Claim: TP	Claim No: SNM19D204411C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK5140J	Engine No:	L15B34100294
Make & Model:	HONDA JAZZ, 1.5 (A)	Chassis No:	JHMGK5850KS204561
Reg. Date:	12/04/2019 (Man. Year: 2019)	Odometer:	5515 km
Colour:	Red		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,641.37	6,268.85	2,372.52	27.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,380.00	14,325.00	1,055.00	6.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,021.37	20,593.85	3,427.52	14.27
+ GST 7.00/7.00% (S\$)	1,681.50	1,441.57	239.93	14.27
Nett Amount (S\$)	25,702.87	22,035.42	3,667.45	14.27

INSPECTION

Date of Assignment:	14/10/2019	Inspected At:	Kah Motor Co Sdn Bhd 6A MANDAI ESTATE SINGAPORE 729903
Date Inspected:	19/09/2019		
Estimated Period of Repair:	18.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Oct 2019)
Parts: 144	HONDA JAZZ 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK5140J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SET, L.RR.OUTSIDE	Dented	541.97 FS	*541.97 FS
2	1		*GUTTER COMP, L.RR.PILLAR LOWER	Dented	84.17 FS	*84.17 FS
3	1		*STIFFENER COMP, L.RR.SIDE	Dented	82.55 FS	*82.55 FS
4	1		*PANEL COMPRR.	Dented	304.38 FS	*304.38 FS
5	1		*TAILGATE COMP	Dented	694.07 FS	*694.07 FS
6	2		*HINGE COMP TAILGATE	Not Necessary	58.52 FS	*- FS
7	1		*WEATHERSTRIP TAILGATE	Not Necessary	87.68 FS	*- FS
8	1		*LOCK ASSY, TAILGATE	Not Necessary	81.22 FS	*- FS
9	1		*STAY ASSYR. TAILGATE OPEN	Not Necessary	89.30 FS	*- FS
10	1		*STAY ASSYL. TAILGATE OPEN	Not Necessary	89.30 FS	*- FS
11	1		*EMBLEMRR	Necessary	10.35 FS	*10.35 FS
12	1		*EMBLEMRR.RS	Not Necessary	16.91 FS	*- FS
13	1		*GARNISH ASSYRR.LICENSE	Not Necessary	190.57 FS	*- FS
14	1		*EMBLEMH	Not Necessary	10.16 FS	*- FS
15	2		*NUTPUSH 3MM	Not Necessary	3.99 FS	*- FS
16	1		*TAILLIGHT ASSYL.	Scratched	212.70 FS	*212.70 FS
17	1		*FACE, RR.BUMPER	Dented	477.37 FS	*477.37 FS
18	1		*COVER,L.RR.BUMPER	Broken	19.66 FS	*19.66 FS
19	1		*COVER,R.RR.BUMPER	Not Necessary	19.66 FS	*- FS
20	1		*DIFFUSER ASSY,RR.PR	Broken	196.46 FS	*196.46 FS
21	1		*SPACER,R.RR.BUMPER SIDE	Broken	16.05 FS	*16.05 FS
22	1		*SPACER,L.RR.BUMPER SIDE	Broken	16.05 FS	*16.05 FS
23	1		*CLIP, BUMPER (9 pcs)	Necessary	19.66 FS	*19.66 FS
24	1		*LINING ASSY TAILGATE LOWER	Cut	51.01 FS	*51.01 FS
25	1		*POCKET TAILGATE LINING PULL	Not Necessary	4.84 FS	*- FS
26	1		*LID ASSY SPARE TIRE	Not Necessary	180.31 FS	*- FS
27	1		*BOX ASSY, CARGO FLOOR	Not Necessary	105.07 FS	*- FS
28	1		*LINING ASSYL.TRUNK	Crushed	160.55 FS	*160.55 FS
29	1		*LINING ASSYRR.PANEL	Not Necessary	57.76 FS	*- FS
30	1		*DUNLOP TYRE	Torn	225.00 FS	*225.00 FS
31	1		*DISK ALUMINIUM WHEEL,16X6	Scratched	733.68 FS	*733.68 FS
32	1		*PANEL COMPL.RR.DOOR	Repair	655.12 FS	*- FS
33	1		*RUBBER A W SHIELD DAM	Serviceable	35.15 FS	*- FS
34	2		*RUBBER D W SHIELD DAM	Serviceable	9.31 FS	*- FS
35	1		*STICKER I-VTEC	Serviceable	11.97 FS	*- FS
36	4		*FASTENER BW/SHIELD	Serviceable	20.14 FS	*- FS
37	1		*FASTENER B (2 pcs)	Necessary	10.07 FS	*10.07 FS
38	2		*FASTENER A W/SHIELD	Necessary	7.22 FS	*7.22 FS
39	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
40	1		*GLASS ASSYL.RR.DOOR	Not Necessary	208.43 FS	*- FS
41	1		*SET ACT RR.SENSOR (4 pcs)	Shorted	320.00 FS	*320.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
43	1		*RUBBER B W SHIELD	Not Necessary	30.49 FS	*- FS
44	1		*RUBBER C WINDSHIELD DAMPER	Necessary	10.83 FS	*10.83 FS
45	1		*RUBBER WINDSHIELD DAMPER (2 pcs)	Necessary	12.35 FS	*12.35 FS
46	1		*DAMPER STD 5X5	Necessary	8.07 FS	*8.07 FS
47	1		*STIFFENER COMP,L.RR.SIDE	Repeated	82.55 FS	*- FS
48	1		*FLANGERR.FRAME END	Dented	10.45 FS	*10.45 FS
49	1		*RUBBERRR QTR W/SHIELD (2 pcs)	Necessary	18.43 FS	*18.43 FS
50	1		*CLIP A, QUARTER WINDSHIELD	Necessary	3.23 FS	*3.23 FS
51	1		*CLIP B, QUARTER WINDSHIELD	Necessary	3.51 FS	*3.51 FS
52	1		*CLIP C, QUARTER WINDSHIELD	Necessary	2.28 FS	*2.28 FS
53	1		*COVER,L.RR.FENDER	Missing	40.47 FS	*40.47 FS
54	1		*FENDER,L.RR.INNER	Dented	75.05 FS	*75.05 FS
55	2		*GROMMETCOWL TOP	Necessary	3.80 FS	*3.80 FS
56	2		*CLIP INNER FENDER	Necessary	0.76 FS	*0.76 FS
57	4		*CLIP, INNER FENDER	Necessary	10.64 FS	*10.64 FS
58	1		*OUTLETRR AIR	Broken	23.94 FS	*23.94 FS
59	1		*GROMMETRR.COMBINATION LIGHT	Necessary	2.37 FS	*2.37 FS
60	2		*SCREW TAPPING 5X16	Necessary	0.76 FS	*0.76 FS
61	2		*SCREW TAPPING 5X20	Necessary	7.60 FS	*7.60 FS
62	1		*DIFFUSER ASSY, RR.PR	Repeated	196.46 FS	*- FS
63	1		*LINING ASSYRR.PANEL	Cut	57.76 FS	*57.76 FS
64	1		*CLIPTRIM 7MM (2 pcs)	Necessary	4.37 FS	*4.37 FS
65	1		*PANEL COMP, L.RR.INSIDE	Dented	494.00 FS	*494.00 FS
66	1		*FRAME BL.RR	Dented	43.60 FS	*43.60 FS
67	1		*BEARING ASSYRR.HUB	Jammed	273.12 FS	*273.12 FS
68	1		*BEAM ASSYRR.AXLE	Bent	865.45 FS	*865.45 FS
69	1		*FASTENER C WINDSHIELD (4 pcs)	Necessary	3.04 FS	*3.04 FS
70	1		*LIGHT ASSYL.LID	Not Necessary	77.61 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	8,641.37	6,268.85
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE RR.WINDSCREEN.	New	560.00	560.00
2	REMOVE & INSTALL FUEL TANK FUEL PIPES.	New	600.00	380.00
3	REPLACE RR.L DOOR GLASS.	New	250.00	250.00
4	RESET VEHICLE SMART ENTRY SYSTEM.	New	450.00	320.00
5	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.	New	450.00	320.00
6	REMOVE & RENEW REVERSE SENSOR -4PCS.	New	120.00	120.00
7	WINDSCREEN DAM KIT.	New	100.00	80.00
8	BODY JOINT SEALANT END PANEL	New	100.00	80.00
9	BODY JOINT SEALANT TAILGATE.	New	100.00	80.00
10	BODY JOINT SEALANT LHR FENDER.	New	100.00	80.00
11	BODY UNDERSIDE COATING.	New	100.00	80.00
12	INSTALL RIMS & TYRES.	New	150.00	80.00
13	CUT OFF & RENEW RR PANEL, LHR FENDERS & DAMAGE PA.	New	6,160.00	6,160.00
14	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	New	3,500.00	3,375.00
15	REMOVE & REPLACE RR UNDERCARRIAGE PARTS.	New	560.00	560.00
16	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT.	New	1,200.00	1,200.00
17	WHEEL ALIGNMENT X4.	New	180.00	180.00
18	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE	New	600.00	320.00
19	TOWING SERVICES. (MBBS)	New	100.00	100.00
Gross Labour Cost (S\$)			15,380.00	14,325.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >