



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

25 September 2019

QUOT201909-000047
HHTPCLAIMS19-182

AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 SHENTON WAY, #07-16
AIG BUILDING
SINGAPORE 079120

Attn: Motor Claims Department

ACCIDENT INVOLVING SKW6629X & SLS4987J ON 16/09/2019 AT 290A BISHAN ST 24 MULTI-STOREY CAR PARK AT ABOUT 1415 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No. : SKW6629X
Vehicle Make : TOYOTA
Vehicle Model : COROLLA ALTIS CLASSIC 1.6 CVT
Vehicle Chassis No. : MR053REH104538264
Policy No. : 5109921641-000035
Date of Accident : 16/09/2019

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper / DD		\$ 511.20
2	10	Front Bumper Clip - NEC	\$ 2.50	\$ 25.00
3	1	Front Bumper Retainer (RH) / Br.		\$ 55.10
4	1	Front Bumper Foam ?		\$ 78.39
5	1	Front Bumper Lower Grille X		\$ 148.60
6	1	Front Fog Lamp Cover (RH) SCH /		\$ 135.00
7	1	Front Fog Lamp (RH) ?		\$ 220.00
8	1	Front Grille X		\$ 564.00
9	1	Front Grille Top Garnish X		\$ 73.00
10	10	Front Grille Top Garnish Clip X	\$ 2.50	\$ 25.00
11	1	Front Headlamp (RH) / CRU. (RH)	\$ 2,816.10	\$ 5,632.20
12	2	Front Headlamp Clip (RH) - NEC	\$ 2.50	\$ 5.00
13	1	Front Reinforcement ?		\$ 386.60
14	1	Front Fender (RH) / DD		\$ 858.00
15	20	Front Fender Inner Shield Clip (LH/RH) X	\$ 2.50	\$ 50.00
16	1	Washer Tank / CRU		\$ 145.00
17	1	Rear Bumper X R		\$ 486.50
18	10	Rear Bumper Clip - NEC	\$ 2.50	\$ 25.00
19	1	Rear Bumper Retainer (LH) / BR		\$ 72.10
20	1	Emblem X		\$ 30.50
21	1	Logo (VVT) - NEC		\$ 19.10
22	1	Front Engine Under Cover X		\$ 130.80
				\$ 9,676.09
Less 20%				\$ 1,935.22
				\$ 7,740.87

CONTINUE NEXT PAGE



HUA HONG PRIVATE LIMITED

25D SUNGEI KADUT STREET 1, SINGAPORE 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

25 September 2019

QUOT201909-000047
HHTPCLAIMS19-182

ACCIDENT INVOLVING SKW6629X & SLS4987J ON 16/09/2019 AT 290A BISHAN ST 24 MULTI-STOREY CAR PARK AT ABOUT 1415 HOURS

Estimate Repair List for vehicle SKW6629X - TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

S/N	Quantity	Description	Unit Price S\$	Amount S\$
		To dismantle & change front bumper, front RH headlamp, front RH fender, front reinforcement, rear bumper, knocking & pull straight front RH panel and all area affected by accident	\$	900.00 ⁵⁰⁰
		To perform wire checking	\$	20.00 ✓
		To spray front bumper, front reinforcement, front support panel, front RH fender and rear bumper	\$	900.00 ⁶⁰⁰
				\$ 9,560.87
7% GST				\$ 669.26
Total				\$ 10,230.13

Repair Day - 4 days
26/09/2019 @ 12.00 p.m.
Steve / Pm

TP without Prejudice.

Lump Sum Repair
after spray

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Authorised by Claims Dept