

Tanfikh

AKG CC3/AIG/90/6792/11v3n2

ASSIGNMENT

merimen

Date 23.9.2019

Veh No: SMN7489A Reg: 2019, 4kg

Followed Code

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ QD / TP / WS / TP RES / CO RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle In: SMN 7489A

Make: Audi A8 3.0 cc 2995

at Workshop In: Premium

Colour: Green A/C: Insured / Std / NI / NA

at 24 Benoi Sector

Sp. Reading: 751 T/Radio: Insured / Std / NI / NA

Insured

Eng/No:

Policy No: 1900152865

C/No: WA4777F10KDO10053

Claims No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured Excess: \$4400

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Make of Veh: After 2.00 p.m

Mod: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 275/50R20

Remark: The veh has commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Est. of Market Value: 4366K

Front: R/Bal: 7 mm

IDAC Accident Rptn: Consistent? Yes or No

Rear: R/Bal: 7 mm

GIA / PR. Geni: Consistent? Yes or No

L/Bal: 7 mm

Est. Repair: days Res: Yes or No

D.O.A: 29/8/19 D.O.I: 23/9/19 345p

Turn Sum: % 3 Val: Yes or No

Survey held at: Premium Benoi

CA (REV) REP: / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop of

N/S

Date Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SMN 7489A - CC3/AIG/90/6792/11v3n2 Date: 12/09/2019
24/9/19	Revert via merimen
26/9/19	Rece approved \$10,448 from victor by merimen
26/9/19	Informed TRcy clA ex \$4400 by email
22/10/2020	Final fig \$9869.36 (Red 12,724.64, 56%) confirmed by email

One/Two Fee Paid Out ☐ Preli. Report

Days Of Repair: 7

☐ Final Report

Resurvey No. of Trip: 1

Cost/Time Fee Taken In:

Survey Fee:

Transportation

S + RS

Phone

Spec

HTK

28p - typist

Add Fee: ☐ Site Insp 15

☐ Interview 15

☐ Tech. Ins 15

☐ (Meal and) 15

Fig. Officer:

merimen

Group Amount: p/p \$9869.36

200

11

211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 24 Sep 2019

Preliminary Advice

Vehicle No	: SMN7489A	Accident Date	: 29/08/2019
Make	: AUDI Q8	Policy No.	: 1900152865
Assignment Date	: 24/09/2019	Excess	: S\$0.00
Date of Inspection	: 23/09/2019	Est. Duration of Repair	: 7.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,594.00
Revised Amount	:S\$	10,448.00
Check Items (Estimated)	:S\$	2,402.00
Total	:S\$	12,850.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	366,000.00
COE / PARF Rebate	:S\$	116,650.00
Salvage Value	:S\$	
Margin for Repair	:S\$	249,350.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 September 2019 10:14 AM
To: Claims; SUR
Cc: (nora.khai@premiumauto.com.sg)
Subject: RE: OD CLAIM FOR SMN 7489 A ON 29/8/2019
Attachments: MARK_EST_0001.pdf

Dear TRoy,

As instructed by our client , please proceed to repair the **insured vehicle SMN 7489A (Excess \$4400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Tuesday, 24 September 2019 7:31 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SMN 7489 A ON 29/8/2019

Dear Veron,

Apologies for the late reply on this matter. Herein attached the document for your next action.

Thanks

Best Regards,

TRoy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 24 September 2019 11:05 AM
To: Claims; SUR
Subject: RE: OD CLAIM FOR SMN 7489 A ON 29/8/2019

Dear TRoy,

Interview form and undertaking.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Claims <claims@premiumauto.com.sg>
Sent: Monday, 23 September 2019 10:18 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SMN 7489 A ON 29/8/2019

Aside to Troy,

FYNA

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183 e. claims@premiumauto.com.sg w. www.audi.com.sg Audi
Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65
6836 2223

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

-----Original Message-----

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Monday, 23 September 2019 8:08 AM
To: SUR <sur@lkkauto.com>; 'Claims Dept' <claims@premiumauto.com.sg>
Subject: FW: OD CLAIM FOR SMN 7489 A ON 29/8/2019

Dear Syafiq,

Interview form and undertaking.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

From: Claims <claims@premiumauto.com.sg>

Sent: Friday, 20 September 2019 5:26 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: OD CLAIM FOR SMN 7489 A ON 29/8/2019

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report for your reference.

We will forward you the estimate once it is available.

Please arrange survey on 23/9/2019 @ 24 benoi sector. Vehicle is in our compound.

Best Regards,

Syafiq

Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg<mailto:claims@premiumauto.com.sg> w.

www.audi.com.sg<http://www.audi.com.sg/>

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65

6836 2223

[cid:image001.png@01D56FD8.7D8FC1D0]

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Veron Chen (LKKAUTO)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 25 September 2019 11:00 AM
To: Taufikh (LKKAUTO)
Subject: SMN7489A / OD / 29/08/2019 / Coverage & Excess update

This mail is associated with :
***SMN7489A (1816452211SG)**
OD
Aug 29 2019 8:00PM
[GAO KANG]
Premium Automobiles Pte Ltd

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$4400.00

Thank you
Azlan, Syazairdina

This is an auto-generated email. Do not reply to this email.

Sent by : Azlan, Syazairdina (AIG Asia Pacific Insurance Pte. Ltd.)



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

View Received Message

This mail is associated with :

***SMN7489A (1816452211SG)**

OD

Aug 29 2019 8:00PM

[GAO KANG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 26/09/2019 10:05 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$10448.00) - SMN7489A - Claim Handler: Azlan, Syazairdina

Approved:10448.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0301
Vehicle Details	
Vehicle No.:	SMN7489A
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2019
Vehicle Make:	AUDI
Vehicle Model:	Q8 3.0 TFSI QU TIP
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	DCB051783
Chassis No.:	WAUZZZF10KD010053
Maximum Power Output:	250.0 kW (335 bhp)
Open Market Value:	\$73,585.00
Original Registration Date:	27 Aug 2019
First Registration Date:	27 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$104,453.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Aug 2029
PARF Rebate Amount:	\$78,339.00
Intended COE Rebate Details	
COE Expiry Date:	26 Aug 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,602.00
COE Rebate Amount:	\$38,311.00
Total Rebate Amount:	\$116,650.00

The information contained herein is correct as at 23 Sep 2019

OK



Name of Policyholder : GAO KANG
Period of Insurance : 27 Aug 2019 To 26 Aug 2020
Engine No. : DCB 051783
Chassis No. : WAUZZZF10KD010053

Vehicle No. : SMN7489A
Policy No. : 1900152865
Endorsement No. :
Issued Date : 04 Sep 2019

Make/Model : AUDI Q8 3.0 TFSI QU
Engine Capacity/Tonnage : 2,995.00 CC
Driver Restriction : NA

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2019
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

Any person other than the Policyholder who is driving on the Policyholder's, under or with his/her permission

This Policy will indemnify any authorized driver other than the Policyholder only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 22 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Polystyroler's business

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

^a Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2018, are not to be included under these headings.

Section 1
Fire - \$0 Own Damage - \$1400 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen: £100

Named Driver and Excess (where applicable)

HU SHUAN - \$1400 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Ausli Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 83862121

For other Approved Reporting Centroids/Authorized Repairs, please contact our 24-hour accident emergency hotline at 405 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

5/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 100), Part IV of the Road Transport Act, 1967 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504 125292

PREMIUM LEASING - LXI

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159958

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Germany Law

DRIVING LICENSE OF THE PEOPLE'S REPUBLIC OF CHINA

License No: 142603199608192027

Name : Guo Jinfeng

Sex : Female

Nationality : China

Address : Room 501, Unit 1, Building 5, West Block of Yunsha, Jian'anchu Residential Area, Xinzhi Town, Huozhou City, Linfen City, Shanxi Province

Issuing Authority :
Linfen Traffic Police
Branch, Linfen Public
Security Bureau, Shanxi

Date of Birth : 19-08-1996

Date of first Issue : 23-02-2018

Type of Vehicle for which this license is issued : C1

Photo of
Guo Jinfeng

Valid Period : 23-02-2018 to 23-02-2024

Driving License Of The People's Republic Of China Supplementary Page

License No: 142603199608192027

Name : Guo Jinfeng

Administration Number : 141050038578

Record : The probationary period ends on 22-02-2019.

Vehicle Classification Code

A1	Large Passenger Vehicle & A3, B1, B2	C4	Tri-wheeled Vehicles
A2	Towing Vehicles & B1, B2	C5	Small Automatic Passenger Vehicles for Disabled
A3	Urban Public Transport Vehicles & C1	D	Ordinary Motor Tricycles & E
B1	Medium-sized Passenger Vehicles & C1, M	E	Ordinary Motorbikes & F
B2	Large Trucks & C1, M	F	Light Motorbikes
C1	Small Passenger Vehicles & C2, C3	M	Drivable Wheeled Machinery
C2	Small Automatic Passenger Vehicles	N	Trolley Bus
C3	Low Speed Goods Trucks & C4	P	Trams

Barcode: *14X0014265753*

Apart from the Vehicle Control Office of the Police, no other organisation or individual is allowed to confiscate the certificate.

Certification: This is to certify that the foregoing text is a true and accurate translation prepared by professional Chinese <> English translator Minghan Deng on the 6 August 2019.



AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME : Guo Jin Fang
VEHICLE NUMBER : SUN 7489 A
DATE/ TIME OF ACCIDENT : 29/8/2019
PLACE OF ACCIDENT : Liang Court Carpark
THIRD PARTY VEHICLE (IF ANY) : N.A.

.....
WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

went out from carpark.

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT WAS THE RESULTS?

No.

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

Property damage.

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

No.


NAME:

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

UNDERTAKING

I, Guo Jin Feng, (NRIC No. Gxxxx048k), hereby confirm that the Singapore Accident Statement lodged by me on 20/9/2019 at 11.30am hours pertaining to the accident involving motor car Reg. No: SMN 7489A, in which I was the driver are true and accurate to the best of my knowledge, information and belief.

I acknowledge that my insurers are not liable under the contract of insurance if there is a breach of policy terms and conditions.

In the event that an unrelated/unreported third party property or injury claim arises or there is evidence emerges that there is a breach of policy terms and conditions, I irrevocably undertake to absolve my insurer from all liability under the contract of insurance and I undertake to re-pay any sums paid by my insurers pursuant to the contract of insurance upon receipt of written demand by my insurers.

Signature : [Signature]
Name of Insured / Driver : Guo Jin Feng
Nric No. : Gxxxx048k
Date : 20/9/2019

Signature : [Signature]
Name of Policyholder : Gao Kang
Nric No. : Sxxxx030I
Date : 20/9/2019



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 13156

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1140/2019/NS
Date	:	21-Sep-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Gao Kang
Address	:	1 Grace Park
	:	Singapore 557761
Telephone	:	HP +65 87813910
Type of Claim	:	Own Damage Claim
Policy No.	:	1900152865
Vehicle No	:	SMN 7489 A
Model Code	:	Audi Q8 3.0 TFSI qu 4MNOX
Model / Year	:	Aug-19
Engine No	:	DCB 051783
Chassis No	:	WAUZZZF10KD010053
Mileage	:	
Date In	:	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMN 7489 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	✓
2	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 360.00 ✓	✓
3	To dismantle and renew rear bumper and lhs rear door. To repair lhs rear fender. Re-organise crash management components. Reinstall all parts removed.	600 \$ 3,150.00	1500 ✓
4	To respray lhs rear door, door cover, door handle, lhs rear fender, lhs rear door wheel arch trim, both rear wheel arch trims, rear upper bumper and rear lower bumper.	600 \$ 6,000.00	2700 ✓
5	To carry out diagnostic checks.	S/N \$ 384.00 ✓	✓
SUB TOTAL LABOUR CHARGES		: \$ 10,254.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7489 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER - UPPER	S 1,121.00	Ry
2	REAR BUMPER - LOWER	S 2,269.00	Ry
3	REAR BUMPER FIXING PARTS	S 154.00	? X nn
4	REAR BUMPER GUIDE SECTION - LH	S 68.00	? X nn
5	REAR WHEEL HOUSING LINER - LH	S 327.00	X nn
6	WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT AND REAR	S 66.00	X nn
7	REAR WHEEL COVER - LH / RH	2 S 688.00	LH - mis / RH - 344
8	REAR DOOR WHEEL COVER - LH	S 179.00	cut / 143.00
9	REAR DOOR - LH	S 3,570.00	ht / 3856
10	REAR DOOR OUTER SEAL - LH	NEC S 157.00	nei / 125.60
11	BONDING AGENT	NEC S 45.00	nei / X nn
12	CLEANING SOLUTION	NEC S 65.00	nei / X nn
13	REAR DOOR ATTACHMENT PARTS	S 191.00	? X nn
14	OUTER DOOR SEAL - LH	S 234.00	? 187.00 nei
15	REAR DOOR CATCH	S 96.00	? 76.16 nei
16	OUTER DOOR SEAL - LH	S 174.00	? X nn
17	SILL PANEL SEAL - LH	S 234.00	? X nn
18	REAR DOOR COVER - LH	S 464.00	cut / 370.80
19	EXTERIOR DOOR HANDLE - LH	S 320.00	cut / 256
20	DOOR HANDLE CAP - LH	S 36.00	? X nn
	SUB SPARE PARTS CHARGES	S 10,458.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7489 A

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/Nett</u>	<u>Remarks</u>
21	DOOR HOUSING	\$ 16.00	?
22	REAR DOOR HANDLE SENSOR - LH	\$ 237.00	?
23	REAR DOOR MOUNTING BAR - LH	\$ 118.00	?
24	ROOF MOLDING - LH	\$ 493.00	X
25	WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER	\$ 191.00	X
26	WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER	\$ 327.00	X
27	SUNDRIES	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 12,340.00
TOTAL LABOUR CHARGES		:	\$ 10,254.00
GRAND TOTAL		:	\$ 22,594.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :


26/9/19

Tan Hin 9749 5749

Not Authorised

Ex \$4400

23/9/19 @ 4pm

Resurvey before paint

surveillance

07 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7489 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER - UPPER	\$ 1,121.00	Rx
2	REAR BUMPER - LOWER	\$ 2,269.00	Rx
3	REAR BUMPER FIXING PARTS	\$ 154.00	?
4	REAR BUMPER GUIDE SECTION - LH	\$ 68.00	?
5	REAR WHEEL HOUSING LINER - LH	\$ 327.00	X
6	WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT AND REAR	\$ 66.00	X
7	REAR WHEEL COVER - LH / RH	2 \$ 688.00	LH-mis, RH-?
8	REAR DOOR WHEEL COVER - LH	\$ 179.00	cut
9	REAR DOOR - LH	\$ 3,570.00	bl ✓
10	REAR DOOR OUTER SEAL - LH	NEC \$ 157.00	new ✓
11	BONDING AGENT	NEC \$ 45.00	new ✓
12	CLEANING SOLUTION	NEC \$ 65.00	new ✓
13	REAR DOOR ATTACHMENT PARTS	\$ 191.00	?
14	OUTER DOOR SEAL - LH	\$ 234.00	?
15	REAR DOOR CATCH	\$ 96.00	Loose ✓
16	OUTER DOOR SEAL - LH	\$ 174.00	?
17	SILL PANEL SEAL - LH	\$ 234.00	?
18	REAR DOOR COVER - LH	\$ 464.00	cut ✓
19	EXTERIOR DOOR HANDLE - LH	\$ 320.00	cut ✓
20	DOOR HANDLE CAP - LH	\$ 36.00	?
	SUB SPARE PARTS CHARGES	\$ 10,458.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 13156

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1140/2019/NS
Date : 21-Sep-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Taufikh

7 days - ok - Jb 5 Dec 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Gao Kang
Address : 1 Grace Park
Singapore 557761
Telephone : HP +65 87813910
Type of Claim : Own Damage Claim
Policy No. : 1900152865
Vehicle No : **SMN 7489 A**
Model Code : Audi Q8 3.0 TFSI qu 4MN0X
Model / Year : Aug-19
Engine No : DCB 051783
Chassis No : WAUZZZF10KD010053
Mileage :
Date In :

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMN 7489 A

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00	\$ 360.00
2	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	360.00	\$ 360.00
3	To dismantle and renew rear bumper and lhs rear door. To repair lhs rear fender. Re-organise crash management components. Reinstall all parts removed.	\$	3,150.00	\$ 1,500.00
4	To respray lhs rear door, door cover, door handle, lhs rear fender, lhs rear door wheel arch trim, both rear wheel arch trims, rear upper bumper and rear lower bumper.	\$	6,000.00	\$ 2,700.00
5	To carry out diagnostic checks.	S/N \$	384.00	\$ 384.00
SUB TOTAL LABOUR CHARGES		:	<u>\$ 10,254.00</u>	<u>\$ 5,304.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7489 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER - UPPER	\$ 1,121.00	
2	REAR BUMPER - LOWER	\$ 2,269.00	
3	REAR BUMPER FIXING PARTS	\$ 154.00	
4	REAR BUMPER GUIDE SECTION - LH	\$ 68.00	
5	REAR WHEEL HOUSING LINER - LH	\$ 327.00	
6	WHEEL HOUSING LINER ATTACHMENT PARTS - FRONT AND REAR	\$ 66.00	
7	REAR WHEEL COVER - LH / RH	2 \$ 688.00	\$ 550.40
8	REAR DOOR WHEEL COVER - LH	\$ 179.00	\$ 143.20
9	REAR DOOR - LH	\$ 3,570.00	\$ 2,856.00
10	REAR DOOR OUTER SEAL - LH	NEC \$ 157.00	\$ 125.60
11	BONDING AGENT	NEC \$ 45.00	
12	CLEANING SOLUTION	NEC \$ 65.00	
13	REAR DOOR ATTACHMENT PARTS	\$ 191.00	
14	OUTER DOOR SEAL - LH	\$ 234.00	\$ 187.20
15	REAR DOOR CATCH	\$ 96.00	\$ 76.16
16	OUTER DOOR SEAL - LH	\$ 174.00	
17	SILL PANEL SEAL - LH	\$ 234.00	
18	REAR DOOR COVER - LH	\$ 464.00	\$ 370.80
19	EXTERIOR DOOR HANDLE - LH	\$ 320.00	\$ 256.00
20	DOOR HANDLE CAP - LH	\$ 36.00	
	SUB SPARE PARTS CHARGES	\$ 10,458.00	\$ 4,565.36

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7489 A

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remarks</u>
	<i>c/f</i>		\$ 4,565.36
21	DOOR HOUSING	\$ 16.00	
22	REAR DOOR HANDLE SENSOR - LH	\$ 237.00	
23	REAR DOOR MOUNTING BAR - LH	\$ 118.00	
24	ROOF MOLDING - LH	\$ 493.00	
25	WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER	\$ 191.00	
26	WINDOW SLOT SEAL WITH TRIM STRIP - LH OUTER	\$ 327.00	
27	SUNDRIES	\$ 500.00	
	TOTAL SPARE PARTS CHARGES	\$ 12,340.00	\$ 4,565.36
	TOTAL LABOUR CHARGES	\$ 10,254.00	\$ 5,304.00
	GRAND TOTAL	\$ 22,594.00	\$ 9,869.36

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved. Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 22 January 2020 8:42 AM
To: Boo seng yak; Taufikh (LKKAUTO); SUR; Carrine Leong;
jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SMN7489A - OD AIG - SURVEYED 23 SEP 19

Dear Mr Boo,

Confirm repair cost of \$9869.36 before excess \$4400 and GST @ 7 days

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Thursday, 5 December 2019 2:25 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SMN7489A - OD AIG - SURVEYED 23 SEP 19

Hi Adrian, Taufikh and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$9869.36 @ 7 days exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMN 7489 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1140/2019/NH

19th February 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SMN 7489 A, Audi Q8 3.0 TFSI qu.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SMN 7489 A**, claimant, **Mr. Gao Kang**, please find the related document per attached.

1. A copy of the Original invoice no. 85014855 – S\$ 5,852.22.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SMN 7489 A

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 10:54

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014855 Date : 18/02/2020 Order : SMN7489A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SMN7489A (V 40191)	Regn Date: 27/08/2019	Mileage: 2741	WIP No.: 13156
Model: Q8 3.0 TFSI qu 4MNOX2	Chassis: WAUZZZF10KD010053	Engine: DCB 051783	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-4400.00	1.00	-4,400.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW LHS REAR DOOR. TO REPAIR LHS REAR FENDER.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1500.00	1.00	1,500.00
S	BODYWORK	M: TO RESPRAY LHS REAR DOOR,DOOR HANDLE, LHS REAR FENDER,LBOTH REAR WHEEL ARCH TRIMS,REAR UPPER BUMPER AND REAR LOWER BUMPER	2700.00	1.00	2,700.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	384.00	1.00	384.00
X	A4M8853817A GRU	(GER)COVER	Less 020%	1.00	344.00
X	A4M8853818A GRU	007455/(V) (GER) COVER	Less 020%	1.00	344.00
X	A4M8854819A GRU	007455/(V) (GER) COVER	Less 020%	1.00	179.00
X	A4M8833051C	(V) (GER) DOOR 26/9/19	Less 020%	1.00	3570.00
X	A4M8839911	(V) (GER) SEAL 26/9/19	Less 020%	1.00	157.00
X	A4M8839119B	007486/(V) (GER) DOOR	Less 020%	1.00	234.00
X	A4M8839249	007473/(V) (GER) CHECK	Less 020%	1.00	95.20
X	A4M8853969B GRU	007455/(V) (GER) COVER	Less 020%	1.00	463.50
X	A4M8837205 GRU	007455/(V) (GER) HANDL	Less 020%	1.00	320.00
Parts 4,565.36					Sub-Total 5,469.36
Labour 0.00					7% GST 382.86
Sublet 5,304.00					Grand Total 5,852.22
Menus 0.00					
Lubricant 0.00					



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SMN 7489 A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1140/2019/TG
24 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q8 3.0 TFSI QU 4MN0X
Vehicle Chassis No. : WAUZZZF10KD010053
Vehicle Regn No. : SMN 7489 A
Vehicle Mileage : 758 KM
Vehicle Owner : Mr. Gao Kang
Certificate No : 1900152865
Own Damage Excess : S\$ 4708.00 (inclusive 7% GST)
Accident Date : 29/08/2019
Place : Liang Court Carpark
Repair Cost : \$ 5852.22
WIP No. : 13156
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 3pm
Date : 25/10/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Sep 2019 12:09		24 Sep 2019 11:29 Edit Adj Rpt	S\$9,869.36 Edit Estimates	S\$9,869.36 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GAO KANG, ID: S9576030I, Tel: +6587813910			
Vehicle Reg. No.:	SMN7489A	Date of Loss:	29/08/2019 20:00 - :59 [2 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 1816452211SG	Policy/Cover Note No.:	1900152865 (Comprehensive)	
		Excess:	S\$4,400.00	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Azlan, Syazairdina] syazairdina.azlan@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 03/10/2019]			
Driver/Custodian:	GUO JIN FENG (23 / Female) , NRIC: G1975048K, Tel: +6582503471 Email: NOEMAIL			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (26/09/2019): Alert - Adj Mandate Approved (S\$10448.00) - SMN7489A - Claim Handler: Azlan, Sya...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMN7489A (1816452211SG)

OD

Aug 29 2019 8:00PM

[GAO KANG]

Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/09/19 13:34	Adjuster Immediate Advice	 Load HTM	☒
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/09/19 12:45	General View	 Load JPG	☒
2	24/09/19 12:45	General View	 Load JPG	☒
3	24/09/19 12:45	General View	 Load JPG	☒
4	24/09/19 12:45	General View	 Load JPG	☒
5	24/09/19 12:45	General View	 Load JPG	☒
6	24/09/19 12:45	General View	 Load JPG	☒
7	24/09/19 12:45	General View	 Load JPG	☒
8	24/09/19 12:45	General View	 Load JPG	☒
9	24/09/19 12:45	General View	 Load JPG	☒
10	24/09/19 12:45	General View	 Load JPG	☒
11	24/09/19 12:45	General View	 Load JPG	☒
12	24/09/19 12:45	General View	 Load JPG	☒
13	24/09/19 12:45	General View	 Load JPG	☒
14	24/09/19 12:45	General View	 Load JPG	☒
15	24/09/19 12:45	General View	 Load JPG	☒
16	24/09/19 12:45	General View	 Load JPG	☒
17	24/09/19 12:45	General View	 Load JPG	☒
18	24/09/19 12:45	General View	 Load JPG	☒
19	24/09/19 12:45	General View	 Load JPG	☒
20	24/09/19 12:45	General View	 Load JPG	☒
21	24/09/19 12:45	General View	 Load JPG	☒
22	24/09/19 12:45	General View	 Load JPG	☒
23	24/09/19 12:45	General View	 Load JPG	☒
24	24/09/19 12:45	General View	 Load JPG	☒
25	24/09/19 12:45	General View	 Load JPG	☒
26	24/09/19 12:45	General View	 Load JPG	☒
27	24/09/19 12:45	General View	 Load JPG	☒
28	24/09/19 12:45	General View	 Load JPG	☒
29	24/09/19 12:45	General View	 Load JPG	☒
30	24/09/19 12:45	General View	 Load JPG	☒
31	21/01/20 17:53	Reinspection Photo	 Load JPG	☒
32	21/01/20 17:53	Reinspection Photo	 Load JPG	☒
33	21/01/20 17:53	Reinspection Photo	 Load JPG	☒
34	21/01/20 17:53	Reinspection Photo	 Load JPG	☒
35	21/01/20 17:53	Reinspection Photo	 Load JPG	☒
36	21/01/20 17:53	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print

Assessment Reports			1 per page ▾	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/09/19 14:15	OID's Passport Entry Record	Load JPG	☒
2	30/09/19 14:15	OID's Passport	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/09/19 12:25	Singapore Accident Statement	Load PDF	
2	24/09/19 12:25	Certificate of Insurance	Load JPG	☒
3	24/09/19 12:26	Driver's Driving License	Load PDF	
4	24/09/19 12:26	MARK ESTIMATE	Load PDF	
5	25/09/19 07:41	INTERVIEW FORM AND UNDERTAKING	Load PDF	
6	02/03/20 14:27	WORKSHOP INVOICE	Load PDF	
7	02/03/20 14:28	DISCHARGE VOUCHER	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser ▾
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1 per page ▾	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/12/19 18:42	Accident Statement	Load HTM	
2	06/12/19 18:45	Accident Statement	Load HTM	
3	06/12/19 18:45	Accident Statement	Load HTM	
4	06/12/19 18:48	Accident Statement	Load HTM	
Photos/Images			3 per page ▾	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/09/19 17:21	Accident Photo	Load JPG	☒
2	20/09/19 17:21	Accident Photo	Load JPG	☒
3	20/09/19 17:21	Accident Photo	Load JPG	☒
4	20/09/19 17:21	Accident Photo	Load JPG	☒
5	20/09/19 17:21	Accident Photo	Load JPG	☒
6	20/09/19 17:21	Accident Photo	Load JPG	☒
7	20/09/19 17:21	Accident Photo	Load JPG	☒
8	20/09/19 17:21	Accident Photo	Load JPG	☒
9	20/09/19 17:21	Accident Photo	Load JPG	☒
10	20/09/19 17:21	Accident Photo	Load JPG	☒
11	20/09/19 17:21	Accident Photo	Load JPG	☒
12	20/09/19 17:21	Accident Photo	Load JPG	☒
13	20/09/19 17:21	Accident Photo	Load JPG	☒
14	20/09/19 17:21	Accident Photo	Load JPG	☒
15	20/09/19 17:21	Accident Photo	Load JPG	☒
Documentation			1 per page ▾	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/09/19 17:22	Sketch Plan	Load JPG	☒
2	20/09/19 17:22	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19016792/T1VF3N2

Date: 02/03/2020

REFERENCE

Insured/Claimant:	GAO KANG	Policy No:	1900152865	Claim No:	1816452211SG
Date of Loss:	29/08/2019	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN7489A	Engine No:	DCB051783
Make & Model:	AUDI Q8, 3.0 TFSI QU TIP (A)	Chassis No:	WAUZZZF10KD010053
Reg. Date:	27/08/2019 (Man. Year: 2018)	Odometer:	751 km
Colour:	Green		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S\$366,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/50R20	Rear Tyre Size:	275/50R20
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,340.00	4,565.36	7,774.64	63.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,254.00	5,304.00	4,950.00	48.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,594.00	9,869.36	12,724.64	56.32
- Excess (S\$)	4,400.00	4,400.00	0.00	0.00
(S\$)	18,194.00	5,469.36	12,724.64	69.94
+ GST 7.00/7.00% (S\$)	1,273.58	382.86	890.72	69.94
Nett Amount (S\$)	19,467.58	5,852.22	13,615.36	69.94

INSPECTION

Date of Assignment:	24/09/2019	24 Benoi Sector
Date Inspected:	23/09/2019	Inspected At: Repairer: Premium Automobiles Pte Ltd (UBI)
		55 Ubi Road 1
		Singapore 408699
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER-UPPER	Repair	1,121.00 FS	*-FS
2	1		*REAR BUMPER-LOWER	Repair	2,269.00 FS	*-FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	154.00 FS	*-FS
4	1		*REAR BUMPER GUIDE SECTION-LH	Not Necessary	68.00 FS	*-FS
5	1		*REAR WHEEL HOUSING LINER-LH	Not Necessary	327.00 FS	*-FS
6	1		*WHEEL HOUSING LINER ATTACHMENT PARTS-FRONT AND REAR	Not Necessary	66.00 FS	*-FS
7	2		*REAR WHEEL COVER-LH/RH	N/s Missing/O/s Deformed	688.00 FS	*550.40 FS
8	1		*REAR DOOR WHEEL COVER-LH	Cut	179.00 FS	*143.20 FS
9	1		*REAR DOOR-LH	Bent	3,570.00 FS	*2,856.00 FS
10	1		*REAR DOOR OUTER SEAL-LH	Necessary	157.00 FS	*125.60 FS
11	1		*BONDING AGENT	Not Necessary	45.00 FS	*-FS
12	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*-FS
13	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	191.00 FS	*-FS
14	1		*OUTER DOOR SEAL-LH	Necessary	234.00 FS	*187.20 FS
15	1		*REAR DOOR CATCH	Necessary	96.00 FS	*76.16 FS
16	1		*OUTER DOOR SEAL-LH	Not Necessary	174.00 FS	*-FS
17	1		*SILL PANEL SEAL-LH	Not Necessary	234.00 FS	*-FS
18	1		*REAR DOOR COVER-LH	Cut	464.00 FS	*370.80 FS
19	1		*EXTERIOR DOOR HANDLE-LH	Cut	320.00 FS	*256.00 FS
20	1		*DOOR HANDLE CAP-LH	Not Necessary	36.00 FS	*-FS
21	1		*DOOR HOUSING	Not Necessary	16.00 FS	*-FS
22	1		*REAR DOOR HANDLE SENSOR-LH	Not Necessary	237.00 FS	*-FS
23	1		*REAR DOOR MOUNTING BAR-LH	Not Necessary	118.00 FS	*-FS
24	1		*ROOF MOLDING-LH	Not Necessary	493.00 FS	*-FS
25	1		*WINDOW SLOT SEAL WITH TRIM STRIP-LH OUTER	Not Necessary	191.00 FS	*-FS
26	1		*WINDOW SLOT SEAL WITH TRIM STRIP-LH OUTER	Not Necessary	327.00 FS	*-FS
27	1		*SUNDRIES	Not Necessary	500.00 FS	*-FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 12,340.00 4,565.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	360.00	360.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR.TO REPAIR LHS REAR FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,150.00	1,500.00
4	TO RESPRAY LHS REAR DOOR,DOOR COVER,DOOR HANDLE,LHS REAR FENDER,LHS REAR DOOR WHEEL ARCH TRIM,BOTH REAR WHEEL ARCH TRIMS,REAR UPPER BUMPER AND REAR LOWER BUMPER	New	6,000.00	2,700.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	384.00	384.00
Gross Labour Cost (S\$)			10,254.00	5,304.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >