## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

То : AIG Asia Pacific Insurance Pte. Ltd.

: MdNoor, Norsiah Attn

Your Ref : 4894368498SG

Our Ref : CC3/AIG19016818/T1HB3

Date : 06 Nov 2019 "WITHOUT PREJUDICE"

## ACCIDENT INVOLVING SMP1377T & SMK9681M ON 23/09/2019

Refer to the above accident.

The accident occurred when Insured vehicle rear-ended TP vehicle (BOLA 27). A letter was sent out to the Insured to notify TP claim and that his/her NCD would be affected. A copy of TP video footage was also uploaded in merimen.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have successfully / not successfully carried out TP Express Settlement between your insured (vehicle no. SMP1377T) and third party claimant (vehicle no. SMK9681M).

Summary of offer made to workshop Performance Motors Limited is as follows:

		Claimed	Revised
Cost of Repairs (w/gst)	\$	2,678.91	\$ 1,318.03
Loss of Rental (\$100 x 2 days)	\$	200.00	\$ 200.00
GIA Search Fee	\$	2.00	\$ 2.00
TOTAL	. \$	2,880.91	\$ 1,520.03

Amount of claim at Liability 100% 1,520.03

## **TOTAL NO. OF DAYS = 2 days (Surveyor recommended 3 Days)**

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,

VIC ALPEH

LKK Auto Consultants Pte Ltd