PRE-REPAIR INSPECTION REQUEST - SMM4545H vs SLA1820X (OI) on D.O.A.: 23/09/2019

From: Hor, Yinrul

To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)

Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Parthiban, Theerthan, Subramaniam, Divy

Sent: 9/23/2019 3:42:19 PM

Attachments: 7 20190923125656597.r

Hi.

Please refer to the enclosed request from Esteem Performance Pte Ltd.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster I

Singapore FNOL | Claims Operations - Auto

Tel: 8001206556 | Ext: 1002208 Yinrul.Hor@aig.com | www.aig.sg

From: Carmen Lim [mailto:carmen@esteemperf.com.sg]

Sent: Monday, September 23, 2019 2:52 PM

To: AIG SGP, Claims-Survey

Subject: [EXTERNAL] REQUEST FOR PRI SURVEY SMM4545H

This message is from an external sender; be cautious with links and attachments.

Dear AIG,

Accident involving SMM4545H & SLA1820X on 23.09.2019.

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOAL FOR NON INJURY MOTOR ACCICDENT CASES (NIMA)

We act for Tan Boon Chye who has appointed the under-mentioned workshop to repair his motor vehicle no.SMM 4545 H.

Please be informed that the said vehicle can be inspected at :

Name of workshop: Esteem Performance Pte Ltd

Address: 385 SIN MING DRIVE (S) 575718 (INSIDE VICOM)

Tel: 8799 0066 / 6566 2112

Fax: 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

We are prefer LKK Auto Consultants Pte Ltd- KENNETH to survey the car.

Thanks

Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division

Esteem Performance Pte Ltd

M: 8799 0066

P: 6484 1221

E: carmen@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259 (Head

Office

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



IMPORTANT NOTICE:

IMPORIANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.