

INS. CASE OWNER: **Loh Chee Heng**

CC6/AIG19016896/Aea3

LKK:
IDAC:

ASSIGNMENT

Surveyor: **ADRIAN** DOI: **24/09/2019** Date / Time: **24/09/2019**
Registered in Merimen: **24/09/2019**

Pre-assign / CCU / FTE



Insured Vehicle No.: **SLQ 997S** Claim No.: **1936116064SG**
Name of Insured: **LIM KOK KEONG** Policy No.: **1700020867**
Insured Tel No.: _____ HP: **+65-98710716** Make / Model: **NISSAN QASHQAI-1.2 DIG-T CVT**
Excess Sec II :SS _____ D.O.A: **23/09/2019 18:10** Place of Accident: **NUS CARPARK 2(ENGINEERING FACU**
Is driver the owner? (**YES** / NO) Nature of Accident: _____
If NO, Driver Name / Age: _____ OI GIA REPORT: **YES** / NO : TP GIA REPORT: **YES** / NO
Driver Tel No.: _____ (V/L: **YES** / NO) Insured Liability: _____ % Final ? **Yes** / No

SGB 3644D



INSRS:
WSP: **KANG CAR**
Tel: _____
Liability: _____
RMKS: _____



INSRS:
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS:
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS:
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	EMAIL 11/10
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☒ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA :	☒ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD	☒ ☐
	Payment Breakdown Form:	☐ ☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: 43 SS3,500	(10 days) Reduction: 75%	Confirm by: WSP
FINAL SETTLEMENT	Date/Time: 05.03.20	Confirm with: Surveyor
Final Liability: % 100	(Agreed / Assessed) BOLA S/N No.: 24	Email ☒ Call ☐
Repair Cost: W/169 SS3,145.00	On Bst From The Pre-Assigning Lot.	If NO or B 28, Ass. Lia: _____
Loss of Rental (LOR): SS -	(5 days)	
Loss of Use (LOU): SS 840.00	(560 x 14 days)	
Loss of Income (LOI): SS -	(5 x days)	
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐	(Tick only one)	
GIA/LTA Search: SS2.00		
Medical: SS -		
Disbursement: SS -	(e.g. Tow/ Independent)	
Legal Cost: SS -		
Total: SS4,581.00	Global Sum SS:	
FINAL PAYMENT	Date/Time: 05.03.20	Confirm with: Surveyor
Payee 1: SS4,581.00	Name 1: Wong Chee Heng Pte Ltd	Email ☒ Call ☐
Payee 2: (Strike if N.A.) SS	Name 2: _____	
Payee 3: (Strike if N.A.) SS	Name 3: _____	

COPY SENT
10/3/2020

16896/AE

SG33644D

2005 Dec

Toyota Vio
Gold

1487

163040

MR053HY4204, 58826.

Color ☒ Fair / ☐ Poor / ☐ Burnt

Engine ☒ Running / ☐ Stalled / ☐ Leaked / ☐ Burnt

Brake ☒ Working / ☐ Locked / ☐ Leaked / ☐ Burnt

Model ☒ STD / ☐ STD A / ☐ STD B

Tires ☒ F 175/65R14
☒ R 175/65R14

ES/DU/EXNOVA/GY/FG/LZA/MC/CHTSU/PR/SUM/

TOYO ☒ OK / ☐ NG

Front

Rear

REar

06

REar

06

LEar

06

LEar

06

D.O.A

D.O.A

24/09/19.

Surveyed at

Kang

Des. of Damage: ☒ Front / ☐ Rear / ☐ N/S / ☐ U/C / ☐ Rollover

The U/C / Chassis frame / Body Structure should remain intact

TPAIG.

COE Expiry: 30/11/20.

1/2: +3,500 (RED: +10,721.51 75%)

MV 10K 10,500

PV 67K 6,495

Nett 331C 3,805

Repay Limited +3,500.



Print Name
Print Name

Date of Issue

Expiry Date



Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/09/2019
TP Veh Reg No: SLQ997S

Estimate No: EST1900315
Date: 25 Sep 2019
Veh Reg No: SGB3644D
Make/Model: TOYOTA VIOS 1.5E A
Chassis No: MR053HY4204158826
Reg. Date: 16/12/2005
Your Ref No: SLQ997S

Asher

Estimate Repair Cost to Vehicle No :SGB3644D

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC FRT FENDER RH <i>Distorted</i>	530.10	✓
2	1 PC FRT FENDER COWLING RH <i>Distorted</i>	151.90	✓
3	1 PC FRT DOOR RH <i>Distorted</i>	819.20	✓
4	2 PCS FRT DOOR HINGE RH <i>Distorted</i>	171.60	✓
5	1 PC FRT DOOR CHECK RH	152.10	✓
6	1 PC FRT DOOR PROTECTOR RH <i>Distorted</i>	160.70	✓
7	1 PC FRT DOOR OUTER HANDLE RH <i>Distorted</i>	88.40	+
8	1 PC FRT DOOR KEY LOCK RH <i>Distorted</i>	166.70	✓
9	1 PC FRT DOOR KEY COVER RH	38.50	✓
10	1 PC FRT RH DOOR INNER LOCK <i>Distorted</i>	424.80	✓
11	1 PC FRT RH DOOR INNER LOCK CHECKER <i>Distorted</i>	24.50	✓
12	1 PC FRT RH DOOR OUTER MOULDING <i>Distorted</i>	83.20	+
13	1 PC FRT DOOR GLASS CHANNEL RH <i>Distorted</i>	150.70	+
14	1 PC FRT DOOR REGULATOR ASSEMBLY RH <i>Distorted</i>	738.30	+
15	1 PC FRT DOOR RUBBER RH <i>Distorted</i>	186.90	✓
16	1 PC FRT RH DOOR TRIM <i>Distorted</i>	749.30	+
17	1 PC REAR DOOR RH <i>Distorted</i>	703.60	✓
18	2 PCS REAR DOOR HINGE RH <i>Distorted</i>	157.60	✓
19	1 PC REAR DOOR RH CHECK <i>Distorted</i>	152.10	✓
20	1 PC REAR DOOR PROTECTOR RH <i>Distorted</i>	78.80	✓
21	1 PC REAR DOOR OUTER HANDLE RH <i>Distorted</i>	65.90	+
22	1 PC REAR DOOR INNER LOCK RH <i>Distorted</i>	437.30	✓
23	1 PC REAR DOOR RUBBER RH <i>Distorted</i>	158.90	✓
24	1 PC REAR DOOR GLASS CHANNEL RH	150.70	+
25	1 PC REAR DOOR GLASS CHANNEL PILLAR RH	165.50	+
26	1 PC REAR DOOR GLASS REGULATOR ASSY RH	695.20	+
27	1 PC REAR DOOR TRIM RH	689.50	+
28	1 PC REAR DOOR OUTER MOULDING RH	83.20	+
29	1 PC REAR FENDER RH <i>Distorted</i>	804.80	✓
30	1 PC REAR WINDSCREEN MOULDING <i>Distorted</i>	89.30	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/09/2019
TP Veh Reg No: SLQ997S

Estimate No: EST1900315
Date: 25 Sep 2019
Veh Reg No: SGB3644D
Make/Model: TOYOTA VIOS 1.5E A
Chasis No: MR053HY4204158826
Reg. Date: 16/12/2005
Your Ref No: SLQ997S

Estimate Repair Cost to Vehicle No :SGB3644D

Quantity	Description	List Price	Amount
		SS	SS
31	1 PC TAIL LAMP - RH <i>new</i>	352.70 <i>x</i>	
32	1 PC REAR BUMPER <i>Rpr</i>	427.90 <i>T</i>	
33	1 PC REAR BUMPER RETAINER RH <i>2</i>	113.80 <i>x</i>	
34	1 PC FRT SHOCK ABSORBER RH	325.50 <i>x</i>	
35	1 PC FRT LOWER ARM RH	792.30 <i>x</i>	
36	1 PC FRT KNUCKLE ARM RH	542.60 <i>x</i>	
37	1 PC FRT WHEEL HUB RH	190.70 <i>x</i>	
38	1 PC FRT DRIVE SHAFT RH	1,253.80 <i>x</i>	
		13,068.60	
		Less 25%	3,267.15
			9,801.57
	Special Net		
39	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	40.00 <i>30</i>	
40	1 PC REAR WINDSCREEN SEAL <i>3 new</i>	60.00 <i>40</i>	
41	1 PC REAR WINDSCREEN SEALANT <i>2 new</i>	60.00 <i>40</i>	
42	1 SET REAR BUMPER CLIPS <i>new</i>	40.00 <i>x</i>	
		200.00	200.00
	Labour		
43	1 TOWING	50.00 <i>✓</i>	
44	1 TO CHECK WIRING	50.00 <i>30</i>	
45	1 TO REMOVE AND REFIX REAR DOOR GLASS <i>fitting</i>	100.00 <i>80</i>	
46	1 TO REMOVE AND REFIX FRT DOOR GLASS <i>fitting</i>	100.00 <i>20</i>	
47	1 TO REMOVE AND REFIT SEAT CUSHION	150.00 <i>x</i>	
48	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 <i>✓</i>	
49	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 <i>50</i>	
50	1 TO REMOVE AND REFIT UNDERCARRIAGE	300.00 <i>x</i>	
51	1 TO CHECK WHEEL ALIGNMENT	120.00 <i>x</i>	
52	1 TO SPRAY UNDERSEAL	150.00 <i>80</i>	
53	1 TO SPRAY PAINTING	1,500.00 <i>1000</i>	
54	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00 <i>1000</i>	

2490

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST-201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 23/09/2019
TP Veh Reg No: SLQ997S

Estimate No: EST1900315
Date: 25 Sep 2019
Veh Reg No: SGB3644D
Make/Model: TOYOTA VIOS 1.5E A
Chasis No: MR053HY4204158826
Reg. Date: 16/12/2005
Your Ref No: SLQ997S

Estimate Repair Cost to Vehicle No :SGB3644D

Quantity	Description	List Price SS	Amount SS
		4,220.00	4,220.00
Total			SS 14,221.57
Add GST @ 7%			995.51
Total Amount Payable			SS 15,217.08

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND TWO HUNDRED SEVENTEEN AND CENTS EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 6484.77

h/s : 35K (Next Value)

11 Days

35K

11 Days

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 624C

Vehicle Details

Vehicle No.: SGB3644D
Vehicle to be Exported: No
Intended Deregistration Date: 24 Sep 2019
Vehicle Make: TOYOTA
Vehicle Model: VIOS 1.5E A
Primary Colour: Gold
Manufacturing Year: 2005
Engine No.: 1NZX340515
Chassis No.: MR053HY4204158826
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$12,903.00
Original Registration Date: 16 Dec 2005
First Registration Date: 16 Dec 2005
Transfer Count: 4
Actual ARF Paid: \$14,194.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Nov 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$28,292.00
COE Rebate Amount: \$6,695.00
Total Rebate Amount: \$6,695.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Sep 2019

OK



ISLAMIC. FAST. CONVENIENT.
Your financial needs fulfilled.



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Renewal Coe Toyota Altis 1.6A



2.88% P.A. \$0 Admin, \$0 Down,
From \$468 Mthly, Sta "B" 2 Yrs
Warranty Engine, Gear
GV Credit Pte Ltd - StarAd



**Lake View
Credit Pte Ltd**

[View our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category



Save Search



Print

< Back (1 2 3 4 5 6) Next >

Sort by Date Posted

20 results/page

105 vehicles

Search Vios

Advanced Search

Search

View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection Vios Any Any > 10 year(s) old Any Any Any Available



☐ Toyota Vios 1.5A E (New 5-yr COE)

\$27,800

\$5,550 /yr

23-Jul-2009

1,497 cc

-

Sedan

Available

2.88% Per Annum, \$438 Monthly, \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox. In House Finance, In House Work...
2.88% P.A. \$0 Admin, \$0 Down, From \$438 Mthly, Sta "B" 2 Yrs Warranty Engine, Gear
GV Credit Pte Ltd

RENEWAL COE

Posted: 24-Sep-2019 Tags: 2009 Toyota Vios, 2009 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Vios, Vios, Used Toyota



☐ Toyota Vios 1.5M E (COE till 12/2020)

\$8,800

\$7,320 /yr

07-Dec-2005

1,497 cc

-

Sedan

Available

New Engine Mounting! Very Well Maintained By Owner. No Repairs Needed. Car In Original Condition. Call Our Friendly Representatives For More Information Or For A Viewing Of The Car.

88 Motor Trading

Posted: 30-Aug-2019 Tags: 2005 Toyota Vios, 2005 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Vios, Vios, Used Toyota



☐ Toyota Vios 1.5A E (COE till 11/2020)

\$9,500

\$8,010 /yr

20-Dec-2005

1,497 cc

-

Sedan

Available

Full Loan Available At, We Can Help To Convert To Z10 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including Weekend Fro...

88 Motor Trading

Posted: 30-Aug-2019 Tags: 2005 Toyota Vios, 2005 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Vios, Vios, Used Toyota



☐ Toyota Vios 1.5A E (COE till 01/2021)

\$10,500

\$8,220 /yr

03-Jan-2006

1,497 cc

105,722 km

Sedan

Available

Excellent And Original Condition, Well Maintained Interior And Exterior, Call Now For Viewing. Tax Till Jan 2020. Tip Top Condition.

Posted: 17-Sep-2019 Tags: 2006 Toyota Vios, 2006 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Vios, Vios, Used Toyota

WARRANTY OWNER

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ Toyota Vios 1.5A E (COE till 06/2021)

\$12,800

\$7,500 /yr

09-Jun-2006

1,497 cc

-

Sedan

Available

Car Well Maintained. Serviced Regularly. Idea For Short Term Drive. Call Now To Arrange A Test Drive Today!

Posted: 15-Sep-2019 Tags: 2006 Toyota Vios, 2006 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Vios, Vios, Used Toyota



☐ Toyota Vios 1.5A E (COE till 05/2021)

\$12,800

\$7,600 /yr

12-Jun-2006

1,497 cc

148,271 km

Sedan

Available

Well Maintained Original Condition, Engine Oil/Oil Filter, Toyota Transmission Fluid, New Amaron Battery Just Changed, A Unit Not To Be Missed, Call Now For Viewing!

Posted: 14-Sep-2019 Tags: 2006 Toyota Vios, 2006 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Vios, Vios, Used Toyota

DIRECT OWNER

SHORTLISTED HISTORY

Compare (4)

Toyota Vios 1.5A E (COE till

\$13,999

\$7,920 /yr

06-Jul-2006

1,497 cc

140,855 km

Sedan

Available

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Tuesday, 8 October 2019 9:35 AM
To: kangcar@singnet.com.sg
Cc: Kang Car (yahoo); Admin A
Subject: RE: ACCDT INVLG SGB3644D & SLQ997S ON 23.09.2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Su Li (LKK Auto) <suli@lkkauto.com>
Sent: Monday, 7 October 2019 11:21 AM
To: kangcar@singnet.com.sg; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Cc: Kang Car (yahoo) <kangcar176@yahoo.com.sg>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: RE: ACCDT INVLG SGB3644D & SLQ997S ON 23.09.2019

Without Prejudice

Dear Sir / Madam,

Thank you for your email.

Please be informed that this matter is now handled by my colleague, Ms Asher.

Hi Asher,

FYNA, our ref CC6/AIG19016896/Aea3

Thank you.

Best Regards,

Su Li | Admin Support

LKK Auto Consultants Pte Ltd

Phone: 6841 2157 (Ext:119) Email: SuLi@lkkauto.com Fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: kangcar@singnet.com.sg [<mailto:kangcar@singnet.com.sg>]

Sent: Monday, 7 October 2019 11:19 AM

To: CS A Team

Cc: Kang Car (yahoo); Admin A

Subject: ACCDT INVLG SGB3644D & SLQ997S ON 23.09.2019

WITHOUT PREJUDICE

Dear Sirs,

We refer to the above matter.

Our client's vehicle was surveyed by Mr Adrian Ling on 24.09.2019.

We would like to proceed for Direct Settlement and kindly advise if your insured reported the accident and the liability.

Kindly revert.

Thank you & Regards,

Sharon

Kang Car Repairers Pte Ltd

Tel: 6747 7636

Fax: 6748 5071

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	25 Sep 2019 17:29	Clim Dtl Modified	Claimant's Name: -> CHIA PUEY LENG. Claimant's ID: -> S1719624C.	[A] HOW MEI KWAN
2	25 Sep 2019 17:29	Clim Veh Model Changed	(200942) TOYOTA VIOS 1.5 E (A).	[A] HOW MEI KWAN
3	25 Sep 2019 17:29	Clim Created	Reg No: SGB3644D. Acct Date: 2019/09/23. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ). Workshop: Kang Car Repairers Pte Ltd (HQ)	[A] HOW MEI KWAN
4	25 Sep 2019 17:29	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	25 Sep 2019 17:29	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/04	[A] HOW MEI KWAN
6	25 Sep 2019 17:29	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	25 Sep 2019 17:29	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	25 Sep 2019 17:29	Label Added	(19):Fastlane.	[A] HOW MEI KWAN
9	25 Sep 2019 17:29	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] HOW MEI KWAN
10	21 Feb 2020 08:46	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
11	21 Feb 2020 08:46	Clim Dtl Modified	Claim Conclusion: -> 3.	[A] JOANNE LEE KHANG MIN
12	21 Feb 2020 08:46	Clim Dtl Modified	JPJ Reg. Date: -> 2005/12/16.	[A] JOANNE LEE KHANG MIN
13	21 Feb 2020 08:46	Clim Details Notified		[A] JOANNE LEE KHANG MIN
14	26 Feb 2020 11:56	Adj Mandate Request	Cur.Req:4587.00:LIABILITY: 100% B:24 OI EXIT FROM PARKING LOT HIT TP	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No.	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2292954	26 Sep 2019 16:05:44	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SGB3644D	SLQ997S	11.77
2445301	21 Feb 2020 08:46:41	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SGB3644D	SLQ997S	11.77

Print Received Message

This mail is associated with :

***SGB3644D (1936116064SG)**
[SLQ997S]

TP
CHIA PUEY LENG
Sep 23 2019 6:00PM
[LIM KOK KEONG]
Kang Car Repairers Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 03/03/2020 17:33 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4587.00) - SGB3644D - Claim Handler: Loh, Chee-Heng

Approved:4587.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Sep 2019 Edit Reg		24 Sep 2019 00:00 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	LIM KOK KEONG, ID: S7734544B		
Main Claimant:	CHIA PUEY LENG, ID: S1719624C		
Vehicle Reg. No.:	SGB3644D	Date of Loss:	23/09/2019 18:00 - :59 [165 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1936116064SG	Policy/Cover Note No.:	17D0020867 (Comprehensive) Coverage: 28/06/2019 - 27/06/2020
Vehicle Reg. No. (Insured):	SLQ997S	Policy No. (Claimant):	5109490392
		Excess:	
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477635		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 04/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (03/03/2020): Alert - Adj Mandate Approved (S\$4587.00) - SGB3644D - Claim Handler: Loh, Chee-H...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGB3644D (1936116064SG)
[SLQ997S]
TP
CHIA PUEY LENG
Sep 23 2019 6:00PM
[LIM KOK KEONG]
Kang Car Repairers Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View View in Browser

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/11/19 14:27	General View	1	Load JPG	☒
2	27/11/19 14:27	General View	1	Load JPG	☒
3	27/11/19 14:27	General View	1	Load JPG	☒
4	27/11/19 14:27	General View	1	Load JPG	☒
5	27/11/19 14:27	General View	1	Load JPG	☒
6	27/11/19 14:27	General View	1	Load JPG	☒
7	27/11/19 14:27	General View	1	Load JPG	☒
8	27/11/19 14:27	General View	1	Load JPG	☒
9	27/11/19 14:27	General View	1	Load JPG	☒
10	27/11/19 14:27	General View	1	Load JPG	☒
11	27/11/19 14:27	General View	1	Load JPG	☒
12	27/11/19 14:27	General View	1	Load JPG	☒
13	27/11/19 14:27	General View	1	Load JPG	☒
14	27/11/19 14:27	General View	1	Load JPG	☒
15	27/11/19 14:27	General View	1	Load JPG	☒
16	27/11/19 14:27	General View	1	Load JPG	☒
17	27/11/19 14:27	General View	1	Load JPG	☒
18	27/11/19 14:27	General View	1	Load JPG	☒
19	27/11/19 14:27	General View	1	Load JPG	☒
20	27/11/19 14:27	General View	1	Load JPG	☒
21	27/11/19 14:27	General View	1	Load JPG	☒
22	27/11/19 14:27	General View	1	Load JPG	☒
23	27/11/19 14:27	General View	1	Load JPG	☒
24	27/11/19 14:27	General View	1	Load JPG	☒
25	27/11/19 14:27	General View	1	Load JPG	☒
26	27/11/19 14:27	General View	1	Load JPG	☒
27	27/11/19 14:27	General View	1	Load JPG	☒
28	27/11/19 14:27	General View	1	Load JPG	☒
29	27/11/19 14:27	General View	1	Load JPG	☒
30	27/11/19 14:27	Reinspection Photo	1	Load JPG	☒
31	27/11/19 14:27	Reinspection Photo	1	Load JPG	☒
32	27/11/19 14:27	Reinspection Photo	1	Load JPG	☒
33	27/11/19 14:27	Reinspection Photo	1	Load JPG	☒
34	27/11/19 14:27	Reinspection Photo	1	Load JPG	☒
35	27/11/19 14:27	Reinspection Photo	1	Load JPG	☒
36	27/11/19 14:27	Reinspection Photo	1	Load JPG	☒
37	27/11/19 14:27	Reinspection Photo	1	Load JPG	☒
38	27/11/19 14:27	Reinspection Photo	1	Load JPG	☒
39	27/11/19 14:27	Reinspection Photo	1	Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/09/19 17:29	TP GIA REPORT	 Load PDF	
2	11/10/19 11:04	LETTER TO OI	 Load PDF	
3	21/02/20 09:05	GIA SEARCH	 Load PDF	
4	21/02/20 09:05	LOD	 Load PDF	
5	12/03/20 10:43	WORKSHOP INVOICE	 Load PDF	
6	12/03/20 10:43	AUTHORISATION TO ACT FORM	 Load PDF	
7	12/03/20 10:43	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/09/19 16:03	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLQ997S (Insd veh)	Model:	TOYOTA VIOS 1.5 E (A)
	SGB3644D (TP veh)		
Date of Accident:	23/09/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	15,216.95
Final Repair Cost	:	\$	3,745.00
Loss of Use	:	\$	840.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,587.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kang Car Repairers Pte Ltd	:	\$ 4,587.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

12 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19016896/AEA3Q2

Date: 12/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700020867

Claimant Vehicle No: SGB3644D Insured Vehicle No: SLQ997S

Date of Loss: 23/09/2019 Nature of Claim: TP Claim No: 1936116064SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGB3644D

Make & Model: TOYOTA VIOS, 1.5 E (A)

Engine No: 1NZX340515

Reg. Date: 16/12/2005 (Man. Year: 2005)

Chassis No: MR053HY4204158826

Colour: Gold

Odometer: 163040 km

Engine Capacity: 1497 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R14

Rear Tyre Size: 175/65 R14

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,001.45	3,994.77	6,006.68	60.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,220.00	2,490.00	1,730.00	41.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,221.45	6,484.77	7,736.68	54.40
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	14,221.45	3,500.00	10,721.45	75.39
+ GST 7.00/7.00% (S\$)	995.50	245.00	750.50	75.39
Nett Amount (S\$)	15,216.95	3,745.00	11,471.95	75.39
+ Loss of Use (14.0 x S\$60.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,587.00		

INSPECTION

Date of Assignment: 24/09/2019

Date Inspected: 24/09/2019 Inspected At:

Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 11.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER RH	Distorted	530.10 FL	*530.10 FL
2	1		*FRT FENDER COWLING RH	Deformed	151.90 FL	*151.90 FL
3	1		*FRT DOOR RH	Distorted	819.20 FL	*819.20 FL
4	2		*FRT DOOR HINGE RH	Bent	171.60 FL	*171.60 FL
5	1		*FRT DOOR CHECK RH	Bent	152.10 FL	*152.10 FL
6	1		*FRT DOOR PROTECTOR RH	Distorted	160.70 FL	*160.70 FL
7	1		*FRT DOOR OUTER HANDLE RH	Repair	88.40 FL	*- FL
8	1		*FRT DOOR KEY LOCK RH	Not Necessary	166.70 FL	*- FL
9	1		*FRT DOOR KEY COVER RH	Not Necessary	38.50 FL	*- FL
10	1		*FRT RH DOOR INNER LOCK	Damaged	424.80 FL	*424.80 FL
11	1		*FRT RH DOOR INNER LOCK CHECKER	Not Necessary	24.50 FL	*- FL
12	1		*FRT RH DOOR OUTER MOULDING	Not Necessary	83.20 FL	*- FL
13	1		*FRT DOOR GLASS CHANNEL RH	Not Necessary	150.70 FL	*- FL
14	1		*FRT DOOR REGULATOR ASSEMBLY RH	Not Necessary	738.30 FL	*- FL
15	1		*FRT DOOR RUBBER RH	Necessary	186.90 FL	*186.90 FL
16	1		*FRT RH DOOR TRIM	Not Necessary	749.30 FL	*- FL
17	1		*REAR DOOR RH	Distorted	703.60 FL	*703.60 FL
18	2		*REAR DOOR HINGE RH	Bent	157.60 FL	*157.60 FL
19	1		*REAR DOOR RH CHECK	Bent	152.10 FL	*152.10 FL
20	1		*REAR DOOR PROTECTOR RH	Distorted	78.80 FL	*78.80 FL
21	1		*REAR DOOR OUTER HANLE RH	Not Necessary	65.90 FL	*- FL
22	1		*REAR DOOR INNER LOCK RH	Damaged	437.30 FL	*437.30 FL
23	1		*REAR DOOR RUBBER RH	Bent	158.90 FL	*158.90 FL
24	1		*REAR DOOR GLASS CHANNEL RH	Not Necessary	150.70 FL	*- FL
25	1		*REAR DOOR GLASS CHANNEL PILLAR RH	Not Necessary	165.50 FL	*- FL
26	1		*REAR DOOR GLASS REGULATOR ASSY RH	Not Necessary	695.20 FL	*- FL
27	1		*REAR DOOR TRIM RH	Not Necessary	689.50 FL	*- FL
28	1		*REAR DOOR OUTER MOULDING RH	Not Necessary	83.20 FL	*- FL
29	1		*REAR FENDER RH	Distorted	804.80 FL	*804.80 FL
30	1		*REAR WINDSCREEN MOULDING	Necessary	89.30 FL	*89.30 FL
31	1		*TAIL LAMP -RH	Repair	352.70 FL	*- FL
32	1		*REAR BUMPER	Repair	427.90 FL	*- FL
33	1		*REAR BUMPER RETAINER RH	Not Necessary	113.80 FL	*- FL
34	1		*FRT SHOCK ABSORBER RH	Not Necessary	325.50 FL	*- FL
35	1		*FRT LOWER ARM RH	Not Necessary	792.30 FL	*- FL
36	1		*FRT KNUCKLE ARM RH	Not Necessary	542.60 FL	*- FL
37	1		*FRT WHEEL HUB RH	Not Necessary	190.70 FL	*- FL
38	1		*FRT DRIVE SHAFT RH	Not Necessary	1,253.80 FL	*- FL
39	1		*SET FRT FENDER COWLING CLIPS RH	Necessary	40.00 FS	*30.00 FS
40	1		*REAR WINDSCREEN SEAL	Necessary	60.00 FS	*40.00 FS
41	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
42	1		*SET REAR BUMPER CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,268.60	5,289.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,267.15	1,294.93
Total Parts (\$\$)	10,001.45	3,994.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	50.00	50.00
2	TO CHECK WIRING	New	50.00	30.00
3	TO REMOVE AND REFIX REAR DOOR FITTINGS	New	100.00	80.00
4	TO REMOVE AND REFIX FRT DOOR FITTINGS	New	100.00	80.00
5	TO REMOVE AND REFIT SEAT CUSHION	New	150.00	0.00
6	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
7	TO REMOVE AND REFIT REVERSE SENSOR	New	80.00	50.00
8	TO REMOVE AND REFIX UNDERCARRIAGE	New	300.00	0.00
9	TO CHECK WHEEL ALIGNMENT	New	120.00	0.00
10	TO SPRAY UNDERSEAL	New	150.00	80.00
11	TO SPRAY PAINTING	New	1,500.00	1,000.00
12	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING /WELDING WORKS	New	1,500.00	1,000.00
Gross Labour Cost (\$\$)			4,220.00	2,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >